

RESTORATION CONTRACTOR'S REPORT

Crossroads Restoration Services · Our reference CRS-2026-0126

INSTRUCTIONS

Instructed by:	Pemberton Wexler Associates, Inc.
On behalf of:	Meadowcrest Assisted Living Communities, Inc.
Policy number:	CP-6650-11223
Author:	Perpetua Vandenberg-Okoye, IICRC CDS
Instructed by:	Meadowcrest Assisted Living Communities, Inc.
Instructed on:	26 January 2026, 06:20
Site attendance:	26 January to 8 February 2026
Scope:	Emergency mitigation, drying and controlled demolition

COMMUNITY AND AREAS AFFECTED

Community:	Meadowcrest at Zionsville, 88 licensed beds, built 2013
Construction:	Two storeys, wood frame with brick veneer, NFPA 13R sprinklered
East wing:	Rooms 118 to 142 and 218 to 242, 50 rooms
Kitchen and servery:	Serving line, two reach-ins, dish machine, dry goods
Systems:	Nurse call head end degraded, elevator No. 2 out of service

RESTORATION CONTRACTOR'S REPORT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

A two-storey assisted living community of 88 licensed beds, fully sprinklered to NFPA 13R. The split occurred in the east wing attic, which is served by two unit heaters. The facilities director reports both were operational and that the split occurred at a section of line running close to a soffit vent.

FINDINGS

Findings:

Water tracked from the attic through the ceiling assemblies into fifty resident rooms on both floors and along the east corridor, and through the kitchen ceiling onto the serving line. Ceiling collapse occurred in nine rooms. Moisture readings on arrival ranged from 34% to 46% WME. Controlled demolition of saturated ceiling assemblies began the same morning. A continuous fire watch was maintained from 04:20 on 26 January until the system was restored to service at 11:40 on 28 January, and the Indiana State Department of Health was notified at 08:00 on 26 January under the licensure requirements.

Date of loss:	26 January 2026
Cause of loss:	Freeze — frozen sprinkler branch line in the east wing attic
Incident reference:	ZFD-2026-000188
Injuries reported:	0

RESTORATION CONTRACTOR'S REPORT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Emergency mitigation, extraction and drying	USD 214,000
Resident rooms, 50, ceilings and finishes	USD 940,000
East corridor and common areas:	USD 186,000
Kitchen, servery and equipment:	USD 268,000
Nurse call, elevator pit and electrical:	USD 232,000
Estimated loss:	2,900,000
Currency:	USD

ON RESIDENT RELOCATION

Comment:

Twenty-two residents were relocated within the community and twenty-eight to two sister communities and a contracted skilled nursing partner. Relocation, transfer and agency staffing costs are accruing and are not included in the figures above.

RECOMMENDATION

Recommendation:

Complete drying before reinstatement. Do not return the east wing to service until the nurse call system is fully restored and certified.