

# STRUCTURAL ENGINEER'S REPORT

Braeburn Structural Group · Our reference BSG-2026-0227

---

## INSTRUCTIONS

|                  |                                                           |
|------------------|-----------------------------------------------------------|
| Instructed by:   | <b>Ashcombe Vail Commercial Insurance Services</b>        |
| On behalf of:    | <b>Rivergate Development Partners, LLC</b>                |
| Policy number:   | <b>BR-3358-20471</b>                                      |
| Author:          | <b>Ingrid Achterberg-Nakamura, PE, SE</b>                 |
| Instructed by:   | <b>Vanterra Construction Group, LLC</b>                   |
| Instructed on:   | <b>26 February 2026</b>                                   |
| Site attendance: | <b>27 February 2026</b>                                   |
| Scope:           | <b>Podium deck integrity and the Level 3 wall section</b> |

## PROJECT AND WORKS AFFECTED

|                     |                                                                      |
|---------------------|----------------------------------------------------------------------|
| Project:            | <b>Rivergate Commons Phase II, 214 units over a two-level podium</b> |
| Level 3 north-east: | <b>26 lin ft wall destroyed, 340 sq ft sheathing and WRB torn</b>    |
| Podium deck:        | <b>Two impact craters, shored pending engineer's detail</b>          |
| Materials:          | <b>38 joists, 6 LVLs, 46 sheets sheathing</b>                        |
| Construction hoist: | <b>Mast tie bent, hoist out of service</b>                           |

# STRUCTURAL ENGINEER'S REPORT

Circumstances and findings

---

## CIRCUMSTANCES

Circumstances:

The building is a five-storey light-gauge and wood-framed structure over a two-level precast concrete parking podium. At the date of loss the podium and Levels 2 and 3 were framed and sheathed, Level 4 was in progress, and the building was not dried in.

## FINDINGS

Findings:

Two impact locations on the podium topping. The larger, approximately 460 mm by 610 mm, has fractured the topping through to the plank and exposed two prestressing strands over a 300 mm length. Neither strand is severed. Hammer sounding either side of the crater indicates delamination extending roughly 400 mm beyond the visible edge. The second location is surface spalling only. The Level 3 wall section is racked and out of plumb by 38 mm over the storey height and is not repairable in place; it requires demolition and rebuild. The bay has been shored and no load is permitted on it.

|                     |                                                     |
|---------------------|-----------------------------------------------------|
| Date of loss:       | <b>26 February 2026</b>                             |
| Cause of loss:      | <b>Dropped load — wind gust during a crane pick</b> |
| Incident reference: | <b>RGC2-IR-2026-014</b>                             |
| Injuries reported:  | <b>0</b>                                            |

# STRUCTURAL ENGINEER'S REPORT

Preliminary quantum and reserve advice

---

## PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Podium deck repair to engineer's detail: **USD 165,000**

Level 3 wall demolition and rebuild: **USD 74,000**

Materials — joists, LVLs, sheathing: **USD 96,500**

Temporary shoring and edge protection: **USD 31,000**

Construction hoist inspection and repair: **USD 18,500**

Estimated loss: **407,200**

Currency: **USD**

## ON THE STRANDS

Comment:

Neither exposed strand is severed and neither shows section loss. Core sampling either side of the crater is required to confirm that before the repair detail is finalised; if section loss is found the repair becomes a plank replacement and the figure above will not hold.

## RECOMMENDATION

Recommendation:

Maintain the shoring until the repair is complete and cored. Do not reload the bay. Re-survey the Level 3 frame either side of the rebuilt section.