

FIRE INVESTIGATION REPORT

Tulsa Fire Department, Fire Investigation Division · Our reference TFD-2025-0091447

INSTRUCTIONS

Instructed by:	Kettleridge Risk Partners, LLC
On behalf of:	Sundale Property Group, LLC
Policy number:	
Author:	R. Halvorsen-Ekwueme, Fire Investigator, Badge 4471
Report type:	NFIRS 111 — building fire
Alarm:	21 November 2025, 02:14 CST
Controlled:	03:41 CST
Released:	Public records copy, 4 December 2025

BUILDING AND UNITS AFFECTED

Building:	Residential Building K, also Building 06 on the site plan
Units:	24 dwelling units in three stacked tiers, built 2004, not sprinklered
Total loss:	K-206 unit of origin and K-306 directly above
Uninhabitable:	All 24 units pending electrical clearance
Adjacent:	Building L east elevation, 400 sq ft siding, four windows

FIRE INVESTIGATION REPORT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

A three-storey garden apartment building of wood frame with brick veneer and a composition shingle roof, built in 2004 and not sprinklered. Each unit has hard-wired interlinked smoke alarms; there is no common-area detection. On-site management identified the ownership entity as Windrow Grove Apartments LP and the manager as Sundale Residential Management, with a regional office in Tulsa.

FINDINGS

Findings:

The area of origin is the enclosed laundry alcove of Unit K-206 and the point of origin is at or immediately behind the electric clothes dryer. The transition duct is a foil-type flexible connector, crushed behind the appliance, with heavy lint accumulation. Thermal patterns, the appliance's internal fire damage and the elimination of other ignition sources support ignition at the dryer. The cause is classified accidental. No indication of incendiary activity and no accelerant alert. The attic void is common across each stack and no draftstopping was observed at the unit demising walls in the area examined, which is what allowed the fire to run above the second and third floors.

Date of loss:	21 November 2025
Cause of loss:	Fire — lint ignition at a clothes dryer
Incident reference:	TFD-2025-0091447
Injuries reported:	3

FIRE INVESTIGATION REPORT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Structure loss estimate, NFIRS:	USD 1,850,000
Contents loss estimate, NFIRS:	USD 410,000
Pre-incident structure value:	USD 3,150,000
Pre-incident contents value:	USD 620,000
Estimated loss:	2,610,000
Currency:	USD

EVIDENCE RETAINED AND INTERESTED PARTIES

Comment:

The dryer, the flexible transition duct, the rigid wall-cavity duct section and the terminal block are held in secure evidence storage under numbers TFD-E-25-2211 to TFD-E-25-2214 and will be released to the property's insurer or its engineer on written request and a joint examination protocol. Management was advised in writing that the appliance manufacturer and the party responsible for installation may have an interest. The appliance was installed by the complex's maintenance department in 2019.

RECOMMENDATION

Recommendation:

Arrange a joint examination before any destructive testing. Referred to City of Tulsa Development Services on the question of attic draftstopping at construction.