

ROOF CONSULTANT'S REPORT

Ridgeline Roof Consultants · Our reference RRC-2026-0442

INSTRUCTIONS

Instructed by:	Kettleridge Risk Partners, LLC
On behalf of:	Sundale Property Group, LLC
Policy number:	CP-7735-19042
Author:	Étienne Baumgartner-Osei, RRO
Instructed by:	Kettleridge Risk Partners, LLC
Instructed on:	20 April 2026
Site attendance:	20 and 21 April 2026
Scope:	Hail and wind damage assessment across all fifteen roofs

AFFECTED BUILDINGS

Buildings 03, 04, 06, 08, 11:	Hail bruising with mat fracture, creased tabs
Building 05:	240 sq ft decking loss, water into four units
Building 13 — clubhouse:	Skylight shattered, 1,100 sq ft flooring
Building 15 — carports:	Nine of 36 bays crushed or displaced

ROOF CONSULTANT'S REPORT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

The community comprises twelve three-storey residential buildings, a clubhouse, a maintenance building and detached carports, built in 2004. All composition shingle roofs were replaced in 2019. Drone imagery was flown over all fifteen roofs and 4 ft by 4 ft test squares were cut on Buildings 03, 05 and 11.

FINDINGS

Findings:

Test squares on Buildings 03, 05 and 11 returned 9, 11 and 8 hail impacts respectively per square, with mat fracture confirmed on 24 of the 28 strikes examined. Mat fracture is functional damage, not cosmetic marring: the mat is the water-shedding layer and a fractured mat will fail within one to three seasons regardless of appearance. Buildings 04, 06 and 08 show comparable density on drone imagery and warrant the same conclusion. Buildings 01, 02, 07, 09, 10, 12 and 14 show granule loss without mat fracture and are, in this consultant's opinion, cosmetic only. Full replacement is indicated on six buildings, not fifteen.

Date of loss:	19 April 2026
Cause of loss:	Hail and straight-line wind
Incident reference:	NWS-TSA-2026-0419
Injuries reported:	0

ROOF CONSULTANT'S REPORT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Roof replacement, six buildings:	USD 1,284,000
Building 05 decking, interior repair, four	USD 268,000
Clubhouse skylight and interior:	USD 96,000
Carport structures, nine bays:	USD 142,000
HVAC condensing units, 31 off:	USD 118,000
Siding, signage, site lighting, landscaping	USD 78,000
Estimated loss:	2,400,000
Currency:	USD

ON THE COSMETIC DAMAGE EXCLUSION

Comment:

The policy carries a cosmetic damage exclusion for roof surfacing. That exclusion is written to defeat claims for appearance, and this consultant's test squares distinguish the two conditions on evidence rather than assertion: the six buildings claimed exhibit mat fracture and the nine excluded from the claim do not.

RECOMMENDATION

Recommendation:

Replace the six identified roofs to current code including ice and water shield at the eaves.
Re-inspect the remaining nine at the next renewal.