GEK-SA-1047B

WEXP for the UCPA Controller

Instructions for GE Lufkin

Aug 2021



 ***Warning***	To prevent personal injury or damage to equipment, follow all equipment safety procedures, Lockout Tagout (LOTO), and site safety procedures as indicated by Employee Health and Safety (EHS) guidelines.

 ***Warning***	This equipment contains a potential hazard of electric shock, burn, or death. Only personnel who are adequately trained and thoroughly familiar with the equipment and the instructions should install, operate, or maintain this equipment.

 *Warning*	Isolation of test equipment from the equipment under test presents potential electrical hazards. If the test equipment cannot be grounded to the equipment under test, the test equipment's case must be shielded to prevent contact by personnel. To minimize hazard of electrical shock or burn, approved grounding practices and procedures must be strictly followed.

 *Warning*	To prevent personal injury or equipment damage caused by equipment malfunction, only adequately trained personnel should modify any programmable machine.

 ***Warning***	Always ensure that applicable standards and regulations are followed and only properly certified equipment is used as a critical component of a safety system. Never assume that the Human-machine Interface (HMI) nor the operator will close a safety critical control loop.

 ***Warning***	Explosion hazard - do not connect or disconnect equipment unless power has been switched off or the area is known to be non-hazardous.

1 Instructions for GE Lufkin

The IS400WEXPH1A is an expansion I/O board that is included with UCPAH2A. GE Lufkin can purchase the WEXP for installation into an existing UCPAH1A or as spares. The GE part number for the WEXP upgrade kit is 336A5026ATG01.

1.1 Remove UCPA Cover

The UCPA requires partial disassembly for any of the following reasons:

- Replacement of a failed WEXP; installing a new board into an existing UCPAH2A
- Installation of a new WEXP into an existing UCPAH1A provides additional I/O capability
- Removal of the WEXP jumpers to set the analog inputs to 0–5 V mode (default with jumpers is 4–20 mA); refer GEI-100719 for more information

➢ **To remove the UCPA cover**

1. Use a small flat-head screwdriver to unscrew the retaining screws on the power connector and remove it.

2. Remove the field wiring portion of both terminal blocks.

3. Locate the two indented sections of the cover (as shown in the following photo) and press firmly inward while pulling the cover away from the base.



1.2 Install WEXP into Existing UCPA

An existing UCPAH1A must be disassembled to install the additional I/O offered by the WEXP board, or additionally if a WEXP should fail within an existing UCPAH2A.

 ***Caution***	To prevent component damage caused by static electricity, treat all boards with static-sensitive handling techniques. Wear a wrist grounding strap when handling boards or components, but only after boards or components have been removed from potentially energized equipment and are at a normally grounded workstation.

➢ **To install the WEXP into an existing UCPA**

1. *Remove the UCPA cover.*
2. Carefully attach the new WEXP onto the STWC board connector at a straight-on angle to prevent damage to the STWC.

3. Use the four mounting screws provided with the upgrade kit to secure the new WEXP onto the spacers.

4. Reinstall the module cover by first removing the TB2 filler insert. Then, align tabs on one side followed by pressing in the locking tabs on the other side of the housing. Check to make sure that the module cover is fully seated, with no gaps between the cover and the module metal base.

GE Power *www.ge.com/power/resources*
© 2015 – 2021 General Electric Company.
Issued: April 2015 Aug 2021
Non-Public Information
* Indicates a trademark of General Electric Company and/or its subsidiaries.
All other trademarks are the property of their respective owners.
For complete legal information, refer to *GEI-100719*.

GEK--
SA-1047B