	962-20	56	9				Dr	000	200	. CI	<b>~</b>	v Chart	Project	Engineer / Responsabile proge	tto:		
Process Flow											U	V Chart					
Product	: / Prod	dotto										KTL					
Custom	er / Cl	liente										Item Code / Codice articolo					
Custom	er Co	de / Cod	ice Clie	nte								Drawing No./ Disegno N°					
Custom		wing No	./ Diseg	10		//		Indic		//	7	Item version / Versione :					
1. Issue emissio						F	Performe	d by/ E	ffettua	to da:		Feci G Moretti M Bosc	Feci G Moretti M Boschetti P.				
1. Chan date / d	ata					Change	e/ Revisio	one N°:				Performed by/ Eseguito da:  Moretti M.				Moretti M.	
Change P= prod S= softw L= label	uct / P /are / p	Prodotto program				T= toolin	ng / attrez	zzature-i	impiant	i		Inspection A= automatic V= visual T = Internal Lab	ection Ke M= man Q= qua	ual			
			S	mbol Inst	tructions									•			
working phase		work	move	Store/Get	control	re-work	Scrap/Contain				Changeover	Process operation description / descrizione dell'attività	KPC /SC <sup>®</sup>	Characteristic description / descrizione delle caratteristiche (Outputs)	KPC/SC <sup>(5)</sup>	Significant Process Characteristics / caratteristiche significative di processo	
		$\Diamond$	0	Δ	V												
1			Q									materials unloading from truck					
2					V -			)				delivery documents check and visual control on the batch		correct identification with label / aesthetic appearance NO oxidation - dents -scratches - bad welding zones		the internal Operative Instruction will be followed by the controller	
3		$\Diamond$										internal identification label print		date of receiving / threatment / Customer / internal bar-code			

L= label / identificazione		Inspection Key  A= automatic					
working phase  work  control  Scrap/Contain	Changeover	Process operation description / descrizione dell'attività	KPC /SC <sup>®</sup>	Characteristic description / descrizione delle caratteristiche (Outputs)	KPC /SC®	Significant Process Characteristics / caratteristiche significative di processo	
4	·	storage of the accepted material					
5		pick up of the pieces in store and pick up of the specific's hanging frames		EMMEGI working schedule			
7		100% visual and aesthetic control during hanging pieces on frame		100% visual inspection, visual appearance to detect presence of oxidations - dents - scratches oil and grease on the surface		Visual aids for visual inspection available to the line manager and avaliable at the control point REMARK Quality agreement with Customer needed for welding and oil/grease on the surface	
8		set up proper working cicle on line PLC		working cicle n° on PLC Line		approved machining cycle stored on line PLC	
9		chemical pre-degreasing		respect of acid concentrations in the bath		concentration measurement according to specific I.O. and at each bath restoration	
10 V/T		chemical de greasing		respect of acid concentrations of the bath		concentration measurement according to specific I.O. and at each bath restoration	

Significant Process   Characteristic description   descr	S= software / programma V L= label / identificazione T												Inspection Key  A= automatic				
Process operation description / describone deflatività   Secritatione delle   caratteristiche   Courtputs   Characteristics / caratteristiche significative   di processo		Symbol Instructions															
washing bath must be clean to allow proper washing with complete change every month  the bath, sulfuric acid concentrations in the bath, sulfuric acid concentration measurement according to specific I.O. and at each bath restoration the bath with complete change every month  washing bath must be clean to allow proper washing with complete change every month  the bath washing bath must be clean to allow proper washing with complete change every month  the bath washing bath must be clean to allow proper washing with complete change every month  the bath washing bath must be clean to allow proper washing with complete change every month  the bath washing bath must be clean to allow proper washing with complete change every month  transfer tank // // // // // // // // // // // // //	working phase		work	evom	Store/Get	control	re-work	Scrap/Contain				Changeover		KPC /SC <sup>®</sup>	descrizione delle caratteristiche	KPC /SC <sup>®</sup>	Characteristics / caratteristiche significative
bath must be cean to allow proper washing with complete change every month  the bath, suffuric acid concentration measurement according to specific I.O. and at each bath restoration the bath suffuric acid concentration, temperature of the bath at each bath restoration the bath with complete change every month  washing bath must be clean to allow proper washing with complete change every month  to specific I.O. and at each bath restoration with complete change every month  to specific I.O. and at each bath restoration in the bath according to specific I.O. and at each bath restoration measurement according to specific I.O. and at each bath restoration washing bath must be clean to allow proper washing with complete change every month  transfer tank // // // // // // // // // // // // //			$\Diamond$	0	$\triangle$	V											
the bath, suffuric acid concentrative of the bath according to specific I.O. and at each bath restoration the bath bath bath bath bath bath bath bath	11		<b>\frac{1}{2}</b>										washing		proper washing		with complete change every
washing bath must be clean to allow proper washing with complete change every month  ultrasonic pickling respect of acid concentrations in the bath right of the bath at each bath restoration  washing bath must be clean to allow proper washing with complete change every month  washing bath must be clean to allow proper washing with complete change every month  bath must be clean to allow proper washing with complete change every month  transfer tank // // // // // // // // // // // // //	12		<b>\rightarrow</b>			V/T							chemical pickling		the bath, sulfuric acid concentration,temperature of		according to specific I.O. and
ultrasonic pickling respect of acid concentrations in the bath according to specific I.O. and at each bath restoration  washinig bath must be clean to allow proper washing with complete change every month  transfer tank // // // // // // // // // // // // //	13		<b>\( \frac{\display}{\display} \)</b>										washing				with complete change every
washinig  washinig  bath must be clean to allow proper washing  with complete change every month  Visual check of the tank status with complete change every month  transfer tank  // // // // // // // // // // // // //	14		<b>*</b>			V/T							ultrasonic pickling		'		according to specific I.O. and
washinig bath must be clean to allow proper washing with complete change every month  transfer tank // // // // // // // // // // // // //	15		<b>\( \frac{1}{2} \)</b>										washinig				with complete change every
surface preparation to allow evenly phosphating over the frequence	16		<b>\frac{1}{2}</b>										washinig				with complete change every
chemical activation evenly phosphating over the ph control with pn-meter	17			Ò									transfer tank		11		
entire surface of the workpiece	18					V/T							chemical activation				pH control with ph-meter frequence

S= software / programma V L= label / identificazione T											Inspection Key  A= automatic M= manual  V= visual Q= quality audit  T = Internal Lab					
			Sy	mbol Inst	ructions						T					
working phase		work	тоvе	Store/Get	control	re-work	Scrap/Contain			Changeover	Process operation description / descrizione dell'attività	KPC /SC <sup>®</sup>	Characteristic description / descrizione delle caratteristiche (Outputs)	KPC /SC <sup>®</sup>	Significant Process Characteristics / caratteristiche significative di processo	
		$\Diamond$	0	$\triangle$	V											
19		<b>\</b>			V/T						phosphating		maintain the equilibrium of the concentrations of the various chemical products inside the tank		control free acidity , total acidity and gas points with I.O. specific to the processing cycle	
20		<b>\frac{1}{2}</b>									washing		bath must be clean to allow proper washing		Visual check of the tank status with complete change every month	
21		<b>\langle</b>									demineralized washing		bath must be clean to allow proper washing		Visual check of the tank status with complete change every month	
22		<b>\rightarrow</b>			V/T						cataphoresis		maintain the concentration of the paste and resin in relation to the specification		Dry residue check and pH check. Once per month external laboratory control of the whole solution in the tank	
23		<b>\frac{1}{2}</b>									ultra filtration 1		correct setting of pump and filter to properly separate paint from water		check the correct functioning of the filtering part check the values of microsiemens detected by continuous hath/tank control check the correct functioning of	
24		<b>\( \)</b>									ultra filtration 2		correct setting of pump and filter to properly separate paint from water		the filtering part check the values of microsiemens detected by continuous	
25		<u></u>									oven drying		temperature and stationing time in the oven		T and t parameters set on the specific machining cycle within the PLC	

P= produ S= softw	S= software / programma V=										Insp. A= automatic V= visual T = Internal Lab	ection Key M= man Q= qual	ual		
working phase		work	move	Store/Get	control	re-work	Scrap/Contain			Changeover	Process operation description / descrizione dell'attività	KPC /SC <sup>®</sup>	Characteristic description / descrizione delle caratteristiche (Outputs)	KPC /SC <sup>®</sup>	Significant Process Characteristics / caratteristiche significative di processo
		$\Diamond$	0	Δ	V										
26		$\Diamond$	Š								pieces load off from oven		pieces should be well dryed		visual check on pieces
27					V						control pieces		Vamish thickness on piece surface . Absence of halos - spots , absence of dents - scratches and areas not properly covered by Vamish.		specific features and control features written on specific I.O. Visual aids and pictures to lead the control
28		<b>\( \)</b>									packing and labelling		see I.O. packaging instructions VERIFY IF NECESSARY TO PROTECT THE PAINTED FRAME		
29			•								storage and ready to delivery				