

DX-D 100 DX-D 100 Wireless DX-D 600 Type 5410 SB 99

Type 5411 SB 113

Type 5430 SB 114

DD+DIS134.17E

Service Bulletin

Updated IEC 62353 safety test document available

Task

Timing	Timing Category		Scope	
	\bigcirc	Apply at all sites		
Next service as agreed with	•	Apply at affected sites as listed below		Problem Record: PRB0054996
customer	\bigcirc	Optional to improve functionality of product		

Task Tracking

Task Tracking		_
After completion of your task the following entry in your Service Report is required:	DD+DIS134.17E	*
* Insert the document number into the field "Comment" (SMS form).		

Purpose of this document:

This document announces the availability of updated IEC 62353 safety test documents for DX-D 600, DX-D 100 and DX-D 100 Wireless.

Affected serial number(s) / batch:

The updated IEC 62353 safety test documents are applicable for all DX-D 600, DX-D 100 and DX-D 100 Wireless systems.

The signatures on the approval page indicate the solutions described in this Service Bulletin have been reviewed and are NOT reportable because no actions are taken to reduce a "Risk to Health" according to our risk assessment process.

Use, dissemination, distribution or reproduction of this bulletin by unauthorized personnel is not permitted and may be unlawful. The controlled version of this document is available from the Agfa HealthCare Library. Any printed copy of this document is uncontrolled.

Copyright © 2017 Agfa HealthCare N.V. | Document ID: 61284176 | service_bulletin_template_v10

Release date: 09-2017 DX-D 100, DX-D 100 Wireless



Service Bulletin DD+DIS134.17E

1 Introduction

Frequent failures of protective earth resistance measurements were reported when performing the IEC 62353 safety test based on the following documents:

- DX-D 100 / DX-D 100 Wireless IEC 62353 safety test document 42283613 Rev. 1.1
- DX-D 600 IEC 62353 safety test document 35475878 Rev. 1.2 In detail the following symptoms were reported:

Symptom 1

DX-D 100 / DX-D 100 Wireless: The protective earth resistance measurement frequently fails at "Test point 2 – Upper parking detent". This mainly happens at system with telescopic column. The measured resistance exceeds the allowed 0,3 Ohm.

Symptom 2

DX-D 600: The protective earth resistance measurement frequently fails at "Test point 9 - Bucky handle with bucky carriage completely inserted". The measured resistance exceeds the allowed 0,3 Ohm.

Cause

Test points are suited for measurements in production, but not for reliable measurements in the field with test equipment using low current. In the field typically 200 mA are used for the protective earth resistance measurement. In production the test is performed with 25 A.

Solution

The two affected test points have been replaced by two equivalent test points that are suited for reliable testing in the field.

The updated safety test documents have been published in September 2017:

- DX-D 100 IEC 62353:2007 Test Documentation rev. ≥ 1.2, Document ID 42283613
- DX-D 600 IEC 62353:2007 Test Documentation rev. \geq 1.3, Document ID <u>35475878</u> Note, that the updated documents are published as PDF forms.

They can be

- printed and filled in manually or
- filled in and signed on the PC in the PDF reader (Reader ≥ V8 required for signature feature).

2 Keywords

IEC62353, safety test

3 Version history

Version	Change	Date
1.0	Initial version	09-2017

Release date: 09-2017



Details as of PDF Creation Date

Document Metadata

Title:	DX-D 600 - Service Bulletin No. 113 - Updated safety test document available
Livelink ID:	61284176
Version#:	6
Version Date:	2017-09-27 01:46 PM CET
Status:	Approved on 2017-11-08 05:57 PM CET
Owner:	Arthur Hermle (exfha)
Created By:	Arthur Hermle (exfha)
Created Date:	2017-09-20 06:09 PM CET
PDF Creation Date:	2017-11-08 05:57 PM CET

This document was approved by:

Signatures:

- 1. Paul Merckx (amdag) on 2017-10-02 09:17 AM CET
- 2. Bart Biesemans (amajm) on 2017-09-27 02:37 PM CET
- 3. Manfred Rösner (siroe) on 2017-09-28 10:36 AM CET
- 4. Lieven Lauwers (awibr) on 2017-10-11 10:54 AM CET

Detailed Approver History:

- Approval Workflow started on 2017-09-27 01:50 PM CET
 - Approval task originally assigned to and completed by Paul Merckx (amdag) on 2017-10-02 09:17 AM CET
 - Approval task originally assigned to and completed by Bart Biesemans (amajm) on 2017-09-27 02:37 PM CET
 - Approval task originally assigned to Josef Wagner (agwj)
 - Approval task completed by Manfred Rösner (siroe) on 2017-09-28 10:36 AM CET
 - Approval task originally assigned to and completed by Lieven Lauwers (awibr) on 2017-10-11 10:54 AM CET

V	areian	2.	Statue	History
w		\sim	SIMILE	\square

Version#	Date Created	Status
6	2017-09-27 01:46 PM CET	Approved - 2017-11-08
5	2017-09-27 01:46 PM CET	
4	2017-09-27 06:25 AM CET	Reviewed - 2017-09-27
3	2017-09-27 06:24 AM CET	
2	2017-09-25 12:06 PM CET	Reviewed - 2017-09-27
1	2017-09-20 06:09 PM CET	