# ECE 697 Modeling and High-Performance Control of Electric Machines HW 10 Solutions Spring 2022

**Problem 1** State Space Form Starting with the model

$$\frac{d\omega}{dt} = \frac{n_p M}{JL_R} \left( i_{Sb} \psi_{Ra} - i_{Sa} \psi_{Rb} \right) - \frac{f}{J} \omega - \frac{\tau_L}{J}$$

$$\frac{d\psi_{Ra}}{dt} = -\frac{R_R}{L_R} \psi_{Ra} - n_p \omega \psi_{Rb} + \frac{MR_R}{L_R} i_{Sa}$$

$$\frac{d\psi_{Rb}}{dt} = -\frac{R_R}{L_R} \psi_{Rb} + n_p \omega \psi_{Ra} + \frac{MR_R}{L_R} i_{Sb}$$

$$u_{Sa} = R_S i_{Sa} + \sigma L_S \frac{di_{Sa}}{dt} + \frac{M}{L_R} \frac{d\psi_{Ra}}{dt}$$

$$u_{Sb} = R_S i_{Sb} + \sigma L_S \frac{di_{Sb}}{dt} + \frac{M}{L_R} \frac{d\psi_{Rb}}{dt}$$

substitute

$$\begin{split} \frac{d\psi_{Ra}}{dt} &= -\frac{R_R}{L_R}\psi_{Ra} - n_p\omega\psi_{Rb} + \frac{MR_R}{L_R}i_{Sa}\\ \frac{d\psi_{Rb}}{dt} &= -\frac{R_R}{L_R}\psi_{Rb} + n_p\omega\psi_{Ra} + \frac{MR_R}{L_R}i_{Sb} \end{split}$$

into

$$u_{Sa} = R_S i_{Sa} + \sigma L_S \frac{di_{Sa}}{dt} + \frac{M}{L_R} \frac{d\psi_{Ra}}{dt}$$
$$u_{Sb} = R_S i_{Sb} + \sigma L_S \frac{di_{Sb}}{dt} + \frac{M}{L_R} \frac{d\psi_{Rb}}{dt}$$

to obtain

$$u_{Sa} = R_S i_{Sa} + \sigma L_S \frac{di_{Sa}}{dt} + \frac{M}{L_R} \left( -\frac{R_R}{L_R} \psi_{Ra} - n_p \omega \psi_{Rb} + \frac{MR_R}{L_R} i_{Sa} \right)$$
$$u_{Sb} = R_S i_{Sb} + \sigma L_S \frac{di_{Sb}}{dt} + \frac{M}{L_R} \left( -\frac{R_R}{L_R} \psi_{Rb} + n_p \omega \psi_{Ra} + \frac{MR_R}{L_R} i_{Sb} \right)$$

or

$$u_{Sa} = R_S i_{Sa} + \sigma L_S \frac{di_{Sa}}{dt} - \frac{MR_R}{L_R^2} \psi_{Ra} - \frac{M}{L_R} n_p \omega \psi_{Rb} + \frac{M^2 R_R}{L_R^2} i_{Sa}$$
$$u_{Sb} = R_S i_{Sb} + \sigma L_S \frac{di_{Sb}}{dt} - \frac{MR_R}{L_R^2} \psi_{Rb} + \frac{M}{L_R} n_p \omega \psi_{Ra} + \frac{M^2 R_R}{L_R^2} i_{Sb}.$$

Solving for the derivative of the currents gives

$$\frac{di_{Sa}}{dt} = \eta \beta \psi_{Ra} + \beta n_p \omega \psi_{Rb} - \gamma i_{Sa} + u_{Sa} / \sigma L_S$$

$$\frac{di_{Sb}}{dt} = \eta \beta \psi_{Rb} - \beta n_p \omega \psi_{Ra} - \gamma i_{Sb} + u_{Sb} / \sigma L_S$$

where

$$\eta \triangleq \frac{R_R}{L_R}, \beta \triangleq \frac{M}{\sigma L_R L_S}, \mu \triangleq \frac{n_p M}{J L_R}, \text{ and } \gamma \triangleq \frac{M^2 R_R}{\sigma L_R^2 L_S} + \frac{R_S}{\sigma L_S}.$$

**Problem 2** Induction Motor Model in the Space Vector Formulation A space vector representation of the induction motor is given by

$$R_{S}\underline{i}_{S} + L_{S}\frac{d}{dt}\underline{i}_{S} + M\frac{d}{dt}\left(\underline{i}_{R}e^{jn_{p}\theta_{R}}\right) = \underline{u}_{S}$$

$$R_{R}\underline{i}_{R} + L_{R}\frac{d}{dt}\underline{i}_{R} + M\frac{d}{dt}\left(\underline{i}_{S}e^{-jn_{p}\theta_{R}}\right) = 0$$

$$n_{p}M\operatorname{Im}\{\underline{i}_{S}(\underline{i}_{R}e^{j\theta_{R}})^{*}\} - \tau_{L} = J\frac{d\omega_{R}}{dt}$$

Define new (fictitious) flux linkages as

$$\underline{\psi}_{R} \triangleq \psi_{Ra} + j\psi_{Rb} \triangleq \underline{\lambda}_{R} e^{jn_{p}\theta_{R}} = L_{R} \underline{i}_{R} e^{jn_{p}\theta_{R}} + M\underline{i}_{S}$$

and substitute into

$$R_{S}\underline{i}_{S} + L_{S}\frac{d}{dt}\underline{i}_{S} + M\frac{d}{dt}\left(\underline{i}_{R}e^{jn_{p}\theta_{R}}\right) = \underline{u}_{S}$$

to obtain

$$\begin{split} R_S \underline{i}_S + L_S \frac{d}{dt} \underline{i}_S + \frac{M}{L_R} \frac{d}{dt} \left( \underline{\psi}_R - M \underline{i}_S \right) &= \underline{u}_S \\ \Longrightarrow \frac{M}{L_R} \frac{d}{dt} \underline{\psi}_R + \sigma L_S \frac{d}{dt} \underline{i}_S + R_S \underline{i}_S &= \underline{u}_S \end{split}$$

where  $\sigma \triangleq 1 - M^2/L_S L_R$  is the leakage factor.

Next, multiply both sides of

$$R_R \underline{i}_R + L_R \frac{d}{dt} \underline{i}_R + M \frac{d}{dt} \left( \underline{i}_S e^{-jn_p \theta_R} \right) = 0$$

by  $e^{jn_p\theta_R}$  to obtain

$$R_{R}\underline{i}_{R}e^{jn_{p}\theta_{R}} + L_{R}\frac{d}{dt}\left(\underline{i}_{R}e^{jn_{p}\theta_{R}}\right) - jn_{p}\omega_{R}L_{R}\underline{i}_{R}e^{jn_{p}\theta_{R}} + M\frac{d}{dt}\underline{i}_{S} + jn_{p}\omega_{R}M\underline{i}_{S} = 0$$

$$\implies \frac{R_{R}}{L_{R}}\left(\underline{\psi}_{R} - M\underline{i}_{S}\right) + \frac{d}{dt}\left(\underline{\psi}_{R} - M\underline{i}_{S}\right) - jn_{p}\omega_{R}\left(\underline{\psi}_{R} - M\underline{i}_{S}\right) + M\frac{d}{dt}\underline{i}_{S} + jn_{p}\omega_{R}M\underline{i}_{S} = 0$$

$$\implies \frac{R_{R}}{L_{R}}\left(\underline{\psi}_{R} - M\underline{i}_{S}\right) + \frac{d}{dt}\left(\underline{\psi}_{R} - M\underline{i}_{S}\right) - jn_{p}\omega_{R}\underline{\psi}_{R} + M\frac{d}{dt}\underline{i}_{S} = 0$$

$$\implies \frac{R_{R}}{L_{R}}\left(\underline{\psi}_{R} - M\underline{i}_{S}\right) + \frac{d}{dt}\underline{\psi}_{R} - jn_{p}\omega_{R}\underline{\psi}_{R} = 0$$

$$\implies \left(-\frac{1}{T_{R}} + jn_{p}\omega_{R}\right)\underline{\psi}_{R} + \frac{M}{T_{R}}\underline{i}_{S} = \frac{d}{dt}\underline{\psi}_{R}$$

where  $T_R \triangleq L_R/R_R$  is the rotor time constant. Finally, rewrite the torque equation

$$n_p M \operatorname{Im}\{\underline{i}_S(\underline{i}_R e^{jn_p\theta_R})^*\} - \tau_L = J \frac{d\omega_R}{dt}$$

as

$$n_{p} \frac{M}{L_{R}} \operatorname{Im} \left\{ \underline{i}_{S} \left( \underline{\psi}_{R} - M \underline{i}_{S} \right)^{*} \right\} - \tau_{L} = J \frac{d\omega_{R}}{dt}$$

$$\implies n_{p} \frac{M}{L_{R}} \operatorname{Im} \left\{ \underline{i}_{S} \underline{\psi}_{R}^{*} - M \underline{i}_{S} \underline{i}_{-S}^{*} \right\} - \tau_{L} = J \frac{d\omega_{R}}{dt}$$

$$\implies \frac{n_{p} M}{L_{R}} \operatorname{Im} \left\{ \underline{i}_{S} \underline{\psi}_{R}^{*} \right\} - \tau_{L} = J \frac{d\omega_{R}}{dt}$$

$$\implies \frac{n_{p} M}{J L_{R}} \operatorname{Im} \left\{ \underline{i}_{S} \underline{\psi}_{R}^{*} \right\} - \frac{\tau_{L}}{J} = \frac{d\omega_{R}}{dt}.$$

Combining the above gives

$$\frac{d}{dt}\underline{\psi}_{R} = \left(-\frac{1}{T_{R}} + jn_{p}\omega_{R}\right)\underline{\psi}_{R} + \frac{M}{T_{R}}\underline{i}_{S}$$

$$\underline{u}_{S} = \frac{M}{L_{R}}\frac{d}{dt}\underline{\psi}_{R} + \sigma L_{S}\frac{d}{dt}\underline{i}_{S} + R_{S}\underline{i}_{S}$$

$$\frac{d\omega_{R}}{dt} = \mu \operatorname{Im}\left\{\underline{i}_{S}(\underline{\psi}_{R})^{*}\right\} - \frac{\tau_{L}}{J}$$

where  $\mu \triangleq n_p M/(JL_R)$ .

Equating real and imaginary parts, the model can be rewritten as the five differential equations

$$\begin{split} \frac{d\psi_{Ra}}{dt} &= -\frac{R_R}{L_R}\psi_{Ra} - n_p\omega_R\psi_{Rb} + \frac{MR_R}{L_R}i_{Sa}\\ \frac{d\psi_{Rb}}{dt} &= -\frac{R_R}{L_R}\psi_{Rb} + n_p\omega_R\psi_{Ra} + \frac{MR_R}{L_R}i_{Sb}\\ u_{Sa} &= R_Si_{Sa} + \sigma L_S\frac{di_{Sa}}{dt} + \frac{M}{L_R}\frac{d\psi_{Ra}}{dt}\\ u_{Sb} &= R_Si_{Sb} + \sigma L_S\frac{di_{Sb}}{dt} + \frac{M}{L_R}\frac{d\psi_{Rb}}{dt}\\ \frac{d\omega_R}{dt} &= \frac{n_pM}{JL_R}\left(i_{Sb}\psi_{Ra} - i_{Sa}\psi_{Rb}\right) - \frac{\tau_L}{J}. \end{split}$$

Problem 3 Induction Motor Model in Terms of the Flux Linkages

With  $\lambda_{Sa}$  and  $\lambda_{Sb}$  the total flux linkage in stator phases a and b, respectively, define

$$\underline{\lambda}_S \triangleq \lambda_{Sa} + j\lambda_{Sb} \triangleq L_S \underline{i}_S + M \underline{i}_R e^{+jn_p\theta_R}.$$

Similarly, let  $\lambda_{Ra}$  and  $\lambda_{Rb}$  be the total flux linkage in rotor phases a and b, respectively, and define

$$\underline{\lambda}_R \triangleq \lambda_{Ra} + j\lambda_{Rb} \triangleq L_R \underline{i}_R + M \underline{i}_S e^{-jn_p \theta_R}.$$

(a) By Faraday's law, the electrical equations of the induction motor may be written as

$$R_{S}\underline{i}_{S} + \frac{d}{dt}\underline{\lambda}_{S} = \underline{u}_{S}$$
$$R_{R}\underline{i}_{R} + \frac{d}{dt}\underline{\lambda}_{R} = 0.$$

(b) Inverting the relationship

$$\left[\begin{array}{c} \underline{\lambda}_S \\ \underline{\lambda}_R e^{+jn_p\theta_R} \end{array}\right] = \left[\begin{array}{cc} L_S & M \\ M & L_R \end{array}\right] \left[\begin{array}{c} \underline{i}_S \\ \underline{i}_R e^{+jn_p\theta_R} \end{array}\right]$$

gives

$$\left[\begin{array}{c} \underline{i_S} \\ \underline{i_R} e^{+jn_p\theta_R} \end{array}\right] = \frac{1}{L_S L_R - M^2} \left[\begin{array}{cc} L_R & -M \\ -M & L_S \end{array}\right] \left[\begin{array}{c} \underline{\lambda_S} \\ \underline{\lambda_R} e^{+jn_p\theta_R} \end{array}\right].$$

Substituting these expressions for  $\underline{i}_S$  and  $\underline{i}_R e^{+jn_p\theta_R}$  into

$$R_{S}\underline{i}_{S} + \frac{d}{dt} \left( L_{S} \frac{d}{dt} \underline{i}_{S} + M \underline{i}_{R} e^{jn_{p}\theta_{R}} \right) = \underline{u}_{S}$$

$$R_{R}\underline{i}_{R} + \frac{d}{dt} \left( L_{R}\underline{i}_{R} + M \underline{i}_{S} e^{-jn_{p}\theta_{R}} \right) = 0$$

$$n_{p} M \operatorname{Im} \{ \underline{i}_{S} (\underline{i}_{R} e^{jn_{p}\theta_{R}})^{*} \} - \tau_{L} = J \frac{d\omega_{R}}{dt}$$

gives

$$\frac{R_S}{L_S L_R - M^2} \left( L_R \underline{\lambda}_S - M \underline{\lambda}_R e^{+jn_p \theta_R} \right) + \frac{d}{dt} \underline{\lambda}_S = \underline{u}_S$$

$$\frac{R_R}{L_S L_R - M^2} \left( -M \underline{\lambda}_S e^{-jn_p \theta_R} + L_S \underline{\lambda}_R \right) + \frac{d}{dt} \underline{\lambda}_R = 0$$

$$\frac{n_p M}{\left( L_S L_R - M^2 \right)^2} \operatorname{Im} \left\{ \left( L_R \underline{\lambda}_S - M \underline{\lambda}_R e^{+jn_p \theta_R} \right) \left( -M \underline{\lambda}_S + L_S \underline{\lambda}_R e^{+jn_p \theta_R} \right)^* \right\} - \tau_L = J \frac{d\omega_R}{dt}.$$

The last equation is simplified by

$$\frac{n_p M}{(L_S L_R - M^2)^2} \operatorname{Im} \left\{ \left( L_S L_R \underline{\lambda}_S (\underline{\lambda}_R e^{+jn_p \theta_R})^* + M^2 (\underline{\lambda}_R e^{+jn_p \theta_R}) \underline{\lambda}_{-S}^* \right) \right\} - \tau_L = J \frac{d\omega_R}{dt}$$

$$\frac{n_p M}{(L_S L_R - M^2)^2} \operatorname{Im} \left\{ \left( L_S L_R \underline{\lambda}_S (\underline{\lambda}_R e^{+jn_p \theta_R})^* - M^2 \underline{\lambda}_S (\underline{\lambda}_R e^{+jn_p \theta_R})^* \right) \right\} - \tau_L = J \frac{d\omega_R}{dt}$$

$$\frac{n_p M}{(L_S L_R - M^2)^2} \operatorname{Im} \left\{ \left( \left( L_S L_R - M^2 \right) \underline{\lambda}_S (\underline{\lambda}_R e^{+jn_p \theta_R})^* \right) \right\} - \tau_L = J \frac{d\omega_R}{dt}$$

so that finally

$$\frac{R_S}{L_S L_R - M^2} \left( L_R \underline{\lambda}_S - M \underline{\lambda}_R e^{+jn_p \theta_R} \right) + \frac{d}{dt} \underline{\lambda}_S = \underline{u}_S$$

$$\frac{R_R}{L_S L_R - M^2} \left( -M \underline{\lambda}_S e^{-jn_p \theta_R} + L_S \underline{\lambda}_R \right) + \frac{d}{dt} \underline{\lambda}_R = 0$$

$$\frac{M}{L_S L_R - M^2} \operatorname{Im} \{ \underline{\lambda}_S (\underline{\lambda}_R e^{+jn_p \theta_R})^* \} - \tau_L = J \frac{d\omega_R}{dt}$$

$$\frac{d\theta_R}{dt} = \omega_R$$

is a representation of the induction motor in terms  $\underline{\lambda}_S \triangleq \lambda_{Sa} + j\lambda_{Sb}, \underline{\lambda}_R \triangleq \lambda_{Ra} + j\lambda_{Rb}, \omega_R$ , and  $\theta_R$ . Note that by equating real and imaginary parts of the answer to part (b), a statespace representation of the induction motor in terms of the state variables  $\lambda_{Sa}, \lambda_{Sb}, \lambda_{Ra}, \lambda_{Rb}, \omega_R$ , and  $\theta_R$  is

$$\frac{d\lambda_{Sa}}{dt} = -\frac{R_S L_R}{L_S L_R - M^2} \lambda_{Sa} + \frac{R_S M}{L_S L_R - M^2} \left( \lambda_{Ra} \cos(n_p \theta_R) - \lambda_{Rb} \sin(n_p \theta_R) \right) + u_{Sa}$$

$$\frac{d\lambda_{Sb}}{dt} = -\frac{R_S L_R}{L_S L_R - M^2} \lambda_{Sa} + \frac{R_S M}{L_S L_R - M^2} \left( \lambda_{Ra} \sin(n_p \theta_R) + \lambda_{Rb} \cos(n_p \theta_R) \right) + u_{Sb}$$

$$\frac{d\lambda_{Ra}}{dt} = -\frac{R_R L_S}{L_S L_R - M^2} \lambda_{Ra} + \frac{M R_R}{L_S L_R - M^2} \left( \lambda_{Sa} \cos(n_p \theta_R) + \lambda_{Sb} \sin(n_p \theta_R) \right)$$

$$\frac{d\lambda_{Rb}}{dt} = -\frac{R_R L_S}{L_S L_R - M^2} \lambda_{Rb} + \frac{M R_R}{L_S L_R - M^2} \left( -\lambda_{Sa} \sin(n_p \theta_R) + \lambda_{Sb} \cos(n_p \theta_R) \right)$$

$$J \frac{d\omega_R}{dt} = \frac{M}{L_S L_R - M^2} \left( -\lambda_{Sa} \left( \lambda_{Ra} \sin(n_p \theta_R) + \lambda_{Rb} \cos(n_p \theta_R) \right) + \lambda_{Sb} \left( \lambda_{Ra} \cos(n_p \theta_R) - \lambda_{Rb} \sin(n_p \theta_R) \right) \right) - \tau_L$$

$$\frac{d\theta_R}{dt} = \omega_R.$$

Problem 4 Field-Oriented Induction Motor Model

We have

$$\frac{d}{dt}\underline{\psi}_{R} = \left(-\frac{1}{T_{R}} + jn_{p}\omega\right)\underline{\psi}_{R} + \frac{M}{T_{R}}\underline{i}_{S}$$

$$\underline{u}_{S} = \frac{M}{L_{R}}\frac{d}{dt}\underline{\psi}_{R} + \sigma L_{S}\frac{d}{dt}\underline{i}_{S} + R_{S}\underline{i}_{S}$$

$$\frac{d\omega}{dt} = \mu \operatorname{Im}\left\{\underline{i}_{S}(\underline{\psi}_{R})^{*}\right\} - \frac{\tau_{L}}{J}$$

where

$$\underline{\psi}_{R} \triangleq \psi_{Ra} + j\psi_{Rb} = \psi_{d}e^{j\rho}$$

$$\psi_{d} \triangleq \sqrt{\psi_{Ra}^{2} + \psi_{Rb}^{2}}$$

$$\rho \triangleq \tan^{-1}(\psi_{Rb}/\psi_{Ra})$$

$$\underline{i}_{dq} \triangleq i_{d} + ji_{q} = \underline{i}_{S}e^{-j\rho}$$

$$\underline{u}_{dq} \triangleq u_{d} + ju_{q} = \underline{u}_{S}e^{-j\rho}.$$

Then

$$\begin{split} \frac{d}{dt} \left( \psi_d e^{j\rho} \right) &= \left( -\frac{1}{T_R} + j n_p \omega \right) \psi_d e^{j\rho} + \frac{M}{T_R} \underline{i}_{dq} e^{j\rho} \\ &\underline{u}_{dq} e^{j\rho} = \frac{M}{L_R} \frac{d}{dt} \left( \psi_d e^{j\rho} \right) + \sigma L_S \frac{d}{dt} \left( \underline{i}_{dq} e^{j\rho} \right) + R_S \underline{i}_{dq} e^{j\rho} \\ &\frac{d\omega}{dt} = \mu \operatorname{Im} \left\{ \underline{i}_{dq} e^{j\rho} (\psi_d e^{j\rho})^* \right\} - \frac{\tau_L}{J} \end{split}$$

or

$$\begin{split} \psi_d e^{j\rho} j \frac{d\rho}{dt} + e^{j\rho} \frac{d}{dt} \psi_d &= \left( -\frac{1}{T_R} + j n_p \omega \right) \psi_d e^{j\rho} + \frac{M}{T_R} \underline{i}_{dq} e^{j\rho} \\ \underline{u}_{dq} e^{j\rho} &= \frac{M}{L_R} \left( \psi_d e^{j\rho} j \frac{d\rho}{dt} + e^{j\rho} \frac{d}{dt} \psi_d \right) + \sigma L_S \left( e^{j\rho} \frac{d}{dt} \underline{i}_{dq} + \underline{i}_{dq} e^{j\rho} j \frac{d\rho}{dt} \right) + R_S \underline{i}_{dq} e^{j\rho} \\ \frac{d\omega}{dt} &= \mu \operatorname{Im} \left\{ \underline{i}_{dq} \psi_d \right\} - \frac{\tau_L}{J}. \end{split}$$

After some rearrangement, one obtains

$$\begin{split} j\psi_d\frac{d\rho}{dt} + \frac{d}{dt}\psi_d &= \left(-\frac{1}{T_R} + jn_p\omega\right)\psi_d + \frac{M}{T_R}\underline{i}_{dq} \\ \underline{u}_{dq} &= \frac{M}{L_R}\left(\psi_dj\frac{d\rho}{dt} + \frac{d}{dt}\psi_d\right) + \sigma L_S\left(\frac{d}{dt}\underline{i}_{dq} + \underline{i}_{dq}j\frac{d\rho}{dt}\right) + R_S\underline{i}_{dq} \\ \frac{d\omega}{dt} &= \mu i_q\psi_d - \frac{\tau_L}{I}. \end{split}$$

Equating real and imaginary parts one obtains

$$\begin{split} \frac{d}{dt}\psi_d &= -\frac{1}{T_R}\psi_d + \frac{M}{T_R}i_d \\ \psi_d \frac{d\rho}{dt} &= n_p \omega \psi_d + \frac{M}{T_R}i_d \\ u_d &= \frac{M}{L_R}\frac{d}{dt}\psi_d + \sigma L_S \left(\frac{di_d}{dt} - i_q \frac{d\rho}{dt}\right) + R_S i_d \\ u_q &= \frac{M}{L_R}\psi_d \frac{d\rho}{dt} + \sigma L_S \left(\frac{di_q}{dt} + i_d \frac{d\rho}{dt}\right) + R_S i_q \\ \frac{d\omega}{dt} &= \mu i_q \psi_d - \frac{\tau_L}{J}. \end{split}$$

Using  $d\rho/dt = n_p\omega + Mi_q/(T_R\psi_d)$  and  $d\psi_d/dt = -(1/T_R) + (M/T_R)i_d$ , this becomes

$$\begin{split} \frac{d}{dt}\psi_d &= -\frac{1}{T_R}\psi_d + \frac{M}{T_R}i_d \\ \frac{d\rho}{dt} &= n_p\omega + \frac{M}{T_R}\frac{i_q}{\psi_d} \\ u_d &= \frac{M}{L_R}\left(-\frac{1}{T_R}\psi_d + \frac{M}{T_R}i_d\right) + \sigma L_S\frac{di_d}{dt} - \sigma L_Si_q\left(n_p\omega + \frac{M}{T_R}\frac{i_q}{\psi_d}\right) + \ R_Si_d \\ u_q &= \left(\frac{M}{L_R}\psi_d + \sigma L_Si_d\right)\left(n_p\omega + \frac{M}{T_R}\frac{i_q}{\psi_d}\right) + \sigma L_S\frac{di_q}{dt} + R_Si_q \\ \frac{d\omega}{dt} &= \mu i_q\psi_d - \frac{\tau_L}{I}. \end{split}$$

Finally, rearranging gives

$$\begin{split} \frac{d\theta}{dt} &= \omega \\ \frac{d\omega}{dt} &= \mu \psi_d i_q - \tau_L/J \\ \frac{d\psi_d}{dt} &= -\eta \psi_d + \eta M i_d \\ \frac{di_d}{dt} &= -\gamma i_d + (\eta M/\sigma L_R L_S) \psi_d + n_p \omega i_q + \eta M i_q^2/\psi_d + u_d/\sigma L_S \\ \frac{di_q}{dt} &= -\gamma i_q - (M/\sigma L_R L_S) n_p \omega \psi_d - n_p \omega i_d - \eta M i_q i_d/\psi_d + u_q/\sigma L_S \\ \frac{d\rho}{dt} &= n_p \omega + \eta M i_q/\psi_d \end{split}$$

where

$$\eta \triangleq \frac{R_R}{L_R}, \beta \triangleq \frac{M}{\sigma L_R L_S}, \mu \triangleq \frac{n_p M}{J L_R}, \text{ and } \gamma \triangleq \frac{M^2 R_R}{\sigma L_R^2 L_S} + \frac{R_S}{\sigma L_S}$$

**Problem 5** Stator Flux Induction Motor Model

(a) The stator flux linkage is given by

$$\underline{\lambda}_{S} = L_{S}\underline{i}_{S} + M\left(\underline{i}_{R}e^{jn_{p}\theta_{R}}\right) = \lambda_{S}e^{j\rho_{S}}.$$

Rewrite the system model

$$R_{S}\underline{i}_{S} + L_{S}\frac{d}{dt}\underline{i}_{S} + M\frac{d}{dt}\left(\underline{i}_{R}e^{jn_{p}\theta_{R}}\right) = \underline{u}_{S}$$

$$R_{R}\underline{i}_{R} + L_{R}\frac{d}{dt}\underline{i}_{R} + M\frac{d}{dt}\left(\underline{i}_{S}e^{-jn_{p}\theta_{R}}\right) = 0$$

$$n_{p}M\operatorname{Im}\left\{\underline{i}_{S}\left(\underline{i}_{R}e^{jn_{p}\theta_{R}}\right)^{*}\right\} - \tau_{L} = J\frac{d\omega_{R}}{dt}$$

in terms of  $\underline{\lambda}_S, \underline{i}_S$ , and  $\omega_R$ . The first equation becomes

$$\frac{d}{dt}\underline{\lambda}_S = -R_S\underline{i}_S + \underline{u}_S.$$

Letting  $\underline{i}_r \triangleq \underline{i}_R e^{jn_p\theta_R}$ , the second equation becomes

$$R_{R}\underline{i}_{r} + L_{R}\frac{d}{dt}\underline{i}_{r} + M\frac{d}{dt}\underline{i}_{S} - jn_{p}\omega_{R}\left(L_{R}\underline{i}_{r} + M\underline{i}_{S}\right) = 0.$$

Substituting

$$\underline{i}_r = \frac{\underline{\lambda}_S - L_S \underline{i}_S}{M},$$

this can be rewritten as

$$R_R\left(\frac{\underline{\lambda}_S - L_S \underline{i}_S}{M}\right) + L_R \frac{d}{dt}\left(\frac{\underline{\lambda}_S - L_S \underline{i}_S}{M}\right) + M \frac{d}{dt}\underline{i}_S - jn_p \omega_R\left(L_R\left(\frac{\underline{\lambda}_S - L_S \underline{i}_S}{M}\right) + M \underline{i}_S\right) = 0$$

or

$$\frac{R_R}{M}\underline{\lambda}_S + \frac{L_R}{M}\frac{d}{dt}\underline{\lambda}_S - jn_p\omega_R\frac{L_R}{M}\underline{\lambda}_S - R_R\frac{L_S}{M}\underline{i}_S - \frac{L_SL_R}{M}\frac{d}{dt}\underline{i}_S + M\frac{d}{dt}\underline{i}_S + jn_p\omega_R\left(\frac{L_SL_R}{M}\underline{i}_S - M\underline{i}_S\right) = 0$$

oı

$$\frac{R_R}{L_R}\underline{\lambda}_S + \frac{d}{dt}\underline{\lambda}_S - jn_p\omega_R\underline{\lambda}_S - \frac{R_R}{L_R}L_S\underline{i}_S - L_S\frac{d}{dt}\underline{i}_S + \frac{M^2}{L_R}\frac{d}{dt}\underline{i}_S + jn_p\omega_R\left(L_S\underline{i}_S - \frac{M^2}{L_R}\underline{i}_S\right) = 0$$

or

$$\frac{R_R}{L_R}\underline{\lambda}_S + \frac{d}{dt}\underline{\lambda}_S - jn_p\omega_R\underline{\lambda}_S - \frac{R_R}{L_R}L_S\underline{i}_S - \sigma L_S\frac{d}{dt}\underline{i}_S + jn_p\omega_R\sigma L_S\underline{i}_S = 0$$

or

$$\frac{d}{dt}\underline{\lambda}_S + \left(\frac{1}{T_R} - jn_p\omega_R\right)\underline{\lambda}_S - \sigma L_S \frac{d}{dt}\underline{i}_S - L_S \left(\frac{1}{T_R} - jn_p\omega_R\sigma\right)\underline{i}_S = 0.$$

The equation for torque is

$$n_p M \operatorname{Im} \left\{ \underline{i}_S \left( \underline{i}_R e^{j n_p \theta_R} \right)^* \right\} = n_p M \operatorname{Im} \left\{ \underline{i}_S \left( \frac{\underline{\lambda}_S - L_S \underline{i}_S}{M} \right)^* \right\} = n_p \operatorname{Im} \left\{ \underline{i}_S \left( \underline{\lambda}_S \right)^* \right\}.$$

Collecting the equations together, we have

$$\frac{d}{dt}\underline{\lambda}_{S} = -R_{S}\underline{i}_{S} + \underline{u}_{S}$$

$$\frac{d}{dt}\underline{\lambda}_{S} + \left(\frac{1}{T_{R}} - jn_{p}\omega_{R}\right)\underline{\lambda}_{S} - \sigma L_{S}\frac{d}{dt}\underline{i}_{S} - L_{S}\left(\frac{1}{T_{R}} - jn_{p}\omega_{R}\sigma\right)\underline{i}_{S} = 0$$

$$n_{p}\operatorname{Im}\left\{\underline{i}_{S}\left(\underline{\lambda}_{S}\right)^{*}\right\} - \tau_{L} = J\frac{d\omega_{R}}{dt}$$

or

$$\frac{d}{dt}\underline{\lambda}_{S} = -R_{S}\underline{i}_{S} + \underline{u}_{S}$$

$$\sigma L_{S}\frac{d}{dt}\underline{i}_{S} + L_{S}\left(\frac{1}{T_{R}} - jn_{p}\omega_{R}\sigma\right)\underline{i}_{S} = -R_{S}\underline{i}_{S} + \underline{u}_{S} + \left(\frac{1}{T_{R}} - jn_{p}\omega_{R}\right)\underline{\lambda}_{S}$$

$$n_{p}\operatorname{Im}\left\{\underline{i}_{S}\left(\underline{\lambda}_{S}\right)^{*}\right\} - \tau_{L} = J\frac{d\omega_{R}}{dt}.$$

(b) In statespace form, this becomes

$$\begin{split} \frac{d\lambda_{Sa}}{dt} &= -R_S i_{Sa} + u_{Sa} \\ \frac{d\lambda_{Sb}}{dt} &= -R_S i_{Sb} + u_{Sb} \\ \frac{di_{Sa}}{dt} &= \left( -R_S i_{Sa} + u_{Sa} - \frac{L_S}{T_R} i_{Sa} - n_p \omega_R \sigma L_S i_{Sb} + \frac{1}{T_R} \lambda_{Sa} + n_p \omega_R \lambda_{Sb} \right) / \sigma L_S \\ \frac{di_{Sb}}{dt} &= \left( -R_S i_{Sb} + u_{Sb} - \frac{L_S}{T_R} i_{Sb} + n_p \omega_R \sigma L_S i_{Sa} + \frac{1}{T_R} \lambda_{Sa} - n_p \omega_R \lambda_{Sa} \right) / \sigma L_S \\ J \frac{d\omega_R}{dt} &= n_p \left( i_{Sb} \lambda_{Sa} - i_{Sa} \lambda_{Sb} \right) - \tau_L. \end{split}$$

Problem 6  $\psi_d$  and  $\psi_q$ 

Now

$$\rho = \tan^{-1} (\psi_{Rb}/\psi_{Ra})$$

$$\Rightarrow \tan(\rho) = \psi_{Rb}/\psi_{Ra}$$

$$\Rightarrow \tan^{2}(\rho) + 1 = (\psi_{Rb}/\psi_{Ra})^{2} + 1 = \sec^{2} (\psi_{Rb}/\psi_{Ra})$$

$$\Rightarrow \cos^{2} (\rho) = \frac{1}{(\psi_{Rb}/\psi_{Ra})^{2} + 1} = \frac{\psi_{Ra}^{2}}{\psi_{Ra}^{2} + \psi_{Rb}^{2}}$$

$$\Rightarrow \cos(\rho) = \frac{\psi_{Ra}}{\sqrt{\psi_{Ra}^{2} + \psi_{Rb}^{2}}} = \frac{\psi_{Ra}}{\psi_{d}}$$

and also

$$\sin^{2}(\rho) = 1 - \cos^{2}(\rho) = 1 - \frac{\psi_{Ra}^{2}}{\psi_{Ra}^{2} + \psi_{Rb}^{2}} = \frac{\psi_{Rb}^{2}}{\psi_{Ra}^{2} + \psi_{Rb}^{2}}$$
$$\sin(\rho) = \frac{\psi_{Rb}}{\sqrt{\psi_{Ra}^{2} + \psi_{Rb}^{2}}} = \frac{\psi_{Rb}}{\psi_{d}}.$$

Finally,

$$\psi_q = -\sin(\rho)\psi_{Ra} + \cos(\rho)\psi_{Rb} = -\frac{\psi_{Rb}}{\psi_d}\psi_{Ra} + \frac{\psi_{Ra}}{\psi_d}\psi_{Rb} \equiv 0.$$

#### Feedback Control and Reference Trajectories

Problem 7 Tracking a Constant Flux Reference

Substitute

$$i_{dr} = K_{\psi I} \int_0^t (\psi_{d0} - \psi_d) dt + K_{\psi P} (\psi_{d0} - \psi_d) + i_{d0}$$

into

$$\frac{d\psi_d}{dt} = -\eta\psi_d + \eta M i_{dr}$$

to obtain

$$\frac{d\psi_d}{dt} = -\eta\psi_d + \eta M \left( K_{\psi I} \int_0^t (\psi_{d0} - \psi_d) dt + K_{\psi P} (\psi_{d0} - \psi_d) + i_{d0} \right).$$

Then, with  $e_0 = \int_0^t (\psi_{d0} - \psi_d) dt$ ,  $e_1 = \psi_{d0} - \psi_d$  and  $\psi_{d0} = Mi_{d0}$ , we have

$$\begin{split} \frac{de_0}{dt} &= e_1 \\ \frac{de_1}{dt} &= \eta \psi_d - \eta M K_{\psi I} \int_0^t (\psi_{d0} - \psi_d) dt - \eta M K_{\psi P} (\psi_{d0} - \psi_d) - \eta M i_{d0} \\ &= -\eta \left( \psi_{d0} - \psi_d \right) - \eta M K_{\psi I} \int_0^t (\psi_{d0} - \psi_d) dt - \eta M K_{\psi P} (\psi_{d0} - \psi_d) \\ &= -\eta M K_{\psi I} e_0 - \eta \left( M K_{\psi P} + 1 \right) e_1. \end{split}$$

Setting

$$\eta \left( MK_{\psi P} + 1 \right) = r_1 + r_2$$
$$\eta MK_{\psi I} = r_1 r_2$$

or

$$K_{\psi P} = \frac{\left(r_1 + r_2\right)/\eta - 1}{M}$$
$$K_{\psi I} = \frac{r_1 r_2}{\eta M}$$

this becomes

$$\frac{de_0}{dt} = e_1 \frac{de_1}{dt} = -r_1 r_2 e_0 - (r_1 + r_2) e_1.$$

Taking the Laplace transform gives

$$sE_0(s) - e_0(0) = E_1(s)$$
  

$$sE_1(s) - e_1(0) = -r_1r_2E_0(s) - (r_1 + r_2)E_1(s)$$

or

$$\begin{bmatrix} s & -1 \\ r_1 r_2 & s + r_1 + r_2 \end{bmatrix} \begin{bmatrix} E_0(s) \\ E_1(s) \end{bmatrix} = \begin{bmatrix} e_0(0) \\ e_1(0) \end{bmatrix}.$$

Solving for  $E_0(s)$  and  $E_1(s)$  gives

$$\begin{bmatrix} E_0(s) \\ E_1(s) \end{bmatrix} = \frac{1}{(s+r_1)(s+r_2)} \begin{bmatrix} s+r_1+r_2 & 1 \\ -r_1r_2 & s \end{bmatrix} \begin{bmatrix} e_0(0) \\ e_1(0) \end{bmatrix}$$
$$= \frac{1}{(s+r_1)(s+r_2)} \begin{bmatrix} (s+r_1+r_2)e_0(0)+e_1(0) \\ -r_1r_2e_0(0)+se_1(0) \end{bmatrix}$$

where it follows by the method of partial fractions  $(r_1, r_2 \text{ distinct})$ 

$$E_1(s) = \frac{-r_1 r_2 e_0(0) + s e_1(0)}{(s+r_1)(s+r_2)} = \frac{A}{s+r_1} + \frac{B}{s+r_2}$$

so that  $e_1(t) \to 0$  with  $r_1 > 0, r_2 > 0$ .

**Problem 8** Trajectory Tracking via Field-Oriented Control Substitute

$$i_{qr} = \left(K_0 \int_0^t (\theta_{ref} - \theta) dt + K_1(\theta_{ref} - \theta) + K_2(\omega_{ref} - \omega) + (f/J)\omega + \alpha_{ref}\right) / \mu \psi_{d0}$$

into

$$\frac{d\theta}{dt} = \omega$$

$$\frac{d\omega}{dt} = \mu \psi_{d0} i_{qr} - (f/J)\omega - \tau_L/J$$

to obtain

$$\begin{aligned} \frac{d\theta}{dt} &= \omega \\ \frac{d\omega}{dt} &= K_0 \int_0^t (\theta_{ref} - \theta) dt + K_1 (\theta_{ref} - \theta) + K_2 (\omega_{ref} - \omega) + \alpha_{ref} - \tau_L / J. \end{aligned}$$

With  $e_0 = \int_0^t (\theta_{ref} - \theta) dt$ ,  $e_1 = \theta_{ref} - \theta$ , and  $e_2 = \omega_{ref} - \omega$ , and assuming the reference trajectory satisfies

$$\frac{d\theta_{ref}(t)}{dt} = \omega_{ref}(t)$$
$$\frac{d\omega_{ref}(t)}{dt} = \alpha_{ref}(t),$$

one obtains

$$\begin{split} \frac{de_0}{dt} &= e_1 \\ \frac{de_1}{dt} &= e_2 \\ \frac{de_2}{dt} &= -K_0 e_0 - K_1 e_1 - K_2 e_2 + \tau_L/J. \end{split}$$

The Laplace transform of this system is

$$sE_0(s) - e_0(0) = E_1(s)$$
  

$$sE_1(s) - e_1(0) = E_2(s)$$
  

$$sE_2(s) - e_2(0) = -K_0E_0(s) - K_1E_1(s) - K_2E_2(s) + \tau_L(s)/J$$

or

$$\begin{bmatrix} s & -1 & 0 \\ 0 & s & -1 \\ K_0 & K_1 & s + K_2 \end{bmatrix} \begin{bmatrix} E_0(s) \\ E_1(s) \\ E_2(s) \end{bmatrix} = \begin{bmatrix} e_0(0) \\ e_1(0) \\ e_2(0) \end{bmatrix} + \begin{bmatrix} 0 \\ 0 \\ \tau_L(s)/J \end{bmatrix}.$$

Then

$$\begin{bmatrix} E_0(s) \\ E_1(s) \\ E_2(s) \end{bmatrix} = \frac{1}{s^3 + K_2 s^2 + K_1 s + K_0} \begin{bmatrix} s^2 + K_2 s + K_1 & s + K_2 & 1 \\ -K_0 & s^2 + K_2 s & s \\ -K_0 s & -(K_1 s + K_0) & s^2 \end{bmatrix} \begin{pmatrix} \begin{bmatrix} e_0(0) \\ e_1(0) \\ e_2(0) \end{bmatrix} + \begin{bmatrix} 0 \\ 0 \\ \tau_L(s)/J \end{bmatrix} \end{pmatrix}.$$

With  $\tau_L(s) = \tau_{L0}/s$  and

$$K_2 = r_1 + r_2 + r_3$$
  
 $K_1 = r_1r_2 + r_1r_3 + r_2r_3$   
 $K_0 = r_1r_2r_3$ ,

the characteristic polynomial may be written as

$$a(s) = s^{3} + K_{2}s^{2} + K_{1}s + K_{0} = s^{3} + (r_{1} + r_{2} + r_{3})s^{2} + (r_{1}r_{2} + r_{1}r_{3} + r_{2}r_{3})s + r_{1}r_{2}r_{3}$$
$$= (s + r_{1})(s + r_{2})(s + r_{3}).$$

The errors can then be written in the form

$$E_0(s) = \frac{\left(s^2 + K_2 s + K_1\right) e_0(0) + \left(s + K_2\right) e_1(0) + e_2(0)}{\left(s + r_1\right)\left(s + r_2\right)\left(s + r_3\right)} + \frac{\tau_{L0}/J}{\left(s + r_1\right)\left(s + r_2\right)\left(s + r_3\right)} \frac{1}{s}$$

$$E_1(s) = \frac{-K_0 e_0(0) + (s^2 + K_2 s) e_1(0) + s e_2(0)}{(s+r_1)(s+r_2)(s+r_3)} + \frac{s (\tau_{L0}/J)}{(s+r_1)(s+r_2)(s+r_3)} \frac{1}{s}$$

$$E_2(s) = \frac{-K_0 s e_0(0) - (K_1 s + K_0) e_1(0) + s^2 e_2(0)}{(s + r_1)(s + r_2)(s + r_3)} + \frac{s^2 (\tau_{L0}/J)}{(s + r_1)(s + r_2)(s + r_3)} \frac{1}{s}.$$

The closed-loop poles are  $p_1 = -r_1$ ,  $p_2 = -r_2$ ,  $p_3 = -r_3$  and assuming these poles are distinct,  $E_1(s)$  becomes

$$E_1(s) = \frac{-K_0 e_0(0) + \left(s^2 + (K_2 + f/J)s\right) e_1(0) + s e_2(0)}{(s+r_1)(s+r_2)(s+r_3)} + \frac{\tau_{L0}/J}{(s+r_1)(s+r_2)(s+r_3)} \frac{1}{s}$$
$$= \frac{A}{s+r_1} + \frac{B}{s+r_2} + \frac{C}{s+r_3}$$

where A, B, and C are constants. The inverse Laplace transform of  $E_1(s)$  is

$$e_1(t) = Ae^{-r_1t} + Be^{-r_2t} + Ce^{-r_3t} \to 0.$$

Similarly,  $e_2(t) \to 0$ .

## Problem 9 Back Emf

The field-oriented model of the induction motor is given by

$$\begin{split} \frac{d\omega}{dt} &= \mu \psi_d i_q - (f/J)\omega - \tau_L/J \\ \frac{d\psi_d}{dt} &= -\eta \psi_d + \eta M i_d \\ \frac{di_d}{dt} &= -\gamma i_d + (\eta M/\sigma L_R L_S)\psi_d + n_p \omega i_q + \eta M i_q^2/\psi_d + u_d/\sigma L_S \\ \frac{di_q}{dt} &= -\gamma i_q - (M/\sigma L_R L_S) n_p \omega \psi_d - n_p \omega i_d - \eta M i_q i_d/\psi_d + u_q/\sigma L_S \\ \frac{d\rho}{dt} &= n_p \omega + \eta M i_q/\psi_d. \end{split}$$

The mechanical power produced is

$$\tau\omega = J\mu\psi_d i_q \omega = \frac{n_p M}{L_R} \psi_d i_q \omega$$

and the electrical power into the q axis is  $u_q i_q$ . In particular, the voltage term  $-(M/L_R)n_p\omega\psi_d$  in the q axis absorbs the electrical power

$$\left(-\frac{n_p M}{L_R}\omega\psi_d\right)i_q$$

which is the negative of the mechanical power produced. The back-emf term in the voltage is the term that when multiplied by the current in that phase gives the (negative of the) mechanical power produced. Thus the back emf in the field-oriented coordinate system is

$$-\frac{n_p M}{L_R} \omega \psi_d.$$

**Problem 10** Tracking a Time-Varying Flux Reference

Substitute

$$i_{dr} = K_{\psi P}(\psi_{dref} - \psi_d) + K_{\psi I} \int_0^t (\psi_{dref} - \psi_d) dt + i_{dref}$$

into

$$\frac{d\psi_d}{dt} = -\eta\psi_d + \eta M i_{dr}$$

to obtain

$$\frac{d\psi_d}{dt} = -\eta \psi_d + \eta M \left( K_{\psi I} \int_0^t (\psi_{dref} - \psi_d) dt + K_{\psi P} (\psi_{dref} - \psi_d) + i_{dref} \right).$$

Then, with  $e_0 = \int_0^t (\psi_{dref} - \psi_d) dt$ ,  $e_1 = \psi_{dref} - \psi_d$ , and  $(i_{dref}, \psi_{dref})$  satisfying

$$d\psi_{dref}/dt = -\eta\psi_{dref} + \eta Mi_{dref},$$

it follows that

$$\begin{split} \frac{de_0}{dt} &= e_1 \\ \frac{de_1}{dt} &= \frac{d\psi_{dref}}{dt} + \eta\psi_d - \eta M K_{\psi I} \int_0^t (\psi_{dref} - \psi_d) dt - \eta M K_{\psi P} (\psi_{dref} - \psi_d) - \eta M i_{dref} \\ &= -\eta \left( \psi_{dref} - \psi_d \right) - \eta M K_{\psi I} \int_0^t (\psi_{dref} - \psi_d) dt - \eta M K_{\psi P} (\psi_{dref} - \psi_d) \\ &= -\eta M K_{\psi I} e_0 - \eta \left( M K_{\psi P} + 1 \right) e_1. \end{split}$$

Setting

$$\eta \left( MK_{\psi P} + 1 \right) = r_1 + r_2$$
$$\eta MK_{\psi I} = r_1 r_2$$

or

$$K_{\psi P} = \frac{\left(r_1 + r_2\right)/\eta - 1}{M}$$
 
$$K_{\psi I} = \frac{r_1 r_2}{\eta M}$$

this becomes

$$\frac{de_0}{dt} = e_1 \frac{de_1}{dt} = -r_1 r_2 e_0 - (r_1 + r_2) e_1.$$

Taking the Laplace transform gives

$$sE_0(s) - e_0(0) = E_1(s)$$
  

$$sE_1(s) - e_1(0) = -r_1r_2E_0(s) - (r_1 + r_2)E_1(s).$$

or

$$\left[\begin{array}{cc} s & -1 \\ r_1 r_2 & s + r_1 + r_2 \end{array}\right] \left[\begin{array}{c} E_0(s) \\ E_1(s) \end{array}\right] = \left[\begin{array}{c} e_0(0) \\ e_1(0) \end{array}\right].$$

Solving gives

$$\begin{bmatrix} E_0(s) \\ E_1(s) \end{bmatrix} = \frac{1}{(s+r_1)(s+r_2)} \begin{bmatrix} s+r_1+r_2 & 1 \\ -r_1r_2 & s \end{bmatrix} \begin{bmatrix} e_0(0) \\ e_1(0) \end{bmatrix} = \frac{1}{(s+r_1)(s+r_2)} \begin{bmatrix} (s+r_1+r_2)e_0(0)+e_1(0) \\ -r_1r_2e_0(0)+se_1(0) \end{bmatrix}$$

where it follows by the method of partial fractions (assuming  $r_1$  and  $r_2$  are distinct)

$$E_1(s) = \frac{-r_1 r_2 e_0(0) + s e_1(0)}{(s+r_1)(s+r_2)} = \frac{A}{s+r_1} + \frac{B}{s+r_2}$$

so that  $e_1(t) \to 0$  with  $r_1 > 0$  and  $r_2 > 0$ .

**Problem 11** Trajectory Tracking Via Input-Output Linearization Substitute

$$i_{qr} = \left(K_0 \int_0^t (\theta_{ref} - \theta)dt + K_1(\theta_{ref} - \theta) + K_2(\omega_{ref} - \omega) + (f/J)\omega + \alpha_{ref}/\mu \psi_d\right)$$

into

$$\begin{split} \frac{d\theta}{dt} &= \omega \\ \frac{d\omega}{dt} &= \mu \psi_d i_{qr} - (f/J)\omega - \tau_L/J \end{split}$$

to obtain

$$\begin{split} \frac{d\theta}{dt} &= \omega \\ \frac{d\omega}{dt} &= K_0 \int_0^t (\theta_{ref} - \theta) dt + K_1 (\theta_{ref} - \theta) + K_2 (\omega_{ref} - \omega) + \alpha_{ref} - \tau_L / J. \end{split}$$

With  $e_0 = \int_0^t (\theta_{ref} - \theta) dt$ ,  $e_1 = \theta_{ref} - \theta$ , and  $e_2 = \omega_{ref} - \omega$ , and assuming the reference trajectory satisfies

$$\frac{d\theta_{ref}(t)}{dt} = \omega_{ref}(t)$$
$$\frac{d\omega_{ref}(t)}{dt} = \alpha_{ref}(t),$$

one obtains

$$\begin{aligned} \frac{de_0}{dt} &= e_1\\ \frac{de_1}{dt} &= e_2\\ \frac{de_2}{dt} &= -K_0 e_0 - K_1 e_1 - K_2 e_2 + \tau_L/J. \end{aligned}$$

The Laplace transform of this system is then

$$sE_0(s) - e_0(0) = E_1(s)$$
  

$$sE_1(s) - e_1(0) = E_2(s)$$
  

$$sE_2(s) - e_2(0) = -K_0E_0(s) - K_1E_1(s) - K_2E_2(s) + \tau_L(s)/J$$

or

$$\begin{bmatrix} s & -1 & 0 \\ 0 & s & -1 \\ K_0 & K_1 & s + K_2 \end{bmatrix} \begin{bmatrix} E_0(s) \\ E_1(s) \\ E_2(s) \end{bmatrix} = \begin{bmatrix} e_0(0) \\ e_1(0) \\ e_2(0) \end{bmatrix} + \begin{bmatrix} 0 \\ 0 \\ \tau_L(s)/J \end{bmatrix}.$$

Then

$$\begin{bmatrix} E_0(s) \\ E_1(s) \\ E_2(s) \end{bmatrix} = \frac{1}{s^3 + K_2 s^2 + K_1 s + K_0} \begin{bmatrix} s^2 + K_2 s + K_1 & s + K_2 & 1 \\ -K_0 & s^2 + K_2 s & s \\ -K_0 s & -(K_1 s + K_0) & s^2 \end{bmatrix} \begin{pmatrix} \begin{bmatrix} e_0(0) \\ e_1(0) \\ e_2(0) \end{bmatrix} + \begin{bmatrix} 0 \\ 0 \\ \tau_L(s)/J \end{bmatrix} \end{pmatrix}.$$

With  $\tau_L(s) = \tau_{L0}/s$  and

$$K_2 = r_1 + r_2 + r_3$$
  
 $K_1 = r_1r_2 + r_1r_3 + r_2r_3$   
 $K_0 = r_1r_2r_3$ ,

the characteristic polynomial may then be written as

$$a(s) = s^{3} + K_{2}s^{2} + K_{1}s + K_{0} = s^{3} + (r_{1} + r_{2} + r_{3})s^{2} + (r_{1}r_{2} + r_{1}r_{3} + r_{2}r_{3})s + r_{1}r_{2}r_{3}$$
$$= (s + r_{1})(s + r_{2})(s + r_{3}).$$

Then

$$E_0(s) = \frac{\left(s^2 + K_2 s + K_1\right) e_0(0) + \left(s + K_2\right) e_1(0) + e_2(0)}{(s + r_1)(s + r_2)(s + r_3)} + \frac{\tau_{L0}/J}{(s + r_1)(s + r_2)(s + r_3)} \frac{1}{s}$$

$$E_1(s) = \frac{-K_0 e_0(0) + (s^2 + K_2 s) e_1(0) + s e_2(0)}{(s+r_1)(s+r_2)(s+r_3)} + \frac{s (\tau_{L0}/J)}{(s+r_1)(s+r_2)(s+r_3)} \frac{1}{s}$$

$$E_2(s) = \frac{-K_0 s e_0(0) - (K_1 s + K_0) e_1(0) + s^2 e_2(0)}{(s + r_1)(s + r_2)(s + r_3)} + \frac{s^2 (\tau_{L0}/J)}{(s + r_1)(s + r_2)(s + r_3)} \frac{1}{s}.$$

The closed-loop poles are  $p_1 = -r_1$ ,  $p_2 = -r_2$ ,  $p_3 = -r_3$  and, assuming these poles are distinct,  $E_1(s)$  has the form

$$E_1(s) = \frac{-K_0 e_0(0) + (s^2 + (K_2 + f/J)s) e_1(0) + se_2(0)}{(s+r_1)(s+r_2)(s+r_3)} + \frac{\tau_{L0}/J}{(s+r_1)(s+r_2)(s+r_3)} \frac{1}{s}$$

$$= \frac{A}{s+r_1} + \frac{B}{s+r_2} + \frac{C}{s+r_3}$$

where A, B, and C are constants. The inverse Laplace transform of  $E_1(s)$  is then

$$e_1(t) = Ae^{-r_1t} + Be^{-r_2t} + Ce^{-r_3t} \to 0.$$

Similarly,  $e_2(t) \to 0$ .

#### Problem 12 Field Weakening

When the motor is decelerating, it is generating voltage rather than consuming voltage from the source. Consequently, the limits of the supply voltage are not a constraint in this mode. However, the reverse blocking voltage of the switches of a PWM amplifier are a constraint on the voltage.

## Problem 13 Maximum Torque

$$\tau = J\mu M i_{d0} i_{q0} = J\mu M \sqrt{I_{\rm max}^2 - i_{q0}^2} i_{q0}$$

or

$$\tau^2 = (J\mu M)^2 \left(I_{\text{max}}^2 - i_{q0}^2\right) i_{q0}^2.$$

To maximize with respect to  $i_{q0}$ , one proceeds as follows:

$$\frac{\partial}{\partial i_{q0}} \tau^2 = 0$$

$$\implies (-2i_{q0}) \left(i_{q0}^2\right) + \left(I_{\max}^2 - i_{q0}^2\right) 2i_{q0} = 0$$

$$\implies I_{\max}^2 = 2i_{q0}^2$$

$$\implies i_{q0} = I_{\max}/\sqrt{2}$$

$$\implies i_{d0} = I_{\max}/\sqrt{2}.$$

## **Problem 14** Closed-Loop Poles of the Input-Output Controller

# (a) Field-Oriented Controller

The poles of the closed-loop mechanical system are the roots of

$$s^3 + K_2 s^2 + K_1 s + K_0 = s^3 + 1.07 \times 10^3 s^2 + 7.04 \times 10^5 s + 1.07 \times 10^6 = 0$$

which are

$$-1.5234, -534.24 \pm j645.73$$

The poles of the closed-loop flux tracking controller are the roots of

$$s^{2} + \eta \left(MK_{\psi P} + 1\right)s + \eta MK_{\psi I} = s^{2} + \frac{R_{R}}{L_{R}}\left(MK_{\psi P} + 1\right)s + \frac{R_{R}}{L_{R}}MK_{\psi I}$$

$$= s^{2} + \frac{3.9}{0.014}\left(0.0011 \times 1600 + 1\right)s + \frac{3.9}{0.014}0.0011 \times 23000$$

$$= s^{2} + 768.86s + 7047.9$$

which are

$$-759.58, -9.2787$$

#### (b) Input-Output Linearization Controller

The poles of the closed-loop mechanical system are the roots of

$$s^3 + K_2 s^2 + K_1 s + K_0 = s^3 + 125 s^2 + 5.5 \times 10^4 s + 3 \times 10^5 = 0$$

which are

$$-5.5208, -59.740 \pm j225.33$$

The poles of the closed-loop flux tracking controller are the roots of

$$s^{2} + \eta \left(MK_{\psi P} + 1\right)s + \eta MK_{\psi I} = s^{2} + \frac{R_{R}}{L_{R}}\left(MK_{\psi P} + 1\right)s + \frac{R_{R}}{L_{R}}MK_{\psi I}$$

$$= s^{2} + \frac{3.9}{0.014}\left(0.0011 \times 10000 + 1\right)s + \frac{3.9}{0.014}0.0011 \times 420000$$

$$= s^{2} + 3342.9s + 1.287 \times 10^{5}$$

which are

$$-3303.9, -38.953$$