



American Roofing Company · Changing the Industry
Anthony Cross · Master Contractor · LIC BC-0043 · MASTER · RESIDENTIAL & COMMERCIAL

Lexington, KY · Regency Road District
(859) 555-0143 · americanroofing.co

// CLAIM SNAPSHOT · STRATEX™ DIFFERENCE REPORT

The Bingham Family Trust

2440 Regency Road · Lexington, KY 40503 · PASSPORT STX-877D9E3C8FC3

CLAIM
SUPPORTABLE
96% CONFIDENCE

// HEADLINE DELTAS · BASELINE → POST-EVENT

NEW DAMAGE 3	WORSENERD 1	RESOLVED 0	AREA Δ (SF) 343.1	ENVELOPE Δ -24	REPAIR EST. Δ \$26,510
-----------------	----------------	---------------	----------------------	-------------------	---------------------------

// ADJUSTER NARRATIVE

The Bingham Family Trust property at 2440 Regency Road sustained storm-correlated damage on 2026-06-25 from a confirmed 0.5-inch hail and 62 mph wind event (NOAA-877D9E3C8FC3-HW-001). Post-storm drone re-scan recorded an envelope score drop of 24 points (92 to 68) and a moisture rise of 22.5 percentage points (12.0% to 34.5%) across 343.1 sq ft of new damage. Three new items were identified: URGENT hail bruising on Facet F2 Rear Hip (184.7 sq ft, \$14,820), SEVERE ridge cap lift on 18 of 62 LF primary ridge (\$4,620), and HIGH sub-surface moisture intrusion into F2 decking at 96.4 sq ft (\$6,210); a pre-existing soffit blockage on the north eave worsened from LOW to HIGH severity (\$1,240). Total repair delta is \$26,510 at 96% system confidence. Recommend escalate to field inspector to verify moisture extent and decking integrity before settlement authorization.

// STORM CORRELATION

EVENT HAIL+WIND	INTENSITY 0.5” hail · 62 mph gust	DATE 2026-06-25	NOAA NOAA-877D9E3C8FC3-HW-001
--------------------	--------------------------------------	--------------------	----------------------------------

// BASELINE SCAN · Baseline Scan

CAPTURED · 2026-06-25 14:26:50

ENVELOPE 92/100	MOISTURE 12.0%	ANOMALIES 1
--------------------	-------------------	----------------

// POST-EVENT SCAN · Post-Storm Re-Scan

CAPTURED · 2026-06-25 13:26:50

ENVELOPE 68/100	MOISTURE 34.5%	ANOMALIES 4
--------------------	-------------------	----------------



American Roofing Company · Changing the Industry
Anthony Cross · Master Contractor · LIC BC-0043 · MASTER · RESIDENTIAL & COMMERCIAL

Lexington, KY · Regency Road District
(859) 555-0143 · americanroofing.co

NEW DAMAGE • WORSENER • RESOLVED

// EVERY DELTA THE STRATEX DIGITAL TWIN COULD RECONCILE BETWEEN THE TWO SCANS

// NEW DAMAGE – NOT PRESENT IN BASELINE

SEV	TYPE	LOCATION	AREA (SF)	CONF	EST. \$	DIAGNOSIS
URGENT	Hail Bruising	Facet F2 (Rear Hip)	184.7	96.4%	\$14,820	Distinct 0.5-0.75" hail strikes – granule loss + mat fracture confirmed.
SEVERE	Lifted Ridge Cap	Primary ridge (62 LF)	62.0	94.0%	\$4,620	Wind uplift exceeded fastener pull-out load – ridge cap lifted 0.4" on 18 LF.
HIGH	Sub-Surface Moisture Intrusion	Facet F2 → Decking	96.4	89.0%	\$6,210	Thermographic Δ confirms wet decking under hail-damaged field – saturation 34.5%.

// WORSENER – PRESENT IN BASELINE, ESCALATED POST-EVENT

SEV	TYPE	LOCATION	AREA (SF)	CONF	EST. \$	NOTES
HIGH	Soffit Blockage	North eave run	0	91%	\$1,240	WORSENER • was LOW • +0.0 sqft new area

// RESOLVED – BASELINE FINDINGS NO LONGER PRESENT

SEV	TYPE	LOCATION	AREA (SF)	CONF	EST. \$	DIAGNOSIS
No baseline findings have resolved.						