2.1.2 ADDRESS AND FUNCTION CHARACTERS

Address characters and their meanings are shown in Table 2.2.

Table 2.2 Address Characters

Address Characters	Meanings	B: Basic O: Optional
A	Additional rotary axis parallel to X-axis	0
В	Additional rotary axis parallel to Y-axis	0
С	Additional rotary axis parallel to Z-axis	0
D	Tool radius offset number	В, О
E	User macro character	0
F	Feedrate	В
G	Preparatory function	В, О
Н	Tool length offset number	. В
I	X-coordinate of arc center Radius for circle cutting	В О
J	Y-coordinate of arc center Cutting depth for circle cutting	В, О
K	Z-coordinate arc center	В
L	Number of repetitions	В, О
М	Miscellaneous functions	В
N	Sequence number	В
0	Program number	В
Р	Dwell time, Program No. and sequence No. designation in subprogram	B O
Q	Depth of cut, shift of canned cycles	О
R	Point R for canned cycles Radius designation of a circular arc	О, В
S	Spindle-speed function	В
Т	Tool function	B
U	Additional linear axis parallel to X-axis	0
V	Additional linear axis parallel to Y-axis	О
W	Additional linear axis parallel to Z-axis	0
x	X-coordinate	В
Y	Y-coordinate	В
Z	Z-coordinate	В