SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

Task / Activity:	**GENERAL CONSTRUCTION**	**SWMS Number:**	001
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		

Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
General Safety Induction EWP Certification Scissor Certification Working at Heights Certification	Hand Tools Power Tools EWP Ladders Scaffold Working at Heights Equipment Sunscreen Temporary Fencing	Grouts & Adhesives Sealants & Fillers Paints Sealants and Fillers Cleaning Chemicals Fertilisers Poisons Insulation Material Cement

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

		Fuels

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			
Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

Site preparation	• Slips, trips and falls
	• Unfamiliar with job processes and hazards
	• Unauthorised site access
		Moderate	Possible	M13	• Appropriate site signage and delineation must be put in place to inform persons on site as well as members of the public of the hazards associated with the works.
					• Appropriate waste disposal areas must be set up and regularly serviced.
					• Appropriate amenities must be provided, such as:
					  • cool drinking water
					  • toilets
					  • shade
					  • break area
					• Appropriate WHSE documentation and equipment must be set up on site in an obvious location.
					• Appropriate first aid and & firefighting equipment must be provided.
					• Any overhead or underground services shall be located, marked, and adequately protected
					• Fauna and flora controls must be in place.
					• Site parking must be made clear.
					• Access and exit to and from site must be free of hazards.
					• Use appropriate barriers to prevent unauthorised access to the site and sufficient barricading to prevent access to high-risk work areas or hazards.
						Supervisor and WHSE Manager in Site Establishment Checklist and regular Site Inspections	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Site for equipment to be placed must be level and of a sufficient capacity to safely handle the weight of the equipment, materials and/or plant. • All relevant personnel must have read, fully understood, and agreed to comply with the information and requirements contained within the SWMS. • All subcontractor companies on site must be successfully onboarded into Tallan's system prior to arrival on site. • All persons working on site must complete the following mandatory inductions before starting work. • General Construction Induction (White Card) • Site Specific Induction.		
Accessing the site	• Slips, trips and falls	Moderate	Possible	M13	• Onsite induction to highlight any slip trip and fall hazards • Site supervisor to ensure that work area is clean, tidy, ventilated and well lit	Supervisor in Site Inspection	L6
Access Work Areas	• Fall from ladder • Fall from heights • Confined space entry • Door closing or opening on workers	Major	Likely	H21	• Use a platform ladder where possible • Perform visual check on ladder for obvious faults and defects prior to use • Damaged ladders are to be removed from use, "tagged not for use" and repaired • Erect ladder on clean, level surface	Supervisor in Site Inspection	M14

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Hearing and eye damage				• Do not place a ladder in front of the doorway unless locked or guarded • Secure work area around the ladder • Clean mud, grass etc. from boots to prevent slippage • Use a tool pouch to carry tools • Do not leave tools and equipment on ladder rungs • Do not over-reach while on ladder • Only one person on a ladder at any one time • Select appropriate fall protection equipment where a worker can fall from one level to another • Site supervisor must implement the use of either a work platform, physical barrier or physical restraint • Ensure sound footing at all times		

Temporary fence barricades	• Struck by vehicle
	• Pedestrian movement
	• Hazardous manual tasks
	• MSD
	• Cuts
	• Laceration
		Major	Possible	H18	• Utilise barricades, signs, and traffic controllers as required. Consider:
					  • Safe detours for pedestrians if existing pathways are affected
					  • Reversing vehicles, roadway obstruction, and other factors as required
					• Provide information to workers and other people on-site advising them of the exclusion zones
					• Provide supervision so that no unauthorised person enters an exclusion zone
						Supervisor in Site Inspection
						Worker Take 5
							M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Use traffic control where necessary:
					  • Only accredited traffic controllers are to perform traffic control duties
					  • Traffic controllers must have the required accreditation to perform traffic control duties
					  • Traffic controllers must have sufficient experience to set up and control traffic safely and efficiently.
					• Ensure there are sufficient number of workers for the task to allow for rapid fence construction
					• Movement of material from the delivery point to the installation area usually represents the greatest opportunity for damage or injury:
					  • Use hand trucks to move heavy materials
					  • Lift within physical capabilities of individual
					• Unload and place base blocks. Handle only one fencing foot at a time
					• Use team-lifts for fence panels
					• Clamp the fencing bracket using a battery-operated drill.		

Work area and equipment preparation and use	• Personal injury - • Cuts, strains, abrasions, burns • Possible eye injury	Moderate	Possible	M13	• Authority and empowerment to Stop the Job. • Follow all site rules and procedures.	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Dust inhalation (depends on surrounds – these tasks should not cause dust or fumes) • Pinch/ crush injury • Musculoskeletal Injuries				• Conduct a manual handling risk assessment before lifting, pushing, pulling, or carrying any object. • Use mechanical tools and aids whenever possible to avoid manual handling. • Plan your lift, remove obstructions, and ensure the object is light, steady, and easy to grip, position hands to avoid pinch/ crush points. • When lifting keep the head up, bend the knees, and move smoothly. Avoid twisting, bending, or leaning the back. • Utilize two-man lifts, no one man lifts over 20kg. • Manual handing tasks must be split up between multiple workers to avid repetitive work injuries. • Wear all mandatory PPE and task specific PPE. • Communicate task clearly with all work crew members. • Ensure a thorough understanding of expectations. • If a hazard is identified in the work area – fix it immediately or if unable to do so, isolate the hazard and inform you supervisor. • Work on flat surface where practicable	Worker Take 5	

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Secure all tools and/or equipment by lanyard or store in a toolbox/basket when on the work platform.		
Delivery of materials – by others or from your work vehicle	• Unskilled workers selecting/using lifting equipment. • Unstable loads – load falling on site personnel. • Slips, trips and falls • Loads falling from heights and hitting site personnel.	Moderate	Possible	M13	• Check load has not moved during transport. • Once load has been checked and is deemed safe, tie down straps can then be released. Remove only one strap at a time continually checking load. • Check area in which you are working and make sure it is safe and free from trip hazards, ensure good housekeeping. • Ensure no personnel to be beneath loads. • Correct manual handling practices are to be utilised- assess the load, look for a clear path, place the body as close to the items as possible and avoid lifting and twisting back, if you need to change path move feet to path direction - only lift what you can carry. • Get assistance if person is not capable of lifting the load and sustaining an injury. • The use of gloves to carry items is encouraged where required	Supervisor and WHSE Manager in regular Site Inspections	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Manual Handling Lifting Objects (Load)	• Limb or back injuries (Muscle strain)	Moderate	Possible	M13	• Access the weight and ensure your path of movement is free of obstruction. • If unsure of the weight of the load to be lifted ask for assistance or use mechanical means. • Do not lift any load beyond your capability. • Get a solid hold on the load to be lifted. • Keep your back straight by tucking in your chin and bending your knees. • Tighten your stomach and lift with your legs. • Lift the load slowly and do not jerk. • Communicate timing of the lift with other persons assisting with the lift. • Hold the load as close to body as possible before lifting. • Avoid twisting back during lifting or when moving the load. • Turn with your feet • If working in teams – ensure all members of the team are of similar height / adequate strength. • Designate one leader for the team.	Supervisor in Monthly Site Inspection	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• When assigning teams consider the age and any pre-existing injuries of the workers.		
Truck Access/ Unloading	• Residence Safety • Manual Handling • Moving Vehicles • Cuts/Scratches and/or Lacerations to hands	Minor	Likely	M12	• Spotters must be used to keep public away from trucks when entering/exiting site and unloading. • If unloading by hand, use proper manual handling techniques. • Gloves to be worn while manual handling	Supervisor All workers Truck driver	L5
Vehicle Mobilization to site	• Not aware of general site hazards and controls • Not aware of area specific issues and controls	Major	Likely	H21	• Completion of Site-Specific Induction • Attendance at / read and sign onto daily prestart meetings. • Understand and observe Site Plant/traffic movement plan (attached to daily Prestart and located at gate entrance)	Supervisor in Site Inspection	M10
Driving on public roads and access through public area's	• Interaction with public traffic and/or pedestrians • Loss of load and/or objects ejected from truck	Major	Possible	H18	• Obey all speed limits, signage and road rules. • Observe requirements Vehicle Management Plan (VMP) • ALL trucks must stop, on site in a safe location, and be checked prior to leaving site for items that may be ejected or fall from the truck e.g. rocks between tires, material on draw bars, materials on tray tops or tarps.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Tray covers/tarps must be fully covering the load prior to truck exiting site. • Inspect truck to determine if clean down required to prevent tracking mud onto public roads		
Entering and leaving site in vehicle	• Interaction with public traffic and/or pedestrians • Interaction with site traffic and/or workers on foot	Major	Possible	H18	• Observe all gate entry/exit requirements as stated in Vehicle Movement Plan HC2G-VMP • Observe all road rules. • When entering site (from a public road) decelerate slowly (no heavy braking) and use indicators and flashing light at least 5 seconds prior to entering. • Announce gate entry via UHF. • Observe 40 km maximum site speed. • Observe 10 km speed limit where posted.	Supervisor in Site Inspection	M10
Driving on site	• Interaction with site traffic and/or workers on foot • Loss of control of vehicle	Major	Possible	H18	• Stay on designated haul routes at all times. • Use positive communication (with UHF call up) whenever coming with 20m of operational plant /Moxy's/ scrapers/ vehicles etc. • Slow to 10kmh when coming within work zone of workers on foot. • Obey all signage including call up points when entering site, crossing over public roads.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• DO NOT ENTER EXCLUSION ZONES unless specifically authorized by Supervisor/ Leading Hand for area. • Flashing light and UHF to be fitted to all vehicle and plant. • Obey all site speed limits e.g. general 40km limit. • Drive to conditions		
Reversing on site	• Interaction with site traffic, workers on foot, machinery, equipment etc	Major	Possible	H18	• Reverse alarm on truck to be operational. • Driver to check intended path (obstacle, obstructions, plant, people, hazards etc) each time prior to reversing. • Spotter to be used (plant operator may spot reversing trucks) where obstacles etc exist (see above) • All other plant, LV's, trucks, workers on foot to maintain operational exclusion zone (minimum 20m) from reversing trucks. • On foot spotter to place themselves well clear or reversing truck but in sight of driver – bollard/s or witches hat/s to be used where practicable to show position for dropping load	Supervisor in Site Inspection	M10
Vehicle Receiving load	• Driver being struck by objects being loaded	Major	Possible	H18	• Truck driver to remain in cab at ALL TIMES while being loaded. • Truck driver to follow directions of plant operator for positioning of truck.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Maintain positive communications with plant operator, other trucks, plant LV's etc. • No excavator/loader is to place load over cab of truck.		
Vehicle Tipping load	• Contact with overhead services/structures • Instability – unintentional movement of truck.	Critical	Possible	H22	• Where practicable, tipping area to be away from overhead services and structures. • "Goal posts", warning signs etc to be erected and maintained in proximity to overhead services. • Trained spotter to be used where there is potential to come within exclusion zone of overhead services (minimum exclusion zone is 3m) • Truck most not move while bin is raised – bin must be completely lowered before moving. • Trucks to be tipped on stable and level ground. • DO NOT TIP on cross slopes. • Area for tipping to be determined by Supervisor/ Leading Hand as suitable – taking into account the stability and slope of the area. • Truck must be stopped prior to bin being hoisted. • Truck driver must remain in cab at all times while load being tipped.	Supervisor in Site Inspection	H15

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• No person (including spotter) is to be within twice the 'fall zone" (minimum 15 metres) from truck while tipping load.		
Check new materials for compliance to spec and standards	• Inappropriate materials	Moderate	Unlikely	M9	• Inspect all materials to ensure that they are the correct type, quantity, labelled correctly and are not damaged • Check all materials purchased comply with spec and that they meet relevant Australian Standards	Supervisor in Site Inspection	L1
Isolate equipment, Lock Out Tag Out	• Contact with services or live cables	Major	Likely	H21	• Take care when opening or closing doors. Doors may fly open or pull shut due to pressure variations or wind. • Do not put hands on doorframe or edge of door	Supervisor in Site Inspection	M14
Use of power tools and hand tools	• Cuts, abrasions, lacerations • Bruises • Amputations • Electrocution	Major	Possible	H18	• Train workers in the correct use of the equipment and supervise until they demonstrate they can operate the tool safely • Use tools and fittings to manufacturers recommendations • Check equipment is tested and tagged and are in good condition, especially power / ext. cords, repair or replace as required • Use Earth Leakage Circuit Breaker (ELCB) or Residual Current All Workers Device (RCD) to prevent electrocution	Site Supervisor during regular site inspections	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Use stands and hooks to raise power cords off the ground in wet or high traffic areas • Wear the appropriate PPE such as safety boots, hearing protection, dust mask or half or full-face respirator, gloves etc. • Keep hair, jewellery and loose clothing etc. away from moving parts.		
Installation of particle board flooring to joists	• Using nail gun • And power saw • Heavy lifting • Walking on joists	Moderate	Possible	M13	• Workers to wear correct PPE. • Team lifts for all heavy materials • Lay temporary flooring to walk on	Site Supervisor during regular site inspections	L6
Cutting of products containing silica	• Dust inhalation	Major	Possible	H18	• M or H class vacuum to be used with dustless saw system, face mask to be worn and all workers to be fit tested	Site Supervisor during regular site inspections	M10
Construction of timber frames, cladding, Fix out	• Using electrical drop saw, nail guns, • Manual handling	Moderate	Possible	M13	• Workers inspect tools that safety guards are working. • All persons to be trained and competent in the use of tools required, • Workers to be competent in tasks assigned. • Appropriate PPE to be worn	Site Supervisor during regular site inspections	L6
Standing frames	• Manual lifting • Crushing	Moderate	Possible	M13	• Workers are trained in safe manual handling practices and use team lifts for placement of frames.	Site Supervisor during	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Bracing to be installed	regular site inspections	
Install trusses/ rafters	• Work at heights • Falls from step ladder	Major	Possible	H18	• Trestles and planks or EWP will be used where necessary, workers to be competent to carry out works. • Ladders will be visually checked for damage prior to use. • Ladders will be checked to ensure that ladder is manufactured for industrial use	Site Supervisor during regular site inspections	M10
Cutting using Circular Saw, Nailing, De-nailing using chisels	• Material in eyes, Noise, Dust. • Rotating cutting blade Vibration • Use of hand tools • Puncture of skin • Hit by object	Moderate	Possible	M13	• Correctly support timber at all times using sawhorses etc. to prevent the materials slipping or cutting other objects or persons. • Keep leads away from cutting area, leads to be placed on lead stands. • Supervise apprentices and unskilled workers and ensure they take Regular breaks. • All timber to have nails removed when stripping to prevent chance of standing on nail. • Waste nails to be put in bin/skips. • Select the Correct tools (hammers and pinch bars) • Correct PPE (Glasses, Hearing Protection), Gloves must be worn when there is a risk of hand injury.	Site Supervisor during regular site inspections	L6
Use of grinders and wet saws	• Hit by flying objects.	Major	Possible	H18	• The correct guard must be in place,	Site Supervisor	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	Lacerations Burns Eye Injuries Amputations • Noise • Fires				• The correct fitting backing plate and front nut is to be used, • The rated RPM of the cutting unit must not exceed the maximum rated RPM of the cutting wheel. • Inspect cutting wheels for damages. • Operator to wear earplugs or earmuffs. • For eye and face protection the operator to wear safety glasses, a high impact face shield. • Persons are to be competent in the use of power tools. • Never direct sparks, dust or debris towards another person. • Provide adequate ventilation for areas where grinding of rusted surfaces or previously painted surfaces, and where dust may be generated because of the process of grinding. • Grinding of uneven surfaces may cause the grinder to move or vibrate in hands. For excessive vibration, switch off the grinder and check the disc for signs of damage. Always use protective clothing such as trousers, long sleeves, overalls and apron. • It is essential to wear a respirator or a suitable mask to filter particulate dust. • Gauntlets or heavy gloves can be used to reduce the effects of vibration.	during regular site inspections	

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• When dry cutting metals ensure fire extinguisher is nearby		
Working from scaffold system	• Falls, falling objects Workers and others being hit by falling objects	Moderate	Possible	M13	• Workers to ensure scaffold is checked for compliance certificate, kick boards remain in place and scaffold is not modified except by licenced person.	Site Supervisor during regular site inspections	L6
Work on trestles, mobile scaffold, EWPs	• Work at heights	Moderate	Possible	M13	• Trestle and planks to be used only for low works. • Mobile scaffold must be erected and used by competent persons. • Worker to be trained and competent in the use of EWPs. • Exclusion zone to be set up around work area if necessary	Site Supervisor during regular site inspections	L6
Sanding	• Cuts, Lacerations, Crush • Eye Injury • Dust Exposure • Irritation to eyes, nose, throat and/or airways • Silicosis (lung damage) • Electrocution	Major	Likely	H 21	• Wear gloves • Wear correct PPE for the activity / task • Keep hand and fingers clear of sander • Wear safety glasses and face shield (double eye protection) • Do NOT breathe dust • Always wear P1 or P2 rated respirator • Wear goggles or double eye protection • Avoid cutting with saw, best practice is to score & snap, then use guillotine, fibre shear and then saw with dust extractor	Site Supervisor during regular site inspections	M 10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Work with wind/breeze to back • Warn others and avoid dust to harm unprotected workers or public • Do Not suspend or tie power leads to trestles • All electrical equipment test and tagged and in date • Do not cut lead • Ensure RCD is always connected		

Using Fillers and Putties	• Skin, Inhalation or eye contact	Moderate	Possible	13	• Ensure application is always on a study platform
					• PPE use as per MSDS see below:
					• Personal protective equipment
					• General protective and hygienic measures
					• Avoid close or long-term contact with the skin.
					• Wash hands before breaks and at the end of work.
					• Protection of hands:
					  • PVA gloves of superior quality.
					• Eye protection:
					  • Safety Glasses
					• First Aid Measures:
					  • Immediately remove any clothing soiled by the product.
					  • After inhalation:
						Site Supervisor during regular site inspections	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Supply fresh air. If required, provide artificial respiration. Keep patient warm. Consult doctor if symptoms persist. • In case of unconsciousness, place patient stably inside position for transportation. • After skin contact Immediately wash with water and soap and rinse thoroughly. • After eye contact • Rinse opened eye for several minutes under running water. Then consult a doctor.		
Application of Liquid Nails	• Slips, trips, falls, cuts, abrasions, fumes	Moderate	Possible	13	• Ensure adequate ventilation is provided when using gloss paints or during sanding activities i.e. natural ventilation or mechanical extraction fans etc. • Ensure MSDS for the paints are on site and readily available • Ensure the work area is free of obstacles • PPE to be worn as recommended by the MSDS for the paint being used	Site Supervisor during regular site inspections	M9
Mixing Sand and Cement	• Hazardous substances coming into contact with skin, eyes, inhalation	Moderate	Likely	H 17	• Always carry MSDS for all hazardous substances • Wear PVC gloves • Wash hands with soap and water after use	Site Supervisor during regular site inspections	L 6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure good ventilation of work area • Dispose of all packaging in general waste bin		
Installation of tiles	• Manual Handling • Musculoskeletal injuries (working on knees).	Moderate	Possible	M 13	• If possible, use mechanical means to transport tiles to the work areas, i.e. trolley or wheelbarrow. • Use PPE including kneepads and safety footwear. • Ensure good posture when kneeling and getting up.	Site Supervisor during regular site inspections	L6
Cutting of tiles with grinder or other power tile cutting saw.	• Electrocution, shocks, burns • • Lung, skin and eye irritation from exposure to silica dust. • Cuts & other injuries from blade / cutting wheel. • Noise and Eye injuries	Critical	Likely	VH 24	• Ensure cutting equipment has current test tag. Ensure RCD protection at the power source • All leads to have current test tags and to be elevated using insulated stands if possible • Use wet-cutting where possible. Ensure enough water/coolant is supplied to the work area to suppress dust. Ensure P2 respirators are provided where there is still a likelihood of exposure. • Check for smooth sliding operation of cutter. • Ensure the cutting blade is not loose. • Ensure that the tile is properly supported and won't slide or move. Ensure the cut-off will fall safely or will be supported. Check floor is clear of obstructions and debris. Remove any off-cuts at the end of the working day.	Site Supervisor during regular site inspections	M 10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					Operator position must be comfortable, no reaching or working off balance. Keep hands/fingers well clear of cutting blade. • Wear the correct PPE – Hearing protection and safety glasses.		
Mixing Adhesive and grouts	• Electrocution • Lung, skin and eye irritation from exposure to silica dust.	Critical	Likely	VH 24	• Ensure mixing drill has current test tag. Ensure RCD protection at the power source. All leads to have current test tags and to be elevated using insulated stands. • Open containers of adhesive in a well-ventilated area. Wear dust mask and safety glasses.	Site Supervisor during regular site inspections	M 10
Grouting of tiles	• Musculoskeletal injuries (working on knees). • Skin irritation to hands • Splashing into eyes	Mod	Likely	H 17	• Use PPE including kneepads and safety footwear. Ensure good posture when kneeling and getting up. • Wear rubber or latex gloves when washing off grout. • Wear safety glasses.	Site Supervisor during regular site inspections	M 9
Use of Hazardous Substances and Chemicals	• Fire • Explosion • Spills • Environmental damage	Critical	Possible	H 22	• Ensure that a material safety data sheet is available and that recommendations are followed. • Switch off motors when refuelling welder/generator. Do not smoke when refuelling. • Store in appropriately labelled fuel containers.	Site Supervisor during regular site inspections	L 5

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Store in a well-ventilated area free of sources of ignition and with danger - no smoking signs. • Spill kit to be available for use • Clean up and contain any spills and dispose correctly. • Dispose of empty containers correctly		
Painting set up	• Fall from Heights	Major	Possible	H 18	• Use suitable Trestles (and brace planks) in preference to ladders • Do not use non-compatible components • Never sit on handrails • Do not climb framework	Site Supervisor during regular site inspections	M9

Painting work	• Eye Contamination
	• Skin Contamination
	• Inhalation of Fumes
		Major	Possible	H 18	• For advice, contact a Poisons Information Centre (e.g. phone Australia 131 126; New Zealand 0800 764 766) or a doctor.
					• Inhalation:
					  • Remove victim from area of exposure - avoid becoming a casualty. Remove contaminated clothing and loosen remaining clothing. Allow patient to assume most comfortable position and keep warm. Keep at rest until fully recovered. Seek medical advice if effects persist.
					• Skin Contact:
					  • If skin or hair contact occurs, immediately remove any
						Site Supervisor during regular site inspections	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					contaminated clothing and wash skin and hair thoroughly with running water. If swelling, redness, blistering or irritation occurs seek medical assistance. • Eye Contact: • If in eyes, hold eyelids apart and flush the eye continuously with running water. Continue flushing until advised to stop by a • Poisons Information Centre or a doctor, or for at least 15 minutes. • Ingestion: • Rinse mouth with water. If swallowed, do NOT induce vomiting. Give a glass of water. Seek medical advice. • Engineering controls: • Ensure ventilation is adequate • PPE: • Wear long sleeved clothing, chemical goggles and impervious gloves. Avoid generating and inhaling dusts. Always wash hands before smoking, eating, drinking or using the toilet. Wash contaminated clothing and other protective equipment before storage or re-use.		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Avoid breathing in fumes • Wear P1 or P2 respirator if necessary • Read SDS • Ensure adequate ventilation (open doors and windows where feasible)		
Painting manual tasks	• Person Injury Manual Handling • Sprains • Strains • Musculoskeletal	Moderate	Likely	M 12	• Use correct manual handling practices & techniques • Use material rope to hoist paint tins and equipment • Use assisted lifts	Site Supervisor during regular site inspections	M9
Working outside	• Effects of UV Rays • Effect of adverse weather conditions – storms / lightning / floods & cyclones causing flooding / damage / personal injury	Moderate	Possible	M13	• Apply Sunscreen, Hat, Glasses, Shade as often as possible. • Drink Water up to 10 litres per day. • If you are feeling overheated, you need to take a 5 min rest in the shade. • If there is a storm approaching, take cover and ensure plant is free from the potential for water rush or being bogged. • Personnel to take shelter in buildings or vehicles not under trees.	Site Supervisor during regular site inspections	M8
Pruning of trees	• Manual handling injuries • Cuts & abrasions • Eye Injuries	Moderate	Possible	M13	• Ensure that tools are in good working order and suited to the task being performed. • Warn workers that using hand tools incorrectly can cause strains or back injury. • Workers to always wear correct PPE for the task (gloves, glasses)	Supervisor in Monthly Site Inspection	L5

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Use wheelbarrow if load greater then 15kg when removing off cuts. • Ensure a tidy work area free of tripping hazards do not allow off cuts to build up in such a manner as tripping becomes a risk. • Be aware of hand location in relation secateurs. • Secure tools properly when not in use – i.e. tool pouch. • Ensure fall zone is clear prior to falling. • Use of shovel and rake to hold the tool as close to body as possible before lifting. • Avoid twisting back during lifting or when moving the rake and shovel. • Turn with your feet. • Rotate workers. • Gloves to be worn while manual handling. • Workers to wear long sleeve protective clothing, wide brim hat and sunscreen to be made available for use. Workers to maintain hydration levels throughout shift and take regular breaks if they are feeling the effects of heat exposure. • Wear the correct PPE for use of power saw Hearing and Eye protection.		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure test and tag for power tools is current and leads out of the cutting path. • Use portable RCD		
Placing Soils	• Plant and machinery impact injuries. • Manual handling injuries.	Major	Possible	H 18	• Keep clear of machinery when operating in the area. Wear high visibility clothing. • Ensure operator is aware of site personnel. • Training in manual handling.	Supervisor in Monthly Site Inspection	L5
Mulching & Graveling	• Manual handling – back and muscle • strain. • Eye damage, cuts, dust, inhalation, • irritation. • Sun burn.	Moderate	Likely	H 17	• Use correct tools for the task. Stockpile mulch/gravel close to work area. • Do not overload wheelbarrow and ensure load is even. • Keep path clear. • The use of P.P.E such as sunscreen cream, hats & protective clothing	Supervisor in Monthly Site Inspection	L5
Raking up and stockpiling of old mulch, rubbish or trees.	• Limb or back injuries (Muscle strain) • Hand injuries (blisters, lacerations) • Exposure to outdoor elements: UV, Dehydration, heat exhaustion	Mod	Possible	M 13	• Use of shovel and rake to hold the tool as close to body as possible before lifting. • Avoid twisting back during lifting or when moving the rake and shovel. • Turn with your feet. • Rotate workers. • Gloves to be worn while manual handling. • Workers to wear long sleeve protective clothing, wide brim hat and sunscreen	Supervisor All workers	M 9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					to be made available for use. Workers to maintain hydration levels throughout shift and take regular breaks if they are feeling the effects of heat exposure.		
Hedging	• Cuts and amputation	Major	Likely	H 21	• Carry out hedging works as planned and discussed at start. • Ensure hedger is operated at safe distance from body. • When hedging vertical faces of hedges, operate hedger at a safe distance from operator – minimum clearance to be 300mm (forearm length) from body, arms and legs. • Do not operate hedgers for extended periods of time at full reach and above chest height. • If hedging in difficult locations, awkward spaces or hedges with heights above chest revise procedure and consider using extended reach hedge unit.	Operator	M 10
Fuel Powered Equipment Operation (blowers, whipper snippers, hedgers etc.)	• Faulty equipment may cause injuries • Trip hazards and collisions with other workers	Major	Likely	M 21	• Users of equipment are required to visually inspect, prior to use, all equipment and any damage or suspected damage must be checked, replaced or repaired prior to use. • Personnel using equipment shall inspect all fuel levels for suitability and damage	Operator	L 5

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Grazes, trips, falls and manual handling				prior to use and ensure switches are off before starting. • When refuelling, ensure the task is done in a well-ventilated area and in compliance with the owner's manual recommendations. • Do not smoke while operating or refuelling the equipment. • Should any equipment fail, be damaged or not operate correctly during its use, it is to be "tagged out" with an Out of Service Tag and not used again until inspected and/or repaired by a competent person. • Use of equipment should be restricted to: Personnel who have been trained and are proficient in the operation of the tools or equipment and who have a sound knowledge of the necessary safety procedures associated with those tools or equipment; or • Other personnel required to undertake straightforward tasks, provided they are under the direct supervision of a competent operator. • Prepare / check work area. • Ensure work area is clear from obstructions and/or debris.		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure appropriate signage/safety barricades are in place if required. i.e. eye protection to worn is this area. • Do not operate equipment above shoulder height. • All guards and handles as supplied the manufacturer must be fitted and be in good working order. • Only attachments and fittings designed for the task and equipment are to be used. • All equipment must be switched off before attachments etc. are to be removed or changed. • Never touch a potentially hot part unless the equipment has been switched off and allowed to cool. • Always use the correct fitting tools to change or inspect the centre plug. • Maintain a clean and safe work area. • Never place equipment anywhere and walk away from it whilst switched on and running. • The immediate area around the task must be checked to ensure it is a safe environment to operate the equipment and all personnel are protected from injury due to dust, flying debris etc. Shields, barriers etc. must be utilised		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					whenever there is a risk to other personnel. • Check weather conditions prior to commencing work. Never work in excessive windy conditions. • Ensure you have a good footing; use two hands and be prepared to release the power trigger. Be prepared for jamming – the circular or rotating motion of the equipment may result in a twisting motion. • Do not leave any tools or equipment in an unsafe position on work benches, vehicles or in an overhead position where there is a chance the tool or equipment could fall and injure personnel below or damage the tool or equipment. • When not in use, ensure that the tool or equipment is placed in a safe position where it cannot fall or be tripped over		
Mower Operation	• Trip hazards, sun burn, moving parts and flying objects • Faulty equipment may cause injuries. • Fuel fires. • Unskilled operator	Major	Likely	M 21	• Prepare / check work area. • Always wear the right clothing – work boots, long pants, long sleeved shirt, sunscreen and a wide brimmed hat. • Remove any rocks, sticks and other debris that could be flung by the mower. • Ensure appropriate signage/safety barricades are in place if required.	Supervisor Operator	L 6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Injuries from moving parts				• Check over the mower for debris stuck in it / damage/wear to blades etc. Never use a mower that is damaged. If damaged contact your supervisor. • Disconnect the centre plug lead and remove any debris from under the mower. (Wear your gloves and use the provided wire brush and scrapers as necessary). • Set up signage, witches' hats and barricades as necessary around the work site to warn and exclude people from entering. (unless you are working in an isolated area where there are no other people) • Appropriate Personal Protective Equipment must be worn where and when required. ((e.g. eye protection, steel capped footwear, clothing, hearing protection (ear plugs or muffs) etc.)) • Users of equipment are required to visually inspect, prior to use, all equipment and any damage or suspected damage must be checked, replaced or repaired prior to use. • Personnel using equipment shall inspect all fuel levels prior to use and ensure switches are off before starting.		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Should any equipment fail, be damaged or not operate correctly during its use, it is to be "tagged out" with an Out of Service Tag and not used again until inspected and/or repaired by a competent person.
					• Use of equipment should be restricted to:
					  • Personnel who have been trained and are proficient in the operation of the mowers or equipment and who have a sound knowledge of the necessary safety procedures associated with those tools or equipment; or
					  • Other personnel required to undertake straightforward tasks, provided they are under the direct supervision of a competent operator. (as in point above)
					• All guards and handles as supplied by the manufacturer must remain fitted to all equipment and be in good working order.
					• Only attachments and fittings designed for the task and the equipment are to be used.
					• Manufacturer's instructions as supplied with the equipment are to form part of		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					this SWMS and must be always adhered to. E.g. replacement cutting blades.
					• The immediate area around the task must be checked to ensure it is a safe environment to operate the equipment and all personnel are protected from injury due to flying debris etc. Shields, barriers etc. must be utilised whenever there is a risk to other personnel.
					• Check weather conditions prior to commencing work. Never work in excessive windy conditions.
					• When fuelling the mower:
					  • Always wear safety glasses, goggles or face shield.
					  • Ensure you are in a well-ventilated area.
					  • Do not smoke.
					  • Use a funnel or hose to minimise spills.
					  • Ensure caps are replaced on both the mower and fuel drum.
					  • Store the fuel drum in a safe place (in the shade if possible).
					• Always wear safety glasses and hearing protection when mowing.		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Keep an eye out for other people – stop the mower (or disengage the clutch) if someone approaches. • Always attempt to operate forwards when mowing and not backwards. • Do not operate the mower up and down slopes – operate left and right across the slope and do not operate the mower on a slope if you believe there is a chance the mower may roll over. • Use a line trimmer on very steep slopes. • Before removing the grass catcher, if fitted, turn off the engine. (or disengage the clutch) • Never remove the catcher when the blades are turning. • Never reach under the mower unless the engine is stopped and the sCentre plug lead is disconnected. • If you hit a rock / branch / debris, turn off the engine and check the mower and blades for damage. • Never use a mower that is damaged. Contact your supervisor if damaged.		
Plant Movement on Site	• Uncontrolled and Unauthorised access and egress	Critical	Possible	H 22	• Supervisor to conduct and communicate movement of pedestrian and plant.	Supervisor All Workers Daily	M 10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	by persons and / or mobile plant				• Erect barricading and signage as required and where necessary. • Monitor work area for unauthorised persons. • External parties allowed access should read, sign and understand the work process and be escorted by a Project representative whilst on site. • All visitors to sign Visitors Register at site office		
Spraying Herbicides and pesticides Fertilizing	• Exposure to hazardous substances	Major	Possible	H 18	• Always check if a less hazardous substances can be used • Follow instructions on label or MSDS, • PPE must be worn as per the MSDS, • Inform people in proximity of what is being used and how to avoid exposure	Supervisor All workers	L 5
Clean-up of paths and roadways -	• Run off into storm water and hazard	Minor	Likely	M12	• Remove all debris from road environments and other areas where debris is likely to enter a storm water or water cause	Supervisor All workers	L6
Placing and securing ladders to complete general maintenance tasks, cleaning tasks.	• Ladder could fall if not secure, falls from ladder, falling objects	Moderate	Possible	M 13	• Barricade work area or work with spotter to control access to work area. • Ensuring first that the lights are switched off when performing this task. • Ladders to be placed on flat surface. • All ladders are to be marked Industrial and with the appropriate weight and site approved.	Supervisor All workers	L 6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• All ladders and steps need to be inspected prior to use to ensure no damage to runs or frame. • All work above 1.8m requires a working at heights permit. • Ladder could fall if not secure. • Secure ladder to structure before climbing onto steps, if it is not possible to secure, obtain assistance to hold the ladder securely. • Maintain the 4:1 ratio for the ladder angle. • If using for access, the ladder must overhang the access area by at least one metre. • Do not allow children near ladder. • Have another staff member near the ladder, supervising the area and to support the ladder when necessary		
Ascending descending & using ladder + perform light work.	• Fall from ladder. • Falling objects	Moderate	Possible	M 13	• Wear appropriately footwear when climbing ladders. • Always have three limbs on the ladder. • Never at any stage use hands to carry items on ladder. • Do not use ladder when broken, patched, oily or cracked rails, damage rungs or steps Only one person stands on or works from a standard ladder.	Supervisor All workers	L 6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Perform light work only. • Establish drop zone below.		
Planning for Plastering Works	• Unauthorised Personnel entering site • Untrained or unlicenced workers may access site • Inappropriate tool and equipment allocation may lead to injury	Moderate	Unlikely	M9	• Arrange access to work area via owner or facility manager. • If you see a hazard present itself, an unsafe act or the site conditions change use your STOP Right Authority to prevent an injury or incident. • Complete a Pre-Start Hazard Risk Assessment Form for low frequency tasks • Review site risk register • Consider any heritage contents within site • All workers to complete site induction prior to commencement • Where induction is not available workers to liaise with site controller about site hazards, emergency procedures and any other site requirements • All workers to be trained in and sign safe work method statement • All workers to be qualified/licenced/ticketed/trained as required for activities performed • Competent person to supervise all new workers	Supervisor in Site Inspection	L1

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Toolbox talk to be conducted prior to commencement of works • Workers to be in a fit state to commence work and be of zero blood alcohol concentration and must not be suffering from fatigue or under the influence of drugs • Risk assessment of site to be carried out prior to commencement of work and changes made to SWMS where necessary • Site supervisor to review the site prior to commencement of work • Appropriate equipment must be used, and correct procedures must be in place for the works being completed		
Cutting materials to length	• Cuts to fingers or body parts	Major	Unlikely	M14	• Workers must wear safety glasses, leather gloves and long sleeve shirts • All waste materials to be collected and placed into rubbish immediately, not left in work area	Supervisor in Site Inspection	L5
Install Plasterboard	• Fall from ladder • Fall from heights • Contact with services or live parts • Manual handling	Major	Possible	H18	• Use a platform ladder where possible • Perform visual check on ladder for obvious faults and defects prior to use • Damaged ladders are to be removed from use, tagged not for use and repaired • Erect ladder on clean level surface	Supervisor in Site Inspection	L3

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Harm due to Dust Emissions • Skin Irritation				• Do not place a ladder in front of the doorway unless locked or guarded • Secure work area around the ladder • Clean mud grass etc. from boots to prevent slippage • Use a tool pouch to carry tools • Do not leave tools and equipment on ladder rungs • Do not over-reach while on ladder • Only one person on a ladder at one time • Face the ladder at all times • Ensure legs are fully extended and latch is in place to secure • Maintain three points of contact on ladder • Do not step above the third step from the top • Select appropriate fall protection equipment where a worker can fall from one level to another • Site supervisor must implement the use of either a work platform, physical barrier or physical restraint (in that order) for all work at heights • Site supervisor to inspect roof for any hazards and inform workers of dangers • Isolate power, water and other services where necessary • Lock out/tag out all services		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Do not work near live services
					• Steel capped work boots to be worn
					• Insulated tools to be used
					• Check services to ensure dead before working on them
					• If fuses removed keep with you
					• Materials to be delivered directly to site where possible
					• Correct manual handling procedures are to be followed:
					  • Use mechanical lifting devices and trolleys where possible
					  • Only lift objects within your safe lifting limit
					  • Use team lifts where needed
					• Clear a path, assess the load, get a good grip, ensure a wide stance, bend the knees, keep the spine strait, use the legs to lift, do not twist the trunk, use a smooth action, brace the stomach muscles and lower safely
					• Ensure dust emissions are kept under control
					• Ensure dust masks are worn when operating tools and equipment that cause dust to be emitted
					• Ensure correct use of PPE - safety glasses.
					• Wash eyes/hands in event of adverse reaction		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Opening Bags of Insulation	• Harm / injury to workers from cutting implements when opening bags of insulation. • Harm / injury to workers from inhalation of fibres when opening bags of inhalation. • Slips / trips / falls	Moderate	Likely	H17	• Ensure full and appropriate PPE is worn at all times including face masks & gloves when working with insulation • Ensure safety knives are used when opening bags • Maintain good housekeeping when opening bags and tidy up and dispose of rubbish while working	Supervisor in Site Inspection	L3
Install insulation	• Slip trip or fall • Harm / injury / death to workers while placing insulation in trusses • Fire • Fall from heights • Contact with services or live parts • Cuts and abrasions	Major	Likely	H21	• Take care to avoid all trip hazards • Do not run cables or hoses on the ground and keep tools out of walking paths • Ensure full and appropriate PPE is worn at all times including disposable overalls, face coverings and gloves. • Ensure the electricity to the property is switched off prior to the installation of the insulation to avoid electrocution of workers. • Workers should be certified with confined spaces experience or under the guidance of a supervisor with confined spaces certification. • Ensure to leave the required distance around light and other electrical fixtures	Supervisor in Site Inspection	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					as per manufacturer's recommendations • Select appropriate fall protection equipment where a worker can fall from one level to another • Site supervisor must implement the use of either a work platform, physical barrier or physical restraint (in that order) for all work at heights • Site supervisor to inspect roof for any hazards and inform workers of dangers • Isolate power, water and other services where necessary • Lock out/tag out all services • Do not work near live services • Steel capped work boots to be worn • Insulated tools to be used • Check services to ensure dead before working on them • If fuses removed keep with you		
Installing Bricks and Blocks	• Pinch / harm / injury when installing bricks / blockwork • Harm / Injury / Death from falling bricks / blockwork	Major	Likely	H21	• Only trained bricklayers to install bricks / blockwork. • Ensure all hand and power tools are in good working order prior to work commencing. • Ensure correct manual handling techniques are used at all times	Supervisor in Site Inspection	M9

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Fall from ladder • Fall from heights • Contact with services or live parts • Manual handling				• All bricks / blockwork to be installed as per manufacturers guidelines • Only trained bricklayers to install bricks / blockwork • Ensure no worker lifts above their capabilities. • Ensure correct manual handling techniques are used at all times. • When installing heavy objects ensure two or more workers or mechanical aids are used • Ensure all hand and power tools are in good working order prior to work commencing. • Ensure all necessary equipment is on hand prior to work commencing • Ensure reinforcing rods are secured in place prior to placing bricks/ blockwork • Use a platform ladder where possible • Perform visual check on ladder for obvious faults and defects prior to use • Damaged ladders are to be removed from use, tagged not for use and repaired • Erect ladder on clean level surface • Do not place a ladder in front of the doorway unless locked or guarded • Secure work area around the ladder		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Clean mud grass etc. from boots to prevent slippage • Use a tool pouch to carry tools • Do not leave tools and equipment on ladder rungs • Do not over-reach while on ladder • Only one person on a ladder at one time • Face the ladder at all times • Ensure legs are fully extended and latch is in place to secure • Maintain three points of contact on ladder • Do not step above the third step from the top • Select appropriate fall protection equipment where a worker can fall from one level to another • Site supervisor must implement the use of either a work platform, physical barrier or physical restraint (in that order) for all work at heights • Site supervisor to inspect roof for any hazards and inform workers of dangers • Isolate power, water and other services where necessary • Lock out/tag out all services • Do not work near live services		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Steel capped work boots to be worn • Insulated tools to be used • Check services to ensure dead before working on them • If fuses removed keep with you • Materials to be delivered directly to site where possible • Correct manual handling procedures are to be followed: • Use mechanical lifting devices and trolleys where possible • Only lift objects within your safe lifting limit • Use team lifts where needed • Clear a path, assess the load, get a good grip, ensure a wide stance, bend the knees, keep the spine strait, use the legs to lift, do not twist the trunk, use a smooth action, brace the stomach muscles and lower safely		
Receiving concrete by mixer truck	• Electricity (overhead power lines) Traffic and moving plant - impact and crushing injuries	Major	Possible	H18	• Make sure that the area where the mixer truck (and pumping truck where relevant) will unload is stable, clear of rubbish, debris and other trip hazards • Make sure that all holes and services are clearly marked • Make sure a minimum clearance of 3m is maintained between mixer truck and	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					pump boom from overhead power lines		
Pouring Concrete	• Injury due to mechanical failure • Eye or hearing damage • Harm / Injury / death to workers / personnel from concrete pouring from agitator truck • Burns from wet concrete • Trip / falls while walking over steel to place wet concrete	Major	Possible	H18	• Have emergency stop at the ready for quick shutdown in emergency • Do not put hands, body parts or hair near equipment • Look, listen and observe closely for any abnormalities and shut off immediately if problems noted • Workers must wear hearing and eye protection in all plant rooms and areas where plant is running • Ensure only authorised workers in work area. • Ensure work zone clearly sign posted. • Use of spotter with truck at all times if necessary • Wear full appropriate PPE at all times • Ensure all workers are alert to wet concrete moving down chute • Be aware and pro-active when stepping through wet concrete. • Only workers required to place concrete over steel to be working in that area	Supervisor in Site Inspection	M10
Pumping concrete	• Traffic and moving plant - impact and crushing injuries	Moderate	Possible	M13	• Make sure contractor is proficient at his/her job	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Impact injuries				• Warn all workers before starting or recommencing the pour • Keep delivery hose and joints in good working order • Train 'Tbar' operator in its use • Secure connecting pipes with safety pins on lever couplings • Support pipe where there is a change in direction or a reducer		
Use of auger or post hole digger	• Equipment – Injured operator particularly hands and feet Services / Utilities • Burns - heated fittings/equipment Noise - hearing damage • Manual Handling – strains, sprains and back injury Vibrations - soft tissue damage	Moderate	Likely	H17	• Always use the posthole digger on reasonably level ground, as digging on an incline is dangerous. • Check the work area prior to using the machine and clear all hazardous obstructions, such as stones, bricks, wire, glass etc. • Check for underground services – dial before you dig 1100. • Always stop the engine before cleaning or moving the machine to another location • Keep hands, feet, body and clothing away from rotating parts whilst the engine is running, and also from exhaust muffler during or soon after operation. • Keep hair, jewellery and loose clothing etc. away from moving parts. • Never clear the auger with hands or feet	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Never insert any tools or equipment into the hole while the digger is operating		
Use of portable concrete mixer	• Equipment – Injured operator Burns - heated fittings/equipment Noise - hearing damage. • Manual Handling – strains, sprains and back injury	Moderate	Likely	H17	• Position the concrete mixer on a firm stable surface. • After positioning the concrete mixer, the operator must give a clear verbal signal before mixing commences. • During operation, the operator must be satisfied that no person is within 2m of the concrete mixer at all times. • Keep hands, feet, body and clothing away from rotating parts whilst the equipment is running. • Keep hair, jewellery and loose clothing etc. away from moving parts. • Consult manufacturer's SDS. Make sure manufacturer's instructions are followed when using concrete products. • Wear recommended Personal Protective Equipment (PPE) including a P1 dust mask, waterproof gloves, long sleeved shirt, full length trousers and approved eye protection when working with concrete products. • Separate the workers from the noise where possible. • Maintain equipment or install noise suppressors.	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Wear hearing protection - earplugs or earmuffs •		
Mixing cement render by hand	• Manual Handling - strains, sprains and back injuries Flying debris – eye injuries Dust – lung damage	Moderate	Possible	M13	• Use 20kg bags of cement when possible. • Make sure sand stockpile nearby. • Wear eye protection, gloves and respirator or dust mask • Do not overload wheelbarrow, keep load even and route clear	Supervisor in Site Inspection	L6
Concrete handling	Hazardous Substances – skin, eye, lung damage and illness Flying debris – eye injuries Burns • Dust – lung damage	Moderate	Likely	H17	• Wear a dust mask or half or full face respirator • Consult manufacturer's SDS. Make sure manufacturer's instructions are followed when using concrete products • Wear recommended Personal Protective Equipment (PPE) including a P1 dust mask, waterproof gloves, long sleeved shirt, full length trousers and approved eye protection when working with concrete products • Make sure regular wetting down and/or sweeping of dusty areas is carried out to minimise dust • Minimise cutting, drilling, sawing, chasing, sanding, grinding or breaking concrete which may release silica dust • When standing in wet concrete, always wear gumboots or similar to prevent contact with wet concrete	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Immediately wash concrete products from your skin after use • If concrete products come into contact with your eyes, immediately flush eyes with clean water • Rinse clothing if they are affected by concrete products as indirect contact through clothing may be as hazardous as direct contact.		
Operating 'Tbar' and 'Jhook'	Manual Handling – strains, sprains and back injury	Moderate	Possible	M13	• Train 'Tbar' and 'Jhook' operators in the correct use of the equipment • Rotate tasks between workers to prevent repetitive strain injuries • Keep clear of machinery at all times • Wear high visibility clothing when working with or near equipment	Supervisor in Site Inspection	L6
Using concrete vibrator	Hand and arm vibrations can cause White Finger Syndrome or Reinhold Syndrome Manual Handling – strains, sprains and back injury Flying debris – eye injuries Noise – hearing damage	Moderate	Possible	M13	• Get assistance to move vibrator into position • Wear hearing and eye protection • Keep water nearby for flushing eyes where required • Make sure machine is maintained and engine is muffled • Make sure operator is adequately trained • Where required train the operator in the correct use of the machine • Wear thick cotton gloves • Rotate tasks to prevent prolonged use of vibrating equipment	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Exercising and massage hands to encourage blood circulation		
Use of concrete helicopter float	Manual Handling – strains, sprains and back injury Equipment - cuts from blades Noise – hearing damage Vibration Hazardous Substances – skin, eye, lung damage and illness Fumes – lung damage	Moderate	Possible	M13	• Get assistance to lift or move float • Train the operator in the correct use of the machine • Make sure machine is maintained and engine is muffled • Make sure the machine has guards attached • Wear hearing protection and thick gloves with cotton lining • Wear a half or full-face respirator with chemical filters	Supervisor in Site Inspection	L6
Sealing concrete/ curing	Chemicals – skin, eye, lung damage and illness Hazardous Substances – skin, eye, lung damage and illness Flying debris – eye injuries Burns	Moderate	Possible	M13	• Follow the manufacturers recommendations on label and SDS • Prevent skin and eye contact, inhalation of fumes or ingestion of substance by using PPE recommended by the manufacturer • Make sure suitable first aid and a spill kit are available • Wash hands after use and before eating, smoking or using toilet • Wear the appropriate PPE	Supervisor in Site Inspection	L6
Rendering walls	• Fall from heights. • Manual Handling - strains, sprains and	Major	Likely	H21	• Make sure guard rail is in place for all platforms when working at heights.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	back injuries Hazardous Substances – skin, eye and lung damage				• Overhand work is not to take place unless adequate scaffolding is erected on both sides of the wall. • Wear eye protection, gloves and respirator or dust mask		
Lowering tools, equipment, debris and off-cuts from height	• Hit by falling objects Sharp edges - cuts	Major	Likely	H21	• Provide safe means of lowering tools, equipment, debris and off- cuts. • Make sure all debris is collected in suitable containers, such as hessian bags, so they can be safely lowered to the ground. • Wear gloves when handling bags or other containers to avoid cuts from any protruding metal off-cuts	Supervisor in Site Inspection	M10
Use of shovel	• Manual Handling – strains, sprains and back injury Slips, trips and falls	Moderate	Possible	M13	• Check and repair shovel as necessary (remove splinters from handle etc.) • Wear appropriate gloves, safety boots and any other appropriate PPE • Make sure a wheelbarrow or other appropriate shifting equipment is used to move materials that cannot be reasonably shifted by throwing with the shovel • Where possible, avoid using a shovel in difficult terrain • Use correct stance - keep back straight, position one hand near shovel head, the other hand should be near the end of the handle	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Before engaging material - bend knees and move the head of shovel towards the material. Use your body weight (not arms) to step forward and push shovel into material • To lift material - the hand closest to the shovel head should be relocated further down to take the additional load of the material whilst lifting. Straighten your knees to lift the loaded shovel (avoid using your back and avoid twisting the body) • To move the material - move feet to the correct position for dumping or placing the load		
Use of wheelbarrow	• Manual Handling – strains, sprains and back injury Slips, trips and falls	Moderate	Possible	M13	• Check tyre pressure and repair as necessary • Use suitable gloves, safety boots and any other appropriate PPE • Make sure load is distributed evenly and as far forward as possible • Limit contents to an amount suitable for worker and conditions • Keep pace even and steady, keep back and arms straight and chin in • At your destination, prepare to move weight of load forward over the wheel to use momentum for dumping • If load is staying in the wheelbarrow, bend your knees (not back) to lower	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					wheelbarrow legs to ground. Make sure ground is sufficiently level so the wheelbarrow is stable • Make sure rubbish, rubble and debris within the work area is cleared prior to commencement of work • Make sure any access ramps and planks are secure • Always make sure wheelbarrow is facing forward in the direction of travel		
Placing formwork– hammering in pegs and nails.	• Manual Handling – strains, sprains and back injury Slips, trips and falls Impact / crushing injuries	Moderate	Possible	M13	• Get assistance to carry long, heavy and awkward formwork • Use the correct tools for the task • Train workers in the correct use of the tools and techniques for the task • Check tools are in good working order	Supervisor in Site Inspection	L6
Cutting steel reinforcement bar and mesh	Sharp edges – cuts Electric tools – cuts • Electricity (power tools / other) Machine / equipment guarding Flying debris – eye injuries	Major	Possible	H18	• Make sure workers are trained in the safe work procedures of electric nibblers and grinders • Use tools and fittings to manufacturers recommendations • Wear the appropriate PPE such as hearing and eye protection and gloves • Make sure equipment is in good working condition before use • Carry out basic housekeeping regularly, keeping access ways and the work area clear of materials, tools and debris	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Placing steel reinforcement bar and mesh	• Manual Handling – strains, sprains and back injury Cuts and abrasions	Moderate	Possible	M13	• Make sure sufficient workers are available on site to lift and place steel reinforcement bars • Make sure all workers are adequately trained in the carrying and placing of steel reinforcement bars • Make sure the steel used for reinforcement is not greasy • Always use caution as to where your feet are placed whilst walking over steel bars already laid • On completion, check the reinforcement and make sure there are enough chairs and ties in place	Supervisor in Site Inspection	L6
Fixing steel reinforcement bar and mesh	• Manual Handling – strains, sprains and back injury Cuts and abrasions	Moderate	Possible	M13	• Make sure all workers have sufficient breaks from repetitious bending, twisting and cutting nips • Make sure starter bars and end bars are fitted with caps to prevent cuts • Turn down tie wire into reinforcement cage • Make sure sufficient training is provided for all workers involved in tying off steel reinforcement and avoid working too fast • Always wear gloves when handling sharp objects	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Installation of floor coverings	• Dust – lung damage Flying debris – eye injuries Manual Handling - strains, sprains and back injuries Tools – Cuts	Moderate	Possible	M13	➢ Use tools and equipment to manufacturers recommendations ➢ Check tools are in good working condition ➢ Wear eye protection, gloves and respirator or dust mask ➢ Use correct lifting techniques, lifting equipment and rotate tasks • Use the correct tool for the task and train workers in its correct use	Supervisor in Site Inspection	L6
Lifting joinery to install to wall	• Manual Handling Risks	Moderate	Possible	M13	➢ Use Mechanical means where possible (trolleys) to assist in lifting. Bend kneesand hold heavy loads close to body. Vary tasks. ➢ Use spotter and planned lifts for large or awkward items. ➢ Ensure areas are cordoned off when required ➢ Make others aware of any hazard that maybe created • Use spotters where required when moving large items/cabinetry	Supervisor in Site Inspection	L6
Set up survey equipment, Interaction with other work groups plant/ machinery	• Equipment damaged	Moderate	Possible	M13	• All workers required to wear site PPE. • Notify working operators in working area. • Place Barricades if necessary. • Place vehicle near setup with flashing light on	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Placing and hammering surveying pegs and operating nail gun.	• Strike underground services • Injury to Eyes and hearing damage • General injury from operating i.e. Nailing finger, other extremities • Slips, Trip or Falls and Debris in public areas	Major	Possible	H18	• Dial Before You Dig & service drawings to be obtained. • Underground services are to be identified and clearly marked. • Competent, Authorised and qualified personnel completing the job. • Right Tool, for the job • Whilst operating always wear eye/ear protection (Full face, high impact face shield recommended). • Never carry tool with trigger depressed. • Do not point at own body or others. • Remove all nails that are exposed more than 10mm. • Operator to read and understand operator manual/safety procedures prior to use. • Competent, Authorised, personnel to use equipment. • Gloves to be worn. • Exclusion zone to protect other workers • Keep work areas tidy and access ways clear. • No materials to be stored in public areas. • All materials to be stacked and stored in a safe manner. • No loose materials to be left lying around. • Place all rubbish in the industrial bins. • Inspect area regularly.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Clean up after shift	• Tripping –falling over items.	Minor	Possible	M8	• Keep work areas tidy and access ways clear. • No materials to be stored in public areas. • All materials to be stacked and stored in a safe manner. • No loose materials to be left lying around. • Place all rubbish in the industrial bins.	Supervisor and WHSE Manager in regular site inspections	L5
Pressure Cleaning	• Compressed air towards body or compressed air hoses hitting persons. • Eye and hand injuries • Slip on wet concrete. • Slip trips and falls over leads and hoses. • Eye and hand injuries • Slip on wet concrete. • Slip trips and falls over leads and hoses.	Moderate	Possible	M13	• Consult operator's manual. • Toolbox re safe use for all workers • Checks all hoses and connection prior to use ensure secure fitting for all connections to reduce risk of blow outs. • Always have air blowing away from all persons • Direct air into hole and only have operational when required. • Use of P2 dusk mask for workers in area • May need to supply to workers if they are in immediate area. • Use goggles while operating pressure cleaner and buffer. • Barricade work area so only those who are involved in spraying can access that area. • Keep hands well clear at all times of pressurised water.	Supervisor and WHSE Manager in regular site inspections	L5

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure Safety glasses are always worn. • Wear no-slip steel capped work boots or steel capped gum boots and always spray the ground in a manner that the worker will be standing on dry ground until at end of concrete base. • Always have leads well clear of operations ahead of worker and do not roll over cords with machine.		
Sweeping	• Sprains and strains; • Flying particles; • Slips, Trips and falls; • Bruises and lacerations; • Repetitive movement; • Dust inhalation	Moderate	Possible	M13	• Eye protection must be worn; • Ensure good housekeeping is maintained to provide clear access ways; • Employ the use of Exhaust Fans to redirect airborne contaminants out of the area; • Task lighting to be provided when in dark areas / rooms; • Wear appropriate PPE including; non-slip rubber soled safety boots, hard hat, gloves and glasses;	Supervisor and WHSE Manager in regular site inspections	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Erect barricade i.e. signage, tape etc. to direct unauthorised people around the immediate work area; • All personnel are required to provide their site supervisor with all relevant information if any of the symptoms exist; • Personnel expected to remove overstretching to reach certain areas. • Where practicable move all necessary tools and position the body as close as possible to all areas where work is to be performed; • Personnel required to perform repetitious activities should decrease the likelihood of RSI by performing; warm up exercises, stretching the muscles prior to undertaking each task, using proper body mechanics, taking regular short breaks during repetitive activities and looking at ways to perform strengthening exercises		
Mopping	• Slips, trips and falls • Bruises and lacerations • Sprains and strains • Repetitive movement • Chemical splashes whilst decanting	Moderate	Possible	M13	• Wear rubber soled non-slip safety boots and maintain good balance when walking on slippery, wet floors; • Ensure standing water is removed by using a squeegee or broom to relocate water to drain; • Personnel required to perform repetitious activities should decrease the likelihood of RSI by performing; warm up exercises, stretching the	Supervisor and WHSE Manager in regular site inspections	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					muscles prior to undertaking each task, using proper body mechanics, taking regular short breaks during repetitive activities and looking at ways to perform strengthening exercises; • Personnel expected to remove overstretching to reach certain areas. • Where practicable move all necessary tools, and position the body as close as possible to all areas where work is to be performed; • Ensure after using / decanting chemicals into appropriate vessels that all chemicals or items are stored correctly. • Do not leave items in walkways or in areas where you are working; • Maintain vigilance when working on wet, potentially slippery surfaces. • Do not overreach and maintain balance; • When working with chemical agents ensure the use of PPE including; long sleeve shirt and pants to cover exposed skin, safety glasses and gloves; • Wash affected area of skin immediately should contact occur		
Vacuum	• Slips, trips and falls • Airborne dust • Back injury or muscle strain	Major	Possible	H18	• Have all vacuum cleaners fitted with H.E.P.A. filters. • Empty and clean regularly;	Supervisor and WHSE Manager in	M10

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	caused by repetitive movement • Electrocution				• Wear dust mask, glasses, gloves and long sleeve shirts. • Damp wipe where possible; • Apply good housekeeping techniques; do not leave vacuum cleaner hoses or attachments laying in walkways, roll up and store items neatly out of the way when not in use; • Personnel required to perform repetitious activities should decrease the likelihood of RSI by performing; warm up exercises, stretching the muscles prior to undertaking each task, using proper body mechanics, taking regular short breaks during repetitive activities and looking at ways to perform strengthening exercises;	regular site inspections	
Clean Wet	• Dust • Sprains and strains; • Slip, trip and fall; • Bruises and lacerations; • Damage to equipment;	Moderate	Possible	M13	• Vacuum areas where possible or damp wipe; • Wear appropriate PPE; dust mask, safety glasses, gloves and long sleeve shirts to avoid dust from getting onto the skin, into eyes, mouth and respiratory system; • Wear rubber soled non-slip safety boots and maintain vigilance when walking on wet slippery surfaces; • Remove standing water with squeegee or broom to eliminate puddles etc.;	Supervisor and WHSE Manager in regular site inspections	L6

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

A	B	C			D	E	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Use long handled dusters /scrubbers / or squeegees to minimise the need to use a ladder or EWP in all instances; • Ensure all wet areas are cordoned off with signage to warn unauthorised personnel / pedestrians to keep clear due to wet, slippery floors; • Personnel required to perform repetitious activities should decrease the likelihood of RSI by performing; warm up exercises, stretching the muscles prior to undertaking each task, using proper body mechanics, taking regular short breaks during repetitive activities and looking at ways to perform strengthening exercises; • Personnel expected to limit overstretching to reach certain areas. Where practicable move all necessary tools and position the body as close as possible to all areas where work is to be performed		

SAFE WORK METHOD STATEMENT – GENERAL CONSTRUCTION

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)

HIERARCHY OF CONTROL
Elimination

to cause harm or damage.

Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

Substitution
Engineering
Administration
PPE

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -

Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

Name	**Roles**	**Signature**

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

Task / Activity:	**RESPIRABLE CRYSTALLINE SILICA DUST – High Risk Construction Work**	**SWMS Number:**	002
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		
Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
General Safety Induction Fit Test Certification	RPE Dust Extractors Vacuums Hoses Safety Signage Barricading	Nil

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			

Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

Training	• Exposure to respirable crystalline silica (RCS)
	• Inexperienced workers
		Major	Likely	H21	• Training and information provided to workers on respirable crystalline silica (RCS) should include the following:
					  • Information on RCS through Safety Datasheet (SDS) or labels
					  • Risk management process
					  • Work practices, procedures and control measures
					  • How to fit, use, maintain and clean personal protective equipment (PPE)
					  • Emergency procedures, including any special decontamination procedures or PPE failures
					  • First aid and incident reporting procedures
					  • The purpose and results of air monitoring, including the types of health tests that may be required
					  • Checking controls are working and using them
					  • Waste collection and disposal.
					• Supervision provided to inexperienced or new workers, e.g. Cutting stone or concrete for
						Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					the first time or using new machinery.		
Worker consultation	• Exposure to RCS	Major	Likely	H21	• Ensure workers have been consulted and allowed the opportunity to express their views on the safety controls • Workers and Employers must be satisfied that the controls are sufficient for the task before the work commences • If an HSR represents employees, the consultation must involve that HSR.	Supervisor and WHSE Manager in regular Site Inspections	M10
Health monitoring	• Exposure to RCS	Major	Likely	H21	• Identify if any materials and work practices on-site will lead to the generation of respirable crystalline silica dust (Identify silica through the SDS, a label or other source) • Silica-containing materials supplied and brought into workplaces need to be accompanied by both the SDS and the label • Determine if exposure to dust containing RCS exceeds the minimum workplace exposure standards • The workplace exposure standard is generally 0.05	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					milligrams per cubic metre (mg/m3) averaged over eight hours (8-h time-weighted average or TWA)
					• Employees must not be exposed to levels above 0.02 mg/m3 as an eight-hour TWA.
					• Based on the exposure levels, determine if air monitoring is required for workers.
					• Ensure health monitoring is provided to workers if there is a significant risk to the worker's health because of exposure to RCS
					• In addition to the ongoing schedule, conduct air monitoring:
					  • When there are changes to working practices
					  • Changes to the materials used or the work environment
					  • A worker health monitoring report indicates an adverse change in health status which may be related to silica exposure
					  • If an HSR requests a review of control measures		

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• When changes are made to the workplace exposure standard.		
Work area setup	• Exposure to RCS	Major	Likely	H21	• An exclusion zone should be set up and maintained to exclude workers and other people who are not wearing RPE. Warning signs should be located so that they are clearly visible before entering the area.	Supervisor and WHSE Manager in regular Site Inspections	M10
General workplace dust control **– High Risk Construction Work**	• Exposure to RCS	Major	Likely	H21	• Remove non-essential personnel from the dust-producing area • Ensure all people that remain in the area are provided with respiratory protection • Regularly undertake inspections of controls • Use the highest level of control available. • Use water sprays or dust suppressants whenever possible. • Do not use compressed air to clean in areas where silica dust may be present. • Do as much work as possible under controlled conditions instead of on-site, or perform work outdoors or in well-ventilated areas.	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Cover sensitive areas (power outlets, food storage)
					• Separate indoor RCS processes from other work areas by enclosing the immediate area.
					• Working indoors or in enclosed areas:
					  • Keep silica exposures low using extra ventilation, i.e., portable exhaust fans.
					  • Ensure airflow is not impeded by workers' movements during work or by opening or closing doors and windows. Position the ventilation to move contaminated air away from the workers' breathing zones.
					• Rotate workers to reduce exposure
					• Maintain good housekeeping, including:
					  • Regular cleaning of work areas and equipment
					  • Never use compressed air for cleaning or personal decontamination
					  • Restrict housekeeping practices, such as the use of compressed air without a		

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					ventilation system and dry brushing or sweeping. • Place warning signs to identify silica dust hazard areas and required PPE/RPE.		

Respiratory PPE	• Exposure to RCS	Major	Likely	H21	• Undertake daily checks of guards, PPE, and exhaust ventilation equipment
					• Wear respiratory protective equipment (RPE) such as a half-face negative respirator or powered air-purifying respirator (PAPR).
					• Respiratory protection, e.g. P1/P2 face mask minimum:
					  • people medically fit to wear the face mask
					  • Issued to individuals
					  • A competent person conducts fit testing
					  • Complete facial seal (no facial hair)
					  • Correct cartridge for contaminant (see SDS for flammable vapour / concrete dust)
					• Wear disposable or washable coveralls and eye protection
					• Maintain a daily check of PPE and equipment.
						Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

• Using powered saws/grinder
• Brick or tile saws
• Handheld saws
• Walk-behind saws
• Floor and handheld grinders **– High Risk Construction Work**
	• Exposure to RCS	Major	Likely	H21	• Never cut materials unless the use is controlled
					• Minimise dust emissions by operating and maintaining tools according to the manufacturer's instructions
					• Only use equipment that has an integrated water delivery system or a HEPA- filtered dust collection system
					• Check guards have no visible damage before use
					
					• Water delivery control method:
					  • The equipment must utilise a water delivery system that continuously supplies water to the working surface:
					  • Check water is flowing to the cutting area before making contact with the material
					  • Ensure spray guards are in place before commencing work
						Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Regularly clean the work area and surrounding areas
					• Manage slurry to prevent it from drying out (cover or remove)
					
					• Dust control method:
					  • The equipment must use an integrated HEPA-filtered dust collection system or a commercially available dust collection system with a dust collector rated to either M or H-Class per AS/NZS 60335.2.69.
					  • System to have a filter-cleaning mechanism
					
					• When operating a grinder, ensure an airflow of ≥ 25 cubic feet per minute (cfm) per inch/ ~700 litres per 25mm of wheel diameter.		

Using Drills **– High Risk Construction Work**	• Exposure to RCS	Major	Likely	H21	• Never drill materials unless the use is controlled. • Minimise dust emissions by operating and maintaining tools according to the manufacturer's instructions.	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Drills equipped with a commercially available shroud with a dust collection system:
					  • Ensure the dust collection system provides sufficient airflow as recommended by the tool manufacturer.
					  • The drill must use an integrated HEPA-filtered dust collection system or a commercially available dust collection system with a dust collector rated to either M or H-Class per AS/NZS 60335.2.69.
					• If using a vacuum to clean holes, ensure the vacuum is rated to either M or H-Class per AS/NZS 60335.2.69 when cleaning holes.		

Operating cab-mounted plant and vehicles that generate or are adjacent to silica dust **– High Risk Construction Work**	• Exposure to RCS	Major	Likely	H21	• Operate equipment from within an enclosed cabin:
					  • Ensure windows are always closed.
					  • Ensure the cabin remains at positive pressure. Ensure door jambs, window grooves, power line entries and other joints are tightly sealed.
						Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Use high-efficiency air filtering system (e.g. HEPA filters) for air intakes (*Use an intake air filter with a minimum MERV16 rating (at least 95 per cent efficient in the 0.3-10.0 µm range)* • Keep the area free of settled dust by regular cleaning and maintenance to prevent dust from becoming airborne inside the enclosure. • Do not exit the cab unless clear of the dust generation area or dust suppressants are used to minimise dust emissions.		
On completion **– High Risk Construction Work**	• Exposure to RCS • Personal contamination	Major	Likely	H21	• Respiratory protective equipment used until all contaminated disposable coveralls and clothing has been removed and bagged for disposal, and personal washing completed • Clean up any slurry produced to prevent the slurry from drying & releasing silica dust into the air	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Use damp rags to wipe down RCS-contaminated areas and equipment • Carefully roll or fold any plastic sheeting used to cover any surface within the RCS work area, so as not to spill any collected dust or debris • If necessary, use damp rags or a HEPA vacuum cleaner to clean any remaining visibly contaminated sections of the RCS work area • If possible, fully dismantle tools and decontaminate using the appropriate method in a controlled environment. • *Never use compressed air for cleaning.* • Ensure contaminated clothing is removed before leaving the work area (to ensure dust not transferred to other workplace areas). • Use a HEPA vacuum cleaner to remove apparent signs of contaminated material • Wipe coveralls, shoes, eye protection with a damp cloth • Wipe the respirator with a damp cloth – but do not remove		

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Remove coveralls, boots and any other PPE • Remove respirator • Wash face and hands with soapy water. Pay attention to under the fingernails • *Never use compressed air for personal decontamination.*		

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – RESPIRABLE CRYSTALLINE SILICA DUST

Name	Roles	Signature

Ref. No.: HSE-SWMS-003

Issue Date: 12/12/2025

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

Task / Activity:	**WORKING AT HEIGHTS – High Risk Construction Work**	**SWMS Number:**	003
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		
Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

Relevant to:
Division: All
Department: All
Site: All

Document Owner: Managing Director
Change Control: Level 1

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
General Safety Induction EWP Certification Scissor Certification Working at Heights Certification	Hand Tools EWP Ladders Scaffold Fall Arrest Harness Fall Arrest System including anchorages and Fall-arrest devices (if applicable)	Nil

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			

Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Planning and undertaking general work at heights **- High Risk Construction Work**	• Weather conditions may make work unstable. • Falls from height resulting in injuries or death. • Electrocution from overhead power lines. • People untrained. • Failure to identify a suitable means of access and / or working at height – fall from height	Major	Possible	H18	• Review and abide by the documented requirements for this activity outlined in the project's Safety Management Plan • Provide appropriate training and instruction on the task before proceeding to work. • Check that weather conditions are suitable for working at height; consider wind strength and rain or approaching storms. • Ensure that all trades are notified of work at height and an exclusion zone is established. • Check for overhead wires when slewing and placing the loads safe working distances are for wires on poles up to 133kV a spotter is required if coming inside 6.4 m away and come no closer than 3m from the wires. • No work at heights is to be carried out on site unless one of the following control measures is adopted: • the erection of physical barriers (such as guardrails and scaffolding),	Supervisor and WHSE Manager in regular Site Inspections	M13

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• providing a personal fall protection system (fall-arrest harness system or travel restraint system), or • providing a catch system (e.g. fall arresting platform, catch net etc). • providing an exclusion zone		
Accessing and working at height in areas protected by physical barriers- handrails or guard rails **- High Risk Construction Work**	• Falls from height and falling objects resulting in injuries or death	Critical	Possible	H22	• A suitable means of access to areas at height is to be provided and used (e.g. appropriately placed / secured ladder, stairs, EWP etc. • Workers are not to access any area(s) where edge protection has not been erected or where any other fall hazard may exist. • Under no circumstances are workers to climb on or otherwise position themselves where they are at risk of falling onto and / or over protected edges. • Where there is a risk of objects falling onto workers / persons below, a suitable means of restraining tools, equipment and any other materials is to be used (e.g. lanyards / wrist straps, toe boards (min 150mm high) etc).	Supervisor, WHSE Manager and all workers via daily checks and Take 5's	M10

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Exclusion zone(s) to be established below (where relevant). • Tools, equipment and any other objects / materials are not to be positioned where they could fall.		
Accessing and working at heights using personal fall protection (where physical barrier not practicable) **- High Risk Construction Work**	• Falls from height resulting in injuries or death	Critical	Possible	H22	• A pre-use inspection of harnesses and all other associated fall protection equipment is to be undertaken by a competent person prior to use. • Harnesses and associated equipment are to also be inspected at least once every 6 months by a competent person with a written record of the inspection(s) maintained for not less than 4 years or the life of the system. • All workers using personal fall protection are to have received suitable training in the selection and use of the equipment and systems of work used. • No person is to use any component of any personal fall protection system, including an anchorage, if that component shows evidence of wear, damage or weakness to an	Supervisor, WHSE Manager and all workers via daily checks and Take 5's	M10

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					extent that may affect the system's safety.		
Accessing and working at height using a fall arrest system **- High Risk Construction Work**	• Incorrect set-up / use of personal fall protection equipment • Falls from Height and falling objects resulting in injury or death. • Pendulum effect • No Rescue Plan	Critical	Possible	H22	• All workers using personal fall protection are to have received suitable training in the selection, use of the equipment and systems of work used. • Personal fall protection equipment is be used in accordance with any instructions or requirements of the system's manufacturer or supplier. • Fall distance is to be taken into consideration to ensure that there is enough distance available for a person falling into the system to avoid them from hitting an object, the ground or other protrusion during a potential fall. • Users of fall-arrest protection systems are to put in place controls that ensure components of the system are protected from potential friction and damage during use and during a potential fall (i.e. padding around rough anchorages and covers over sharp edges). • A safety 'belt' is not to be used in a fall-arrest system (i.e. to arrest a	Supervisor, WHSE Manager and all workers via daily checks and Take 5's	M10

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					person who may fall more than 600mm) • A lanyard assembly is to be as short as practicable and the working slack length short enough to ensure that a fall of a user of not more than 2m, when used in conjunction with a fall-arrest system, will result. • The components of a fall-arrest system are to be compatible. The use of non-compatible components could lead to ineffective equipment that presents a risk of injury from falling to the person using the equipment. • A suitable means of access to areas at height is to be provided and used (e.g. appropriately placed / secured ladder, stairs, EWP - with gate) • The system is to be set up to allow a person to attach to the anchorage point(s) prior to accessing any area where they may be exposed to a fall hazard. • Anchorage points for fall-arrest systems are to: • Be designed by an engineer; or		

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Install as per manufacturers specification, when fixing to concrete elements (and not limited to the following test criteria):
					  • verify MPA strength of concrete to match the fixings
					  • Test installed fixings with hydraulic tester as per manufacturer's instruction.
					  • Ensure the safety ring is compatible to the installed fixing(s).
					• be inspected and approved for use by a competent person prior to work commencing; and
					• be located so that the user can connect their lanyard or device to the system prior to moving into a position where they would be at risk of a fall; and
					• have a capacity of at least-
					  • 15kN for 1 person using the anchorage point, or
					  • 21kN for 2 people using the anchorage point.
					• The system's device to absorb the energy must be able to limit the		

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					force applied to the person to not more than 6kN. • Where used, the second attachment arm of a twin-tailed lanyard is not to remain attached to the harness when not in use, especially were shorter lanyards are used. • Where there is a risk of objects falling onto workers / persons below, a suitable means of restraining tools, equipment and any other materials is to be used (e.g. lanyards / wrist straps etc.). • Exclusion zone(s) to be established below using barrier mesh / tape and suitable signage etc. (where relevant). • Tools, equipment and any other objects/ materials are not to be positioned where they could fall. • The potential for pendulum effect may be minimized in the case of a fall via the implementation of the following controls (where relevant): • establish anchorage perpendicular to edge from which a fall can be sustained,		

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• connect to anchorage line running parallel with edge, • diversion anchorages, • End stops. • No work involving personnel wearing fall-arrest systems is to be undertaken unless adequate provisions have been made for the retrieval or rescue of a person from fall-arrest systems immediately after they fall. This must include: • ensuring that there are written procedures for the retrieval of persons, • ensuring that an adequate number of workers are present, • ensuring that there is additional retrieval equipment provided as required, and • Suitable retrieval/rescue training has been undertaken by those working at heights.		
Accessing and working at heights using travel restraint	• Incorrect set-up / use of personal fall protection equipment	Critical	Possible	H22	• All workers using personal fall protection are to have received suitable training in the selection, use of the equipment and systems of work used.	Supervisor, WHSE Manager and all	M10

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

system **- High Risk Construction Work**	• Falls from Height and falling objects resulting in injury or death.				• Personal fall protection equipment is be used in accordance with any instructions or requirements of the system's manufacturer or supplier.
					• Users of travel restraint protection systems controls are to put in place, that ensure components of the system are protected from potential friction and damage during use and during a potential fall (i.e. padding around rough anchorages and covers over sharp edges).
					• A suitable means of access to areas at height is to be provided and used (e.g. appropriately placed / secured ladder, stairs, EWP - with gate).
					• The system is to be set up to allow a person to attach to the anchorage point(s) prior to accessing any area where they may be exposed to a fall hazard.
					• A travel restraint system is to:
					  • be installed by a competent person,
					  • have an anchorage point capable of withstanding a load that could be expected to be exerted on it by a
						workers via daily checks and Take 5's	

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					person during normal operation (minimum 6kN). • A restraint system is to be substituted with a fall-arrest system where: restrain line/system permits adjustment or other misuses such that a free fall could occur; or where there is a danger of falling. • Where there is a risk of objects falling onto workers / persons below, a suitable means of restraining tools, equipment and any other materials is to be used (e.g. lanyards / wrist straps, etc.) or; • Exclusion zone(s) to be established below using barrier mesh / tape and suitable signage etc. (where relevant). • Tools, equipment and any other objects / materials are not to be positioned where they could fall. • A suitable means of access to areas at height is to be provided and used (e.g. appropriately placed / secured ladder, stairs, EWP etc. • Workers are not to access any area which has not been protected with a suitable catch		

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					system (fall arrest platform), or where any other fall hazard may exist. • Where there is a risk of objects falling onto workers / persons below, a suitable means of restraining tools, equipment and any other materials is to be used (e.g. lanyards / wrist straps, etc). • Exclusion zone(s) to be established below (where relevant). • Tools, equipment and any other objects / materials are not to be positioned where they could fall.		
Accessing and working in areas protected by an work exclusion zone (Flag bunting placed back a minimum of 4 -6 metres from the unprotected edge) **- High Risk Construction Work**	• Falls from Height and falling objects resulting in injury or death.	Critical	Possible	H22	• A suitable means of access to areas at height is to be provided and used (e.g. appropriately placed / secured ladder, stairs, EWP etc. with applicable safe access to the work zone. • Workers are not to access any area outside the work exclusion zone, or where any other fall hazard may exist • Exclusion zone(s) to be established below (where relevant). • Tools, equipment and any other objects / materials are not to be positioned where they could fall.	Supervisor, WHSE Manager and all workers via daily checks and Take 5's	M10

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – WORKING AT HEIGHTS

Name	Roles	Signature

Ref. No.: HSE-SWMS-004

Issue Date: 12/12/2025

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

Task / Activity:	**HAZARDOUS CHEMICALS – High Risk Construction Work**	**SWMS Number:**	004
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		
Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

Relevant to:
Division: All
Department: All
Site: All

Document Owner: Managing Director
Change Control: Level 1

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
General Safety Induction	PPE MSDS	Nil

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff

Responsible Director			
Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Emergency Response	• Failure to have emergency response procedure in place	Critical	Possible	H22	• Establishment of Emergency Response Plan • Emergency Response Training • 000 to be called when emergency services required. • Call over radio channel "Emergency, Emergency, Emergency" in event of emergency. • Ensuring effective communication means in all work groups and supervisors	Supervisor in Site Inspection	H15
Public Safety	• Public being exposed to construction activities	Critical	Possible	H22	• Fenced area / compound • Visitor induction where required. • Traffic control establishment and monitoring of controls (where applicable) • Applicable signs and barricades	Supervisor in Site Inspection	H15
Prior to using a hazardous substance / dangerous good on site	• Failing to identify the risks associated with a particular hazardous substance / dangerous good	Critical	Possible	H22	• Conduct risk assessment and purchase/use a less hazardous/dangerous substance where possible. • A current SDS (within 5 years) is to be obtained and kept on site. • A hazardous substance/dangerous goods risk assessment is to be completed prior to use • Where a Risk Assessment for a hazardous	Supervisor in Site Inspection	H15

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					substance/dangerous good determines a 'Significant Level of Risk' a SWMS specific for the use of that substance is to be developed and workers suitably trained. • All containers in which hazardous substances and dangerous goods are stored and transferred are to be suitably labelled (e.g. full product name, safety & risk phrases etc.).		
Transport of a hazardous substance / dangerous goods **– High Risk Construction Work**	• Spills	Moderate	Possible	M13	• Appropriate spill containment (spill kit, absorbing material, kitty litter etc.) is to be transported with the hazardous substance to contain spills (Refer to SDS).	Supervisor in Site Inspection	L6
	• Incompatibility with other substances	Moderate	Possible	M13	• Incompatible substances are not to be transported together unless adequate separation can be maintained in accordance with the SDS.	Supervisor in Site Inspection	L6
	• Fire/ explosion	Major	Possible	H18	• All containers in which hazardous substances and dangerous goods are stored are to be suitably labelled (e.g. full product name, safety & risk phrases etc.).	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Separation of goods from sources of ignition • Suitable fire extinguisher to be located near any area where a substance shows a significant fire risk. • Where incompatible classes of dangerous goods are required to be store within the same area, the following minimum exclusion zones are to be observed: • Incompatible goods stored at least 5m apart. • For other goods 3m • Designated smoking area clear of bunded / locked chemical storage area		
Using / Handling hazardous substances / dangerous goods **– High Risk Construction Work**	• Physical contact and specific effects	Major	Possible	H18	• Hazardous substances / dangerous goods are to be used in accordance with relevant SDS, hazardous substance risk assessments and work method statement (where applicable, Risk assessments utilized, including using required PPE	Supervisor in Site Inspection	M10
	• Appropriate emergency	Moderate	Possible	M13	• Ensure required emergency equipment is readily available (e.g. eye wash etc.)	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	equipment not available				• HSE inspections to ensure equipment is readily available. • Equipment inspected prior to set up		
	• Environmental contamination / spills	Moderate	Possible	M13	• Appropriate spill containment (spill kit, absorbing material, kitty litter, etc.) is to be made available close to location where work is being conducted to contain spills (Refer appropriate clean up from SDS) • Appropriately stored with locked and ventilated, bunded areas, (designated chemical storage area) • Appropriately stored in original containers or labelled and marked containers specified as per manufacturer recommendations as appropriate for use	Supervisor in Site Inspection	L6
	• Person not competent in the use of hazardous substance / dangerous good	Major	Possible	H18	• All persons using a hazardous substance and dangerous good/s are to have received adequate training / instruction and are to be familiar with the relevant SDS, hazardous substance risk assessment and the safe work method statement (where applicable).	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	Exposure to chemicals due to spray drift, off target exposure	Moderate	Possible	M13	• Ensure appropriate training. • Check weather and wind conditions. • Complete risk assessment (where applicable) • Plant and machinery to be used with windows closed. • Check tank, hoses, connections, filters, spray rig, spray bottles and nozzles for leaks. • If faults found DO NOT proceed with works • Appropriate PPE (refer SDS for any chemical specific PPE) • Where applicable health assessments, fit testing masks, health monitoring and surveillance / monitoring e.g. air monitoring, gas monitoring or volatile organic compound monitoring is to be used	Supervisor in Site Inspection	L6
	• Discarding disused packaging and/ container and flammable liquid	Minor	Possible	M8	• Before placing containers of hazardous substance/ dangerous goods into rubbish skips or bins ensuring: • Container is marked Do not Use or • Remove or mark the label illegible. • Ensure all substances are in original containers.	Supervisor in Site Inspection	L3

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Waste flammable liquids may be collected in a clean metal drum. The drum shall be kept in a well-ventilated area at least 3m away from any ignition sources. • Wastes containing flammable or combustible liquids, • even at low concentrations, shall not be poured down to the stormwater drain or included with general waste.		
Storage of hazardous substances / dangerous goods **– High Risk Construction Work**	• Incompatible substance storage	Moderate	Possible	M13	• All hazardous substances/dangerous goods are to be stored in accordance with specific SDS requirements and AS 1940 • Where incompatible classes of dangerous goods are required to be stored within the same area, the following minimum exclusion zones are to be observed: • Incompatible goods stored at least 5m apart. • For other goods 3m • Appropriately stored with locked and ventilated, bunded areas, (designated chemical storage area)	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Appropriately stored in original containers or labeled and marked containers specified as per manufacturer recommendations as appropriate for use. • Where relevant; dangerous goods storage areas are to comply with relevant additional Australian Standards		
	• Environmental contamination / spills	Moderate	Possible	M13	• Appropriately stored with locked and ventilated, bunded areas, (designated chemical storage area) • Appropriately stored in original containers or labelled and marked containers specified as per manufacturer recommendations as appropriate for use. • Appropriate spill containment (spill kit, absorbing material, kitty litter, etc) is to be made available close to location where chemicals are stored. • Contain chemicals as per manufacturer requirements and SDS	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Fire / explosion	Major	Possible	H18	• All containers in which hazardous substances and dangerous goods are stored are to be suitably labelled (e.g. full product name, safety & risk phrases etc.). • Separation of goods from sources of ignition • Suitable fire extinguisher to be located near any area where a substance shows a significant fire risk. • Where incompatible classes of dangerous goods are required to be stored within the same area, the following minimum exclusion zones are to be observed: • Incompatible goods stored at least 5m apart. • For other goods 3m • Designated smoking area clear of bunded / locked chemical storage area	Supervisor in Site Inspection	M10
Clean up site. Pack up materials and tools **– High Risk Construction Work**	• Housekeeping	Moderate	Possible	M13	• All waste to be disposed at designated waste disposal area. • Storage area and waste disposal area to have appropriate barricading and signage to ensure public do not access	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (in consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – HAZARDOUS CHEMICALS

Name	Roles	Signature

Ref. No.: HSE-SWMS-005

Issue Date: 12/12/2025

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

Task / Activity:	**WELDING & HOTWORKS – High Risk Construction Work**	**SWMS Number:**	005
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		

Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

Relevant to:
Division: All
Department: All
Site: All

Document Owner: Managing Director
Change Control: Level 1

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
General Safety Induction Welding Certification	Hand Tools Power Tools Barricading Safety Signage	Fuels & Gasses

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff

Responsible Director			
Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Work area set-up – **High Risk Construction Work**	• Unauthorised access to the work area • Fire • Hazardous atmosphere	Critical	Possible	H22	• Establish an exclusion zone for other workers and the public clearly defined by signage and hazard marking tape or flagging. • Screens (if used) are undamaged. • Maintain awareness of unauthorised people attempting to enter or entering the work area. • If members of the public or unauthorised personnel enter the exclusion zone, stop work until removed from the work zone. • Screens (if used) are undamaged. • Ensure completed Hot Work Permit available at the site. • Follow safety precautions on Hot Work Permit • Note: Do not conduct work that is not listed on the Hot Work Permit. If other Hot Works are required, obtain Hot Work Permit for that task before starting work. • Ensure: • Fire protection equipment provided and accessible - Dry Chemical or CO2 fire extinguishers in the immediate vicinity of	Supervisor and WHSE Manager in regular Site Inspections Workers in personal risk assessments	M14

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					cylinders (ensure fire extinguishers tested and tagged) • Remove all flammable materials (including waste, rags, solvents, empty drums etc.) • Screens are of sufficient size and placed in a manner to prevent hot sparks, slag and hot metal pieces rolling underneath or penetrating any openings. • Do not weld/grind within 15m of: • Grass/vegetation/timber and other combustibles (if not practicable, grass should be wetted sufficiently) • Adequate flammables storage • Gas maintenance access points • Pressure vessels and tanks (including pipelines, flanges, vents and valves). • Check weather requirements: • Do not conduct Hot Works in high temperatures, high winds or on days of Total Fire Bans		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Ensure appropriate trolley provided for oxy-acetylene kit:
					  • Must enable cylinders to remain upright and secure.
					  • Made of non-combustible materials (such as steel)
					  • Undamaged, designed for the purpose.
					• Ensure current Safety Data Sheets (SDS) are obtained for all hazardous chemicals and accessible on-site.
					• Ventilation requirements (indoor or outdoor). Provide mechanical ventilation if required.
					• Welding equipment secured, in good condition, no gas leaks and correct for the task (voltage, current)
					• Gas detecting equipment (if used) calibrated, working and batteries fully charged.
					• Check gas cylinders are free from leaks or dents.
					• Check gas cylinder fittings, hoses and connections are not damaged or in poor condition.
					• Secure gas cylinders to prevent dislodgement.		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

House keeping	• Slips
	• Trips
	• Falls
		Moderate	Likely	H17	• Maintain housekeeping throughout the shift & clean-up
					• Ensure sufficient lighting to detect changes in level (using temporary lighting as required)
					• Do not jump from elevated edges >180mm, step carefully and use prepared access areas
					• The work area is clean and uncluttered as possible
					• Locate equipment where it will not become a tripping hazard:
					  • Run cords/hoses overhead if possible
					  • Place cords/hoses to the side of the walkways and tape down
					  • Avoid running cords/hoses through stairways and ladders
					• Check for stored items, corners or other obstructions that could cause tripping
					• Ensure there is room to manoeuvre the signs and no obstacles in the way
					• Check the end destination is prepared correctly
					• Clean spills immediately
					• Ensure footwear is suitable. Snug-fitting shoes/boots with flat, non-
						Supervisor and WHSE Manager in regular Site Inspections
						
						Workers in personal risk assessments
							L6

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					slip soles, no loose soles, long laces, oily soles, or caked with mud or other contaminants.		
Manual tasks	• Musculoskeletal (MSD) injuries	Moderate	Likely	H17	• Materials/equipment placed as close to the work area as possible • Weight of an object should be known; avoid lifting loads more than 1/4 of your body weight • Do not use extreme force to move items • Lifted items should be held close to the body whenever possible: • Keeping knees bent and back straight and lift, unload keeping knees bent • Use team lifts and mechanical means for heavy items • Schedule regular breaks and practice job rotation • Avoid overreaching, long periods of repetitive movements, awkward and sustained positions, twisting and side-bending • Provide trestles/benches to place workpieces on to reduce manual handling risks (between shoulder and knee height).	Supervisor and WHSE Manager in regular Site Inspections Workers in personal risk assessments	L6

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Carrying out Hot Work – **High Risk Construction Work**	• Burns • Fire • Explosion	Critical	Possible	H22	• Ensure that the appropriate PPE is worn for the type of hot work e.g. Welding (Welding Mask, Leather Apron) Grinding (Double Eye Protection) • Ensure no combustibles are within the work area. • Continually monitor work area for signs of fire, smouldering etc.	Supervisor and WHSE Manager in regular Site Inspections Workers in personal risk assessments	M14

Welding – **High Risk Construction Work**	• Fire / explosion
	• Handling LPG / OXY / Acetylene
	• Burns
	• Exposure to a toxic atmosphere
	• Energised equipment
	• Electric shock
	• Electrocution
	• Eye trauma
	• Air under pressure
	• Noise
	• Heat stress
		Critical	Possible	H22	• Use Spotter as required
					• Always use a striker to ignite, not matches/lighter
					• Ensure welding hoses or cylinders do not come into contact with torch flame or sparks
					• Ensure:
					  • Monitor atmosphere as required, stop work immediately if gas levels reach 5% of UEL or LEL
					  • Note: UEL = Upper Explosive Limit. LEL = Lower Explosive Limit)
					  • Check continuously for sparks or fire outbreak
					• Gas cylinders:
					  • Keep the gas cylinder valve closed when the cylinder is not being used
						Supervisor and WHSE Manager in regular Site Inspections
						
						Workers in personal risk assessments
							M14

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Keep all sources of heat and ignition away from gas cylinders, even if the cylinders do not contain flammable material
					• Ensure cylinders are fitted with correct flashback arresters. Example:
					  • For hoses 3m or less, flashback arrestors fitted to each gas line at the regulator outlet
					  • Hoses longer than 3m, two flashback arrestors fitted to each gas line; one at the blowpipe connection and one at the regulator outlet
					• Incorrect flashback arresters can reduce flow capacity cause flame instability and increase the risk of flashback
					• An appropriate fire extinguisher to be ready for immediate use.
					• Prevent contacting electrodes or welding wire with bare hands when in the holder or welding gun (wear dry welding gloves), and ensure that holders/welding		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					guns are never held under the armpits • Mark or label as 'hot' equipment, metals, plates or items likely to be hot in the welding area to minimise accidental burns • PPE: • Ensure appropriate PPE (cotton clothing, leather or welding type gloves, goggles with side shields or welding mask with filter lens as required). Ensure operator does not have matches or a lighter on them • Avoid clothing that has the potential to capture hot sparks and metal debris, e.g. pockets or other folds • Picking up debris – use gloves. • Do not weld on coated materials, such as galvanised, lead, or cadmium plated steel unless using airline respirators • Fluxes: • Welding to be performed in well-ventilated areas • SDS read and understood		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Avoid hand, clothing, food, and drink contact with metal fume or powders
					• Acids:
					  • Keep the work area well ventilated
					  • Wear goggles, rubber gloves and rubber aprons when handling acids and solutions
					  • Do not inhale fumes
					  • If spilled on the body or clothing, wash immediately with large quantities of cold water. Seek medical attention where required.
					  • Never pour water into acid when preparing solutions; instead, pour acid into water. Always mix acid and water slowly.
					• Do not weld in wet or rainy conditions without effective cover
					• All electrical equipment and leads are tested and tagged and are current
					• Pre-inspect all electrical equipment. If the equipment is damaged, do not use. Take out		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					of service, apply Lock-out/tag-out (LOTO) • Install an RCD as required • Use fully insulated electrode holders. The holder should never be dipped into water to cool or be placed on conductive surfaces. • Never ignore a blown a fuse, it is a warning that something is wrong • Never attempt to connect or change welding cables before disconnecting from the main power supply • Ensure welding cables that are fully insulated throughout their entire length • Never attempt to use pipes or other infrastructure as part of the welding circuit. (Shocks to others may occur) • If welder stops working or requires maintenance always turn off the power and disconnect from main power before removing panels or accessing welder. (Contacting a lead inside the welding set with the power still on can result in a serious electric shock)		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Where possible, work on an insulated floor
					• Wear rubber insulated shoes.
					• Always wear a welding mask when welding, cutting or grinding
					• Ensure welding masks have suitable lens rating
					• Instruct other people in the area that welding operations will be occurring, and not to look at the flash
					• Ensure an opaque screen is used to protect the eyes of others within the vicinity of welding operations. (Use non-flammable screens and partitions)
					• Use PPE including:
					  • Filter shades for goggles and face shields to protect the eyes from radiation.
					  • Protect uncovered skin by wearing gloves and other protective clothing.
					  • Never use Oxygen or fuel gas to blow dirt or dust-off clothing or equipment.
					  • Hearing Protection for operators is required and ensure it is worn by the operator throughout exposure to noise.		

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• In a hot environment, allowing the workers to work for a limited time followed by a suitable rest and cooling-off period
					• Workers should drink cool drinking water during regularly scheduled rest breaks
					• Avoid working alone in hazardous working environments
					• Ensure workers can recognise heat stress symptoms:
					• Mild heat stress:
					  • Tired/weak
					  • Muscle cramps
					  • Feeling sick or vomiting
					• Severe heat stress:
					  • Headache
					  • Rapid pulse
					  • Profuse sweating
					  • Irritability or confusion
					  • Blurred vision
					  • Loss of consciousness
					• Ensure adequate drinking water is supplied. Workers should be encouraged to drink a cup of water (about 200 mL) every 15 to 20 minutes when working in hot environments.		

On Completion – **High Risk Construction Work**	• Unauthorised access • Fire	Critical	Possible	H22	• If acceptable, remove or add barricades. • Check for sparks/smouldering	Supervisor and WHSE	M14

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Hazardous vapours • Burns • Contact with electricity • Security breach • Vehicle/people impact				• Sign off of Hot Work Permit by the responsible person. • Check gas cylinder valves are turned off & cylinders secure. • Remove debris – use gloves. • Disconnect power tool/extension leads from power point before winding up so that you don't get a shock if the lead is damaged • Inspect leads and power equipment for damage • If safe to do so, remove isolation locks/tags and test appliance for function. • All personnel sign-out on Site Register. • Stay to designated access and egress routes • Maintain awareness of surroundings.	Manager in regular Site Inspections Workers in personal risk assessments	

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (in consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – WELDING & HOTWORKS

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – DEMOLITION

Task / Activity:	**DEMOLITION – High Risk Construction Work**	**SWMS Number:**	006
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		

Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT – DEMOLITION

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
Fit Testing Certification Demolition License	RPE Hand Tools Power Tools Acro Props Skip Bins	Nil

SAFE WORK METHOD STATEMENT – DEMOLITION

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff

Responsible Director			
Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

Work area set-up	• Unauthorised access to the work area
	• Contact with utilities
	• Property damage
	• Fire
		Moderate	Possible	M13	• The immediate area should be cordoned off and signs displayed.
					• Establish an exclusion zone for other workers and the public. i.e., those not associated with the activity. This zone should be clearly defined by signage and hazard marking tape or flagging.
					• Maintain awareness of unauthorised people attempting to enter or entering the work area.
					• If members of the public or unauthorised personnel enter the exclusion zone, stop work until removed from the work zone.
					• Identify, locate and disconnect all services. Confirm:
					  • Sewerage, electricity, water, gas, steam, overhead fire sprinkler system or other services in the demolition process have been taken out of service, e.g. capped or shut off
					  • Ensure that all services are de-commissioned by licensed, qualified personnel
						Supervisor and WHSE Manager in regular Site Inspections	L6

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• A scanning report is mandatory before removal or cutting masonry. The scan is to be carried out just before disturbance where possible • Electrical Hazard Identification Record V3 (EHI) and Electrical Clearance Certificate (ECC) required before de-fit. • Ensure equipment not placed in areas where they may be run over, damaged or exposed to water (unless rated for wet environments). Keep power leads up off the ground & out of the way. • Do not disturb or adjust hoarding. • Protect and cover surfaces against damage throughout the project, e.g. cover floors, fixtures and fittings. • Ensure completed Hot Work Permit available at the site. • Follow safety precautions on Hot Work Permit • Do not conduct work not listed on the Hot Work Permit. If other		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					Hot Works are required, obtain Hot Work Permit for that task before the commencement. • Ensure no ignition sources in the area. • Do not interfere with, or alter, any existing sprinklers, detectors or other fire services equipment without the consent of the primary contractor and tenanted building authority. • Do not obstruct access to firefighting equipment or exit ways with any tools or equipment. • Do not use any flammable materials or carry out any "hazardous works" in contravention of the restrictions stated in the Hot Work Permit • Ensure fire protection equipment provided and accessible. Dry Chemical or CO2 fire extinguishers near cylinders (ensure fire extinguishers tested and tagged).		
Allocate a suitable area for Materials Management Site	• Uncontrolled waste management	Moderate	Possible	M13	• The Materials Management Site is to have: • Suitable access/egress • As close to the worksite as possible	Supervisor and WHSE Manager in	L6

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Large, flat, open space
					• Space for salvage and waste
					• ONLY transfer waste outside trading hours if working in commercial premises
					• Determine safe travel routes - mark out pedestrian exclusion zones using barricades/signs
					• Use skip bins:
					  • If required (such as roadside work) provide adequate traffic management (barricades, witches hats, caution signs, stop-go controllers)
					  • Ensure adequate provision is made for the disposal of contaminated waste and the facility/site is capable of facilitating correct disposal methods
					  • Ensure correct disposal requirements for materials are available – (see local council for appropriate waste disposal sites).
						regular Site Inspections	

House keeping	• Slips • Trips • Falls	Moderate	Likely	H17	• Maintain housekeeping throughout the shift & clean-up • Where practicable provide ramps over steps	Supervisor and WHSE Manager in	L6

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Small changes in levels (less than 100mm) often present the greatest trip hazard. In these cases, provide ramping wherever possible
					• Ensure sufficient lighting to detect changes in level (using temporary lighting as required)
					• Provide warning strips and signs to alert others about changed or uneven ground/floor surfaces
					• Adequate handrails on stairs and ramps
					• Do not jump from elevated edges >180mm (concrete slabs)- step carefully and or use prepared access area
					• The work area is clean and uncluttered as possible
					• Locate equipment:
					  • To not become a tripping hazard
					  • Do not place air hoses and power leads across walkways, roadways, thoroughfares
					• Electric leads should be as short as possible
					• Do not run leads along ground/floor, near sharp edges, across doorways or hang them
						regular Site Inspections	

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					over metal structures. Use pendants, lead stand or insulated cable hangers • Check for stairs, stored items, corners or other obstructions that could cause tripping • Clean up the work area and remove rubbish and obstructions regularly • Do not climb or jump over loose materials • Do not store materials in walkways • Stack materials neatly • Stay alert - be aware of your surroundings and others • Always ensure that you have a firm footing • When not in use ensure equipment stowed safely • Check there is room to manoeuvre and no obstacles in the way • Check the end destination is prepared correctly for placement of the materials/equipment • Clean spills immediately • Footwear is suitable. Snug-fitting shoes/boots with flat, non-slip soles, no loose soles, long laces,		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					oily soles, or caked with mud or other contaminants.		

Manual Tasks	• Musculoskeletal Disorder (MSD) injuries	Moderate	Likely	H17	• Ensure materials/equipment is as close to the work area as possible
					• Ensure sufficient people available for the task
					• Adequate lighting
					• Sufficient room for delivery of equipment and removal of materials
					• Check for stairs, stored items, corners or other obstructions that could cause crushing of fingers, or awkward postures when carrying the loads
					• When unloading equipment and tools from work vehicle:
					  • Ensure the access route is clear of hazards
					  • Use hand trucks (trolley), to move heavy materials where practicable
					  • Use team-lifts where possible
					  • As much as possible, team members are of similar height and capability
					  • Team members know their responsibilities during the lift
						Supervisor and WHSE Manager in regular Site Inspections	L6

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Build a ramp for access where necessary - planks placed and secured where required.
					• Weight of an object should be known; avoid lifting loads more than 1/4 of your body weight
					• Do not use extreme force to move items
					• Hold lifted items close to the body whenever possible:
					  • Keeping knees bent and back straight and lift, unload keeping knees bent
					• To reduce risks from manual handling:
					  • Select order of removal to eliminate double handling
					  • Break loads down into lighter loads where possible
					  • Use appropriate mechanical aids and trolleys.
					  • Use equipment as per manufacturer's manual and safety guides
					  • Do not obscure vision with load
					  • Always hold the appropriate equipment		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					firmly with both hands, use a firm grip with thumb and fingers encircling the handles • Remove clutter • Limit time spent on knees • Use kneepads at all times when kneeling • Implement job rotation where required and ensure regular rest breaks • Provide tools with anti-vibration or anti-kickback features where possible • Select a suitable size, weight, type of handle, grip • Use vibration-absorbing gloves as required (particularly in cold weather) • Suspend/ support heavier tools if used repetitively • Ensure triggers are long enough (approx. 5cm long) to allow activation by several fingers • Use triggers that can lock into place for use over longer periods (more than 30 seconds at a time) • Avoid overreaching, long periods of repetitive movements, awkward and sustained positions, twisting and side-bending.		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Working with powered & non-powered tools	• Electrocution • Injury • Fire • Asphyxiation	Major	Possible	H18	• Use tools only for the purpose specified by the manufacturer • Wear PPE as recommended by the manufacturer • Pre-inspect and operate tools following the manufacturer's instructions. If damaged or unsuitable for the task do not use. Take out of service immediately and apply LOTO procedures • The tool operations manual is available, read and understood • Fire protection equipment accessible • Electrical: • All electric power tools and leads are Tested, Tagged and are current • Use electrical sockets protected by RCD (safety-switches) or use portable RCD devices • Switchboards have appropriately rated circuit breaker • Always ensure that the tool is switched off and power isolated before a pre-start check, adjusting, changing set-ups or repairing • Do not overload power outlets • Diesel/petrol-powered tools - Do not run a diesel/petrol-powered	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					tool inside a building (e.g. shed), or where ventilation is limited • Use mechanical ventilation as required.		
Remove non-fixed items – i.e., furnishings, cabinets, rugs, appliances, motors, mobile partitions etc.	• Electric shock / electrocution • Burns • Falling objects	Major	Possible	H18	• Do not remove energised electrical equipment Ensure de-energised equipment cannot be inadvertently re-energised • Before removal, equipment must be tested to ensure it has been isolated from the power source • The tester must understand testing procedures and be competent in the use of the testing equipment and process • Check test equipment and PPE, consult with all workers involved • Ensure all equipment has been switched off and allowed to cool down before removal • Do not touch hot equipment • Ensure PPE is worn when working near hot surfaces, e.g. gloves, long sleeve shirt, pants • Ensure there is an exclusion zone below with barricading • Use lanyards with tools when working externally to EWP platform (i.e., outside of handrails with the risk of falling equipment) • Workers must wear hard hats.	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

Glazing/ mirror removal	• Hazardous manual tasks – MSD
	• Falling Glass
	• Cuts
	• Lacerations
		Moderate	Likely	H17	• Assess the size of the glass and frame
					• Gloves and glass suction lifting aids used
					• Always carry glass panels vertically and avoid twisting
					• Use vacuum lifters or specialist lifting equipment where necessary:
					  • Glass to be carried by use of suctioned glass lifter where pieces of glass are over 1.5m long
					  • Where suction lifting pads are used their ability to lift the glass tested close to the ground
					• Use carry clamps with handles
					• Team lifts, if required, must be coordinated and practised
					• Ensure adequate communication and continue to check for obstacles when moving panels around on site
					• Move carefully when handling glass panels – do not rush.
					• Systems must be in place to prevent glass sheets and panes from falling on people
						Supervisor and WHSE Manager in regular Site Inspections	L6

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Get help if the glass needs to be secured while rubbers are being removed
					• Check the end destination is prepared and correct for placement of glass panel
					• All removed items placed in the allocated area
					• Glass stored in dry conditions, on its edge. Whether storage is on the short or the long edge is dependent on size, substance, availability of space
					• Storage against the wall:
					  • Protection must be placed between glass panels and wall when leaning against a wall
					  • The angle of inclination of glass panels is between 3o- 5o from the vertical
					  • Flooring should be of adequate strength to support the weight of the stack
					  • If location is windy – keep glass panels tied to prevent them from being blown over
					• NEVER leave glass panels unattended unless properly		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					racked, secured and isolated from unauthorised access. • Never attempt to catch a falling glass panel. • Use laceration-resistant gloves • Remove glass surrounds with hand tools • Glass panels not to be carried over the carrier's head. Must always be carried to the side of person/s • Properly equipped first aid kits must be close to the work area at all times • NEVER leave broken glass lying around the work area or not properly disposed of, especially when the work area is unattended. Clean up regularly during the shift • Check for glass chips and clean using materials provided (use laceration-resistant gloves and dustpan/brush or equipment as provided).		
Carpet, vinyl, timber floor covering removal	• Exposure to asbestos • Powered mobile plant movement – floor scraper • Mould	Major	Possible	H18	• Asbestos - If structures were installed or constructed before 31 December 2003. Ensure: • Obtain a copy of the Asbestos register for the structure	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

	• Biological Hazard
	• Cuts
	• Lacerations
	• Punctures
	• Hazardous manual tasks - MSD
					• If no register is present. Ensure:
					  • No work undertaken until the existence or absence of asbestos is confirmed
					  • Use a competent person to determine the existence or absence of asbestos
					• Asbestos Identification
					• Flooring products such as Polyvinyl chloride (PVC or vinyl) tiles, black and brown thermoplastic tiles, sheet floor coverings contain chrysotile
					• Some underfelt, i.e., hessian underlays for carpets and linoleum contain asbestos
					• Adhesives used to bond the floor covering to the surface, could also contain asbestos
					• Some hardwearing composite floors (for example, magnesium oxychloride) also contain about 2 per cent of mineral fibres, which could be asbestos
					• If there is a presence of asbestos, for this task, ensure there are separate, dedicated SWMS and		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					that all workers/employees have relevant training and licensing. • Remove all non-essential workers from the area • Pre-inspect and operate ride-on floor scraper as per manufacturer's instructions • Operator and everyone in the work area should wear safety goggles or glasses, hearing protection during extended use and a dust mask for dusty operations. Hard hats, face shields, safety shoes, worn when specified or necessary • Provide barriers or shields as needed to protect others from debris • Do not force machine - excessive force only causes operator fatigue, increased wear and reduced control • Keep hands away from sharp edges and moving parts • Wear gloves when changing accessories • Follow traffic management plan requirements • Check constantly for changing hazards while working and monitor work position at all times		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Ensure:
					  • High visibility clothing worn at all times
					  • Do not stand behind reversing vehicles
					  • Allow sufficient distance from the plant during operation (allow sufficient room for equipment failures – such as arm/boom failure or plant rollover)
					  • No work conducted in established "no go zones" for pedestrians
					  • Alertness at all times. Listen for reversing alarms/beepers and calls from Plant Operators
					• Safety/warning signs, Spotters, traffic barriers must be obeyed as required
					• Work positions should be in clear sight of plant operators
					• NOTE: Some traffic management plans may say that pedestrians have the right-of-way. Never assume this. Make visual and verbal contact with the plant operator as required.		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Take precautions if the old carpet has been wet or contaminated by mould or other biological substances as that may be hazardous to your health - wear PPE such as face masks/breathing apparatus as required. • Ensure hand protection is worn (cut resistant gloves) • Use caution to avoid sharp objects, protruding nails or tack strips • Exercise caution when using blade – always cut away from the body • Use automatically retracting blade if possible. If not ensure the blade is retracted after use • Utility knives are in good condition; blades are retractable type and sharp • Sharps Disposal Unit is available for disposal of broken or blunt blades. • Carpet/vinyl removal is hard on both your knees and your back. Correct manual handling techniques used.		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Request assistance when moving/lifting carpet/vinyl/heavy items • Coordinate when using team lifts • Maintain adequate communication and continue to check for obstacles during transport.		
Tile, concrete flooring removal	• Exposure to silica dust • Struck by a projectile • Struck by the chisel/pick • Cuts • Lacerations • Hearing loss	Major	Likely	H21	• Task control • Never cut materials unless the use is controlled • Consider the most appropriate control e.g. water delivery or dry dust control • Equipment • Minimise dust emissions by operating and maintaining tools according to the manufacturer's instructions. • Only use equipment that has an integrated water delivery system or a HEPA- filtered dust collection system • Visually check the tool and extraction unit for signs of damage before use • Respiratory PPE • Wear respiratory protective equipment (RPE) such as a half-face negative respirator or	Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					powered air-purifying respirator (PAPR): • Respiratory protection, e.g. P1/P2 face mask minimum • People medically fit to wear the face mask • A competent person conducts fit testing • Complete facial seal • Correct cartridge for contaminant • Area Control • Remove non-essential people from the area • Ensure all people that remain in the area are provided with respiratory protection • Cover sensitive areas (power outlets, food storage) • Wash hands before eating, drinking, smoking, or applying cosmetics in areas where crystalline silica is present • Water delivery control method • The equipment must utilise a water delivery system that continuously supplies water to the working surface • check water is flowing to the cutting area before contacting the material		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• ensure spray guards are in place before commencing work • Regularly clean the work area and surrounding areas • Manage slurry to prevent it from drying out (cover or remove) • Dry dust control method • The equipment must use an integrated HEPA-filtered dust collection system or a • commercially available dust collection system with a dust collector rated to either M or H-Class per AS/NZS 60335.2.69. • System to have a filter-cleaning mechanism • When operating a grinder, ensure an airflow of ≥ 25 cubic feet per minute (cfm) per inch/~700 litres per 25mm of wheel diameter • Drills equipped with a commercially available shroud with a dust collection system • Ensure the dust collection system provides sufficient airflow as recommended by the tool manufacturer • The drill must use an integrated HEPA-filtered dust collection system or a commercially available dust collection system		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					with a dust collector rated to either M or H-Class per AS/NZS 60335.2.69.
					• If using a vacuum to clean holes, ensure the vacuum is rated to either M or H-Class per AS/NZS 60335.2.69 when cleaning holes.
					• Wear safety glasses, long-sleeved shirts and long trousers
					• Concrete saw/grinder:
					  • Perform cuts in a straight line. Twisting the blade while cutting can lead to the blade fracturing
					  • Should the engine stall while cutting, raise blade out of cut before restarting
					• Kickback:
					  • Stay alert – concentrate on what you are doing at all times and be aware of kickback
					  • Kickback occurs more often with small workpieces
					  • Check to make sure the tool is functioning properly
					  • Never attempt to use the concrete saw one-handed.
					• Keep feet clear of the hammer at all times		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Do not angle/aim equipment toward the operator • Do not guide with foot or "ride" drill with one leg • Do not leave unattended • Never start when unit lying down. Wait until unit has finished any movement before resting down. • Use gloves when handling blades or sharp items • Maintain visual contact with workpiece/tools • Direct pry bar/jackhammer away from the body • Ensure grip and footing is secure • Ensure tools not carried in pockets or clothing (use sheaths, tool belts). • Hearing protection worn by all people throughout exposure to noise.		

Removal ceiling fittings, ceiling, wall lining, redundant cabling	• Lack of consultation
	• Cuts, lacerations, puncture wounds
	• Struck by falling objects
		Major	Likely	H21	• Before stripping ceiling components ensure:
					  • Surrounding people are made aware that stripping operations are about to commence
					  • The number of workers needed for the stripping process is determined
						Supervisor and WHSE Manager in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• The method and process of stripping and lowering ceiling components to the ground is pre-planned and understood by all workers • Stripping removed systematically and progressively. • Ensure stripped components are de-nailed • Wear gloves when handling. Be aware of damaged components • Be aware of damaged components with sharp edges. • Ensure PPE worn (hard hat, boots, safety glasses, gloves) • Follow developed stripping and reshoring process • Dismantle in an orderly sequence (Generally, the reverse of the erection process) • Control lowering of all components • Be aware of other person movements • Strip, remove and stack materials progressively to ensure clear access: • Use lanyards to pass tools to people at height		

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure tools cannot fall onto workers below.		
Removing structural walls or supporting framework **– High Risk Construction Work**	• Unauthorised access • Structural collapse • Contact with electricity • Falling objects	Critical	Likely	VH24	• Remove all non-essential people from the area • Provide barricades to ensure people cannot re-enter while props/bracing in place • Inform relevant people of the location of the props and any precautions that must be taken while props are in service. • Do not disturb or damage any existing support structure if it is to remain in place • Prop or brace following the manufacturer's instructions and engineering specs/drawings • If any deviation from specifications is required, seek advice from competent people (design engineer). • Remain alert to overhead wires or extension leads • Do not raise prop where contact with wires or leads is possible. • Hard hats to be worn at all times • Steel cap safety boots are worn.	Supervisor and WHSE Manager in regular Site Inspections	M14
On completion	• Unauthorised access • Inhalation of silica	Major	Likely	H21	• If acceptable, remove or add barricades	Supervisor and WHSE Manager in	M10

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

	• Security breach
	• Vehicle/people impact
					• Ensure machine is parked in a safe, level area, clear of unstable or sloping ground
					• Store the key in a safe place (restrict unauthorised access).
					• Carefully roll or fold any plastic sheeting used to cover any surface within the Silica work area
					• If necessary, use damp rags or a HEPA vacuum cleaner to clean any remaining visibly contaminated sections of the work area
					• If possible, fully dismantle tools and decontaminate in a controlled environment
					• Personal hygiene:
					  • Use HEPA vacuum cleaner to remove obvious signs of contaminated material
					  • Wipe coveralls, shoes, eye protection with a damp cloth
					  • Wipe respirator with a damp cloth – but do not remove
					  • Remove coveralls, shoes and any other PPE
					  • Remove respirator after clean-up and PPE removal
						regular Site Inspections	

SAFE WORK METHOD STATEMENT – DEMOLITION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Wash face and hands with soapy water. Pay attention to under the fingernails. • All personnel sign-out on Site Register. • Stay to designated access and egress routes • Maintain awareness of surroundings.		

SAFE WORK METHOD STATEMENT – DEMOLITION

tallan GROUP

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – DEMOLITION

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – DEMOLITION

Name	Roles	Signature

Ref. No.: HSE-SWMS-007

Issue Date: 12/12/2025

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

Task / Activity:	**WORKING ON PLATFORMS - High Risk Construction Work**	**SWMS Number:**	007
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		

Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

Relevant to:
Division: All
Department: All
Site: All

Document Owner: Managing Director
Change Control: Level 1

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
Working at Heights Certification General Safety Induction	Hand Tools Ladder Trestles Working at Heights Equipment	Nil

Ref. No.: HSE-SWMS-007

Issue Date: 12/12/2025

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			

Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Work on a platform supported by trestle ladders or scaffolding where a person or object could fall less than 2m.	• Falls and falling objects	Moderate	Likely	H17	• Ensure the platform has an unobstructed surface that is: • if the work is light work—at least 225mm wide along the length of the platform; or • if the work is not light work—at least 450mm wide along the length of the platform. • Light work means work that is light having regard to the following: • the amount of physical exertion involved. • the range of movement involved. • The weight or bulk of materials or equipment involved. • Examples of light work: • painting • installing a metal fascia or lighting • placing pine roof trusses in position on the roof of a low-set house • performing inspections or tests • installing an electrical connection	Supervisor, WHSE Manager and workers in regular inspections and risk assessments	L6

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Examples of work that is not light work:
					  • fixing plaster board sheeting to an internal stairwell void
					  • fixing cladding to a gable end of a roof
					  • using a medium or heavy-duty angle grinder or circular saw.
					• A suitable means of access to areas of work is to be provided and used (e.g. appropriately placed / secured ladder, stairs)
					• Under no circumstances are workers to climb on or otherwise position themselves where they are at risk of falling
					• Where there is a risk of objects falling onto workers / persons below, a suitable means of restraining tools, equipment and any other materials is to be used (e.g. lanyards / wrist straps, toe boards (min 150mm high) etc
					• Exclusion zone(s) to be established below (where relevant).
					• Tools, equipment and any other objects / materials are not to be positioned where they could fall.		

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Large tools and materials being hand carried onto the platform from ground level must:
					  • Be carried in a manner that aligns with safe manual handling practices (see manual handling SWMS)
					  • Be carried in a secure stable manner.
					  • Travel a path that does not put other workers at risk of falling from platform.
					  • Have surrounding workers aware of the lift.
					• When using hand and power tools on the platform:
					  • Ensure the most suitable tool is chosen for each task
					  • Ensure the tool and its leads and components are not stored or set out in a manner that will cause an additional hazard such as a trip hazard.
					  • Before each task take a moment to ensure you are positioned in a level, stable position.
					  • Before moving from task to task, take time to plan your		

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					route along the platform to ensure safe passage. • Be aware of how your work may affect other workers and vice versa.		

Work on a platform supported by trestle ladders or scaffolding that could cause a fall of at least 2m. **– High Risk Construction Work**	Falls and falling objects	Major	Possible	H 18	• Trestles will be approved and used in accordance with WH&S Regulations.
					• Each trestle ladder must be secured to prevent it moving.
					• Examples of how a trestle ladder must be secured—
					  • tying the ladder to a sturdy wall
					  • bracing the ladder to the ground
					  • applying weights to the bottom of the ladder
					• Edge protection must be erected along the outer edge of the length of the platform if a worker could fall at least 2m.
					• Ladders are NOT to be used as trestles.
					• Use plank clamps
					• Do not store tools or materials on planks
					• Establish an exclusion zone below trestles and planks
					• A suitable means of access to areas of work is to be provided and used
						Supervisor in Site Inspection	M8

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					(e.g. appropriately placed / secured ladder, stairs)
					• Under no circumstances are workers to climb on or otherwise position themselves where they are at risk of falling
					• Where there is a risk of objects falling onto workers / persons below, a suitable means of restraining tools, equipment and any other materials is to be used (e.g. lanyards / wrist straps, toe boards (min 150mm high) etc
					• Exclusion zone(s) to be established below (where relevant).
					• Tools, equipment and any other objects / materials are not to be positioned where they could fall.
					• Large tools and materials being hand carried onto the platform from ground level must:
					  • Be carried in a manner that aligns with safe manual handling practices (see manual handling SWMS)
					  • Be carried in a secure stable manner.
					  • Travel a path that does not put other workers at risk of falling from platform.		

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Have surrounding workers aware of the lift. • When using hand and power tools on the platform: • Ensure the most suitable tool is chosen for each task • Ensure the tool and its leads and components are not stored or set out in a manner that will cause an additional hazard such as a trip hazard. • Before each task take a moment to ensure you are positioned in a level, stable position. • Before moving from task to task, take time to plan your route along the platform to ensure safe passage. • Be aware of how your work may affect other workers and vice versa.		

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT
WORKING ON PLATFORMS

Name	Roles	Signature

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

Task / Activity:	**SCAFFOLDING & EDGE PROTECTION - HIGH RISK CONSTRUCTION WORK**	**SWMS Number:**	011
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		

Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
EWP Certification Scissor Certification General Safety Induction Scaffolding Certification Working at Heights Certification	Hand Tools EWP Ladder Scaffold	Nil

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			

Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Set up of Scaffold for days work. **– High Risk Construction Work**	• Failure of scaffold • Equipment falls. • Falls • Access to upper levels	Major	Possible	H18	• Mobile scaffolds are for light duty work only. • All Staff mobile scaffolds must be erected in accordance with the manufacturer's specifications. The specifications and erection manuals are to be retained on site by the owner or user of the mobile scaffold for reference for compliance. • No mixing and matching of mobile scaffold components from different manufacturers. • Mobile scaffolds more than 4 metres in height or cantilevered mobile scaffolds must be erected by a licensed scaffolder. Mobile scaffolds under 4 metres in height must be erected and dismantled by trained personnel. • No over-reaching outside handrails when working on balconies (risk of tipping). Note: Cantilevered scaffolds should be used in these situations • Internal access ladders must be provided when the height of the work platform exceeds 2.0 metres. • Handrail height around work platforms on mobile scaffolds more than 2.0 metres in height must be a minimum	Supervisor in Monthly Site Inspection	M10

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					of 900 mm. The height of the mobile scaffold must not exceed three times the least width of the base-frame components (unless outriggers or ties are used). Kickboards are to be installed when material, tools and equipment are used on the mobile scaffold. Mobile scaffolds should not be used where the castors are adjacent to slab edges or penetrations. • Castors/wheels must be locked off before working on mobile scaffold. • Mobile scaffold is not to be moved while persons are on the scaffold. • Mobile scaffold over 4.0m [working deck] to be altered by licenced scaffolder only		
Performing Work at Heights **– High Risk Construction Work**	• Falls and falling objects.	Critical	Possible	H22	• A drop zone must be established under the work environment • Barricades erected to delineate the exclusion area • Signs placed to inform people that there are workers above and to keep clear • The barrier must remain relevant to the overhead work and take "bounce" factors into account • If work platforms can't be used to work off (most preferred) then all fall	Supervisor All Workers	M10

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					prevention PPE must comply with AS 1891 – Industrial fall –arrest systems and devices, Part 4: Selection, use and maintenance • Anchor points for harness attachment, means any fixed, travelling or self-locking anchorage defined in AS 1891.4 for attachment of a safety harness and must comply with this standard • An appropriate rescue plan must be included with the WMS/JSA in the event of a fall and to quickly allay the effects of suspension trauma • All persons undertaking work at heights must have the relevant qualifications		
Dismantling of Scaffold. **– High Risk Construction Work**	• Falls • Falling Objects • Pinch Injuries	Major	Possible	H18	• Retain a platform not less than 450mm in width for the full length of the scaffold being dismantled. • Retain external standards and ledgers to platform edges of higher lift to provide fall protection. • Safe access to the level the scaffold is to be provided. (Temporary stairs or ladder) • Do not work above other construction workers erect barricades if necessary. • As dismantling is in progress stack all components on frames or timbers for	Supervisor in regular Site Inspections	M10

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					strapping ready for removal, stack clear of walkways		
Verify edge protection system	• Missing or inadequate edge protection	Moderate	Possible	M13	• Obtain verification about the edge protection system from the installer • Written information on verification of the system on site (i.e. enclosed in a plastic envelope), attached to the guardrail system so that all users can see the system has been verified as safe to use • Installers of edge protection system must be trained and competent	• Regular site inspections by Supervisor and WHSE Manager Regular personal risk assessments	L6
Inspection of roof edge protection	• Structural integrity of edge protection system fails	Moderate	Possible	M13	• Inspect all connection of temporary edge protection to the building structure to ensure that it is secure • The top rail is fitted to 900mm high • Lower rails and toe boards are fitted where required and in good condition • Visually inspect all connection points. • Inspect that the edge protection fully protects the edge and that it would not allow one to fall over the edge • Thorough inspection is done by a competent person at least monthly • All damages and defects must be repaired prior to work and not to be used unless the damage has been repaired and deemed safe by qualified person	• Regular site inspections by Supervisor and WHSE Manager Regular personal risk assessments	L6

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Safe access and egress points are provided		
Accessing roofs or working at heights above 2m **– High Risk Construction Work**	• Falls from Height	Major	Possible	H18	• A platform more than 300mm below the roof edge must have suitable access to the roof • Roof edge protection must be accessed without having a worker climb over the top rail or mid rail. • If ladders are used as access point onto roofs, ladders must be of industry grade and extend over the roof surface. • If there is no permanent access to roof areas, temporary access must be signposted. • Ensure stepping onto roof landing place is firm, stable and free of obstructions. • Consider the use of personal fall arrest system where edge protection devices are not practicable. • Inspect roofing areas and identify roofing materials that are fragile and/or brittle material. Report areas of fragile/ brittle roofing to Client/ occupier. • Install suitable edge protection around area or install safety mesh over or under the fragile and/or brittle material. Where edge protection is	• Regular site inspections by Supervisor and WHSE Manager • Regular personal risk assessments	M10

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					not used, install suitable flagging of bunting to clearly identify areas of fragile/ brittle roofing. Localised assessment of safety measures taken on the installation is required by a competent person prior to further work commencing.		
Installation and Use – **High Risk Construction Work**	• Edge protection system fails to protect workers from falling •	Major	Possible	H18	• Pre-fabricate edge protection systems on the ground before they are lifted into position • Installation of temporary edge protection must be in accordance with the manufacturer or supplier's instructions. • Only use edge protection when installed in accordance with the manufacturer's instructions. • Workers must use edge protection system based on the manufacturers or installer's instructions. • Every open edge of a stair, landing, platform or shaft opening must be protected to protect people from falling.	• Regular site inspections by Supervisor and WHSE Manager • Regular personal risk assessments	M10
Dismantling of edge protection system – **High Risk Construction Work**	• Falls from height	Major	Possible	H18	• Ensure that dismantling procedures are in accordance with the supplier's instructions to dismantle. • Any anchorage points in the permanent structure must be considered prior to dismantling if	• Regular site inspections by Supervisor and WHSE Manager	M10

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					these anchorage points are not to remain in place.	• Regular personal risk assessments	

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

tallan GROUP

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT
SCAFFOLDING & EDGE PROTECTION

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

Task / Activity:	**WORKING AROUND PLANT AND EQUIPMENT – High Risk Construction Work**	**SWMS Number:**	012
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		
Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
Machinery Certifications General Safety Induction	Hand Tools Machinery	Nil

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff

Responsible Director			
Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Plant Movement on Site	Uncontrolled and Unauthorised access and egress by persons and / or mobile plant	Critical	Possible	H 22	• Supervisor to conduct and communicate movement of pedestrian and plant. • Erect barricading and signage as required and where necessary. • Monitor work area for unauthorised persons. • External parties allowed access should read, sign and understand the work process and be escorted by a Project representative whilst on site. • All visitors to sign Visitors Register at site office	Supervisor All Workers	M 10
Working around plant or equipment **– High Risk Construction Work**	Workers on foot	Critical	Possible	H 22	• Clear delineation for pedestrian access • Agreed exclusion zones. • Maintain good housekeeping. • Personnel to be aware of surroundings at all times. • Essential personnel only in area. • Positive communications with operators before	Supervisor All Workers	M 10

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place to manage potential hazards)**	**MONITOR & REVIEW (Who, how and when)**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					entering operation area of mobile plant. • All hydraulic powered components to be lowered before approaching on foot		

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (in consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – WORKING AROUND PLANT AND EQUIPMENT

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

Task / Activity:	**EARTHWORKS & EXCAVATION – High Risk Construction Work**	**SWMS Number:**	014
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		
Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
Machinery Certifications General Safety Induction	Hand Tools Machinery	Fuels Oils Greases and Lubricants

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			

Zane Taylor	Director		12/12/2026
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Planning for Earthworks and Excavation	• Unauthorised Personnel entering site	Insignificant	Unlikely	L2	• Arrange access to work area via owner or facility manager.	Supervisor in Site Inspection	L1
	• Untrained or unlicenced workers may access site	Insignificant	Unlikely	L2	• If you see a hazard present itself, an unsafe act or the site conditions change use your STOP Right Authority to prevent an injury or incident. • Complete a Pre-Start Hazard Risk Assessment Form for low frequency tasks • Review site risk register • Consider any heritage contents within site • All workers to complete site induction prior to commencement • Where induction is not available workers to liaise with site controller about site hazards, emergency procedures and any other site requirements • All workers to be trained in and sign safe work method statement • All workers to be qualified/licenced/ticketed/trained as required for activities performed	Supervisor in Site Inspection	L1

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Competent person to supervise all new workers • Toolbox talk to be conducted prior to commencement of works • Electrical workers to be in a fit state to commence work and be of zero blood alcohol concentration and must not be suffering from fatigue or under the influence of drugs		
	• Inappropriate plant and equipment allocation may lead to injury	Moderate	Unlikely	M9	• Risk assessment of site to be carried out prior to commencement of work and changes made to SWMS where necessary • Site supervisor to review the site prior to commencement of work • Appropriate plant and equipment must be used and correct procedures must be in place for the works being completed	Supervisor in Site Inspection	L1
Accessing the site	• Slips, trips and falls	Moderate	Possible	M13	• Onsite induction to highlight any slip trip and fall hazards • Site supervisor to ensure that work area is clean, tidy, ventilated and well lit	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• UV Radiation	Moderate	Possible	M13	• Workers must remain hydrated through regularly drinking water • Workers to stay out of sun where possible and implement rest breaks or job rotation where necessary • Workers to consider stopping work in extreme heat • Workers must wear appropriate PPE including sunscreen, sun hats, long sleeve shirts, long pants and sunglasses while working outside, hard hat eye protection, hi visibility safety vest, and steel capped work boots	Supervisor in Site Inspection	L6
	• Individuals entering work site	Moderate	Likely	H17	• Appropriate barriers to be erected to prevent public access to work area • Appropriate signage to be erected indicating work site • Unauthorised access not permitted	Supervisor in Site Inspection	L3
Unload materials, plant and equipment from vehicle and position in work area **– High**	• Manual handling	Moderate	Likely	H17	• Materials to be delivered directly to site where possible • Correct manual handling procedures are to be followed: • Use mechanical lifting devices and trolleys where possible	Supervisor in Site Inspection	L3

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Risk Construction Work					• Only lift objects within your safe lifting limit • Use team lifts where needed • Clear a path, assess the load, get a good grip, ensure a wide stance, bend the knees, keep the spine strait, use the legs to lift, do not twist the trunk, use a smooth action, brace the stomach muscles and lower safely		
	• Inappropriate storage areas	Major	Unlikely	M14	• Workers to discuss material storage area and work areas with site controller prior to commencement • Appropriate work and storage areas to be barricaded off	Supervisor in Site Inspection	L3
	• Uncontrolled Movements • Travelling across unfamiliar worksite	Moderate	Possible	M13	• Delivery to site to be coordinated with supervisor. • Suitable access routes to be determined and clearly identified. • Drivers and Supervisor to check load upon arrival for any load shift or instability before unloading. • Exclusion zone to be established for unloading of plant.	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Spotter to assist in any plant/vehicle movement in particular, reversing and movement on/off trucks • Park vehicle on level ground if available. Ground conditions and slope must be assessed prior to unloading. • Spotters to ensure no other personnel or plant are within the immediate radius of plant being loaded/unloaded. • Supervisor to ensure sufficient room onsite for vehicle to safely park to enable unloading/loading of plant. • All personnel to remain a safe distance (8 metres) from the float/semi-trailer during unloading/loading in case the load shifts or falls from float. • Operator to maintain visual contact between plant and personnel at all times. • Only the transport driver shall remove tie downs, straps etc. • No unloading under power lines • If 'floating' plant under power lines is required – non conducted 'H' goal posts to be erected at 6m on the approach		

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					from both sides of the overhead wires.		
Plant pre– start inspection.	• Plant Failure • Plant damage • Mechanical Failure	Moderate	Likely	H17	• All plant to have pre– start inspection completed prior to works on site to include looking for faults within operating parts of plant. • All faults or damage are to be reported to your supervisor. • All hazardous faults or damage are to be reported immediately and repaired if required for safe operation. • If during operations a mechanical failure occurs – plant is to immediately stop operations and failure addressed prior to re– commencing operations. Ensure the use of Tag Outs where required.	Supervisor in Site Inspection	L6
	• Pressurised Hoses and fittings bursting • Work at heights when checking fluid levels. • Slips, Trips & Falls when ascending and descending	Moderate	Likely	H17	• Daily prestart inspection to be undertaken prior to each shift. Deficiencies to be addressed prior to commencement of operation. • During pre– start check observe and report any chaffing, leaking hoses. Tighten any loose fittings.	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Persons to use manufacturers handrails, steps and non– slip surfaces. • Maintain three points of contact. • Foot, hand holds and walkways in good condition free from dirt and oil/grease. • Maintain clear walkways, store goods clear of path.		
Excavating, Loading & Trimming **– High Risk Construction Work**	• Uncertified operator • Lack of operational experience	Moderate	Possible	M13	• All operators to hold verification of competency for the particular item of plant. • Certified operators must supervise trainees. • Logbooks to be signed off daily by certified operators. • Operators to complete a daily prestart check inspection checklist. • Seatbelts to be worn at all times. • VOC to be completed on operators	Supervisor in Site Inspection	L6
	• Plant/ Vehicle Interaction with Workers • Injury to personnel by interaction with other work areas	Moderate	Possible	M13	• Reversing alarms and flashing lights must be fitted to all mobile plant/vehicles and be operational. • Ensure positive communication with operators prior to entering	Supervisor in Site Inspection	M9

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					the vicinity of any operating plant. • Site traffic management plan to be in place. • Delivery Drivers must be given instruction on access routes and lay– down areas prior to entering site. • Pre– start inspection of plant and vehicles must be completed prior to commencing works on site and any faults and/or damage reported to a supervisor. • A spotter must assist in conditions involving reversing, low clearance, obstacles, tight access or vehicle/pedestrian traffic interaction. • Ensure communication with other work crews in the immediate vicinity. • Exclude all non– essential personnel from area. • Demarcate area and ensure vehicle/truck movements are communicated to all workers in the area • No personnel to stand beside trucks while loading/unloading		

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Interaction with General Public	Moderate	Unlikely	M9	• Any changes to public roads must be approved and done in consideration with the approved TMP. • Appropriate barricading and signage must be in place prior to works commencing. • All enquiries to be directed to the Supervisor. • Ensure general public cannot access loading/unloading areas.	Supervisor in Site Inspection	L6
	• Plant rollover. • Operator ejected from plant	Moderate	Possible	M13	• No personnel to operate any plant or equipment that they are not trained and competent to do so. All operators must have VOC to operate. • Seatbelts must be worn at all times while operating (if fitted) • All operators are to assess the area of works and ensure the plant is capable of safely operating in that environment. • Remain in the cabin if plant starts to overturn. • Raise the alarm by notifying your supervisor over UHF Radio • A ROPS safety canopy is to be fitted to all plant working on slopes.	Supervisor in Site Inspection	M9

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Positive communications to be maintained at all times. • No loading over cabs of trucks • All trucks to be aware of Vehicle movement plan. • Loaded trucks/Moxies have right of way at all times		
	• Plant/Plant/Personnel Interaction	Moderate	Possible	M13	• Site speed limits are to be strictly adhered to (40 kph on site and 10kph past site office) • Persons entering the vicinity of plant are to ensure eye contact with the operator. • Operator is to stop any works and place the plant in a safe position, brake on, with attachments grounded and hands away from controls. • Ensure all mobile plant have reversing beepers/flashing lights and that workers are aware of plant/vehicle movements. • No personnel to stand beside trucks while loading/unloading. • Drivers are to remain inside the truck cab at all times while loading. • No excavator/loader is to place the load over cab of truck – tipper bin to be loaded from rear of cab only.	Supervisor in Site Inspection	M9

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Compactor to spot reversing trucks/Moxies at a distance of 5m • All personnel on foot must remain 30m away from operating plant. Positive communication to be established. Ensure you get operators attentions before proceeding through work area.		
	• Working at Depth	Moderate	Likely	H17	• Excavation method and controls are to be carefully assessed and executed. • Excavations greater than 1.5m deep (depending on conditions) must be benched, battered or shored against collapse and no storage of material or spoil on the edge of the excavation (i.e., maintain a 1:1 distance from the edge, that is the depth = distance from the edge) • Loose material is to be removed to avoid falling down batter	Supervisor in Site Inspection	L6
	• Fall into Excavations • Fall down batter	Moderate	Likely	H17	• Install barricades around all excavations greater than 1 metre in depth. • Only workers involved in the activity are to be present, if	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					leaving the excavation unattended and at the end of shift, a min 900mm high barricade is to be erected. (Back from edge @ 1:1 for depth) • Signage identifying that an excavation is present is to be erected. • Windrows (Berms) to be set at half the wheel height of the largest vehicle at top of batter.		
	• Exposure to contaminated Soil (Acid Sulphate Soil)	Minor	Likely	M12	• Direct skin contact with contaminated soil to be avoided. • Gloves are to be worn at all times when manually handling contaminated soil. • Contaminated soil to be handled with machinery and taken to an approved area for treatment. • When exposed to contaminated soil ensure work boots are washed down prior to entering any non– contaminated area.	Supervisor in Site Inspection	M8
	• Electrocution – loads come within contact of power lines.	Major	Possible	H18	• Establish power line clearance (ground to wire) before mobilising to site (6m)	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Supervisor to ensure sufficient room onsite for vehicle to safely park to enable unloading/loading of plant. • A non– conductive "High Voltage Overhead" 'H' Goal Post warning is to be erected at 6m on the approach from both sides. • Safety Observer/ spotter must be present, trained in this role and ONLY PERFORMS THIS FUNCTION if persons, mobile operating plant, vehicles or materials will enter the 6 metres exclusion zone. • The exclusion zone is to be 6 metres in all directions around the live service. • Excavation permit must be issued before ground is broken • DBYD to be in place only if working within the 6m zone • No excavator to conduct works near overhead power lines without supervisor authorisation. • JSA to be completed prior to start of works. • No ground penetration to commence without supervisor present.		

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• All operators to have excavation permit within cab. • All operators/ supervisors/ spotters to be vigilant around blue flagging – underground services		
	• Contact/ Damage with live services – underground	Major	Likely	H21	• All services in the area must be demarcated or relocated. • Potholing to determine service location – set up exclusion zones. • Ensure excavations are inspected daily. • Known Moxy/scraper crossovers to be depth checked for underground services to ensure upper surface remains intact. • Moxies/scrapers to avoid driving in same wheel ruts to avoid creating crevices	Supervisor in Site Inspection	M10
	• Plant contact or arc with overhead/ underground service • Electrocution • Fire • Damage to service	Major	Possible	H18	• IN THE EVENT THAT MOBILE PLANT ARCS OR CONTACTS LIVE ELECTRICITY: • No person is to approach plant or equipment that is still in contact with live overhead services unless the service is de–energised. • The operator of plant and equipment that has made	Supervisor in Site Inspection	M10

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					contact with live overhead service must not exit the plant unless the service is de–energised or the plant can be driven out and away from the service before exiting the plant. • If it is essential to leave the cabin or the operator's position due to fire or other life-threatening reason, then jump clear of the equipment. Do not touch the equipment and the ground at the same time. When moving away from the equipment, the operator should hop or shuffle away from the plant item (with both feet together) until at least eight metres from the nearest part of the crane or plant. Under no circumstances run or walk from the crane or item of plant as voltage gradients passing through the ground may cause electricity to pass through the body resulting in an electric shock.		
	• Plant / personnel contact causing injury/death. • Damage to Plant	Major	Likely	H21	• Daily plant prestart/JSA Start Card to be completed and all workers signed on.	Supervisor in Site Inspection	M14

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Damage to vehicles from flying debris. • Dust exposure.				• Site traffic flow plan to be completed and attached to daily pre– start. • DBYD/Excavation Permit to be in place. • No ground penetration to commence without supervisor present. • Competent operators to be used – VOC completed. • Traffic Control to be in place and set up as per approved TCP.		
Hauling Materials	• Plant/ Personnel interaction. • Plant/ Plant Contact	Major	Possible	H18	• Spotters must be used when trucks are reversing, in tight areas or where there is a risk of interaction with objects, overhead or underground services, personnel or other plant • A speed limit of 10kph will apply when driving close to people • Prior arrangement must be made to ensure drivers are aware of location and access routes • Traffic control in place (where required) • Personnel must remain in a position of safety at all times and	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					not put themselves between a moving part and a static object • 30m exclusion zone for all personnel on foot and operating plant • 10m exclusion zone for all underground services		
	• Driver unfamiliarity with site	Major	Possible	H18	• Seat belts must be worn • Licensed and competent drivers – ensure VOC completed. • Ensure approved routes are used for delivery to site – Contact Supervisor prior to entering site • Ensure drivers are aware of appropriate route to travel when on site. • Traffic control must be in place (where required) • PC signage with correct UHF Channel posted must be in place at all entrances to job site.	Supervisor in Site Inspection	M10
	• Working adjacent to steep embankment • Plant rolling or tipping	Major	Possible	H18	• Wear seat belts if fitted to the plant. • Remain in the operator cabin if plant starts to over turn • Raise the alarm by notifying your supervisor.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• A ROPS safety canopy is to be fitted to all plant working on slopes. • Always check with the stringer or grade checker for the grade • Use a spotter for reversing trucks and tipping. • No standing within the "fall zone" of a tipping truck. • Always ensure the ground is stable.		
	• Injury to member of public (Local landowner)	Major	Possible	H18	• Maintain appropriate access to landowner's properties at all times • Be aware of other people working near you. • Exclusion Zones when assessed is to be 1.5 times the height of the plant. • Localised traffic management plan. • Spotter to direct operator when working on a common access road for members of the public. • All machinery to have an operating flashing orange light and a reverse alarm, in the case of an excavator it must operate in forward or reverse. • Persons to keep clear of all working machinery, get the	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					operators attention before approaching any machinery. • STOP signs to be in place on haul roads where there is construction vehicle/landowner interaction • All changes must be communicated to affected residents • Any changes to public roads must be approved and done in consideration with the approved TMP • Appropriate barricading and signage must be in place prior to works commencing • All enquiries to be directed to the Superintendent/Supervisor • Ensure general public cannot access loading/unloading areas • All personnel on foot must remain 30m away from operating plant. Positive communication to be established. Ensure you get operators attentions before proceeding through work area		
	• Collision with personnel, vehicles or plant	Major	Possible	H18	• Reduce speed to 10 kph or stop until the hazard is no longer present.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Check that you are on the right channel. Stay alert for warnings over the radio. • All persons to be inducted and made aware of site rules, and daily operations through signing onto a pre– start and JSA prior to accessing work site		
	• Scraper Circuit	Major	Possible	H18	• Under no circumstances are unauthorised personnel to enter the scraper circuit • Should you be required to enter the scraper circuit – contact the area supervisor first and sign on to the JSA/pre– start • Observe movement of scrapers at all times • Maintain positive communications at all times • Give way to scrapers while in their working area • Scraper operators to be aware of their surrounding at all times • No speeding in scrapers permitted • Safe operating procedures must be followed at all times	Supervisor in Site Inspection	M10
	• Falling rocks from load or material blowing off	Major	Possible	H18	• Truck drivers must ensure that tailgates are closed and loads are secure	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	a truck or other vehicle				• Ensure drawbars/tailgates are free from debris • Dual wheels are to be free from rocks prior to leaving site		
	• Access to and from site adjacent to live traffic/pedestrians	Major	Possible	H18	• Drivers to stay away from edges and to notify supervisor of potentially dangerous issues relating to the project both on and off site • No hauling across public road without an approved TCP and traffic control is in place • Loaded trucks are to be given right of way • Haul road, batters and tipping areas to be maintained in a trafficable condition, including signage, windrows and fencing where required.	Supervisor in Site Inspection	M10
Tipping material from trucks Placement of Material	• Rollover, crush, collision, contact with power lines / power poles	Major	Possible	H18	• Spotter to ensure trucks do not tip near soft edges or on uneven ground. • Ground personnel must be clear of tipping range before the hoist is raised and must remain clear until the body has lowered • Spotters to remain behind or in front of tipping loads – not to the side	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Truck body must be fully lowered before driving off • Drivers and plant operators must maintain visual or UHF radio contact at all times • Ensure the wheels are always straight when tipping to avoid rollover, the drawbar is in alignment with the dog trailer • Ensure loads are tipped in a safe distance from excavations and trenches • Trucks to remain 5m from loading plant when tipping • Electrical safety observers must be utilised when tipping near energised services and must stay in contact with the driver at all times • Spotter not to use mobile phone while conducting spotting duties • No stockpiles or tipping areas to be placed under or adjacent to power lines • After a rain event an exclusion zone of 6m must be maintained to prevent bogging adjacent to a power pole		

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Compacting Materials	• Rollover • Collapsing excavation edges • Collision	Major	Possible	H18	• Operations involving plant, truck and personnel operating in the same area must be properly secluded to ensure at least 10m minimum separation, but at all times personnel must be well clear of all potential crush and collision zones associated with the plant and/or heavy vehicles. • Operators must always wear a seatbelt when operating • Compacting batters must not be across the slope, but up and down • Dozers are not to exceed safe operating procedures. Angle at approaches not to exceed 20 degrees or at manufacturers recommendations • Rolling patterns of 45-degree angles to be followed or create earth bund for edge protection • Do not roll parallel to any edge • Operators to be VOC'd • Where possible Operators should plan to compact or roll at angles to the edge of the batter that offer the highest safety • Never operate within the shear zone of any adjacent excavations	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Where a control or condition is not suitable and a hazard exists, the Operator must contact the Leading Hand or Supervisor immediately and ask for assistance.		
	• Damage to plant/operators and equipment when compacting embankments (rolling or tipping)	Major	Possible	H18	• Demarcate area (if possible) and ensure vehicle movements are communicated to all personnel in the area • Spotters to be used where required • All defects and damage are to be recorded on the daily plant pre– start and reported to the supervisor • All machinery to have an operating flashing orange light and a reverse alarm, all excavators must have an alarm operating in forward or reverse directions • Wear seat belts if fitted to the plant. • Remain in the operator cabin if the plant starts to overturn. • Raise the alarm by notifying your supervisor via UHF radio. • A ROPS safety canopy is to be fitted to all plant working on slopes.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Embankments will be compacted at regular levels to avoid any compaction on sloping surfaces. • Rolling patterns of 45-degree angles to be followed or construct earth bund for edge protection • Do not roll parallel to any edge		
	• Plant / vehicle / pedestrian interaction • Crushing injuries causing death	Major	Possible	H18	• Spotters to be used at all times • Spotters to be in view of driver/operator at all times • No personnel to be working in between two items of plant • Operators to look behind before proceeding to reverse • Personnel to stand at side of equipment (5m) distance, not rear of equipment • Distance between rollers, graders and skid steers to be 10m • Constant positive communication to be established and maintained	Supervisor in Site Inspection	M10
Silica Dust Exposure **– High Risk Construction Work**	• Generation of airborne RCS (silica dust) particles that may be inhaled by workers in the vicinity.	Major	Likely	H21	• Provide appropriate and properly fitted RPE and perform suitable fit testing for their application, where required for use.	Supervisor in Site Inspection	M10

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Training in the proper use of vacuum extraction devices including dry and wet vacuuming to hazardous activities. • Training in proper use of RPE devices with a minimum particulate (P) rating of P2, where required for use. • Training in use of tools and equipment specifically designed to eliminate or reduce dust, where required for use. • All containers in which hazardous substances and dangerous goods wastes are stored are to be suitably labelled. • Use of vacuum extraction cups/hoods on equipment including the use of hollow point drill bits with proprietary designed 'integrated' vacuum systems with a minimum M–Class rating • Application of wet cutting/misting/wet vacuuming to hazardous activities. • Collection of all RCS related dusts during the cutting process whilst still wet thereby eliminating		

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					the potential to release 'dry' RCS dust particles. • Use of suitable vacuums and PPE for clean– up activities with disposal of captured RCS dust particles to appropriately labelled repositories to eliminate or reduce RCS dust particles emanating from the clean– up process.		
Refuelling and servicing activities	• Being exposed to a hazardous substance including hose burst	Moderate	Likely	H17	• An SDS must be present with the fitter or refueller • Correct PPE • Anti-burst valves are to be used where possible and ensure hoses are maintained in good condition and not perished. • Have qualified mechanic or fitter carry out replacements or repairs.	Supervisor in Site Inspection	M9
	• Spillage contaminating the environment	Moderate	Possible	M13	• No refuelling to take place within 50m of any watercourse or drainage line • Spill kit available. • Notify Supervisor • Clean up as required by site requirements.	Supervisor in Site Inspection	L6
	• Machine not shut down, keys still in ignition.	Moderate	Possible	M13	• Before work commences the machines, engine must be shut	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					down, all hydraulic equipment lowered, keys removed. • Ensure cabins of sewing machines have returned to the manufacturers recommended stop position (cabin parallel to body or tracks)		
	• Machine only partly serviced and left in an unsafe manner (waiting for parts)	Moderate	Possible	M13	• Place an out of service tag on the ignition or isolation point. • Lock the machine cabin. • Notify the operator of machine and the supervisor that it is not to be used.	Supervisor in Site Inspection	L6
	• Trapped from unsupported engine, guarding covers and tipper trailer bodies	Moderate	Possible	M13	• Follow manufacturers safety information in operator's manual. • Mechanically support all engine covers and guards. • De-energise all automatic services, kinetic or gravitational or pneumatic or pressurised or hydraulic energy sources.	Supervisor in Site Inspection	L6
	• Machine not parked clear of other works.	Moderate	Possible	M13	• Refuelling and servicing should be conducted on a firm level surface preferably the lay down yard. • If a break down prevents the machine from being serviced in the lay down an exclusion zone must be maintained.	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Be aware of other people working near you. • Exclusion Zones when assessed is to be 1.5 times the height of the plant. • Spotter to direct operator when working on a common access road for members of the public. • All machinery to have an operating flashing orange light and a reverse alarm, in the case of an excavator it must operate in forward or reverse. • Persons to keep clear of all working machinery, get the operators attention before approaching any machinery. • Appropriate barricading and signage must be in place prior to works commencing. • All enquiries to be directed to the Superintendent/Supervisor • Ensure general public cannot access loading/unloading areas. • All personnel on foot must remain 30m away from operating plant. Positive communication to be established. Ensure you get		

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					operators attentions before proceeding through work area		
	• Fires	Moderate	Possible	M13	• A suitable class A. B (E) 9.0 kg fire extinguisher, that is within date and fully charged, is to be located no more than 10m from the refuelling site. • Switch off engines of plant and fuel truck. • All portable containers must be removed from back of truck and Utes to prevent static electricity. Refuelling of portable containers must be done on the ground.	Supervisor in Site Inspection	L6
	• After hours communications	Moderate	Possible	M13	• If refuelling is carried outside of construction site work hours that person must have a contact with others for when arriving on and leaving site. • These types of maintenance and servicing personnel must have completed a service provider or full induction before starting activities.	Supervisor in Site Inspection	L6
	• PLANT vs PLANT	Moderate	Possible	M13	• Refuelling and servicing should be conducted on a firm level surface preferably the lay down yard. • If a break down prevents the machine from being serviced in	Supervisor in Site Inspection	L6

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					the lay down an exclusion zone must be maintained. • Be aware of other people working near you. • Exclusion Zones when assessed is to be 1.5 times the height of the plant. • Spotter to direct operator when working on a common access road for members of the public. • All machinery to have an operating flashing orange light and a reverse alarm, in the case of an excavator it must operate in forward or reverse. • Persons to keep clear of all working machinery, get the operators attention before approaching any machinery. • Appropriate barricading and signage must be in place prior to works commencing • All enquiries to be directed to the Superintendent/Supervisor • Ensure general public cannot access loading/unloading areas. • All personnel on foot must remain 30m away from operating plant. Positive communication to be		

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

A	B	C			D	F	F
PROCEDURE / ACTIVITY (break the job down into steps)	**POTENTIAL HAZARDS (what can go wrong)**	**RISK ASSESSMENT (refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					established. Ensure you get operators attentions before proceeding through work area		
Clean up site. Pack up materials and tools	• Housekeeping	Moderate	Unlikely	M9	• All waste to be disposed at designated waste disposal area • Storage area and waste disposal area to have appropriate barricading and signage to ensure public do not access	Supervisor in Site Inspection	L5

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (in consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)
H18 - VH25	Unacceptable: Immediate action required to manage the risk.				
M13 - H17	Issue: Action required to manage the risk.				
L5 - M12	Monitor: Action advisable if cost beneficial.				
L1 - L4	Tolerable: Manage using routine procedures.				

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT – EARTHWORKS & EXCAVATION

Name	Roles	Signature

SAFE WORK METHOD STATEMENT
ROOFING

Task / Activity:	**ROOFING – HIGH RISK CONSTRUCTION WORK**	**SWMS Number:**	017
		Revision Number:	004
		Next Review Date:	12/06/2026
Purpose:	The purpose of this statement is to eliminate (or reduce as far as practicable) the possibility of an incident occurring where persons may suffer injury or work-related illness, or where property may be damaged. The Hierarchy of Controls must govern the choice of controls adopted. A consultative process will be used to complete this statement. The person(s) carrying out the work activities in this SWMS shall be involved in the SWMS preparation and be trained in the relevant procedures, processes, and requirements. ALL PERSONS INVOLVED IN CARRYING OUT THE NOMINATED TASK / ACTIVITY MUST FOLLOW THIS SAFE WORK METHOD STATEMENT.		
Project:	4870 Country Music Hall	**Date Prepared:**	5/03/2026
Project Address:	901 Dayboro Rd, Whiteside QLD 4503		
Company Address:	15 Nicol Way, Brendale, QLD, 4500		
Personnel responsible for implementing, monitoring and ensuring compliance with SWMS	Troy Pears		
Personnel Involved in Developing SWMS:	Zane Taylor (Owner/Director)		
	Adam Henricks (WHSE Manager)		

SAFE WORK METHOD STATEMENT
ROOFING

Legislative Act / Regulation:	Code(s) of Practice:	Australian / NZ Standards, Other:
Work Health and Safety Act 2011 (Qld & NSW) Work Health and Safety Regulation 2011 (Qld & NSW)	Hazardous Manual Tasks CoP 2021 (Qld & NSW) How to Manage Work Health and Safety Risks CoP 2021, (Qld & NSW) Managing the risks of plant in the workplace CoP 2021 (Qld & NSW) Managing risks of Hazardous Chemicals in the workplace CoP 2021 (Qld & NSW) Electrical safety CoP 2020 –Managing electrical risks in the workplace (Qld & NSW) First aid in the workplace CoP 2021 (Qld & NSW) Managing noise and preventing hearing loss at work CoP 2021(Qld & NSW) Managing the risk of falls at workplaces CoP 2021(Qld & NSW) Managing the work environment and facilities CoP 2021 (Qld & NSW) Work health and safety consultation, co-operation and coordination CoP 2021 (Qld & NSW)	(AS1966) (AS3195) (AS1674.2) (AS1674.2) (AS/NZS 3100) (AS1674.2) (AS1674.2) (AS1995) (AS2826) (AS1674.2)
Competencies/Training Required to undertake Activities:	**Specific Plant Required to Undertake Task:**	**Hazardous Substances Required for Task:**
EWP Certification Scissor Certification Working at Height Certification General Safety Induction	Hand Tools EWP SWMS Ladders Scaffold	Nil

SAFE WORK METHOD STATEMENT
ROOFING

AUTHORISATION			
We hereby request acceptance of this statement and confirm that the documented precautions / control measures will be complied with.			
Company Name:	Tallan Group	**Work Area/ Task Location:**	All Areas
ABN.:	22 649 005 096	**Onsite supervisor/person responsible for actioning controls:**	All Staff
Responsible Director			

Zane Taylor	Director		12/12/2025
Name	**Position**	**Signature**	**Date**

Note: All relevant signatures must be obtained prior to the commencement of work.

REVIEW								
Review Number	**1**	**2**	**3**	**4**	**5**	**6**	**7**	**8**
Name	Adam Henricks	Adam Henricks	Adam Henricks	Adam Henricks				
Date	12/06/2024	12/12/2024	12/06/2025	12/12/2025				
Review to be undertaken on a 6 monthly basis or when there is any change that will require the SWMS to be updated to reflect those changes.								

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

Training and Capabilities	• Personal injury, property damage &/or environmental incident.	Major	Likely	H21	• Ensure all persons entering site have a General Construction Induction Card (white card)
					• Ensure all relevant workers have undertaken training and/or received instruction in the installation, use and removal of edge protection systems, including control measures for use of height access equipment. Including:
					  • Reporting procedures for incidents
					  • Construction sites - General Construction Induction Card (white card)
					  • Correct use of height access equipment
					  • Correct use of all tools used.
					• Use of supervision where required (e.g. new starters or new equipment)
					• Ensure supervisors, foremen etc. are suitably experienced
						WHS Officer - Regular Training Audits and inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					in the type of work to be conducted • All workers are trained in this SWMS. • If working on EWPs for this task, ensure there are separate, dedicated SWMS in place for set-up/erection and that all workers/employees have relevant training and licensing. • Workers are in fit condition to work i.e. no signs of fatigue, alcohol or drugs.		

	Suspension Trauma (if using harness system)	Moderate	Possible	M13	• If a fall occurs:
					  • Ensure worker moves legs in the harness – push against foothold.
					  • If unconscious: Take at least 30-40 minutes to slowly move victim from kneeling to sitting to a supine position – sudden rush of blood can cause fatality
					  • Take harness out of service until it is deemed safe to use again by a competent person
						Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• In event of a fall and suspension - Workers should be trained to:
					  • Use a sit – type harness with padded legs to allow legs to remain horizontal
					  • Move their legs in the harness to push against any footholds
					  • Move their legs as high as possible and keep their head as horizontal as possible.
					  • *Note: The ability for workers to be able to follow these procedures should be a consideration when selecting harnesses for use*
					• Ensure all workers on-site are trained and familiar with emergency and evacuation procedures
					• Document and rehearse post-fall rescue plan. Ensure:		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Specific to site • All equipment required is present. • Suitable for effective rescue with 5 minutes (consider the type of work being conducted and lanyard attachment point) • If suspension is likely to exceed 5 minutes, use harness with foothold straps etc. • Self-rescue options are realistic. • Use of pre-rigged retrieval system wherever possible.		
Implement a Falls Emergency Rescue Plan (if using Harness)	• Personal injury from fall	Major	Possible	H18	• Use of a Spotter: • Trained first aid providers must be available • A reliable means to contact emergency services.	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
	• Suspension trauma	Moderate	Possible	M13	• Considerations for rescuing workers who have fallen and are suspended: • Whenever a person is wearing a harness, a rescue plan must be in place as suspension trauma can occur to persons who fall and remain in the harness for more than 5 minutes • The rescue must be able to commence immediately • The victim must be moved from suspension in stages – if moved too quickly from full suspension into a horizontal position serious injury or death can occur • If a suspension may last up to 5 minutes – foothold straps or other way of placing weight on legs must be provided.	Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
Arrival at site	• Hit by mobile plant/roadside	Major	Possible	H18	• Park working vehicles in driveway or allocated parking to avoid travelling across roads when delivering work equipment. • If setting up roadside – comply with local laws and permits. • Erect any barriers & signage necessary to keep others safe and aware. • Follow traffic management plan requirements. • Check constantly for changing hazards while exiting roof: • High visibility clothing worn at all times. • Do not stand behind reversing vehicles. • Allow sufficient distance from plant during operation (allow sufficient room for equipment failure – such as arm/boom failure or plant rollover) • Alertness at all times. Listen for: • Reversing alarms/beepers	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Calls from Plant Operators • Work positions should be in clear sight of plant operators. • NOTE: Some traffic management plans may say that pedestrians have right-of-way. Never assume this. Make visual and verbal *contact with plant operator as required*		
	• Personal injury, property damage &/or environmental incident.	Major	Possible	H18	• Ensure site-specific induction is undertaken (include location of amenities, first aid facilities, emergency plans and evacuation points, incident reporting, communication, contact persons etc.) • Assess mobile phone reception (alternative emergency communications procedures in place if no reception available) • Work site is exactly as detailed in Terms of Agreement or contract • Suitable access for all equipment required	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Suitable space for operation of equipment • Suitable lighting, including night-works (include flood lighting and operator head lamps as applicable) • Conduct risk assessment to identify potential hazards.		

Work area set up **– High Risk Construction Work**	• Hazardous manual tasks	Moderate	Likely	H17	• Movement of material from the delivery point to the installation area usually represents the greatest opportunity for damage or injury, particularly if being placed manually. Ensure:
					  • Use hand trucks to move heavy materials.
					  • Use team-lifts for heavier items.
					• Unload equipment/materials from vehicle:
					  • Lift within physical capabilities of individual
					  • Keep arms close to body (this excludes large/bulky items that are difficult to grasp,
						Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					or hot/cold objects that cannot be held against body) • Flat, even floor surface • Inspect equipment/materials prior to lifting. Check they are in a suitable condition (dry, stable, even distribution of weight, handles where possible, allows good grip, will not block vision, no chemical or other waste residue on the feet, etc.) • Suitable PPE provided (example: snug-fitting gloves, safety shoes with non-slip soles) • Trolley is next to unloading point so there is limited carry distance, when operating the trolley ensure:		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Push rather than pull the trolley where possible. • Do not pull large loads towards yourself. • Do not jerk to get the trolley moving. • Seek assistance if the load is too heavy or break down the load to make it lighter. • Use proper lifting techniques when loading and unloading. • When going down an incline remain on the uphill side • Bend your knees when placing items on the ground. • Do not overreach • Use mechanical hoisting equipment where the height of a roof or other factors		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					makes it impracticable to raise or lower equipment by hand.		
	• Contact with electricity	Major	Possible	H18	• Locate: • Any electrical cabling, power lines, gas pipes, water pipes, air conditioning ducts etc. prior to work commencing. • Power cables should be redirected, or power isolated for the duration of the work where necessary. • Equipment: • All power tools and leads are Tested and Tagged and are current • Pre-inspect equipment. • If equipment is damaged, do not use it. Take out of service, apply Lock-out/tag-out (LOTO) procedures	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					and inform supervisor immediately. • Locate and maintain awareness aware of any power lines when handling components. • Locate and maintain awareness aware of any extension leads while handling components.		
	• Contact with asbestos	Major	Possible	H18	• Determine presence of asbestos/ACM: • Competent person to identify if ACM is present (e.g. roof, eaves etc.) • Obtain as much information as possible on the location, type and condition of ACM. • If available, obtain a copy of the asbestos register for the site. • If older house, try to determine if roof had ever been asbestos in	Project Management Team – Prework inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					the past (roof space may still contain hazardous fibers) • Do not drill or disturb asbestos unless qualified to do so.		
	• Falls	Major	Possible	H18	• Inspect working surfaces / roof: • Check for moisture, dust or any other condition that may cause loss of stable footing • If not using fall arrest system: • Edge protection or scaffolding has been installed along all edges above 1.8m and provides safe access to the roof. • Access is available e.g. entry through edge protection or	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					other (do not climb on the outside of scaffold or over top rails of edge protection) • Suitable weather conditions (no strong wind, rain, storms etc.) • Fragile Roofs: • Conduct a visual inspection without stepping on the roof where possible. (If access is necessary, provide fall protection measures including safety harness with adequate anchorage along route of access • Provide warning signage/barrier around the identified fragile roof surfaces. E.g. skylight, polycarbonate roof etc.		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure height access and/or fall restraint/arrest systems are in place before starting work • Inspect working surfaces: • Check for moisture, dust or any other condition that may cause loss of stable footing • Access is available e.g. entry through edge protection or other (do not climb on the outside of scaffold or over top rails of edge protection) • Suitable weather conditions (no strong wind, rain, storms etc.) • Erect and inspect mobile scaffold as per manufacturers' instructions: • Level, plumb • Casters locked before accessing, not moved when persons on scaffold • Accessed by internal ladder only, do not climb on scaffold		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• Clear of penetrations or floor edges (by at least 1metre where possible)
					• Do not use steps or ladders on top of the work platform to gain extra height
					• Do not move the scaffold with persons or materials on it.
					• Before moving the scaffold ensure that it is clear of obstructions, both overhead and, at ground level
					• Erect and inspect ladders as per manufacturers' instructions:
					  • Ladder extends at least 1 m above the place of landing of the highest rung to be reached by the feet of any person working on ladder
					  • Ladders be set up on a level area on firm footing with the base located approximately a quarter of the vertical		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					height of the ladder from the wall • Secured against movement • Metallic, wire-reinforced or conductive ladders should be avoided around live electrical equipment • Face ladder when ascending/descending. Ensure 3 points of contact remain on ladder at all times • Load rating of at least 120kg • Correct size and length for job • No damage, clean and dry • Secured to work site (base & top) • Ensure only 1 person working from each ladder		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Holes or other openings through which a person can fall. Ensure: • All holes or openings are protected/closed from falls immediately after creating • Ensure the cover is secured to prevent movement • Use signage or other clearly marked hazard alert to identify hazard.		
	• Falling Objects	Major	Possible	H18	• Ensure roof laydown area is suitable for material delivery including: • Stockpile does not exceed weight limit • Stockpile can be stored in a safe secure manner. • Isolate the area below roof work (drop zone) wherever there is any danger of people being struck by falling material or tools.	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					• If drop zone cannot be isolated, toe boards and sturdy mesh are to be fixed to edge protection or scaffolding.
					• Exclusion zones must be in place to separate public from the works.
					• If building is occupied during works ensure there is adequate protection between the roof works and the interior of the building such as:
					  • Protective meshing, wire or slats
					  • Sturdy, secure ceiling such as timber materials secured to ceiling battens capable of withstanding falls.
					• Roof declared a 'No Go' area for all persons except those directly involved in the roof work.		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Ensure mechanical lifting equipment is functioning as manufacturer's instructions avoiding equipment failure allowing falling objects (hoists, lifting aids, pulleys, etc.): • Weight of materials to be lifted is known and displayed. • Lifting equipment in good working condition no sign of obvious damage, rusting • Instruction manuals for equipment use attached • All slings, ropes or chains are rated to relevant Standards, in good condition and tested • Undergone regular servicing / maintenance • Ropes used to be free of cuts or signs of external wear • Handlines to be minimum 12mm • When planning to store materials on the roof, check and ensure that the existing		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					roof structure can support the weight of the materials. • Liaise with other contractors at worksite to ensure no work undertaken underneath area during installation. Provide barricades and place safety signs "Caution Roof Work above."		
	• Suspension trauma	Moderate	Possible	M13	• Ensure workers are trained and instructed in the safe use of fall-arrest equipment and emergency rescue procedures. Fall arrest system: • Fall arrest system must comply with relevant Australian Standard • Formal inspection by competent person per manufacturer (6 monthly or more if exposed to hazardous environment) • Inspect all fall arrest equipment before each use.	Supervisor – Regular site inspections	L6
	• Heat stroke/ sunburn dehydration	Moderate	Possible	M13	• Wear suitable protective clothing • Sun brim on hard hat	Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Safety glasses - UV Rated • Use 30+ sunscreen on exposed skin areas • Adequate drinking water • Access to shade during breaks • Adequate breaks • Check weather conditions – do not work in extreme weather.		

Materials delivery on the roof **– High Risk Construction Work**	• Hazardous manual tasks	Moderate	Likely	H17	• Planning access to the roof location:
					  • Wherever possible, use mechanical methods to deliver materials to the roof e.g. crane.
					  • Ensure all crane operators, riggers and doggers are licenced, competent and trained in the activity.
						Supervisor – Regular site inspections	L6

	• Falling objects	Major	Possible	H18	• Ensure mechanical lifting equipment is functioning as manufacturer's instructions avoiding equipment failure	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					allowing falling objects (hoists, lifting aids, pulleys, etc.): • Weight of materials to be lifted is known and displayed. • Lifting equipment in good working condition no sign of obvious damage, rusting • Instruction manuals for equipment use attached • All slings, ropes or chains are rated to Australian Standards and in good condition and tested • Undergone regular servicing / maintenance • Ropes used to be free of cuts or signs of external wear • Hand-lines to be minimum 12mm		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• When planning to store materials on the roof, check and ensure that the existing roof structure can support the weight of the materials. • Liaise with other contractors at worksite to ensure no work undertaken underneath area during install. Provide barricades and place safety signs "Caution Roof Work above."		

Working on the Roof **– High Risk Construction Work**	• Falls	Major	Possible	H18	• Only perform works from a cladded section of the roof, EWP, Scaffolding or securely connect to fall restraint equipment.
					• When uninstalling roof sheets:
					  • work moving backwards from one end of the run, removing the sheet directly in front whilst standing on the next still secured sheet.
					  • Uninstall last sheet of the run from a cladded section of the roof, EWP,
						Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			

					Scaffolding or securely connect to fall restraint equipment.
					• When installing roof sheets:
					  • Install the first sheet from an adjacent cladded section of roof, EWP, scaffolding or fall restrain system.
					  • Work moving forwards from one end of the run, installing a sheet directly in front of you then move onto this sheet secured sheet to install the next sheet in the run.
					• Do not walk in middle of battens between rafters
					• Only walk on intersections of battens and rafters
					• Walk on strongest part of roof (e.g. for tin roof walk on screw lines)
					• Distribute materials evenly across roof. Do not travel across roof unnecessarily
					• Do not rush, run or play around		

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Use deliberate motion • Do not work close to edge of roof where possible • Do not work with back to edge of roof if within two metres of roof edge • Keep work area clear of trip hazards • Never lunge for dropped objects (maintain balance at all times) • Do not throw tools or material from roof, always lower in a controlled motion.		
	• Falling objects	Major	Possible	H18	• Wear hard hat • Wear tool belts to safely store fixing materials. • All tools to be connected to worker via lanyards or similar.	Supervisor – Regular site inspections	M10
	• Slips, trips	Moderate	Likely	H17	• Wear non-slip, closed-in footwear	Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Keep materials/equipment ordered and know where they are • If possible, keep all tools on a tool belt.		
	• Heat stress, sun burn	Moderate	Likely	H17	• Suitable protective clothing • Sun brim on hard hat • Safety glasses - UV Rated • Use 30+ sunscreen on exposed skin areas • Adequate drinking water • Access to shade during breaks • Adequate breaks • Check weather conditions – do not work if weather conditions change.	Supervisor – Regular site inspections	L6
	• Repetitive, sustained tasks, forced pushing movements – repetitive strain injury	Moderate	Possible	M13	• Do not overreach • Use the correct hand tool for each stage of the task • Take regular breaks	Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Maintain good posture avoiding awkward twisting and side bending • Practice stretching throughout the shift • Implement job rotation to ensure workers are not performing same task for 30 minutes at a time or 2 hours over entire shift.		
Install of Battens, Insolation, Roofing Iron **– High Risk Construction Work**	• Fall from Heights	Major	Possible	H18	• Roll from the Scaffold platform internal for battens • Use of Platform scaffold on External where insolation is rolled over the roof with a clamp and rope system • Lay sheets out and screwed in and then each sheet is used as a platform for next sheet install – site is fully encased by safety scaffold.	Supervisor – Regular site inspections	M10
On Completion	• Slips, trips, falls causing injury	Moderate	Likely	H17	• Clean up tools and any waste ensuring the site is left in clean and tidy condition	Supervisor – Regular site inspections	L6

SAFE WORK METHOD STATEMENT
ROOFING

A	B	C			D	F	F
PROCEDURE / ACTIVITY (Break the job down into steps)	**POTENTIAL HAZARDS (What can go wrong)**	**RISK ASSESSMENT (Refer to risk matrix at end of document)**			**CONTROL MEASURE (Control Measure to be in place in order to manage potential hazards)**	**MONITOR & REVIEW**	**Residual Risk**
		Consequence	**Likelihood**	**Rating (1 – 25)**			
					• Clean debris and ensure offcuts are removed from roof area.		
	• Contact with electricity.	Major	Possible	H18	• Disconnect power tool/extension leads from power point before winding up, so that you don't get a shock if the lead is damaged • Inspect leads and power equipment for damage • If safe to do so, remove isolation locks/tags and test appliance for function.	Supervisor – Regular site inspections	M10
	• Contamination of waterways and water catchment	Major	Possible	H18	• Dispose of off-cut materials in bins provided onsite. • Dispose of empty containers / bags in approved waste containers • Do not wash out tools or containers where residue can enter waterways or drains.	Supervisor – Regular site inspections	M10
	• Public safety	Major	Possible	H18	• If acceptable, remove or add barricades, contact supervisor and return as agreed.	Supervisor – Regular site inspections	M10

SAFE WORK METHOD STATEMENT
ROOFING

INSTRUCTIONS TO COMPLETE THE WORK METHOD STATEMENT

PREPARATION OF SWMS
Select the relevant persons to develop the SWMS
Ensure all sections are completed
Column A – Identify, in working sequence, each activity step. (In consultation with workers involved)
Column B – Identify the Hazards associated with each step.
Column C – Refer to Risk Assessment Tables to determine Likelihood, Consequences and Risk Rating
Column D – Determine appropriate Control Measures in accordance with the 'Hierarchy of Controls'.
Column E – Allocate the responsibility. (e.g. - By supervisor daily)
Submit the SWMS to the relevant person/s for approval.
Relevant person/s to evaluate the SWMS for approval. Any changes required must be made before approval. Any changes after approval will be indicated by a Revision Number and must be re-submitted for approval.
Conduct a specific training meeting or toolbox talk to train all persons involved in the SWMS activities and have them sign the Training/Toolbox Record. If the SWMS is revised (Rev. No.), then repeat this process.

RISK MATRIX

A hazard is anything that has the potential to cause harm or damage.

	CONSEQUENCE				
LIKELIHOOD	**Insignificant**	**Minor**	**Moderate**	**Major**	**Critical**
Almost Certain	M (11)	H (16)	H (20)	VH (23)	VH (25)
Likely	M (7)	M (12)	H (17)	H (21)	VH (24)
Possible	L (4)	M (8)	M (13)	H (18)	H (22)
Unlikely	L (2)	L (5)	M (9)	M (14)	H (19)
Rare	L (1)	L (3)	L (6)	M (10)	H (15)

H18 - VH25	Unacceptable:	Immediate action required to manage the risk.
M13 - H17	Issue:	Action required to manage the risk.
L5 - M12	Monitor:	Action advisable if cost beneficial.
L1 - L4	Tolerable:	Manage using routine procedures.

HIERARCHY OF CONTROL
Elimination
Substitution
Engineering
Administration
PPE

SAFE WORK METHOD STATEMENT
ROOFING

TOOLBOX / TRAINING RECORD – I have read and understood SWMS -				
Toolbox/Training Conducted by:	**Name:**		**Signature:**	

We, the undersigned, confirm that this Safe Work Method Statement has been explained to us and that we understand its contents. We are able to comply with these requirements.

We also confirm that we understand its purpose of reducing, as far as possible, the chance of incidents occurring. We will report any non-compliance of this SWMS to a relevant person/supervisor.

ALL PERSONS INVOLVED IN THE WORKS MUST COMPLETE THE FOLLOWING, PRIOR TO START OF WORKS.

Name	Roles	Signature

SAFE WORK METHOD STATEMENT
ROOFING

Name	Roles	Signature