

GOVERNMENT OF INDIA
MINISTRY OF COAL
DIRECTORATE OF MINES SAFETY

COAL MINE INSPECTION REPORT

SYNTHETIC PROTOTYPE DOCUMENT — FOR AI/ML PROTOTYPE DEVELOPMENT ONLY

Inspection Report No.	DMS/WR/2026/8347
Inspection Date	18 July 2026
Report Date	22 July 2026
Mine ID	MH-CM-047
Mine Name	Bhiravadi Coal Mine, Zone-B
Operator	Bhiravadi Mining Corporation Ltd.
Inspection Type	Periodic Safety Inspection

1. MINE DETAILS

State	Maharashtra
District	Chandrapur
Village	Bhiravadi, Taluka: Ballarpur
Coordinates	19.9156° N, 79.3842° E
Mining Method	Underground Bord and Pillar
Mine Status	Active
Working Depth	220 – 280 meters below surface

2. INSPECTING OFFICER

Inspector Name	Shri Ajay Verma
Designation	Deputy Chief Inspector of Mines
Regional Office	DMS Western Region, Nagpur
Inspection Team	Shri Pradeep Kumar (Safety Engineer)
Inspection Duration	18 – 20 July 2026

3. AREAS INSPECTED

Eastern working panel (Level -2), main haul road (surface), heavy equipment workshop, primary electrical substation, emergency assembly point, ventilation infrastructure.

4. INSPECTION OBSERVATIONS

Finding F-01:

During inspection of the eastern working panel at Level -2, inadequate air circulation was observed in areas remote from the main ventilation inlet. Real-time airflow measurements showed 1.9 m/s against a minimum requirement of 2.5 m/s. The ventilation ducting in this section exhibits visible wear and multiple seams. This deficiency has been recorded in the inspection report from the preceding inspection period, indicating that earlier recommendations for duct replacement have not been implemented.

Finding F-02:

Examination of the roof support system in the active working panel revealed significant deterioration of installed rock bolts. Structural integrity tests indicated that approximately 12 out of 60 bolts inspected show corrosion-induced loss of tensile strength. No roof fall incidents have occurred to date, however this represents a critical stability concern requiring immediate remedial intervention to prevent potential hazards.

Finding F-03:

The Load-Haul-Dump (LHD) equipment in the underground section showed incomplete maintenance records for three operational machines. One vehicle was operated beyond its scheduled service interval. Brake performance testing was not documented for the past three months. Although no equipment failures occurred during the inspection period, these gaps in maintenance documentation present a risk of unexpected operational failure.

Finding F-04:

The primary electrical substation serving underground operations was inspected and found to have moisture accumulation in several cable junction boxes. Insulation resistance measurements on three main distribution circuits showed degraded readings below acceptable standards. Similar electrical safety deficiencies were noted during the immediately preceding inspection, and the prescribed corrective measures remain only partially implemented.

Finding F-05:

The main haul road surface exhibits significant deterioration over a stretch of approximately 200 meters, with multiple potholes and uneven grading creating hazardous conditions. Dust suppression systems in this zone were inoperative during the inspection period. Traffic management controls for haul road operations were observed to be inadequate. This is a new observation not previously documented.

Finding F-06:

Emergency preparedness infrastructure was examined. Emergency assembly points are properly designated and accessible. First aid facilities are available at designated locations. Emergency rescue personnel roster shows 14 trained personnel on record, which aligns with regulatory requirements. Overall emergency preparedness systems appear satisfactory with no critical gaps identified.

5. INSPECTOR'S REMARKS

The inspection has identified six observations spanning operational and safety domains. Two findings—ventilation deficiency and electrical installation concerns—represent recurring issues from the previous inspection cycle, indicating inadequate management follow-up. One finding—roof support corrosion—requires urgent remedial action due to its critical nature. The remaining observations pertain to equipment maintenance gaps, haul road conditions, and operational controls. Enhanced management focus on corrective action implementation and maintenance discipline is essential. A follow-up inspection is recommended within 60 days to verify closure of critical findings.

Inspector: Shri Ajay Verma, DCIM | Date: 22 July 2026 | Regional Office: DMS Western Region