

US Patent & Trademark Office

Patent Public Search | Text View

United States Patent	12411475
Kind Code	B2
Date of Patent	September 09, 2025
Inventor(s)	Uenishi; Daisuke et al.

Numerical control device and control method

Abstract

Provided are: a numerical control device with which it is possible to easily perform a cutting process; a control method; and a processing program. The numerical control device comprises: a processing program analysis unit that analyzes commands that a machine tool can perform simultaneously, from one line of the processing program for commanding the machine tool before and after the cutting process; and a simultaneous operation control unit that uses the analyzed commands that can be performed simultaneously, combines the operations that the machine tool can perform simultaneously, and controls the commanded simultaneous operations.

Inventors:	Uenishi; Daisuke (Yamanashi, JP), Oyamada; Tomohiro (Yamanashi, JP)
Applicant:	FANUC CORPORATION (Yamanashi, JP)
Family ID:	78524398
Assignee:	FANUC CORPORATION (Yamanashi, JP)
Appl. No.:	17/997746
Filed (or PCT Filed):	May 10, 2021
PCT No.:	PCT/JP2021/017706
PCT Pub. No.:	WO2021/230202
PCT Pub. Date:	November 18, 2021

Prior Publication Data

Document Identifier	Publication Date
US 20230350384 A1	Nov. 02, 2023

Foreign Application Priority Data

Publication Classification

Int. Cl.: G05B19/4155 (20060101); G05B19/402 (20060101)

U.S. Cl.:

CPC G05B19/4155 (20130101); G05B19/402 (20130101); G05B2219/34396 (20130101)

Field of Classification Search

CPC: G05B (19/4155); G05B (19/402); G05B (2219/34396)

References Cited

U.S. PATENT DOCUMENTS

Patent No.	Issued Date	Patentee Name	U.S. Cl.	CPC
5005134	12/1990	Nakashima et al.	N/A	N/A
2014/0114465	12/2013	Terada	700/194	G05B 19/4083
2015/0134105	12/2014	Iuchi	700/186	G05B 19/4155
2015/0227130	12/2014	Terada	700/186	B23B 3/162
2016/0282852	12/2015	Endou	N/A	G05B 19/4155
2017/0308060	12/2016	Matsubara	N/A	G05B 19/402
2018/0246498	12/2017	Ono	N/A	G05B 19/4155

FOREIGN PATENT DOCUMENTS

Patent No.	Application Date	Country	CPC
101339438	12/2008	CN	N/A
104076736	12/2013	CN	N/A
109213084	12/2018	CN	N/A
H08-249028	12/1995	JP	N/A
2009-193209	12/2008	JP	N/A
2012-141762	12/2011	JP	N/A
2018-142194	12/2017	JP	N/A
2019-070953	12/2018	JP	N/A
2012/105028	12/2011	WO	N/A
2013/118241	12/2012	WO	N/A
2014/038101	12/2013	WO	N/A

OTHER PUBLICATIONS

International Search Report issued in PCT/JP2021/017706; mailed Jul. 20, 2021. cited by applicant

Primary Examiner: Everett; Christopher E.

Attorney, Agent or Firm: Studebaker Brackett PLLC

Background/Summary

TECHNICAL FIELD

(1) The present invention relates to a numerical control device and a control method thereof.

BACKGROUND ART

(2) Typically, a numerical control device that controls, e.g., a machine tool executes, e.g., workpiece machining by a machining program (see, e.g., Patent Document 1). A machining program processing device described in Patent Document 1 calculates a correction reference point based on a tool tip point command position and a tool posture command angle commanded by the machining program, and rewrites the tool tip point command position with the position of the correction reference point. Patent Document 1: Japanese Unexamined Patent Application, Publication No. 2019-70953

DISCLOSURE OF THE INVENTION

Problems to be Solved by the Invention

(3) The numerical control device uses the machining program for workpiece cutting. Machining cannot be performed only by commanding of cutting conditions by the machining program. For this reason, various types of correction of, e.g., attachment of a tool and a coordinate system number associated with a tool length, a workpiece position, etc. need to be commanded before and after the program for performing operation under the commanded cutting conditions. However, although it is possible to perform cutting by commanding the necessary correction, this does not always result in efficient operation. For example, tool replacement and workpiece movement can be simultaneously commanded by a one-line program, and tool length correction and spindle rotation can also be simultaneously commanded by a one-line program in many cases. A worker who does not know that a machine tool can be simultaneously commanded will run an inefficient and lengthy machining program by commanding on different lines. For this reason, there has been a demand for easy and efficient execution of operation of the machine tool.

Means for Solving the Problems

(4) A numerical control device according to the present disclosure includes a machining program analysis unit that analyzes commands simultaneously executable by a machine tool from a one-line machining program for commanding the machine tool before and after cutting, and a simultaneous operation control unit that uses the analyzed simultaneously-executable commands to control simultaneous operation commanded according to a combination of the commands simultaneously executable by the machine tool.

(5) The method for controlling a numerical control device according to the present disclosure includes the step of analyzing commands simultaneously executable by a machine tool from a one-line machining program for commanding the machine tool before and after cutting, and the step of using the analyzed simultaneously-executable commands to control simultaneous operation commanded according to a combination of the commands simultaneously executable by the machine tool.

Effects of the Invention

(6) According to the present invention, operation of the machine tool can be easily and efficiently executed.

Description

BRIEF DESCRIPTION OF THE DRAWINGS

- (1) FIG. 1 is a diagram showing the configuration of a machining system;
- (2) FIG. 2 is a view showing the outline of a machine tool;

- (3) FIG. 3 is a view showing a specific example of a machining program;
 - (4) FIG. 4 is a flowchart showing the processing of a pre-machining code;
 - (5) FIG. 5 is a flowchart showing processing regarding a tool axis;
 - (6) FIG. 6 is a flowchart showing processing regarding a tool system command;
 - (7) FIG. 7 is a flowchart showing processing regarding an axial system command;
 - (8) FIG. 8 is a flowchart showing processing regarding a movement axial system;
 - (9) FIG. 9 is a flowchart showing processing regarding a peripheral device;
 - (10) FIG. 10 is a flowchart showing processing regarding a peripheral device;
 - (11) FIG. 11 is a flowchart showing the processing of a post-machining code P12;
 - (12) FIG. 12 is a flowchart showing processing regarding a tool axis;
 - (13) FIG. 13 is a flowchart showing processing regarding a tool system command;
 - (14) FIG. 14 is a flowchart showing processing regarding an axial system command;
 - (15) FIG. 15 is a flowchart showing processing regarding a movement axial system;
 - (16) FIG. 16 is a flowchart showing processing regarding a peripheral device;
 - (17) FIG. 17 is a flowchart showing processing regarding a peripheral device;
 - (18) FIG. 18 is a command classification table for the pre-machining code;
 - (19) FIG. 19 is a command classification table for the post-machining code;
 - (20) FIG. 20 is an example of tool axis movement according to a certain pre-machining code P11;
- and

(21) FIG. 21 is an example of tool axis movement according to a certain post-machining code P12.

PREFERRED MODE FOR CARRYING OUT THE INVENTION

(22) Hereinafter, an embodiment of the present invention will be described as one example. FIG. 1 is a diagram showing the configuration of a machining system 1. As shown in FIG. 1, the machining system 1 includes a numerical control device 2 and a machine tool 3.

(23) The numerical control device 2 is a device that controls the machine tool 3 to perform, e.g., predetermined machining. The numerical control device 2 includes a control unit 21. The control unit 21 is a processor such as a central processing unit (CPU), and functions as a machining program analysis unit 211 and a simultaneous operation control unit 212 by executing programs stored in a storage unit (not shown).

(24) The machine tool 3 is a device that performs the predetermined machining such as cutting, tool measurement, etc. based on control by the numerical control device 2. FIG. 2 is a view showing the outline of the machine tool 3.

(25) The machine tool 3 includes, for example, a motor driven to machine a workpiece 41, a spindle and a feed shaft attached to the motor, a jig and a tool for each of these shafts, and a table 42 for fixing the workpiece 41. The machine tool 3 drives the motor based on an operation command output from the numerical control device 2, thereby performing the predetermined machining. Specifically, the machine tool 3 includes a cutting tool 31, a turret 32, the table 42.

(26) Plural types of cutting tools 31 are prepared according to a purpose for machining. Each cutting tool 31 is replaced while being attached to a dedicated tool holder. A specific tool number is assigned to each cutting tool 31.

(27) The turret 32 is a substantially discoid structure provided with a plurality of grips at an outer periphery. The turret 32 turns about a rotation axis C1 at a turning position shown in FIG. 2. The turret 32 turns to move the cutting tool 31 to a position facing the spindle 34.

(28) A work table 33 is a mechanism that movably supports the workpiece 41 in a right-left direction (an X-direction) and a front-back direction (a Y-direction). An X-axis motor, a Y-axis motor, an encoder, etc. (all not shown) are provided at the work table 33. The machine tool 3 of the present embodiment moves the tool 31 held by the spindle 34 in an up-down direction (a Z-direction) while moving the workpiece 41 in the X-direction and the Y-direction, thereby machining the workpiece 41.

(29) Next, operation of the numerical control device 2 will be described. The machining program

analysis unit **211** analyzes commands simultaneously executable by the machine tool **3** from a one-line machining program for commanding the machine tool **3** before and after cutting. Using the analyzed simultaneously-executable commands, the simultaneous operation control unit **212** controls simultaneous operation commanded according to a combination of the commands simultaneously executable by the machine tool.

(30) The machining program described herein includes, as pre-machining codes before cutting, a tool number for replacement of the cutting tool **31**; a tool correction number for tool length and diameter correction; settings of a workpiece coordinate system and a movement management coordinate system; movement axis and speed of the cutting tool **31**, the workpiece **41**, or the table **42** in the coordinate system; a spindle rotation number and spindle control; rotation axis clamping and unclamping; cutting fluid control, tapered surface cleaning control, and center-through control; and measuring machine control.

(31) Further, the machining program includes, as post-machining codes after cutting, homing; a homing axis and a movement speed; settings of the coordinate system and the movement management coordinate system; a tool number for replacement of the cutting tool **31**; rotation axis clamping and unclamping; and the spindle control and the cutting fluid control.

(32) FIG. **3** is a view showing a specific example of the machining program. The example of the machining program shown in FIG. **3** includes a machining program **P1** and machining program operation description **P2**. The machining program **P1** includes a pre-machining code **P11** and a post-machining code **P12**.

(33) FIG. **4** is a flowchart showing the processing of the pre-machining code **P11**, and FIG. **11** is a flowchart showing the processing of the post-machining code **P12**. The machining program analysis unit **211** analyzes corresponding commands according to later-described command classification tables shown in FIGS. **18** and **19** from the machining program **P1** including the commands of the pre-machining code **P11** and the post-machining code **P12**. The simultaneous operation control unit **212** controls the simultaneous operation according to the flowchart of FIG. **4** or **11**.

(34) In Step **S1** of FIG. **4**, the machining program analysis unit **211** reads the pre-machining code **P11** of the machining program from the storage unit (not shown). In Step **S2**, the machining program analysis unit **211** analyzes corresponding commands according to the command classification table shown in FIG. **18** from the commands of the pre-machining code **P11**. Note that the command classification table will be described in detail later.

(35) In Step **S3**, the simultaneous operation control unit **212** executes tool replacement operation. The tool replacement operation in Step **S3** will be described later.

(36) The outside of a tool replacement region in Step **S3** indicates a tool position outside a region defined as the tool replacement region. For example, in a state immediately after completion of drilling, a tool tip end is at an R-point. In the case of a turret-type machining center, such a tool tip end is at a position apart from a tool replacement start position.

(37) The inside of the tool replacement region indicates a region in which a tool axis moves until completion after the start of the tool replacement operation. For example, in the case of the turret-type machining center, the inside of the tool replacement region indicates a region in which the tool moves out of the spindle in a Z+ direction from **Z0**. Moreover, the inside of the tool replacement region indicates, in the case of tool replacement for the turret-type machining center, a period until a spindle holds a tool by rotation of a turret and a grip of the turret moves apart from a holder after the grip has held the tool.

(38) In Step **S4**, the control unit **21** determines whether or not all types of operation have been completed. In a case where all types of operation have been completed (YES), the processing ends thereafter. In a case where all types of operation have not been completed (NO), the processing in Step **S4** is repeated again.

(39) FIGS. **5** to **10** are flowcharts showing specific processing of the tool replacement operation.

FIG. 5 is a flowchart showing the processing for the tool axis.

(40) In Step S11 of FIG. 5 after Step S2 of FIG. 4, the simultaneous operation control unit 212 starts moving the tool axis into the tool replacement region for starting the tool replacement operation. In Step S12, the simultaneous operation control unit 212 completes movement of the tool axis into the tool replacement region.

(41) In Step S13, the simultaneous operation control unit 212 starts tool replacement based on a tool number of a replacement tool system command. In Step S14, the simultaneous operation control unit 212 completes tool replacement.

(42) In Step S15, the simultaneous operation control unit 212 starts moving the tool axis into the tool replacement region. In Step S16, the simultaneous operation control unit 212 completes movement of the tool axis into the tool replacement region, and the processing subsequently proceeds to Step S4 of FIG. 4.

(43) FIG. 6 is a flowchart showing the processing for a tool system command. In Step S21 of FIG. 6 after Step S2 of FIG. 4, the simultaneous operation control unit 212 starts a pre-replacement tool system command. Specifically, the pre-replacement tool system command includes a command of a cancellation code of each function regarding a spindle orientation and the tool axis.

(44) In Step S22, the simultaneous operation control unit 212 completes the pre-replacement tool system command. In Step S23, the simultaneous operation control unit 212 determines whether or not tool replacement has been completed. In a case where tool replacement has been completed (YES), the processing proceeds to Step S24. In a case where tool replacement has not been completed (NO), the processing in Step S23 is repeated again.

(45) In Step S24, the simultaneous operation control unit 212 starts a post-replacement tool system command. Specifically, the post-replacement tool system command includes commands such as a spindle rotation number, the spindle or touch-trigger probe control, tool length correction, a tool length correction number setting, the movement management coordinate system, and a tool axis movement command. In Step S25, the simultaneous operation control unit 212 completes the post-replacement tool system command, and the processing subsequently proceeds to Step S4 of FIG. 4.

(46) FIG. 7 is a flowchart showing the processing for an axial system command. In Step S31 of FIG. 7 after Step S2 of FIG. 4, the simultaneous operation control unit 212 starts a pre-movement axial system command. Specifically, the simultaneous operation control unit 212 starts, as the pre-movement axial system command, a cancellation code of each function regarding rotation axis unclamping and axis movement.

(47) In Step S32, the simultaneous operation control unit 212 completes the pre-movement axial system command. In Step S33, the simultaneous operation control unit 212 determines whether or not axis movement according to a later-described movement axial system command started in Step S42 shown in FIG. 8 has been completed. In a case where axis movement has been completed (YES), the processing proceeds to Step S34. In a case where axis movement has not been completed (NO), the processing in Step S33 is repeated again.

(48) In Step S34, the simultaneous operation control unit 212 starts a post-movement axial system command. Specifically, the post-movement axial system command includes commands such as rotation axis clamping. In Step S35, the simultaneous operation control unit 212 completes the post-movement axial system command, and the processing subsequently proceeds to Step S4 of FIG. 4.

(49) FIG. 8 is a flowchart showing the processing for a movement axial system. In Step S41 of FIG. 8 after Step S2 of FIG. 4, the simultaneous operation control unit 212 causes the processing to proceed to Step S42 in a case where there is no interference and a pre-movement axial system command has been completed (YES). In a case where there is an interference or the pre-movement axial system command has not been completed (NO), the processing in Step S41 is repeated.

(50) In Step S42, the simultaneous operation control unit 212 starts a movement axial system command. Specifically, the movement axial system command includes commands such as an axis

movement command, the workpiece coordinate system, the movement management coordinate system, and a tool diameter correction number.

(51) In Step **S43**, the simultaneous operation control unit **212** completes the movement axial system command, and the processing subsequently proceeds to Step **S4** of FIG. **4**.

(52) FIG. **9** is a flowchart showing the processing for a peripheral device. In Step **S51** of FIG. **9** after Step **S2** of FIG. **4**, the simultaneous operation control unit **212** starts a pre-replacement peripheral device command. Specifically, the simultaneous operation control unit **212** starts, as the peripheral device command, processing a cutting fluid OFF command and an air blower OFF command.

(53) In Step **S52**, the simultaneous operation control unit **212** completes the pre-replacement peripheral device command. In Step **S53**, the simultaneous operation control unit **212** determines whether or not tool replacement has been completed. In a case where tool replacement has been completed (YES), the processing proceeds to Step **S54**. In a case where tool replacement has not been completed (NO), the processing in Step **S53** is repeated.

(54) In Step **S54**, the simultaneous operation control unit **212** starts a post-replacement peripheral device command. Specifically, the simultaneous operation control unit **212** starts, as the post-replacement peripheral device command, the cutting fluid control. Specifically, the simultaneous operation control unit **212** starts a cutting fluid ON command, an air blower ON command, and a center-through ON command. In Step **S55**, the simultaneous operation control unit **212** completes the post-replacement peripheral device command, and the processing subsequently proceeds to Step **S4** of FIG. **4**.

(55) FIG. **10** is a flowchart showing the processing for a peripheral device. In Step **S61** of FIG. **10** after Step **S2** of FIG. **4**, the simultaneous operation control unit **212** determines whether or not tool replacement is in progress. In a case where tool replacement is in progress (YES), the processing proceeds to Step **S62**. In a case where tool replacement is not in progress (NO), the processing in Step **S61** is repeated.

(56) In Step **S62**, the simultaneous operation control unit **212** starts an in-replacement peripheral device command. Specifically, the simultaneous operation control unit **212** starts, as the peripheral device command, processing a tapered surface cleaning command for cleaning tapered surfaces of the spindle and the tool. In Step **S63**, the simultaneous operation control unit **212** determines whether or not tool replacement has been completed. In a case where tool replacement has been completed (YES), the processing proceeds to Step **S64**. In a case where tool replacement has not been completed (NO), the processing in Step **S63** is repeated again.

(57) In Step **S64**, the simultaneous operation control unit **212** completes the in-replacement peripheral device command, and the processing subsequently proceeds to Step **S4** of FIG. **4**.

(58) FIG. **11** is a flowchart showing the processing of the post-machining code **P12**. In Step **S101** of FIG. **11**, the machining program analysis unit **211** reads the post-machining code **P12** of the machining program from the storage unit (not shown).

(59) In Step **S102**, the machining program analysis unit **211** analyzes corresponding commands according to the command classification table shown in FIG. **19** from the commands of the post-machining code **P12**. Note that the command classification table will be described in detail later.

(60) In Step **S103**, the simultaneous operation control unit **212** executes the tool replacement operation. The tool replacement operation in Step **3103** will be described later. In Step **S104**, the control unit **21** determines whether or not all types of operation have been completed. In a case where all types of operation have been completed (YES), the processing ends thereafter. In a case where all types of operation have not been completed (NO), the processing in Step **S104** is repeated again.

(61) FIGS. **12** to **17** are flowcharts showing specific processing of the tool replacement operation. FIG. **12** is a flowchart showing the processing for the tool axis.

(62) In Step **S111** of FIG. **12** after Step **S102** of FIG. **11**, the simultaneous operation control unit

212 starts moving the tool axis into the tool replacement region for starting the tool replacement operation. In Step **S112**, the simultaneous operation control unit **212** completes movement of the tool axis into the tool replacement region.

(63) In Step **S113**, the simultaneous operation control unit **212** determines whether or not a tool number of a replacement tool system command has been commanded, thereby determining whether or not tool replacement is to be performed. In a case where the tool number of the replacement tool system command has been commanded (YES), the processing proceeds to Step **S114**. In a case where the tool number has not been commanded (NO), the processing proceeds to Step **S117**.

(64) In Step **S114**, the simultaneous operation control unit **212** starts tool replacement based on the tool number of the replacement tool system command. In Step **S115**, the simultaneous operation control unit **212** completes tool replacement.

(65) In Step **S116**, the simultaneous operation control unit **212** starts moving the tool axis into the tool replacement region.

(66) In Step **S117**, the simultaneous operation control unit **212** completes movement of the tool axis into the tool replacement region, and the processing subsequently proceeds to Step **3104** of FIG. **11**.

(67) FIG. **13** is a flowchart showing the processing for a tool system command. In Step **S121** of FIG. **13** after Step **S102** of FIG. **11**, the simultaneous operation control unit **212** starts a pre-replacement tool system command. Specifically, the pre-replacement tool system command includes a command of a cancellation code of each function regarding a spindle orientation and the tool axis.

(68) In Step **S122**, the simultaneous operation control unit **212** completes the pre-replacement tool system command, and the processing subsequently proceeds to Step **S104** of FIG. **11**.

(69) FIG. **14** is a flowchart showing the processing for an axial system command. In Step **S131** of FIG. **14** after Step **S102** of FIG. **11**, the simultaneous operation control unit **212** starts a pre-movement axial system command. Specifically, the simultaneous operation control unit **212** starts, as the pre-movement axial system command, a cancellation code of each function regarding rotation axis unclamping and axis movement. Then, in Step **S132**, the simultaneous operation control unit **212** completes the pre-movement axial system command, and the processing subsequently proceeds to Step **S104** of FIG. **11**.

(70) FIG. **15** is a flowchart showing the processing for a movement axial system. In Step **S141** of FIG. **15** after Step **S102** of FIG. **11**, the simultaneous operation control unit **212** causes the processing to proceed to Step **S142** in a case where there is no interference and a pre-movement axial system command has been completed (YES). In a case where there is an interference or the pre-movement axial system command has not been completed (NO), the processing in Step **S141** is repeated again.

(71) In Step **S142**, the simultaneous operation control unit **212** starts a movement axial system command. Specifically, the movement axial system command includes commands such as homing, an axis movement command, the workpiece coordinate system, and the movement management coordinate system. In Step **3143**, the simultaneous operation control unit **212** completes the movement axial system command, and the processing subsequently proceeds to Step **S104** of FIG. **11**.

(72) FIG. **16** is a flowchart showing the processing for a peripheral device. In Step **S151** of FIG. **16** after Step **S102** of FIG. **11**, the simultaneous operation control unit **212** starts a pre-replacement peripheral device command. Specifically, the simultaneous operation control unit **212** starts, as the peripheral device command, processing a cutting fluid OFF command.

(73) In Step **S152**, the simultaneous operation control unit **212** completes the pre-replacement peripheral device command, and the processing subsequently proceeds to Step **S104** of FIG. **11**.

(74) FIG. **11** is a flowchart showing the processing for a peripheral device. In Step **3161**, the simultaneous operation control unit **212** determines whether or not a tool number of a replacement

tool system command has been commanded, thereby determining whether or not tool replacement is to be performed. In a case where the tool number of the replacement tool system command has been commanded (YES), the processing proceeds to Step **S162**. In a case where the tool number is not commanded (NO), the processing proceeds to Step **S104** of FIG. **11**.

(75) In Step **S162**, the simultaneous operation control unit **212** determines, as a peripheral device command, whether or not tool replacement is in progress. In a case where tool replacement is in progress (YES), the processing proceeds to Step **S163**. In a case where tool replacement is not in progress (NO), the processing in Step **S162** is repeated again. In Step **S163**, the simultaneous operation control unit **212** starts an in-replacement peripheral device command. Specifically, the simultaneous operation control unit **212** starts, as the peripheral device command, processing a tapered surface cleaning command for cleaning the tapered surfaces of the spindle and the tool.

(76) In Step **S164**, the simultaneous operation control unit **212** determines whether or not tool replacement has been completed. In a case where tool replacement has been completed (YES), the processing proceeds to Step **S165**. In a case where tool replacement has not been completed (NO), the processing in Step **S164** is repeated again.

(77) In Step **S165**, the simultaneous operation control unit **212** completes the in-replacement peripheral device command, and the processing subsequently proceeds to Step **S104** of FIG. **11**.

(78) FIG. **18** is a view showing the command classification table for the pre-machining code. As shown in FIG. **18**, for a tool system command, an axial system command, and a peripheral device command, codes and command contents are associated with each other. FIG. **19** is a view showing the command classification table for the post-machining code. As shown in FIG. **19**, for a tool system command, an axial system command, and a peripheral device command, codes and command contents are associated with each other.

(79) Specifically, in FIGS. **18** and **19**, the commands executable simultaneously with tool replacement are classified into three classifications including the tool system command, the axial system command, and the peripheral device command. Each of the tool system command, the axial system command, and the peripheral device command is further classified into classifications including before, after, and during tool replacement and before, after, and during a movement command.

(80) The tool system command includes, for example, G-codes and M-codes regarding rotation of the cutting tool **31** attached to the spindle, tool length correction, the spindle control, and a movement axis parallel with the spindle. The axial system command includes, for example, G-codes and M-codes regarding a movement command for each axis for moving the table **42** on which the workpiece **41** is placed, a rotation axis clamping/unclamping command, correction of the tool diameter of the cutting tool **31**. The peripheral device command includes, for example, the cutting fluid control. These commands are stored as the command classification tables in the storage unit (not shown) of the numerical control device **2**.

(81) FIG. **20** shows an example of tool axis movement according to a certain pre-machining code **P11**. In the example shown in FIG. **20**, the tool axis is the Z-axis, the tool replacement region is from **Z100.** to **Z0**, and a Z-axis movement area is **Z-400**. In this case, a position at which the pre-machining code **P11** is commanded outside the tool replacement region is a start position, and the tool axis moves to **Z0** within the tool replacement region for tool replacement. Thereafter, the tool axis moves from **Z0** within the tool replacement region to **Z100.** at which tool replacement is to be executed, and thereafter, tool replacement is executed. After tool replacement, the tool axis moves to **Z0** within the tool replacement region, and thereafter, the position thereof is set at an end position.

(82) FIG. **21** is an example of tool axis movement according to a certain post-machining code **P12**. In the example shown in FIG. **21**, the tool axis is the Z-axis, the tool replacement region is from **Z100.** to **Z0**, and a Z-axis movement area is **Z-400**. In this case, a position at which the pre-machining code **P11** is commanded outside the tool replacement region is a start position, and the

tool axis moves to **Z0** within the tool replacement region for tool replacement. Then, the tool axis moves from **Z0** within the tool replacement region to **Z100**, at which tool replacement is to be executed, and thereafter, tool replacement is executed. After tool replacement, the tool axis moves to **Z0** within the tool replacement region, and thereafter, the position thereof is set at an end position. Note that **Z-400**, in FIGS. **20** and **21** indicates the limit of the stroke of the tool axis.

(83) In the pre-machining code **P11**, a G-code is **G920**, and indicates a pre-machining code for cutting. **T** indicates replacement of the cutting tool **31**, and **H** indicates a tool correction number. Moreover, **G54** indicates a workpiece coordinate system setting, **X** indicates a movement command in the X-axis direction, **Y** indicates a movement command in the Y-axis direction, **A** indicates a movement command in an A-axis direction, and **C** indicates a movement command in a C-axis direction. Further, **Z** indicates an approach position in tool length correction, **S** indicates a spindle rotation number for the spindle control, **M03** indicates forward rotation of the spindle, **M08** indicates that cutting fluid is turned ON, and **M100** indicates pre-movement unclamping of the A- and C-axes and post-movement clamping of the A- and C-axes.

(84) In the post-machining code **P12**, a G-code is **G930**, and indicates a post-machining code for cutting. **G930** indicates operation of fixed cycle cancellation, tool length and diameter correction cancellation, and homing of the X-axis, the Y-axis, the A-axis, the C-axis, and the Z-axis. Each of **X**, **Y**, **A**, **C**, and **Z** indicates the origin of each coordinate axis. Moreover, **M05** indicates spindle stop for the spindle control, **M09** indicates that cutting fluid is turned OFF, and **M101** indicates pre-movement unclamping of the A- and C-axes.

(85) Further, **T** indicates replacement of the cutting tool **31**, and when there is no command, only homing of the Z-axis is performed.

(86) The machine tool **3** shown in FIG. **2** performs the following operation steps (1) to (3), for example. (1) In tool replacement, the spindle **34** of the machine tool **3** moves up in the Z-axis direction, and the turret **32** turns. In upward movement in the Z-axis direction, i.e., as a command before replacement, the numerical control device **2** executes a pre-replacement tool system command and a pre-replacement peripheral device command. For example, the numerical control device **2** cancels tool length correction, a fixed cycle, etc. simultaneously with upward movement in the Z-axis direction. If the spindle is rotating, the machine tool **3** stops the spindle, and orients and sets the position of the spindle to a tool replacement position. Moreover, a measuring machine such as a touch-trigger probe is attached to the spindle, and if the touch-trigger probe is ON, the touch-trigger probe is turned OFF. Further, the cutting fluid and a peripheral device such as an air blower are turned ON/OFF. In addition, the numerical control device **2** cancels, as a pre-movement axial system command, tool diameter correction and coordinate rotation. Moreover, the numerical control device **2** unclamps the rotation axis if the rotation axis is clamped. (2) While the turret **32** is rotating, the work table **33** moves in the X-axis direction and the Y-axis direction. Moreover, while the turret **32** is rotating, the numerical control device **2** determines that replacement is in progress. During replacement, tapered surface cleaning is executed according to **M26** as a peripheral device command. Further, the numerical control device **2** may check not only a condition while the turret **32** is rotating, but also check whether or not there is an interference. (3) After tool replacement, the machine tool **3** executes movement of the spindle **34** in the Z-axis direction, the spindle control, the cutting fluid control, rotation axis clamping, etc.

(87) The numerical control device **2** according to the present embodiment uses the above-described machining program so that the steps of performing the simultaneous operation as in the steps (1) to (3) can be executed simultaneously. Thus, the numerical control device **2** uses, for example, codes such as **G920** and **G930** as described above so that a cycle time can be easily shortened and cutting can be easily performed.

(88) In addition to **X**, **Y**, and **Z**, rotation axis movement commands for, e.g., **A**, **B**, and **C** may be added to the pre-machining code **P11** and the post-machining code **P12**. For example, when commands for the A- and C-axes are made as movement axial system commands in the same block

as that for the X-, Y-, and Z-axes, the A- and C-axes move simultaneously with movement of the X- and Y-axes. When **M100** or **M101** is commanded in the same block, unclamping of **M11**, **M69**, and **M72** is simultaneously executed as pre-movement axial system commands if the A- and C-axes as the rotation axes are clamped upon upward movement in the Z-axis direction. **M100** is executed simultaneously with clamping of **M10**, **M68**, and **M71** after completion of the movement axial system commands.

(89) At this point, it is not necessary to wait until all pre-movement axial system commands and movement axial system commands are completed. For example, for the pre-movement axial system commands, operation for the X- and Y-axes which are axes unrelated to an unclamping state may be started without waiting for unclamping of the rotation axis. For example, for the post-movement axial system commands, in a case where a direct drive motor operable at high speed is employed and a rotation axis reaches a command position before the X- and Y-axes, operation for the rotation axis may be executed without waiting for the X- and Y-axes to reach the command position.

(90) As described above, according to the present embodiment, the numerical control device **2** includes the machining program analysis unit **211** that analyzes the commands simultaneously executable by the machine tool **3** from the one-line machining program for commanding the machine tool **3** before and after cutting and the simultaneous operation control unit **212** that uses the analyzed simultaneously-executable commands to control the simultaneous operation commanded according to the combination of the commands simultaneously executable by the machine tool **3**. With this configuration, the numerical control device **2** can simultaneously command the steps of performing the simultaneous operation. Thus, the numerical control device **2** can shorten the cycle time, and can easily and efficiently execute operation of the machine tool **3**.

(91) The steps of performing the simultaneous operation include replacement of the cutting tool **31**, tool length and diameter correction for the cutting tool **31**, the setting of the workpiece coordinate system, the setting of the movement management coordinate system, movement of the cutting tool **31**, the workpiece **41**, or the table **42** in the workpiece coordinate system, the spindle rotation control, the cutting fluid control, the air control, and the rotation axis clamping/unclamping control. With this configuration, the numerical control device **2** can simultaneously execute these steps in the machine tool **3**.

(92) The machining program includes, as the pre-machining codes before cutting, replacement of the cutting tool **31**, the tool correction number for tool length and diameter correction for the cutting tool **31**, the setting of the workpiece coordinate system, the setting of the movement management coordinate system, movement of the cutting tool **31** in the coordinate system, the spindle rotation control, and the cutting fluid control. With this configuration, the numerical control device **2** can properly compute and execute the pre-machining code.

(93) The machining program includes, as the post-machining codes after cutting, replacement of the cutting tool **31**, homing, the homing axis, the setting of the workpiece coordinate system, the setting of the movement management coordinate system, movement of the cutting tool **31**, the workpiece **41**, or the table **42** in the workpiece coordinate system, the spindle control, the cutting fluid control, and the air control. With this configuration, the numerical control device **2** can properly compute and execute the post-machining code.

(94) The post-machining codes may include, instead of homing and the homing axis, replacement of the cutting tool **31**, the setting of the workpiece coordinate system, and the movement command for the cutting tool **31** and the table **42** in the workpiece coordinate system. With this configuration, the numerical control device **2** can properly compute and execute the post-machining code.

(95) The machining program describes variables, the variables include the command values of replacement of the cutting tool **31**, the tool correction number for tool length and diameter correction for the cutting tool **31**, the workpiece coordinate system, the movement command for the cutting tool **31** and the table **42** in the workpiece coordinate system, homing, the homing axis, the spindle control, the additional axis control, the cutting fluid control, and the peripheral device

control, and the command values are commanded by the one-line machining program. The program invoked by the machining program executes the simultaneous operation of the machine tool **3** by means of the variables. With this configuration, the numerical control device **2** can properly execute the simultaneous operation.

(96) The program invoked by the machining program commands replacement of the cutting tool **31** and movement of the cutting tool **31** and the table **42** in the workpiece coordinate system in the same block.

(97) Thereafter, the invoked program commands the tool correction number for tool length and diameter correction for the cutting tool **31** and tool axis movement, the spindle control, the cutting fluid control, and the peripheral device control in the same block. With this configuration, the numerical control device **2** can properly execute each command.

(98) The embodiment of the present invention has been described above, but the present invention is not limited to the above-described embodiment. The advantageous effects described in the present embodiment have merely been listed as most suitable advantageous effects of the present invention, and the advantageous effects of the present invention are not limited to those described in the present embodiment.

EXPLANATION OF REFERENCE NUMERALS

(99) **1** Machining System **2** Numerical Control Device **3** Machine Tool **31** Cutting Tool **32** Turret **33** Work Table **41** Workpiece **42** Table **21** Control Unit **211** Machining Program analysis Unit **212** Simultaneous Operation Control Unit

Claims

1. A numerical control device comprising: a processor configured to: analyze commands simultaneously executable by a machine tool from a one-line machining program for commanding the machine tool before and after cutting; and use the analyzed simultaneously-executable commands to control simultaneous operation commanded according to a combination of the commands simultaneously executable by the machine tool, wherein a step of performing the simultaneous operation includes replacement of a cutting tool of the machine tool, a tool system command before, during, and after the replacement of the cutting tool, an axial system command before, during, and after axis movement, cutting fluid control, additional axis control, and peripheral device control.
2. The numerical control device according to claim 1, wherein the machining program includes, as a pre-machining code before the cutting, the replacement of the cutting tool, a tool correction number for tool length and diameter correction for the cutting tool, a setting of a workpiece coordinate system, a movement command for the cutting tool and a table in the workpiece coordinate system, spindle control, the additional axis control, the cutting fluid control, and the peripheral device control.
3. The numerical control device according to claim 2, wherein the machining program describes a variable, the variable including command values of the replacement of the cutting tool, the tool correction number for the tool length and diameter correction for the cutting tool, the workpiece coordinate system, the movement command for the cutting tool and the table in the workpiece coordinate system, a homing, a homing axis, the spindle control, the additional axis control, the cutting fluid control, and the peripheral device control and the command values being commanded by the one-line machining program, and a program invoked by the machining program executes the simultaneous operation of the machine tool by means of the variable.
4. The numerical control device according to claim 3, wherein the program invoked by the machining program commands the replacement of the cutting tool and movement of the cutting tool and the table in the workpiece coordinate system in an identical block, and thereafter, commands the tool correction number for the tool length and diameter correction for the cutting

- tool and tool axis movement, the spindle control, the cutting fluid control, and the peripheral device control in an identical block.
5. The numerical control device according to claim 1, wherein the machining program includes, as a post-machining code after the cutting, homing, a homing axis, spindle control, the additional axis control, and the cutting fluid control.
6. The numerical control device according to claim 5, wherein the post-machining code includes, instead of the homing and the homing axis, the replacement of the cutting tool, a setting of a workpiece coordinate system, and a movement command for the cutting tool and a table in the workpiece coordinate system.
7. A method for controlling a numerical control device, comprising: a step of analyzing commands simultaneously executable by a machine tool from a one-line machining program for commanding the machine tool before and after cutting; and a step of using the analyzed simultaneously-executable commands to control simultaneous operation commanded according to a combination of the commands simultaneously executable by the machine tool, wherein a step of performing the simultaneous operation includes replacement of a cutting tool of the machine tool, a tool system command before, during, and after the replacement of the cutting tool, an axial system command before, during, and after axis movement, cutting fluid control, additional axis control, and peripheral device control.
-