

P-999 Troubleshooting Matrix

If the P-999 pump exhibits abnormal behavior, consult the following diagnostic table before escalating to a Tier 2 mechanical work order.

Symptom	Potential Root Cause	Recommended Action
---------	----------------------	--------------------

---	---	---
-----	-----	-----

Zero Discharge Pressure	Pump has lost prime or suction line is blocked.	Vent the casing completely. Check suction strainer for debris.
-------------------------	---	--

Excessive Bearing Temp (>180°C)	Oil level too low, or oil is contaminated with water.	Drain bearing housing, flush, and refill with ISO VG 68 oil.
---------------------------------	---	--

High Frequency Vibration	Impeller imbalance or cavitation.	Check flow rate. If below 150 GPM, open discharge valve further.
--------------------------	-----------------------------------	--

Visible Leak at Shaft	Mechanical seal failure or degraded O-ring.	Shut down immediately. Replace seal cartridge and Part # VT-443-B.
-----------------------	---	--

Note: For any electrical faults related to the P-999 main drive, refer to the site Electrical Safety guidelines.