

Continuous Casting Machine (CCM) - Standard Operating Procedures

Dummy Bar Insertion and Mold Sealing (Start-Up)

Step 1. Inspect the copper mold inner surfaces for wear, scoring, or residue, and verify that the mold oscillator mechanism is free of mechanical play.

Step 2. Drive the dummy bar from the storage area up through the secondary cooling strand until the dummy bar head seats squarely into the bottom of the mold cavity.

Step 3. Pack the gaps around the dummy bar head using ceramic fiber rope or asbestos packing sheets to prevent liquid steel leakage during the initial pour.

Step 4. Place the specified steel or copper cone plug into the dummy bar head cavity to lock the starting head in place.

Step 5. Pour the required amount of mold casting powder uniformly across the cavity to provide proper lubrication and thermal insulation.

Step 6. Confirm that primary cooling water headers are pressurized to specification (inlet pressure around 4 bar, outlet around 2 bar) and flow interlocks are green before clearing the area for hot metal.