

Tundish Preheating and Ladle Teeming Preparation

Step 1. Inspect the tundish refractory lining for cracks, spalling, or excessive wear, and ensure the slide gate or stopper rod mechanism moves freely.

Step 2. Position the tundish over the preheating station and ignite the burners, ramping the temperature up gradually to prevent thermal shock, targeting a steady state above 1,000 degrees Celsius.

Step 3. Check that the submerged entry nozzle (SEN) or metering nozzle is securely bolted, aligned, and free of moisture or carbon deposits.

Step 4. Move the preheated tundish via the tundish car into the casting position directly above the mold centerline using manual alignment rods.

Step 5. Fill the tundish nozzle bore with the approved neutral filler sand or opening compound to prevent premature freezing when the steel hits.

Step 6. Verify that emergency oxygen lances and gas regulators on the casting platform are fully charged, leak-free, and set to 2.5 to 3 bar operating pressure.