

DAMAGE ASSESSMENT REPORT  
=====

Claim Number: CLM-2024-00847  
Assessment Date: March 18, 2024  
Assessor: M. Chen, Field Surveyor

Property Impact Overview  
-----

Water migrated from the second-floor bathroom through ceiling cavities into the kitchen and living room. Moisture meter readings exceeded 25% in affected drywall.

Room-by-Room Findings  
-----

- Bathroom:
- Vanity base swollen
  - Floor underlayment compromised near vanity
- Kitchen:
- Ceiling drywall requires replacement (approx. 64 sq ft)
  - Upper cabinets show water staining and swelling

- Living Room:
- Hardwood cupping across approximately 180 sq ft
  - Baseboards along north wall require replacement

Cause Confirmation  
-----

Physical inspection confirms a failed flexible faucet supply line as the origin of the water release. No roof leaks or exterior water intrusion were identified.

Recommended Remediation  
-----

1. Water extraction and drying (completed March 14-16)
2. Replace bathroom vanity and adjacent drywall
3. Replace kitchen ceiling and damaged cabinetry
4. Refinish or replace living room hardwood as needed

Preliminary Cost Range: USD 16,800 - USD 19,200