

**ATTACHMENT 20 – ADHESIVE ANCHOR REPAIR PROCEDURE SUBMITTED
BY MODERN CONTINENTAL COMPANY TO BECHTEL / PARSONS
BRINCKERHOFF DATED FEBRUARY 16, 2000
(4 pages)**



Adhesive Anchor Repair Procedure

INDEX STAMP

Contract No. 99119-C09B2	Paragraph 3.07 G
Specification Section (Spec-Seq-Rev)	
723.480 - 016 B	

CENTRAL ARTERY / TUNNEL

Permission To Proceed Does Not Constitute Acceptance Or Approval
Of Design Details, Calculations, Analysis, Test Methods, Or Materials
Developed Or Selected By The Contractor / Supplier And Does Not Relieve
The Contractor / Supplier From Full Compliance With Contract Requirements.

☐	1. Work May Proceed
☒	2N. Work May Proceed Subject To The Changes Indicated Resubmittal Not Required
☐	2R. Work May Not Proceed On Indicated Parts Resubmittal Required. Work May Proceed on Other Parts.
☐	3. Revise and Resubmit. Work May Not Proceed.
☐	4. For Information Only.

REVIEWER



B/P/S

Company

2/16/00

Date

January 28, 2000

Submittal No. 723.480 - 016 B
Adhesive Anchor Repair Procedure

At this time, the proposed revised anchor testing procedure is applicable to the adhesive anchors installed in the mock-up area in Ramp HOV. ~~The testing parameters described herein are not consistent with those included in Specification Section 723.480, Paragraph 3.07 G. Modern Continental is proceeding in accordance with direction received via Letter No. C09B2-0498, dated January 7, 2000, and reserves our rights to request an equitable adjustment to the Contract, as stipulated in Division I, Section 4.03.~~

AND LETTER NO C09B2-0498, JAN 7, 2000

Per the Direction received on the previous submittal, the proposed adhesive anchor repair procedure shall be modified as follows:

1. The failed anchor shall be removed from the concrete without damage to drill hole or adjacent concrete.
2. A hammer drill with a carbide bit shall be utilized to re-drill / ream the hole to create a surface free of debris from the removed anchor. All foreign matter will be removed from the hole.
3. A new adhesive anchor shall be installed per the approved submittal (Submittal 723.480-008 D, Section 3, entitled "Installation Procedure & Quality Control Program - Adhesive Anchoring System").

The new anchor shall be tested in accordance with the directive received in Letter No C09B2-0498, dated January 7, 2000. The revised loading requirement for proof testing shall be at 6,350 lb. tension.

4. The hanger attachment plate will be reinstalled and ~~the~~ bolted to the adhesive anchors. Anchor bolts shall be torqued in accordance with Manufacturer's recommendations.

After completion of the revised testing procedure in the Ramp HOV Mock-Up Area, MCC shall provide test results to the Engineer for review, and await further direction.

See attached for additional Comments

Submittal Review Comments

From Field Engineering Staff
C09B2

Submittal # 723.480-016 B

Responsible Field Engineer: J. BARRETT

Date review completed and initials: 1/31/00 JB

Field Engineer Comments:

THE PROPOSED REPAIR PROCEDURE SEEMS TO BE WRITTEN PERTAINING TO "THE" FAILED ANCHOR, AS IF THERE IS ONLY ONE. IT SHOULD PERTAIN TO "ANY" FAILED ANCHORS.

PER STEP 2 OF PROCEDURE: "ALL FOREIGN MATTER WILL BE REMOVED FROM THE HOLE". PROCEDURE FOR REMOVING FOREIGN MATTER SHOULD INCLUDE ① BLOWING OUT THE HOLE WITH COMPRESSED AIR; ② BRUSHING OUT THE HOLE (PREFERABLY WITH A STEEL OR BRONZE WIRE BRUSH—MANUFACTURER RECOMMENDS NYLON BRUSH); ③ BLOWING OUT THE HOLE AGAIN UNTIL NO DUST REMAINS.

Primary Reviewer BOB RICHARD

Date forwarded to Primary Reviewer _____