



PBX Truck Service
Box 26
Blumenort, MB R0A 0C0
204-326-3155



PACCAR



**** Reprint ****

Invoice: **01129924**
Date / Hour: 8/19/2026 2:47:01PM
Repair Order: 129924
Customer: 2603
Branch: 1
Total Invoice: \$3,815.13

Charge

Page 1 of 3

Bill To: FWF HAULING
50142 MUN 40 E
STE GENEVIEVE, MB R5J 0A5

Ship To: FWF HAULING
50142 MUN 40 E
STE GENEVIEVE, MB R5J 0A5
Shop Phone:
Email: info@fwfhauling.ca

Customer P/O:

Add User: Walter Wiens

Open Date: 08/12/2026

Completion Date: 08/18/2026

Salesperson:

Unit Number: WELDING ES

Model Year: 0

Make/Model: WELDING ESTIMATES WELDING ES

Type: WELDING

VIN: WELDING ESTIMATES

Meter: 1 None

Task: 1 12-000002 Axles - Non Driven - Rear - Align

Department: SWelding

Complaint: Remove and replace passenger side front spindle
Customer supplied spindle

Correction: - Inspect Front left spindle, the spindle was over heated and bent, the hub and brakes still attached
- Cut spindle end removing the nut, remove bub from spindle
- Remove mangled brakes and backing pad
- Cut spindle off removing mushroomed portion so we can clean up the remaining part of the spindle to measure the correct length of the axle tube
- Carefully cut the spindle, measure axle and square up the end of the axle tube ensuring to keep the measurement true to the correct length
- Clean up the end of the axle tube on the inside and measure with a bore guage ensuring the tube is round
- Use a straight grinder and carefully tune the ID of the axle tube until round
- Measure the customer supplied spindle and reference it to the axle ID, a sleeve is needed
- Locate the correct size material and machine the ID to fit the spindle to be a heat shrink fit. (interference fit)
- Heat and slide sleeve onto spindle and let cool
- Once cool, set up spindle in the lathe, double check the axle ID to ensure proper fitment
- Machine sleeve on the spindle to match the ID of the axle tube creating an interference fit
- Apply a thin layer of reaseto the sleeve, heat axle tube to correct temerature and slide spindle in place ensuring the spindle is fully seated
- Check the temperature of the spindle and axle tube, once cooled to the correct temp we fully welded the spindle using a certified welding wire, let axle and and spindle cool down completely
- Install brakes and backing plate, hook up wires that had to be cut in order to repair properly
- Install bearings into the oil hub, press in the seal, slide hub onto the spindle, insert tabbed lock washer, spin axle nut onto hub and set the correct bearing tension
- Install hub cap o ring onto the cap, install cap into the hub, fill hub with 75/90 gear oil, once filled to the correct level we inserted the cap plug
- Install wheels and torque lug nuts to MFG specs,
- Spin wheels and check bearing tension is still set correct (trailer came back to readjust bearings, took 30 min no charge)
- Lower trailer and take out

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	10-163-S860-S	SEAL,3.25X0.139 ORING 10K	EA	1.0	\$3.00	\$3.00
	21-88-S860-S	OIL CAP 2.75 CLEAR OIL CAP	EA	1.0	\$26.43	\$26.43
	46-32-S860-S	OIL CAP RUBBER PLUG	EA	1.0	\$5.58	\$5.58
	5-59-S860-S	HARDWARE, SPINDLE WASHER	EA	1.0	\$4.54	\$4.54
	6-109-S860-S	SPINDLE NUT	EA	1.0	\$12.02	\$12.02
	6-39-S860-S	NUT	EA	1.0	\$18.02	\$18.02
	7/16 LWGR8	LOCK WASHER	EA	1.0	\$0.76	\$0.76
	7/16 NFR8	HEX NUT	EA	1.0	\$1.82	\$1.82
	7/16X1-3/4NFR8	NINE THREAD CAP SCREW GR8	EA	1.0	\$4.97	\$4.97

**** See Last Page for Invoice Total ****



PBX Truck Service
Box 26
Blumenort, MB R0A 0C0
204-326-3155



Peterbilt of Steinbach
Independent Parts & Service Provider

PACCAR



Independent Field Service
Representative



**** Reprint ****

Invoice: **01129924**
Date / Hour: 8/19/2026 2:47:01PM
Repair Order: 129924
Customer: 2603
Branch: 1
Total Invoice: \$3,815.13
Charge

Page 2 of 3

Bill To: FWF HAULING
50142 MUN 40 E
STE GENEVIEVE, MB R5J 0A5

Ship To: FWF HAULING
50142 MUN 40 E
STE GENEVIEVE, MB R5J 0A5
Shop Phone:
Email: info@fwfhauling.ca

Customer P/O:

Open Date: 08/12/2026

Completion Date: 08/18/2026

Add User: Walter Wiens

Salesperson:

8-430-05-S860-S	DRUM	EA	1.0	\$1,056.56	\$1,056.56
B1210E-12-S860-S	BACKING C/W BRAKE ASSEMBLY	EA	1.0	\$180.23	\$180.23
WS/166280-100	WIRE CONNECTOR	EA	2.0	\$0.12	\$0.24
WS/3MC7100303967(90007,500428)	GRINDING WHEEL 5" STEEL	EA	1.0	\$19.23	\$19.23
)					
WS/3MC7100304007(90037)	CUTTING DISC 5" STEEL/INOX	EA	1.0	\$12.11	\$12.11
WS/3MC7100313189(90039)	CUTTING DISC 7" STEEL/INOX	EA	1.0	\$11.77	\$11.77
WS/83-6029	TIES NYLON CABLE	EA	4.0	\$0.24	\$0.96
WS/84-5006	SHRINK TUBE	EA	1.0	\$1.24	\$1.24

Task 1 Subtotals

Parts: \$1,359.48

Labor: \$1,440.00

Task 1 Subtotals \$2,799.48

Task: 2 18-000000 Wheels, Hubs and Bearings

Department: SWelding

Complaint: Inspect wheel seals on driverside front and back
and passenger side rear

Correction: - Remove oil hub caps on right front and rear, and left rear hubs
- Oil came out contaminated, the hub caps were all broken and the o-rings were marred up
- Inspect bearings and wheel seals, they appeared to be in good condition but bearings were not set to the correct tension
- Adjust bearings to the correct tension, spin wheels and check for play or being to tight, bearing adjustment is good.
- Install new hub caps and o- rings, fill hubs with 75/90 gear oil
- Install hub cap oil plug

ADVISEMENT, all tires are in poor condition and need replacement ASAP

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	21-88-S860-S	OIL CAP 2.75" CLEAR	EA	1.0	\$79.30	\$79.30
	46-32-S860--S	OIL CAP, RUBBER PLUG	EA	1.0	\$16.75	\$16.75
	WS/75/90-GEAR(223030-PAIL)	DELO SYNGEAR XDM DIFF OIL	EA	1.0	\$14.83	\$14.83

Task 2 Subtotals

Parts: \$110.88

Labor: \$320.00

Task 2 Subtotals \$430.88

Detail Tax Info:

GST Sales Tax #131808628 \$170.32
PST Sales Tax \$238.45
Total: \$408.77

Total Parts: \$1,470.36
Total Labor: \$1,760.00
Total Swelding Shop Supplies: \$176.00
Invoice Subtotal: \$3,406.36
Total Tax: \$408.77
Total Invoice: \$3,815.13

Payment Method

Terms

Due Date

Charge

Net due 15th

9/15/2026



PBX Truck Service
Box 26
Blumenort, MB R0A 0C0
204-326-3155



PACCAR



**** Reprint ****
Invoice: **01129924**
Date / Hour: 8/19/2026 2:47:01PM
Repair Order: 129924
Customer: 2603
Branch: 1
Total Invoice: \$3,815.13
Charge
Page 3 of 3

Bill To: FWF HAULING
50142 MUN 40 E
STE GENEVIEVE, MB R5J 0A5

Ship To: FWF HAULING
50142 MUN 40 E
STE GENEVIEVE, MB R5J 0A5
Shop Phone:
Email: info@fwfhauling.ca

Customer P/O:

Add User: Walter Wiens

Open Date: 08/12/2026

Completion Date: 08/18/2026

Salesperson:

REPRINT

WARRANTIES: EXCLUSIONS AND LIMITATIONS

Any and all warranties on the products sold by PBX Truck Service Inc. are those made by the manufacturer. All vendor products each carry their own designated warranty. The seller hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose and neither assumes nor authorizes any person for it any liability in connection with sale of said products.

PBX Truck Service Inc. obligation under this warranty does not include labour for removal and/or installation of the goods involved and described above, consumable parts such as filters, belts etc., and does not apply to any new or used parts and components supplied by the customer.

PBX Truck Service Inc. liability is hereunder being expressed as limited to repair or replacement of defective goods and excludes, without limiting, failure caused by misuse, abuse or neglect, indirect or consequential losses or any other financial losses (e.g.: downtime) caused by any warrantable failure(s).

TERMS AND CONDITIONS

20% handling charge on all returns

Late fees of 2% per month or 24% per year on any past balance due.

A surcharge of 2.5% may be applied for credit card payments.

Our payment terms are Net 15 unless otherwise stated.

The mention "COD" indicates immediate payment terms.

All return must be in original packaging

All electric or electronic parts, as well as special order parts, are non-returnable

No credit without this invoice or after 30 days of purchase date

Parts remain property of PBX Truck Service Inc. until full payment.