
## **Exercise 1:**



#### **Ordinary Cycle**

O1234

G21

G99

G28 U0 W0

M06 T0101

M03 S1200

G00 X55 Z5

Z0

G01 X-1 F.1

G01 Z1

G00 X50

G01 Z-100 F.1

G01 X51 Z-100

G00 Z1

G00 X48

G01 Z-75 F.1

G01 X49 Z-75

G00 Z1

G00 X46

G01 Z-75 F.1

G01 X47 Z-75

G00 Z1

G00 X44

G01 Z-75 F.1

G01 X45 Z-75

G00 Z1

G00 X42

G01 Z-75 F.1

G01 X43 Z-75

G00 Z1

G00 X40

G01 Z-75 F.1

G01 X41 Z-75

G00 Z1

G00 X38

G01 Z-50 F.1

G01 X39 Z-50

G00 Z1

G00 X36

G01 Z-50 F.1

G01 X37 Z-50

G00 Z1

G00 X34

G01 Z-50 F.1

G01 X35 Z-50

G00 Z1

G00 X32

G01 Z-50 F.1

G01 X33 Z-50

G00 Z1

G00 X30

G01 Z-50 F.1

G01 X31 Z-50

G00 Z1

G00 X28

G01 Z-25 F.1

G01 X29 Z-25

G00 Z1

G00 X26

G01 Z-25 F.1

G01 X27 Z-25

G00 Z1

G00 X24

G01 Z-25 F.1

G01 X25 Z-25

G00 Z1

G00 X22

G01 Z-25 F.1

G01 X23 Z-25

G00 Z1

G00 X20

G01 Z-25 F.1

G01 X21 Z-25

G00 Z1

G00 X28 Z-24

G01 X30 Z-40 F.1

G01 X31 Z-40

G00 Z-24

G00 X26

G01 X30 Z-40 F.1

G01 X31 Z-40

G00 Z-24

G00 X24

G01 X30 Z-40 F.1

G01 X31 Z-40

G00 Z-24

G00 X22

G01 X30 Z-40 F.1

G01 X31 Z-40

G00 Z-24

G00 X20

G01 X30 Z-40F.1

G01 X31 Z-40


G00 Z-24

G00 Z1

G28 U0 W0

M05

## **Exercise 2:**



#### **G71** Canned Cycle

O1234

G21

G99

G28 U0 W0

M06 T0101

M03 S1200

G00 X55 Z5

Z0

G01 X-1 F.1

G01 Z1

G00 X52

G71 U0.5 R1

G71 P10 Q20 U.1 W.1 F.1

N10 G01 X20 Z0 F.1

Z-25

X30 Z-40

Z-50

X40

Z-75

X50

Z-100

X55


N20 G00 Z5

G70 P10 Q20 F0.05

G28 U0 W0

M05

## **Exercise 3:**



### **G72** Canned Cycle

O1234

G21

G99

G28 U0 W0

M06 T0101

M03 S1200

G00 X55 Z5

Z0

G01 X-1 F.1

G01 Z1

G00 X55

G72 W0.5 R1

G72 P10 Q20 U.1 W.1 F.1

N10 G01 X50 Z-100 F.1

Z-75

X40

Z-50

X30

Z-40

X20 Z-25

Z0

Z5

N20 G00 X55


G70 P10 Q20 F0.05

G28 U0 W0

M05

## **Exercise 4**:

### RADIAL GROOVING



O1234

G21

G99

G28 U0 W0

M06 T0101

M03 S1200

G00 X45 Z5

Z0

G01 X-1 F0.1

Z2

G00 X42

G71 U0.5 R1

G71 P10 Q20 U0.2 W0.2 F0.1

N10 G01 X16 Z0

X20 Z-2

Z-33

X30 Z-43

Z-48

G02 X40 Z-53 R5

G01 Z-75

G01 X45

N20 Z2

G28 U0 W0

M05

M06 T0202

M03 S2000

G00 X42 Z2

G70 P10 Q20 F0.1

G28 U0 W0

M05

M06 T0303

M03 S800

G00 X21 Z-33

G75 R1


G75 X15 Z-26 P1000 Q500 R0 F0.1

G28 U0 W0

M05

#### **Exercise 5**:

# THREADING OPERATION



O1234

G21

G99

G28 U0 W0

M06 T0101

M03 S1200

G00 X35 Z5

Z0

G01 X-1 F0.1

Z2

G00 X35

G71 U0.5 R1.0

G71 P10 Q20 U0.2 W0.2 F0.1

N10 G01 X14 Z0

X16 Z-2

Z-20

X20 Z-25

Z-35

G03 X30 Z-40 R5

G01 Z-75

N20 G01 X35

G28 U0 W0

M05

M06 T0202

M03 S2000

G00 X35 Z2

G70 P10 Q20 F0.05

G00 X35

G28 U0 W0

M05

M06 T0303

M03 S800

G00 X35 Z-20

X17

G75 R1.0

G75 X10 Z-18 P1000 Q500 F0.1

G00 X35

G28 U0 W0

M05

M06 T0404

M03 S500

G00 X16 Z5

G76 P030060 Q100 R0.1

G76 X14.16 Z-17 P920 Q200 R0 F1.5


G00 X17

G28 U0 W0

M05

### **Exercise 6:**

#### **AXIAL DRILLING OPERATION**



O1238

G21

G99

G28 U0 W0

M06 T0101

M03 S1200

G00 X105 Z5

Z0

G01 X-1 F0.1

Z2

G00 X105

G71 U0.5 R1.0

G71 P10 Q20 U0.1 W0.1 F0.1

N10 G01 X36 Z0

X40 Z-2

Z-40

G03 X60 Z-50 R10

G01 Z-65

G02 X80 Z-75 R10

G01 X100

Z-100

N20 X105

G28 U0 W0

M06 T0202

M03 S2000

G00 X105 Z5

G70 P10 Q20 F0.05

G00 X105

G28 U0 W0

M05

M06 T0303

M03 S800

G00 X105 Z-40

G00 X41

G75 R1

G75 X30 Z-38 P1000 Q500 R0 F0.1

G00 X105

G28 U0 W0

M05

M06 T0404

M03 S500

G00 X40 Z50

G00 Z2

G76 P030060 Q100 R0.1

G76 X36.93 Z-37 P1533 Q200 F2.5

G00 X105

G28 U0 W0

M05

M06 T0505

M03 S700

G00 X0 Z50

Z2

G74 R1.0

G74 Z-30 Q1000 F0.1


G01 Z2

G28 U0 W0

M05

#### Exercise 7:

# SURFACE MILLING



#### BLANKSIZE:75X75X15 Depth of cut:2

ALL DIMENSIONS ARE IN MM

O1234

G21

G98

G91 G28 Z0

G91 G28 X0 Y0

M06 T01

M03 S1200

G00 G55 G90 X0 Y0

G43 H1 Z13

Z2

G40 G00 X25 Y15.85

G01 Z-2.0 F20

G01 X12.5 Y37.5 F100

G01 X25.0 Y59.15

G01 X50.0 Y59.15

G01 X62.25 Y37.5

G01 X50.0 Y15.85

G01 X25.0 Y15.85

G02 X12.5 Y37.5 R12.5

G02 X25.0 Y59.15 R12.5

G02 X50.0 Y59.15 R12.5

G02 X62.5 Y37.5 R12.5

G02 X50.0 Y15.85 R12.5

G02 X25.0 Y15.85 R12.5

G01 Z2

G00 X22.5 Y37.5

G01 Z-2 F20

G02 X22.5 Y37.5 I15 J0

G01 Z2


G00 Z100


G91 G28 Z0

G91 G28 X0 Y0

M05

#### **Exercise 8:**





O1234

G21

G98

G00 G91 G28 Z0

G00 G91 G28 X0 Y0

M06 T01

G00 G90 G55 X0 Y0

G43 H1 Z13

M03 S1500

Z5

G01 Z0.0 F100

M98P0014000

M70

M98P0014000

M80

M71

M98P0014000

M81

M70

M71

M98P0014000

M80

M81

G00 G90 Z5

G00 G91 G28 Z0

G00 G91 G28 X0 Y0

M05

M30

O4000

G00 G90 X5 Y5

G01 G91 Z-0.5 F100

G01 G90 X5 Y15

G02 X15 Y25 R10

G01 X35

G03 X30 Y30 R5

G03 X25 Y35 R5

G01 Y15

G02 X15 Y5 R10

G01 X5 Y5

G01 X15 Y5

G01 Y15

G01 X5

G00 Z0

G00 X10 Y10

G01 G91 Z-0.5 F100

G00 G90 Z0