Release Notes ZEISS INSPECT 2025

Table of Contents

ZEISS INSPECT 2025 Service Pack 3 1
ZEISS INSPECT 2025 Service Pack 2 Patch 3 4
ZEISS INSPECT 2025 Service Pack 2 Patch 2 4
ZEISS INSPECT 2025 Service Pack 2 Patch 1 4
ZEISS INSPECT 2025 Service Pack 2 6
ZEISS INSPECT 2025 Service Pack 1 9
ZEISS INSPECT 2025 13
Notes for Upgrading from ZEISS INSPECT 2023 18
ZEISS INSPECT Third Party Notices 19
System Requirements 20
Version Information ZEISS INSPECT 2025 21
Necessary Drivers for Sensors 22

ZEISS INSPECT 2025 Service Pack 3

Product version: 2025.4.0.398

The 2025.4.0.398 replaces the temporarily available version 2025.4.0.394, which was withdrawn due to problems with starting the software successfully. This problem is fixed now with 2025.4.0.398. Customers who updated to Service Pack 3 version 2025.4.0.394 already should update to version 2025.4.0.398.

- INSPECT Optical 3D – VMR / Measuring setup instructions: Measuring setup instructions are now displayed again when active measuring setup is switched for calibration series execution.
- ZEISS T-SCAN hawk 2 - Workflow assistant: The workflow assistant shows hyperscale recalibration by default as an option.
- Script Interpreter: With ZEISS INSPECT 2025 Service Pack 3 the python version is updated from 3.9.21 to 3.9.25.
- GD&T - Position tolerances: A bug has been fixed where the tolerance zone of a position check with MMR and an associated element was unexpectedly shifted. This could lead to incorrect results. Existing projects can be updated through an "Edit Creation Parameters" of the position check. (8103439108)
- GD&T - Datum system under Material requirement: Under rare circumstances multiple tolerances with datum system under material requirement that are computed together could result in wrong results. This is fixed now. (CNR-388595-D3X4X0)
- INSPECT Optical 3D - Camera tab / “Compute Exposure Times For Defined Area”: Now, the button “Compute Exposure Times For Defined Area” in the camera tab is available/usable when an appropriate sensor driver license such as "Sensor driver ATOS Q" is available. (8103423778)
- Apps: A possible software crash has been fixed in combination with apps and running multiple instances of the software, as through scripts, over an extended period on a system. (CNR-429731-Q0P2Y8)

- GD&T / Unequally Disposed Tolerance Zone - Deviation label: When the display mode of the deviation plot of a surface profile with unequally disposed tolerance zone is changed, deviation labels get updated properly now. (CNR-438496-B5C5R7)
- Construct Cuboid: A crash has been fixed when using the commands "Point-Direction Cuboid" or "3-Point Cuboid" with specific input values.
- GD&T - Surface Profile: When a project is migrated from ZEISS INSPECT 2023 to ZEISS INSPECT 2025 or higher in rare cases a error of the visualization on the deviation plot of a surface profile could be shown. After "Edit Creation Parameters" of a effected surface profile this error is eliminated in the service pack. (8103444953)
- INSPECT Optical 3D - Image Acquisition: Possible crashes (sensor connection) during automated scanning are reduced. (8103379114, 8103364599, CNR-518499-D3M4C9, CNR-424636-S3L1H1, CNR-570279-H1J3X6)
- INSPECT Optical 3D / ScanBox with integrated thermometer - Sensor Calibration: When a sensor calibration is conducted in a ScanBox, and the hardware thermometer is designated as the temperature source, the value from the hardware thermometer is used, irrespective of any additional project temperature settings. (CNR-540783-G5D7J9)
- Opening / Recovering projects: A specific crash is fixed, when opening or recovering certain damaged projects. (CNR-479855-P3N1F4)
- Export Table - Additional information: When adding additional information to a table export, the exported table starts with the additional information in the first line. (CNR-493255-F3P7V2)
- GD&T - Position tolerances: Now, the position tolerance with ASME standard of a cylinder is transformed according to the alignment, when the alignment is changed. (8103470593)
- User-defined Checks - Labels: Now, the label of a user-defined check, newly created on a deviation label, is attached properly to the deviation label. Also, when loading projects or using project templates containing such checks, the labels are placed properly again at the corresponding deviation label. (CNR-393534-J2G0S3)
- ZEISS INSPECT Installer: With ZEISS INSPECT 2025 Service Pack 3 .Net 8.0.21 is included.
- ZEISS Quality Suite: ZEISS INSPECT 2025 Service Pack 3 includes ZEISS Quality Suite version 7.0.2770.0.
- EULA: The prior end user license agreement of ZEISS INSPECT 2025 Software is replaced by a new end user license agreement. Therefor users must accept this end user license agreement, when starting ZEISS INSPECT 2025 Service Pack 3, when updated from an older installed ZEISS INSPECT 2025 version.
- INSPECT X-Ray - X-Ray source: A bug was fixed, which kept the X-Ray source active (X-RAY ON) even when the user closes the project.
- Measuring Principle "Edges, Gap and Flush": A bug has been fixed, which led under circumstances to wrongly named actual elements, when applying the measuring principle "Edges, Gap and Flush" to an edge curve with only side 1 and "Edge Angle > 90°". (CNR-457768-C6V4G5)
- INSPECT X-Ray - Section View (Unroll) / Set Focus Point: A problem has been fixed, that led to unexpected views for "Section View (Unroll: Side)"/ "Section View (Unroll: Top)", when using "Set Focus Point" in the "Section View (Unroll)" after changing the "Start point" in the "Configure Advanced Unrolling Parameters". (8103191896)
- INSPECT X-Ray - Volume Defect Element (From Volume): A bug has been fixed which could lead to wrong total volume value of "Volume Defects" elements created with "Volume Defect Element (From Volume)" if the resulting defect element has internals.
- INSPECT X-Ray - Project templates: Capturing volume data into project templates with existing empty volume elements is possible now. (8103378373, 8103408301)
- INSPECT X-Ray - "Volume cropping" / Pinned dialogs: The software no longer crashes when opening "Volume cropping" from "Capture Volume" or "Reconstruct Volume From Images" dialogs that are pinned in the UI. (8103324472)
- INSPECT Optical 3D – VMR / Calibrate Measuring Setup: Now, Calibrate Measuring Setup is working with the correct threshold. (CNR-524236-Q9K1N2)
- INSPECT Optical 3D - ScanCobot / Measuring device configuration: Now, when creating a new measuring device configuration for a ScanCobot system with the "Measuring Device Manager", the default accuracy for the ScanCobot is 0,25 instead of 0,10. (CNR-662212-F2F9K5)

- INSPECT Optical 3D - Live camera view: Now, the live view in the "Camera" tab is correct when the sensor has been moved into a measuring position. With this change, also a possible crash is fixed when executing calibration measurement series in a double robot cell environment.
- CORRELATE - Live camera view: The problem has been fixed, and the live video is now available in the "Set Up" workspace after adding or removing a logical sensor.
- INSPECT Optical 3D - Connect measuring device: A possible problem has been fixed, which could have led to an error message, when trying to connect to the sensor if a different ZEISS INSPECT major version was used before. If this happened, a second try to connect helped. (CNR-542315-B1H1X8, CNR-570279-H1J3X6)
- Tolerance Band (Regions) - "Edit Creation Parameters": Now, tolerances of a Tolerance Band (Regions) are applied properly only to the selected regions when they are changed via "Edit Creation Parameters". In prior ZEISS INSPECT 2025 version this was not always the case.
- Cluster - Define Inspection Ballons: When defining inspection balloons on cluster elements, the option to individually number the clusters is working properly again. (8103494023)
- INSPECT X-Ray / METROTOM 1500- Control panel / Capture Volume: Now, when releasing the buttons for manual movements in the "Set Position" area of the Control Panel tab, the movement stops properly, even when the "Capture Volume" dialog is open.
- Correlate - Multi sensor measurements: A crash was fixed, which sometimes occurred on fast ARAMIS multi sensor measurements. (CNR-586455-Q7L5V7)
- INSPECT Optical 3D - DoubleRobotCell / ScanCobot: A problem has been fixed, which led to problems with initializing ATOS sensors in DoubleRobotCell environments or in ScanCobot with an IPC. In prior ZEISS INSPECT 2025 versions initializing the ATOS Sensors on such systems could fail if a proxy is active on the corresponding PCs. (8103579884, CNR-426238-M7Y5L5, CNR-680797-Q0S9Y2)
- INSPECT Optical 3D - Automated Photogrammetry: A problem has been fixed, that caused low exposure times for photogrammetry measurements, when computed automatically for ATOS 5X with PlusBox. (692773-P7Y9P0)
- INSPECT Optical 3D - ATOS ScanPort: A possible crash is fixed when calibrating the ATOS Sensor on a ATOS ScanPort in the Setup workspace while a project is opened. With this fix recording a calibration for Motion Replay into a project is possible again. (8103572685)
- VMR - Editing projects / Licenses: A bug has been fixed, which could have led to confusing error messages, when editing a VMR project without VMR license, also when loading the project with VMR license again. (CNR-633559-H5W8N9, CNR-670429-S4Z1P4, 8103587301)
- GD&T / Surface Profile - Equidistant Deviation labels: The software no longer crashes when using "Create Equidistant Deviation Labels" on a surface profile with unequally disposed tolerance zone and the display mode "Show deviation to tolerance zone center" is chosen in the “Properties” of the surface profile.
- GD&T / Surface Profile - Actual Point clouds: The deviation representation for surface profiles based on patch compounds to actual points clouds respects properly the chosen option "Show deviation to tolerance zone center" and "Show deviation to nominal" when the surface profile is defined with an unequally disposed tolerance zone.
- Airfoil Inspection - Create Separated Curves: A bug has been fixed that caused under circumstances points to be missing because the calculated separate connected curve ignored the last section point.
- ATOS Sensors - Sensor firmware: With ZEISS INSPECT 2025 Service Pack 3 a new sensor firmware for several ATOS sensors (ATOS 5, ATOS 5X, ATOS Capsule) is provided.
- INSPECT X-Ray - Continuous Acquisition / Scatter Control: A possible problem is fixed for performing a continuous scatter control scan, which could lead to broken reconstructed volumes.
- "Correct System" - Systems with Mellanox ConnectX 6X Network Adapter: A bug had been fixed, which led to wrong IP-Address-settings when selecting the connected measuring system (Testing/Metrology) in a pop-up dialog after pressing "Correct System".
- Export "ZEISS elements file" - Clipboard: A crash has been fixed when exporting a mesh as *.zelements file from clipboard twice with "Export Selected Elements". (8103487056)

- CORRELATE - ARAMIS SRX / HD measuring volume: The user is now able to define, calibrate and use a HD measuring volume with the SRX Sensor again. Remaining restriction: After the sensor has been declared in the Setup workspace, a re-initialization of the sensor must be done once manually.
- ZEISS INSPECT Optical 3D - "Select Acquisition Template" / Licenses: Now, when the software is started without the "Professional Inspection" but with an "ATOS sensor driver" license, the "Manage Acquisition Template" button is properly not visible in the "Select Acquisition Template" dialog as using this option for managing different templates requires the "Professional Inspection" license. With this a possible crash is fixed. (CNR-460883-C1F5B7)
- INSPECT Optical 3D - Sensor hot-plugging functionality: A possible bug has been fixed, which could have led to a wrong sensor configuration on the sensor, if two sensors of the same type but with different measuring volumes are alternately operated on the same system. (CNR-649673-P5X0N7)
- INSPECT Optical 3D / Driver "ZEISS Hardware Service (Remote)": Now, installation of "ZEISS Hardware Service (Remote)" driver runs error free, when switching between different major versions of ZEISS INSPECT where it is necessary to install the driver that matches the version of ZEISS INSPECT to be used.
- INSPECT Optical 3D, INSPECT X-Ray - Sensor initialization behavior: In the case that a measuring device (ATOS Sensors, X-Ray systems, T-Scan Hawk) is used from one software instance and the user switches in a second instance into the acquisition workspace or uses the command "Connect measuring devices", he is asked if he want to take over the device into the current software instance. (8103571289, CNR-661544-G3C3X0)
- Export Data (STL and others) - Progress bar: When data is exported with e.g. Export STL, then the progress bar vanishes properly after the export is done. (8103598157)

ZEISS INSPECT 2025 Service Pack 2 Patch 3

Product version: 2025.3.3.4

- Optical 3D - DoubleRobotCell environments: For older revisions of ATOS ScanBox Series 8 or project measuring cells the two robots might have executed measurement series sequentially where parallel execution would have been expected. This has been fixed now. (CNR-560057-L4G8H5, CNR-586479-G9S5J0, CNR-518409-R1L7D2)
- Fitting Elements - Point selection / Mesh adaption: Now, for fitting elements created by measuring principle "Gray Value Features (Mesh Adaption)", the found contours near the hole are qualified, and the best one is chosen. With this, problems are solved, which result in wrong positions of the fitting elements. (CNR-607132-Q0J3W1)

ZEISS INSPECT 2025 Service Pack 2 Patch 2

Product version: 2025.3.2.2

- ZEISS FOSS Disclosure Document: The “ZEISS FOSS Disclosure Document” has been improved for a better readability, facilitating easier interpretation.

ZEISS INSPECT 2025 Service Pack 2 Patch 1

Product version: 2025.3.1.6

- INSPECT X-Ray - Import Volume / ZEISS Xradia X-ray microscopes: Now the import of *.txm files works properly, when these files were created with Zeiss VersaXRM 615, Zeiss VersaXRM 730, and Zeiss XRadia 630 Versa X-ray microscopes and systems using ZEN navx. (8103399007)
- INSPECT X-Ray - METROTOM 6 Scout: Now, the driver for the X-Ray source of METROTOM 6 Scout system can be updated and registered properly again within the Maintenance tab of ZEISS Quality Suite. After this necessary driver update the system can be initialized as usual. (8103397000)
- INSPECT Optical 3D - "Project Elements on Measuring Object": A bug has been fixed, which prevented the usage of the command "Project Elements on Measuring Object" in ZEISS INSPECT 2025 Service Pack 2. (CNR-511284-Y7W0X6, 8103410046, 8103410780)

Known Issue for ZEISS INSPECT 2025 Service Pack 2 Patch 1

- Kiosk Interface - Hyperscale calibration: The Kiosk currently does not execute an unconditional hyperscale calibration before starting ATOS measurements.
  Necessary execution of full calibrations and hyperscale calibration due to temperature drift are not affected by this.

ZEISS INSPECT 2025 Service Pack 2

Product version: 2025.3.0.535

This software version contains several bugfixes and improvements to the prior ZEISS INSPECT 2025 Service Pack 1 version, e.g.

- INSPECT Optical 3D - Acquisition: For multipart workflow the source and target measurement series can now be clearly selected by their scan name + part name.
- ZEISS T-SCAN hawk 2: Firmware Updater for ZEISS T-Scan hawk 2 was removed from installation of ZEISS INSPECT 2025 Service Pack 2, due to bugs with this tool. As there is currently no need for firmware updates of this product this is not a problem for the customers.
- ZEISS INSPECT Installer: With ZEISS INSPECT 2025 Service Pack 2 .Net 8.0.16 is included.
- Crash handling: A problem has been fixed which could led to several additional information messages from Sentinel RMS Development Kit in case of ZEISS INSPECT 2025 software crashes.
- CORRELATE - Tacked elements / Import: An error has been fixed, where elements, which are imported from *.zelement files and tacked to point components, were transformed wrongly in several import scenarios. (CNR-61520-G1Q9F2)
- Reporting - Table / Sorting: The sorting of a table with columns of the same entries is now always consistent. In rare cases, sorting could have been mixed up in prior software versions. (CNR-185408-R8J1C6)
- INSPECT Optical 3D - Exposure times / Camera tab: A bug has been fixed, which could have led to a missing color legend for exposure times in the Camera tab when using the "Interactively" exposure time mode. (CNR-319508-C7S2N5, CNR-319672-P0D7Z6, CNR-362582-K6W5H2, CNR-373449-K7Q5X8, CNR-385020-K1X4V5, CNR-394905-Y3H2B4)
- Surface defect map - Edit Creation Parameters: A bug has been fixed that caused a software crash when recalculating the surface defect map using an updated point selection by Edit Creation Parameters. (CNR-294168-R3T6V9)
- ARAMIS Controller: A new firmware is provided with ZEISS INSPECT 2025 Service Pack 2. With this, possible problems are fixed e.g. plotting only one AD channel during the setup. (CNR-246236-Y1V1C6, CNR-240489-Q6D2Y9, CNR-298152-F9P1V0, CNR-321435-V3W7Y9)
- GD&T Position - ASME Y14.5: When a position check for a circle or a parallel line in ASME standard uses a datum system with material requirements, the data might not be computed if the project was created in a software version 2023 or older. This has been fixed now. (8103247352)
- Scripting: The software no longer crashes if the command “execute_active_measurement_series” is started via a button in a user defined script dialog and then aborted via ESC.
- Scripting - "Define Filter Tag": A bug has been fixed that caused the command 'Define Filter Tag' to be recorded incorrectly. This issue resulted in an error message when attempting to execute the recorded command. (CNR-356642-B0K9R4)
- ZEISS T-SCAN hawk 2 - Remote Workflow: When using the ZEISS T-SCAN Hawk 2 in the Remote Workflow a white screen appeared when clicking the save & close in the report workspace. This bug has been fixed.
- INSPECT X-Ray - Reporting / Stage projects: Reconfiguring a report containing e.g. quad view to a different stage does no longer restore the volume slice information. Instead, it is updated to reflect the data from the new stage. (CNR-336792-F5T7G3)
- Reports - Recalculate Project: A possible crash has been fixed, when recalculating report pages when e.g. an actual mesh is in the clipboard of the project. (CNR-356822-Y8M5H4, CNR-410205-D4Y1C7, CNR-396489-V8P5K2, 8103330536, 8103340131, CNR-460629-Y3L4R8, CNR-469533-H0P5B6, CNR-487355-X7D2N7, CNR-489234-X3V5Y1)
- ARAMIS Controller Settings - Setup Workspace: It is now possible to enter values in a spin box such as for A/D channel filters in the Setup workspace when the mouse cursor leaves the spin box while it has still the input focus. (CNR-247664-X3R6V1)
- Fitting elements - Point selection: A bug regarding point selection has been fixed. With this, e.g. possible crashes are avoided when switching elements visible or switch between alignments after replacing CAD Data. (CNR-376572-D2S3N9)

- Clusters: A bug has been fixed, where software hangs while trying to create cluster in projects with many dependencies. (CNR-376187-D7N4J8)
- INSPECT Optical 3D - Smart Teach: A bug has been fixed that caused under circumstances a software crash when executing Smart Teach with Scanning with robogrammetry. (CNR-387442-M9J2N7)
- INSPECT X-Ray - GD&T / Subparts: A possible bug is fixed, which led under circumstances that inspections such as GD&T were added to the main part instead to the subpart to which the base elements of the inspection is assigned. (8103298496)
- CORRELATE - Configure A/D Channels: Now, setting names containing the character "x" for A/D Channels in the Setup workspace is possible. (8103316230)
- ZEISS T-SCAN hawk 2 - Remote Workflow: When using the ZEISS T-SCAN Hawk 2 in the Remote Workflow and clicking the hint "scan another side" nothing happens or the polygonization hint was shown. This bug has been fixed. (CNR-480322-V9H0R7)
- VMR - Camera tab / Offline: Now, the image of the camera tab is updated properly according to the correct sensor's 3D view of the scene as expected, when switching between scan measurement and photogrammetry series. With this also a bug has been fixed that caused the camera tab to only display a white image when importing a VMR as offline VMR and not the sensor's 3D view of the scene as expected. Furthermore, an interaction with the camera tab caused a crash which was also fixed. (CNR-397731-N0G5V9)
- ARAMIS Controller firmware update: When updating the firmware of an ARAMIS Controller, the dialog displays further information. It indicates that the controller must not be switched off during the update process. Additionally, it informs the user whether the update has finished successfully or failed. (CNR-389174-G9J5D1)
- ARAMIS SRX with tracking spots: Now, tracking spots can be activated by using the light button in the workspaces Set Up and Stage Acquisition. (CNR-389161-M8B4Y5, CNR-397824-D6F3C4)
- INSPECT Optical 3D - 3D View / Execution of measurement series: A bug has been fixed, which prevented rotating the 3D view while executing measurement series or during rotation table measurements. (CNR-252389-Z6D5Q3, CNR-293934-W4P0L3, CNR-293733-M6V1L2)
- INSPECT Optical 3D - Reference Point Measurements: A bug has been fixed that caused a reference point measurement to be displayed as changed when GPU acceleration was activated in the "Acquisition And Project Settings". (CNR-397761-C3R6W6)
- INSPECT Optical 3D / VMR - Execute Measurement Series: A bug has been fixed that previously caused an inconclusive error message to appear when executing a measurement series that had not been computed. Now, in the event of an error during this process, a clearer and more informative error message is displayed. (CNR-403598-L9F2L5, 8103326966, CNR-447401-S1H9S8)
- INSPECT X-Ray - Polygonize Volume: A possible crash has been fixed, when executing the command Polygonize Volume with certain parameters on specific input data.
- Touch Panel / ScanBoxes: Several bugs have been fixed, when using the Touch Panel with ScanBoxes. For example, the 3D view could not be rotated anymore after using the Touch Panel, or it was not possible to use the "Next"/"Back" buttons using the Touch Panel in the Kiosk report view. Additionally, an application freeze was fixed, which happened, if the editing of a 3D view placeholder on a report page was started with the Touch Panel. (CNR-383966-V8C0N6, CNR-414526-F8L9P5, 8103326966, CNR-461996-G3L8V9)
- Surface curves - Edit Creation Parameters: A bug has been fixed that caused a software crash when editing a surface curve under certain conditions, e.g. adding another curve. (CNR-407027-L9D8V4)
- Stage projects - 2-Curve Distance: A possible problem has been fixed, which led under circumstances to software crashes during recalculating certain stage projects containing 2-Curve Distances. (8103274771)
- ATOS Triple Scan with Fiber Optic converter: A bug has been fixed, which prevented using the ATOS Triple Scan with Fiber Optic converter with prior ZEISS Inspect Optical 3D 2025 versions.
- INSPECT Optical3D - Network adapters: A bug has been fixed, which in rare cases could have prevented the connection to a sensor with some older network adapters.
- ZEISS INSPECT Optical 3D - Kiosk Interface / BatchScan: A bug has been fixed which caused the progress of the measurements not to be displayed during a batch scan in the kiosk interface. (CNR-387459-V6T4Z3)

- Photogrammetry - Add Images from WiFi Camera: A possible crash is fixed when adding images from with WiFi camera. (CNR-332239-X0S1M4, CNR-477368-M9S9R0)
- VMR: A bug has been fixed, which made the camera tab invisible after adding a manual scan in a VMR measurement series. (CNR-373449-K7Q5X8)
- Deformation model - Display Properties: When changing the front color of a deformation model using the Properties > Display tab, the visualization of deformation models was not updated accordingly. This has been fixed. (CNR-169702-N3N1D1)
- GD&T - Surface Profile: Surface Profile could have direction inverted. The algorithm to calculate the sign is now improved. To correct existing elements an "Edit Creation Parameters" is necessary. (CNR-385081-J3C8W7)
- GD&T - TED Patterns: A possible bug has been fixed, where the GD&T result visualization was duplicated in the 3D View during recalculation of different alignments. (CNR-420567-L9K4Q5)
- INSPECT Optical 3D - Depending scan measurement series: Executing multiple dependent ATOS scan measurement series respect reference point dependencies.
- GD&T - Position tolerance / Unequally disposed tolerance zone: The visualized tolerance zone for a position tolerance with unequally disposed tolerance zone will now move in 3D view according to the chosen value. This was broken before.
- "Intersection Curve From Geometrical Elements" - Cones: Intersection of two cones now works again.
- Firmware update for automation devices: A bug has been fixed, which prevented the user to get known mandatory firmware updates for automation devices such as ATOS ScanPort. (8103348580, CNR-419331-L3Q1D8)
- GOM Scan 1: The initialization after reboot of GOM Scan 1 is possible again. (CNR-340872-X8Z2X3)
- Image Acquisition driver: A new version of Image Acquisition driver (14.01.006) is provided.
- ZEISS T-SCAN hawk 2 - Hyper scale calibration / Remote Workflow: The hyper scale calibration result is now always displayed when using the remote workflow.
- GD&T - Surface profile / Element groups: When a project with a surface profile and common zone on an element group is migrated from ZEISS INSPECT 2023 to 2025 the deviation does not change when e.g. editing creation parameters. (CNR-456070-L9B2W6)
- Edge Points - Measuring Principle Gray Value Feature (Mesh adaption): When using the Measuring Principle Gray Value Feature (Mesh adaption, the standard values clearance, edge height and angle of the resulting touch point (Edge) element are improved for a more stable automated detection of the related actual values. (CNR-150580-T4L2J7, CNR-281981-D2Y1B2)
- Starting ZEISS INSPECT - Windows user accounts with non-ASCII characters: A specific problem is fixed, which caused, that ZEISS INSPECT crashed directly on start-up for windows user accounts containing non-ASCII characters such as e.g. Japanese, Chinese or Korean.
- Further covered cases: CNR-330223-Z5Z8Q2, CNR-335376-X8Q1K7, CNR-152592-G9K3D, CNR-322364-W5K3K4

Known Issue for ZEISS INSPECT 2025 Service Pack 2

- Kiosk Interface - Hyperscale calibration: The Kiosk currently does not execute an unconditional hyperscale calibration before starting ATOS measurements.
  Necessary execution of full calibrations and hyperscale calibration due to temperature drift are not affected by this.

ZEISS INSPECT 2025 Service Pack 1

Product version: 2025.2.0.1322

This software version contains several bugfixes and improvements to the prior ZEISS INSPECT 2025 version, e.g.

- ZEISS Quality Suite: ZEISS INSPECT 2025 Service Pack 1 includes ZEISS Quality Suite version 6.3.2518.0, which installs the WIBU CodeMeter Runtime 8.20a. During the installation or update of the CodeMeter Runtime from an older version, users may encounter a situation where Windows Explorer windows close and do not reopen automatically. Users who install ZEISS INSPECT 2025 Service Pack 1 directly using the ZEISS INSPECT 2025 Installer will receive a notification regarding this issue and may also experience a longer installation time.
- ZEISS Hardware Service: The new ZEISS Hardware Service version 1.0.2.0 required for ZEISS INSPECT Service Pack 1 now uses ports between 39000 and 39025 for communication between measuring devices and ZEISS INSPECT 2025 Service Pack 1 onwards.
- Polygon - Projected Offset Section: Using the Measuring principle Projected Offset Section works properly on polygon elements and applies the point selection for the fitting elements without error MCADTOOL-0034. For the correction of existing actual fitting polygons editing the measuring principle is necessary. (CNR-189294-R2C2D1)
- Script Interpreter: With ZEISS INSPECT 2025 Service Pack 1 the python version is updated from 3.9.16 to 3.9.21.
- ZEISS INSPECT Installer: With ZEISS INSPECT 2025 Service Pack 1 .Net 8.0.12 is included.
- Reporting - Export as Video / exporting PDFs containing videos: Exporting videos is supported again as it was the case in ZEISS INSPECT 2023 versions.
- Outer Cones - Measuring Principle Fitting element / Minimum circumscribed element: A possible problem has been fixed, which could led to wrong results, when using the computation method "Minimum circumscribed element" for the measuring principle fitting element. The computational method is optimized that this can not happen anymore. For the correction of existing faulty actual fitting cones editing the measuring principle is necessary. (CNR-176858-G6P2M7)
- INSPECT X-Ray: A bug causing continuous-scan reconstruction to fail due to a GPU out-of-memory exception has been resolved. With this, reconstructions can be performed without encountering any errors.
- INSPECT X-Ray - Acquisition: The bug that prevented the tube from being completely warmed up before manually triggering the full centering has been fixed.
- Localization of Apps: A possible problem is fixed, which caused in prior ZEISS INSPECT versions, that not all texts in dialogs were displayed in the correct language even if the texts are translated properly.
- INSPECT VMM - Multisensor measurement: An 'Invalid geometry warning' occurred when measuring a plane using multiple strategies. This issue has been resolved, and this strategy is working now.
- INSPECT Optical 3D - Scan Measurement: A possible bug is fixed, which could have led to the need of a manual restart of the hardware server if the acquisition server crashed during the measurement.
- Airfoil inspection / Waviness Heights: A bug has been fixed that caused that the Waviness Heights check (as part of Airfoil Inspection app) interpret monotonically in/decreasing deviation values along the whole inspection area not as half wave.
- INSPECT X-Ray: Suggested number of projections was too high for Semicircle scan. This is fixed now.
- INSPECT VMM - Z-Positioning strategy / Editing reference point coordinates: An error labeled "MTACTILE-0008" was displayed when the position of an element, which was used as a reference for other nominal elements, was edited. This bug has now been fixed.
- GD&T Position tolerance - Orientation plane: In some constellations a position tolerance on multiple elements offered an orientation plane, that is ignored for calculation. This has been fixed. (CNR-189361-V8Z5J7)
- INSPECT VMM - Align Part Manually (CMM): Layout is changed properly to "tactile mode" on manual alignment by geometric elements when switch from camera tool.
- INSPECT X-Ray - Acquisition: The bug where "Move Axes Simultaneously" would hang indefinitely if C99 drives were offline has been fixed. Now, a warning message will pop up if the drives are offline while moving the axes, and a warning will also be displayed in the "System Status" window.

- INSPECT X-Ray: The positioning system moves to loading position in a safer way so that it is very unlikely that the part collides with the machine housing.
- INSPECT X-Ray - 2D image acquisition: The bug where the scaled pixel size was applied incorrectly to acquired images has been fixed. The scaled pixel size is now applied correctly to the images.
- Automation: A possible bug is fixed, which made it possible to exchange a sensor with a not calibrated sensor of the same type and measure without a valid calibration.
- INSPECT X-Ray: Scheduling CT scans from multiple instances of ZEISS INSPECT in the Measurement Overview was not possible any more in prior ZEISS INSPECT 2025 version. This is fixed now.
- PONTOS Live: Now, reference point measurements can be performed again using ARAMIS systems.
- Virtual Clamping - Recalculate Project: A bug has been fixed, that led under circumstances an infinite loop occurring during the recalculation of a previously performed virtual clamping. (CNR-190341-H0K6L3)
- INSPECT VMM - Relative measurements: It was not possible to measure edge points with the camera distance set to the reference element. This issue has been resolved.
- INSPECT CMM / INSPECT VMM - ZEISS VAST probing mode / "Measure at selected position": Measurements were executed using the project default ZEISS VAST performance mode when using "Measure at selected position", even when the ZEISS VAST probing mode was set to "Fast". This is fixed now.
- Import NASTRAN: The import for NASTRAN data was improved so that data from LS Dyna can be imported, too. (CNR-191001-Y1J4X4)
- GD&T - Surface profile: Now the color deviation representation is computed with the same method as the tolerance fit. The previous, simplified method lead sometimes to mismatches between color representation and tolerance value, especially when using ASME Y14.5 as standard. (CNR-190117-N6L7T6, CNR-181749-R7D7N8)
- INSPECT X-Ray: A bug was fixed to prevent the user to start the scan if there is not enough disk space, with a warning message in "Capture volume" dialog.
- ARAMIS Controller - Deformation tracking / SCPI Server: Now, the software synchronizes itself to a controller clock (but not to Windows system clock) during deformation tracking, and timestamps can be written therefor correctly to the log file (*.csv).
- Measuring Principle Fitting Element: Now, the selection parameters are available again in the "Measuring Principle: Fitting Element" dialog. (CNR-205180-C0Y5L0, CNR-302854-Z1H5N7, CNR-326105-G8J7N1)
- GD&T Position tolerance UZ - Tolerance legend: Now, the deviation visualization of a position tolerance with UZ (Unequally disposed tolerance zone) shows the correct color according to the check, when a tolerance legend is used. (CNR-191020-V6Z3K3)
- INSPECT VMM - Show image content in camera rectangle: Changing camera mode from 3D measuring view to combined live/3D view, does not center the view perpendicular to Z axis anymore.
- INSPECT Optical 3D - Sensor initialization: A bug has been fixed that prevented the initialization of sensors when the "Remote Technology" option was enabled in the preferences under "Hardware export settings" in previous software versions such as ZEISS INSPECT 2023. (CNR-213661-S6X9Q1)
- INSPECT X-Ray: The function to determine measurement parameters crashed on the METROTOM 1. This is fixed now.
- INSPECT X-Ray: The button to apply parameters in the Control Panel was always disabled for the METROTOM 1 in prior ZEISS INSPECT 2025 version. This is fixed now.
- Reporting - Export PDF: Now exporting report pages with semitransparent elements (CAD, mesh, planes, circles, ...) to PDF works properly independently if option "Create PDF/A" is used. (CNR-209853-T9R2L7, CNR-248752-H4V6Y2, CNR-256315-G9L2P4, CNR-331814-D2X2X0)
- Intersection Curve From Geometric Elements: In rare cases curves created by command "Intersection Curve From Geometric Elements" did not get computed. This bug has been fixed. (CNR-219125-S9M7G9)
- Hyperscale recalibration: Now it is possible to execute a hyperscale recalibration in combination with a surface measurement series without getting an error message. (CNR-221626-P2Q6C6)
- Reporting - CAD data / Visibility: When restoring a report page the visibility of CAD bodies is no longer mixed up. This could have happened in specific cases before, especially if CAD bodies were set visible/invisible by Edit CAD. (CNR-189712-D2H1G5, CNR-176189-V6F8N6)

- Reporting / Stage projects - Flipbook / Video: A specific crash is fixed when create report pages with option flipbook or video. In prior ZEISS INSPECT software versions the software could crash when creating multiple report pages using flipbook / video with chosen option "All stages" for certain projects. (CNR-170945-Z0B0D3)
- INSPECT VMM - Part temperature compensation: The correction value is accurately updated when the "Activate part temperature compensation" is enabled in the Acquisition Parameters.
- Measuring systems - Compatibility with later ZEISS INSPECT major versions: ZEISS INSPECT 2025 Service Pack 1 contains a change which ensures that several sensors can be still operated with ZEISS INSPECT 2025 alternately with later ZEISS INSPECT major versions. Therefor updating to "ZEISS INSPECT 2025 Service Pack 1" is highly recommended to avoid future problems when ZEISS INSPECT 2025 (from Service Pack 1 upwards) is to be operated alternately with later ZEISS INSPECT major versions higher than ZEISS INPSECT 2025.
- Starting ZEISS INSPECT 2025 Software: A bug was fixed, which led to a lot of broadcast traffic during the start of ZEISS Inspect 2025 software. (CNR-220294-K1K2G0, CNR-220193-D2R2D9, CNR-227402-G0W0R2, CNR-208649-F0P5S1, CNR-218931-C8H2Y4, CNR-247539-V4F4C5, CNR-315296-Z8M5G2, CNR-310541-W2B7X8, CNR-312015-M5B6J1, CNR-322889-B4M4S7)
- Surface Defects: A bug has been fixed which gives unexpected results when using defect subset by number on grouped surface defect. (CNR-218902-Q4B4K6)
- New version of Image Acquisition driver (14.01.003)
- ATOS III Triple Scan: A bug was fixed, which prevented using ATOS III Triple Scan sensors with a specific camera type with ZEISS Inspect Optical 3D Version 2025. (CNR-235263-H4H3J4, CNR-230169-L0R1W8, CNR-240346-R5Z5V9, CNR-254043-B7T2G6, CNR-279015-K4D6B7, CNR-303047-Y5C2J6)
- T-SCAN hawk 2: Spurious warnings regarding GPU throttling are prevented. (CNR-230573-N2J8F9, CNR-236334-P3C5B4, CNR-236635-H1B8S5, 8103235069)
- ATOS CompactScan 5M: A bug has been fixed that prevented measurements from being taken with the ATOS CompactScan 5M. (CNR-228913-J1H6B7, CNR-330512-D6T5R3, CNR-362012-J4Y1J1)
- VMR projects - Recalculate Project / Scan Coverage: A possible software crash is fixed, when recalculating certain projects when "Do you want to check whether there are enough scan data for your elements?" is set to "Yes" in the "Acquisition Template and Project Settings" dialog to enable the check for scan coverage. (CNR-202397-N0Z0H7)
- VMR - ATOS Capsule: A bug has been fixed where the automatic exposure time could not compute exposure times when using an ATOS Capsule for automated measurements. (CNR-246140-W3P6T2)
- GD&T - Datum systems / ASME Y14.5: Now it is possible to create a datum system based on two or three actual planes and computation mode ASME Y14.5. (CNR-248909-Y3R9Y4)
- GD&T - Linear Size: When creating a linear size using ASME Y14.5 as standard, the standard itself is not changed anymore to ISO 1101 when adjusting tolerances in the dialog. (CNR-238698-Q8X1D5)
- ARAMIS Controller: A new firmware is provided with ZEISS INSPECT 2025 Service Pack 1. With this the order of input / output channels matches with the software.
- Import CAD - PMI data: In rare cases an import of PMI data could lead to a crash of the software. This is fixed. (CNR-253615-Y5K2K6)
- Correlate / "Surface Component From Point Grid" - "Edit Creation Parameters": A possible crash is fixed when using "Edit Creation Parameters" on the surface component from the point grid elements in certain projects.
- INSPECT X-Ray - Acquisition: A bug has been fixed that caused the scan to freeze when the expected position was not reached.
- Fitting circle - Used points: When a fitting circle is now calculated with point elimination by using e.g. 2 sigma for parameter "Used Points", this is taken properly into account in the calculation. Projects with existing incorrect calculations are automatically recalculated in the new software version when "Recalculate All Visible Elements Automatically" is activated. (8103218310, CNR-303178-B6V5B5)
- Surface defect map - Referenced Construction: A bug has been fixed that previously prevented an actual surface defect map, which was created by referenced construction, from updating correctly after the selection area was changed by editing the nominal surface defect map. With this, wrong results on the actual surface defect map are prevented. (CNR-294168-R3T6V9)

- ATOS Sensors - Sensor firmware: With ZEISS INSPECT 2025 Service Pack 1 a new sensor firmware for several ATOS sensors (ATOS 5, ATOS 5X, ATOS LRX, ATOS Capsule) is provided.
- ATOS Compact Scan 12M - Aborting measurements: A bug has been fixed that occasionally required the sensor to be restarted when a manual measurement was aborted. (CNR-304593-W0D6P7)
- Login and license information - Login state: Now, the icon for "Login and license information" changes properly its color according to the login state. (CNR-261185-X5V2L6, CNR-365520-H1G9P8)
- Correlate – New version of FLC App "Forming Limit Curve Evaluation" is available in the Store
  - New workspace and evaluation functionality included
  - Increased usability
  - With this GOM Software v6.3 is not supported anymore
- Correlate - Multiple sensors working in one software instance
  - Measuring with multiple devices into one Software instance is supported now
  - Automated Setup of Secondary measuring sequence
  - Multiple 2D sensors can be declared from 3D systems
- Correlate - Improvements in adapter workflows: It is now easier to tack elements to point components and use them fluently in different projects.
- Further covered cases: CNR-347357-T6Z9L3, CNR-175999-J5V8F5, CNR-176436-M8W6W5, CNR-222855-S1J3J5, CNR-231566-N1P0G5, CNR-181907-S5S0B8

Notes for compatibility for later ZEISS INSPECT major versions – ATOS Sensors / ARAMIS Sensors / T-Scan Hawk 2 / X-Ray Systems (such as METROTOM 6, METROTOM 1)

ZEISS INSPECT 2025 Service Pack 1 contains a change which ensures that several sensors can be still operated with ZEISS INSPECT 2025 alternately with later ZEISS INSPECT major versions. Therefor updating to ZEISS INSPECT 2025 Service Pack 1 is highly recommended to avoid future problems when ZEISS INSPECT 2025 (from Service Pack 1 upwards) is to be operated alternately with later ZEISS INSPECT major versions higher than ZEISS INPSECT 2025.

Known Issues for ZEISS INSPECT 2025 Service Pack 1

- Installation: ZEISS INSPECT 2025 Service Pack 1 includes ZEISS Quality Suite version 6.3.2518.0, which installs the WIBU CodeMeter Runtime 8.20a. During the installation or update of the CodeMeter Runtime from an older version, users may encounter a situation where Windows Explorer windows close and do not reopen automatically. In that case a system reboot is recommended. Users who install ZEISS INSPECT 2025 Service Pack 1 directly using the ZEISS INSPECT 2025 Installer will receive a notification regarding this issue and may also experience a longer installation time.
- Scripting: The software will crash if the command "execute_active_measurement_series" is started via a button in a user defined script dialog and then aborted via ESC. There is currently no workaround available until a later ZEISS INSPECT 2025 Service Pack is released.
- INSPECT X-RAY: Various X-Ray systems may generate error messages when capturing volumes. The reason for this is that communication with hardware modules is impaired by a faulty graphics card driver. The problem can be solved by installing NVIDIA driver 553.24.
- Correlate:
  - Live video problems, especially min Setup workspace and after sensor switches, might occur
  - Live Preview issues:
    - Working only for primary sensor/ device
    - 2D scaling not taken into account
  - 2D calibration on a secondary device might override previous 3D calibrations on this device
  - Only Testing Controllers are suited as Primary devices
  - File permission problems when using image saving in deformation tracking

ZEISS INSPECT 2025

Product version: 2025.1.0.1985

ZEISS INSPECT forms the core of the ZEISS Quality Suite and is available in five industry-specific variants. These are pre-configured, ready to use for the application and challenge at hand, and new features have been added with the 2025 release:

Overarching **basic functions of ZEISS INSPECT**

- Revised User Interface
  - Revised color themes
  - New layout of the start workspace when opening ZEISS INSPECT, where the list of recently Used Projects directly visible
- Changes to the product structure
  - Replacing product ZEISS INSPECT Airfoil by the new app Airfoil Inspection (see also below)
  - ZEISS INSPECT Correlate is renamed to ZEISS CORRELATE
  - New products ZEISS INSPECT VMM and ZEISS INSPECT CMM
  - Removal of ZEISS INSPECT Viewer
  - Making ZEISS INSPECT Optical 3D / ZEISS INSPECT X-Ray / ZEISS Correlate Free easily available for download
    - Limited Volume import in ZEISS INSPECT X-Ray Free
  - Longer ZEISS INSPECT Pro 30-day trial for ZEISS INSPECT Optical 3D / ZEISS INSPECT X-Ray / ZEISS Correlate
- New CAD Convertor supporting following formats "NX 2406", "CATIA 2024", "3DXML 2024", "Inventor 2025", "NX 2312", "JT 10.9", "Revit 2024", "Solid Edge 2024", "Parasolid 36.1", "SolidWorks 2024", "Rhino 8", "Navisworks 2025", "Creo 11"
- Scripting
  - New Interpreter model allows to register scripts as APIs & faster script execution
  - Scripted diagrams
  - Improved App editor
- GD&T
  - Datum targets
  - Wedges as datum
  - NEV: Linear size with fixed direction & one-sided tolerances
  - Global standard (ISO or ASME now selectable for the whole project as global setting)
  - Filters added to fitting-elements
  - PMI improvements
- Surface defects - The new surface defect workflow unlocks new possibilities
  - No coding skills required
  - More intuitive & task-focused workflow
  - Increased flexibility by supporting different base elements (e.g., Surface Comparison)
  - Reduced computation times for large areas with Surface Defect Curve
- Clusters - Clusters have been significantly improved
  - Clusters are parametric
  - Editing of specific clusters possible
  - Cluster category in explorer
  - Improved Copy Cluster dialog
  - Explorer shows hierarchy of cluster and its copies
- User-Defined Inspection Principles The additional parent elements offer many benefits
  - Selecting and adding additional parent elements is easy now
  - Active error prevention
  - Timesaving since descriptive parameter names for the Apply dialog can now be entered upon User-Defined Inspection Principles definition.

- Filter tagging - brings parametric properties to tags
  - Filter tags allow you to predefine a requirement which parametrically updates itself
- New apps will be available
  - Airfoil Inspection
    - In ZEISS INSPECT 2025, Airfoil is no longer a dedicated software
    - Airfoil as an App that allows the flexibility to use different measurement technologies - It has also new functions and improvements
  - INSPECT PiWeb Reporting Plus
    - PiWeb users can integrate Optical 3D projects natively into PiWeb
    - Locally store and evaluate up to 100 results per ZEISS INSPECT project in ZEISS PiWeb Monitor
  - Weld Check
    - The Weld Check App provides the ability to automatically generate visual weld inspections in ZEISS INSPECT
    - Weld inspection based on the standards: DIN EN ISO 5817, DIN EN ISO 10042, DIN EN ISO 13919
    - FAT quality levels for DIN EN ISO 5817, tolerance tables for DIN EN ISO 13920, and seam transition radius & angle
    - Automatic evaluation of imperfections: Undercut & angle offset, Seam elevation, Inequalities in fillet welds, Actual weld thickness, Edge offset for tubes & sheets
    - Show & hide feature enables convenient in-depth evaluation of weld seams
  - Tube Check
    - Check bending points, cylinder angles, radii, diameters and defects: Fitting tube/centerline, Rotary-hoist-bent tubes; Inspect sheath deviation; Inspect LRA/XYZ table values, XYZ/LRA table import/export, Wrinkling inspection, Roundness inspection

Important Note

With the current release of ZEISS INSPECT 2025, we are changing the licensing technology to THALES. This results in important changes with regards to license delivery and license management. Please find more information in the customer information or the FAQ provided in the ZEISS Portal Download Center, or by contacting your local sales contact.

ZEISS INSPECT Optical 3D for inspection and analysis of 3D measurement data

- Workflow assistant - Clear guidance for beginners
  - The workflow assistant provides the user with a recommendation on which main steps to perform and in what order
  - Guidance from the very first step (importing data)
  - Integrated text prompts provide users with guidance during dialog interaction
- Performance - polygonization
  - Polygonization gain of overall ~10%.
  - With upcoming new PC generation, polygonization performance will be 2x as fast.
  - Adaptive polygonizations can be up to 5x as fast.
- CALIGO support - Extended CALIGO export directly into ZEISS INSPECT Optical 3D
  - Data is automatically exported after the measurement has been completed
  - No manual interaction necessary
  - Faster data transfer
  - Faster polygonization of the point cloud in ZEISS INSPECT Optical 3D
  - Extended evaluation capabilities

- New option for Scanning
  - Cut out background points based on a cylinder. Especially helpful while using a rotation table, eliminating everything the sensor would capture outside
  - HyperScale calibration will now be guided in regard to distance and orientation.
  - Audio feedback during Satellite-Mode measurement whether image can be used properly.
  - Improved button workflow:
    - New mode: start scanning and collecting reference points simultaneously
    - Finalizing a project with a walk-through of the report pages in presenter mode
    - Reuse reference points around the object for additional side scan
- DeviceDock: Plug & play model for sensor integration to ZEISS INSPECT Framework
  - DeviceDock allows ZEISS INSPECT to have an agnostic interface & view to hardware
  - Benefits
    - Seamless hardware integration – It simplifies the incorporation of sensors and enhances hardware & software communication
    - Accurate data sourcing – Managing data flow of multiple sensors
- Sensor Fusion: Allow a project to utilize data from multiple sensors
  - Sensor fusion allows ZEISS INSPECT to merge multiple data sources into a single project
  - Benefits
    - Manual scanning – All optical 3D sensors can be used in a single project
    - ScanBox Series 8 – Single project on a single PC to handle entire ScanBox

ZEISS INSPECT X-Ray for analysis of volume data

- Expanding Multiview UI with new section views - Cylinder/cone unroll, 3D path
  - New section view – Virtual unrolling of CT data based on cylinder or cone
  - New section view – Follow a 3D path through CT data (axis, line, normal, curve)
- Volume Slices Visualization Improvements - Brightness curve
  - Brightness curve adds new dimension to CT data visualization adjustments
  - Final colors assigned to the gray values are shown directly in the histogram
- Multi-Material / Multi-Component workflows
  - Interactive Creation of Volume Regions - Improved manual CT data segmentation workflow
- New project structure for Component objects - Sub-parts concept
  - A more convenient way of handling and evaluating multi-component scans in the project
- Volume Defect Analysis
  - ZADD segmentation (App, will be available in the Software Store) - AI-based defect detection
- Improvements in P203 - Image quality factor and local tolerances
  - Expanding support for the most recognized standard for evaluating defects in light metal castings with CT
    - Quality Factor support – the measure for the CT data quality
    - Arbitrary-shaped ROIs support for local P203 evaluations
- Improved UX for previews - Live previews directly in sections views
  - More streamlined approach to preview results of different operations on CT data such as Filter Volume, Reduce Volume Size, Polygonization (single- and multi-material), Identify Materials, Defect From Volume, Volume region creation and modification
- Performance Improvements - Performance boost in comparison with ZEISS INSPECT X-Ray 2023 for many often-used CT features, including:
  - Volume filtering (Average, Gauss), up to 50 times faster
  - Polygonization, up to 20 times faster
  - Prealignment (Volume), up to 20 times faster
  - Defect detection, up to 2 times faster

- X-Ray Acquisition
  - New look of the Control Panel, easy to use, better user experience
  - Scan time Preview: In the Capture Volume dialog the Estimated scan duration is displayed (not including reconstruction time)
  - Two-material beam hardening correction
    - Beam hardening correction: Correction of beam hardening artifacts for a part made of more than one material
  - KIOSK - Measurement runs made easy with very intuitive user interface
    - Works for data acquisition & evaluation
  - Improved 2D image acquisition
    - 2D image acquisition: one or multiple X-ray images of the part (Available as option: requires license)
    - New viewing possibility: 2D Image Acquisition
    - Capture 2D Image: Defining 2D X-ray images which are of interest, Images with different measurement parameters, positions, etc.
    - 2D image annotations: e.g. Add free text via Create annotation, mark defects via Create line, Create rectangle, Create ellipse
    - Filter 2D X-ray images: e.g. Filter for better visualization of specific areas, Toggle between raw and filtered image data to see difference between filtered/not filtered, Different kinds of filters for different kinds of parts

ZEISS INSPECT VMM for inspection of data from ZEISS O-DETECT system

- New Product variant for ZEISS INSPECT 2025 with basic features such as:
  - Open and editing of existing projects
  - Element construction: geometrical elements, points, sections, curves, surfaces, dimensions
  - Autofocus points and planes
  - Backlight, front-light and ring-light illumination
  - Image-based metrology
  - Tactile multi-point metrology
  - Import of CAD data in standard formats: IGES, VDA, STEP, JT Open, STL, PLY
  - Application of common alignment methods
  - Dimensions and evaluation of GD&T according to ISO GPS and ASME Y14.5
  - Report module

ZEISS INSPECT CMM for inspection of CMM data from ZEISS DuraMax system

- New Product variant for ZEISS INSPECT 2025 with basic features such as:
  - Open and editing of existing projects
  - Element construction: geometrical elements, points, sections, curves, surfaces, dimensions
  - Tactile passive scanning metrology
  - Import of CAD data in standard formats: IGES, VDA, STEP, JT Open, STL, PLY
  - Application of common alignment methods
  - Dimensions and evaluation of GD&T according to ISO GPS and ASME Y14.5
  - Report module

ZEISS CORRELATE for the analysis of motion sequences and deformations

- New name: ZEISS INSPECT Correlate is now ZEISS CORRELATE
  - But it remains in the INSPECT family
- Data storage during measurements
  - During the measurements, image data is already stored on the hard drive. This saves time after each measurement.
- Diagram improvements
  - In the Inspection Detail View, you can change line and symbol styles
- Additional Inspections
  - Change local strain coordinate systems, e.g. if you want to evaluate radial strains on a tire but the global system should be the car body coordinate system

Want to learn more about this year's ZEISS INSPECT software? Click here (ZEISS ID required) for an overview.

Notes for upgrading from ZEISS INSPECT 2023

Please refer additionally the section Notes for upgrading from ZEISS INSPECT 2023, because the ZEISS INSPECT 2025 contains compared with ZEISS INSPECT 2023 several new firmware and drivers.

Known Issues for ZEISS INSPECT 2025

- ZEISS CORRELATE 2025 will not support Acquisition with Multiple controllers
- ZEISS CORRELATE has still remaining issues in the sensor and live image handling
  - for productive systems we recommend staying with ZEISS INSPECT 2023 version until a ZEISS INSPECT 2025 Service Pack release
- INSPECT Optical 3D: Connection problem after error "FG-0004" during a data acquisition. As workaround a restart of the computer is necessary
- INSPECT VMM: "Construct Auto 2D Element (Nominal)" may behave unexpectedly and detect unreasonable geometries
- INSPECT VMM - Executing measurements with CNC mode: When executing measurements with CNC mode the executing the measurements is slow. As workaround users have the opportunity to execute an optimized VMM measurement through the utilization of CNCRunOptimizer app (will be available in the Software Store), which has the capability to diminish the amount of time required for CNC runs. The extent of time saved is contingent upon the quantity of measurement positions.
- Reporting - Export as Video / exporting PDFs containing videos: Exporting videos is not supported.

Notes for Upgrading from ZEISS INSPECT 2023

Licenses

The ZEISS INSPECT 2025 requires a new license. For getting the license for the new ZEISS INSPECT 2025 please find more information in the customer information or the FAQ provided in the ZEISS Portal Download Center, or by contacting your local sales contact. Further information for do to update software licenses can be found in the ZEISS Quality Tech guide (ZEISS ID required).

General Notes

- ZEISS INSPECT Airfoil: As the functionality of product ZEISS INSPECT Airfoil 2023 is moved into the app Airfoil Inspection customers must download and install this app from the Software Store (ZEISS ID required) to extend the ZEISS INSPECT 2025 Software such as e.g. ZEISS INSPECT Optical 3D (see also above Changes for product structure).
- Migration of software settings such as apps (formerly known as Add-ons) and separate scripts from prior software version has limitations due to the change of licensing technology as well as a rework of the Apps handling or scripting changes
    - Upgrade from ZEISS INSPECT 2023:
        - Installed Apps will be migrated to ZEISS INSPECT 2025 but might not be useable and must be adapted. In case of apps provided by ZEISS such as for example the "Efficient Blisk Measurement and Inspection". Please search in the Software Store for matching versions suitable for ZEISS INSPECT 2025.
    - Upgrade from GOM Software 2022 and prior:
        - Installed Apps (called packages in GOM Software 2022 or prior) at user level are migrated to ZEISS INSPECT 2025, but the ZEISS INSPECT software must be started for a complete migration a second time. As an alternative export the apps from the old GOM Software and import then by drag and drop in ZEISS INSPECT 2025.
        - User-defined scripts, which are not part of an app in GOM Software 2022 or prior are not migrated. They can be exported from the old software and imported in ZEISS INSPECT 2025 in the App Editor as well.
            - With the app Migration Tools (available in the Software Store) from version 1.0.11 onwards also scripts can be migrated properly.

Firmware and Drivers

ZEISS INSPECT 2025 contains and needs compared with ZEISS INSPECT 2023 several new firmware and drivers

- New version of the GigE image acquisition driver
- New Version of ZEISS Hardware Service
- New sensor firmware / camera firmware for several ATOS Sensors (ATOS Capsule, ATOS 5, ATOS 5X, ATOS Q, ATOS LRX, ATOS Airfoil, GOM Scan 1)
- ZEISS ScanCobot systems: As a Firmware Update for ScanCobot controller is needed before using ZEISS INSPECT 2025, please contact the support.

Additional notes for scripting

The new App Editor replaces the Add-on editor.

For the enhancements of ZEISS INSPECT 2025 including new software functionalities the software is reworked in many areas. This may cause slightly different but better results in ZEISS INSPECT 2025 compared to ZEISS INSPECT 2023, when using a script created with ZEISS INSPECT 2023 with the same input data. Additionally, within these changes several script commands / parameters are renamed in ZEISS INSPECT 2025. Therefore, it is recommended to use the command "Tools" > "Update Script" in the right mouse button menu inside the script view of the App editor.

ZEISS INSPECT integrates a Python interpreter and free and open source Python libraries. This is used for scripting purposes and basis of the framework for ZEISS INSPECT Apps.

ZEISS INSPECT Apps are using many of the contained free and open source Python libraries, but not all of them.

ZEISS is running regular automated vulnerability checks for the ZEISS INSPECT Apps to reduce security risks for our customers. The automated vulnerability checks are only checking those Python libraries that are eventually used by the ZEISS INSPECT Apps.

If customers are using Python libraries in their scripts that ZEISS itself is not using in their ZEISS INSPECT Apps it is in customer's responsibility to check for vulnerabilities. That makes especially sense when a customer written script is provided within their company.

Information for Inspection Kernel

With the version ZEISS Inspect 2023, we have optimized our calculation methods with regard to bestfit calculation. This affects inspections plans created from version 2023 onwards. Inspection plans, created with previous versions, will be computed using the original calculation methods.

The new numerical methods are operating the same class of the smallest deviations as described by PTB.

Release Notes ZEISS INSPECT 2023

Release Notes for ZEISS INSPECT 2023 can be found here.

ZEISS INSPECT Third Party Notices

An overview of third-party software used in the product, is documented in the ZEISS_INSPECT_2025_third_party_notices.html file, which can be found in the installation folder of the ZEISS INSPECT 2025 (C:\Program Files\Zeiss\INSPECT\2025\, when the default installation folder is used). You can also obtain this overview by calling up the "Licensing Information" link in the "About ZEISS INSPECT" dialog and opening "Open Source Licensing Conditions".

System Requirements

User rights**:** Windows standard user rights are required to use ZEISS INSPECT – Note: Administrator rights are needed for the initial installation.

Required disc space for installation**:** ~ 100 GB

ZEISS INSPECT is designed to process and evaluate large amounts of data. To smoothly create the measurement, documentation, and evaluation of the data as well as the calculations based on it, certain requirements for the underlying system and its hardware components must be considered.

To use the complete ZEISS Quality Suite functionality an internet connection and ZEISS ID are required.

Below you will find both the minimum requirements and the parameters we recommend for an optimal setup:

Minimum Requirements	
Processor	>= 8 (logical) Cores
RAM	>= 16 GB
Graphics boards	OpenGL compatible >= 4 GB VRAM
Storage	User-profile (main location for newly created projects) on SSD drive
Operating system	Windows 10 (64 bit as minimum version 1607) with current security updates
Recommended Requirements [1]	
Processor	>= 12 (logical) Cores
RAM	>= 64 GB or more
Graphics board [2]	Certified graphics card (CUDA compatible, Compute Capability >= 7.5) with at least 6 GB VRAM
Storage	User-profile (main location for newly created projects) on NVMe SSD drive with >= 1 TB capacity
Operating system	Windows 10 (64-bit 21H1) with current security updates Windows 11 (64-bit 22H2) with current security updates

[1] Depends on used applications and projects.
[2] Here in the ZEISS Quality Tech guide (ZEISS ID required) you can find a list of certificated graphic boards.

Version Information ZEISS INSPECT 2025

The table below lists the versions of additional software / drivers which comes with the ZEISS INSPECT Software or is needed by it (depending on licenses, see section Necessary Drivers for Sensors). This software may be installed by using the ZEISS Quality Suite or may be downloaded from the ZEISS Portal for manual installation.

During the installation of ZEISS INSPECT 2025 also ZEISS Quality Suite and Microsoft ASP.Net Core Runtime will be installed if necessary.

ZEISS INSPECT	ZEISS Quality Suite [1]	ZEISS Hardware Service [2]	Image Acquisition Driver [2]	Camera driver ARAMIS 24M [2]	colin3D [2]	T-SCAN hawk [2]	ZEISS Hardware Service (Remote) [2]	Connected Quality Tools [2]	Microsoft ASP.Net Core Runtime [3]	ZEISS CMM-OS NEO [4]
2025 Service Pack 3 2025.4.0.398 Build 2025-01-21	7.0.2770.0	1.0.2.0	14.01.006	2.44.02	9.1.0.36	3.0.5	2025.4.0.398	5.2.1	8.0.21	3.2.0
2025 Service Pack 2 Patch 3 2025.3.3.4 Build 2025-09-18	6.3.2518.0	1.0.2.0	14.01.006	2.44.02	9.1.0.36	3.0.5	2025.3.3.4	5.2.1	8.0.16	3.2.0
2025 Service Pack 2 Patch 2 2025.3.2.2 Build 2025-06-26	6.3.2518.0	1.0.2.0	14.01.006	2.44.02	9.1.0.36	3.0.5	2025.3.2.2	5.2.1	8.0.16	3.2.0
2025 Service Pack 2 Patch 1 2025.3.1.6 Build 2025-06-18	6.3.2518.0	1.0.2.0	14.01.006	2.44.02	9.1.0.36	3.0.5	2025.3.1.6	5.2.1	8.0.16	3.2.0
2025 Service Pack 2 2025.3.0.535 Build 2025-06-04	6.3.2518.0	1.0.2.0	14.01.006	2.44.02	9.1.0.36	3.0.5	2025.3.0.535	5.2.1	8.0.16	3.2.0
2025 Service Pack 1 2025.2.0.1322 Build 2025-03-12	6.3.2518.0	1.0.2.0	14.01.003	2.44.02	9.1.0.36	3.0.5	2025.2.0.1322	5.2.1	8.0.12	3.2.0
2025 Release 2025.1.0.1985 Build 2024-10-30	6.2.2479.0	1.0.1.9	14.01.001	2.44.02	9.1.0.36	3.0.5	2025.1.0.1985	-	8.0.10	3.2.0

[1] Bundled within the ZEISS INSPECT Installer.
[2] Can be installed via ZEISS Quality Suite when the system is connected to the Internet or when a local update source is used. Otherwise, they may be installed directly using the installers within the corresponding driver archive, which is available here: ZEISS Download Center (ZEISS ID required). Company administrators may contact the software support for getting further information about installation using company internal update sources or may refer e.g. the Techguide (ZEISS ID required).
[3] Bundled within the ZEISS INSPECT Installer – Update/Installation is done directly over the update/installation of ZEISS INSPECT itself.
[4] ZEISS CMM-OS NEO is available in the ZEISS Download Center (ZEISS ID required)

Necessary Drivers for Sensors

The following tables contain information about drivers which must be installed for the usage with different sensors (depending on the licenses). Here two cases must be distinguished. The general case (Table 1) and the case when the IPC Driver license is used, which is necessary for ZEISS ScanCobot systems (Table 2). In case of an existing IPC Driver license, the "ZEISS Hardware Service (Remote)" must be installed and in case that the IPC Driver license does not exists the "ZEISS Hardware Service" must be installed.

For the driver versions used to be with specific ZEISS INSPECT 2025 version please refer section Version Information ZEISS INSPECT 2025.

Table 1: General case (IPC Driver license does not exist)

✓ must be installed ⊖ must not be installed	ZEISS Hardware Service	Image Acquisition Driver [1]	Camera driver ARAMIS 24M [2]	colin3D	T-SCAN hawk
• **ATOS Sensors** such as ATOS Q, GOM SCAN 1, ATOS 5, …. (Licenses [3]) • **ARAMIS Sensors** such as ARAMIS SRX, ARAMIS 3D Camera, … (Licenses [4]) • **T-SCAN hawk 2** (License: Sensor Driver T-SCAN hawk 2) • **PONTOS Live** (License Sensor Driver PONTOS Live) • **X-Ray Systems** such as METROTOM 6, METROTOM 1, … (Licenses [5])	✓	✓			⊖
• **CMM / VMM systems** such as ZEISS O-DETECT **,** ZEISS DuraMax, (License: Sensor Driver Multisensor CMM) • These system needs additionally CMM-Neo OS	✓				
• **ARAMIS 24M** (License: Sensor Driver ARAMIS 24M)	✓	✓	✓		⊖
• **Photogrammetry** (License: Sensor Driver Photogrammetry)	✓				
• **T-SCAN hawk** (License: Sensor Driver T-SCAN hawk)	✓	⊖			✓
• **T-SCAN** (License: Sensor Driver T-SCAN)	✓			✓	

Table 2: IPC Driver license exists

✓ must be installed ⊖ must not be installed	ZEISS Hardware Service (Remote)	Image Acquisition Driver [1]	Camera driver ARAMIS 24M [2]	colin3D	T-SCAN hawk
• **ATOS Q** • **ATOS Core**	✓				⊖

[1] In the driver archive which may be downloaded from the ZEISS Download Center (ZEISS ID Required) this driver is named "InstallGigE-VERSION.exe" and located in the "InstallGigE" subfolders.
[2] In the driver archive which may be downloaded from ZEISS Download Center (ZEISS ID Required) this driver is named "ARAMIS_24M_Emergent_driver-VERSION.exe" and located in the "ARAMIS_24M_Emergent_driver" subfolders.

[3] Licenses for several ATOS sensors: Sensor Driver ATOS, Sensor Driver ATOS Core 2M, Sensor Driver ATOS Q for eMotors, Sensor Driver ATOS Q, Sensor Driver GOM Scan 1, Sensor Driver ATOS LRX
[4] Licenses for several ARAMIS sensors: Sensor Driver ARAMIS, Sensor Driver ARAMIS 2D, Sensor Driver ARAMIS 5M

[5] Licenses for several X-Ray systems: Sensor Driver METROTOM 6, Sensor Driver METROTOM 1, Sensor Driver VoluMax 9 titan, Sensor Driver Bosello MAX, Sensor Driver METROTOM 1500, Sensor Driver METROTOM 800