

MANUAL DE USUARIO PARA CONECTOR DE RED RJ45 CATEGORÍA 5 NIU



Materiales:

- Cable par trenzado UTP categoría 5 ó 6 o apantallado
- Crimpadora
- 2 Conectores RJ45



5 Cuando ya esté cortado tira del aislamiento hasta dejar ver los 8 hilos cruzados en 4 pares.



2 Las tarjetas de red de los ordenadores emplean 4 de sus 8 conectores para transmitir paquetes de datos. La conexión de los pares de cables en un determinado orden permiten que se comuniquen, directamente, equipos y dispositivos concentradores o conmutadores.

La función de cada una de las conexiones está descrita en la imagen adjunta.




3 Cogemos el cable (éste tendrá que ser de 2 metros de largo como mínimo y 50 metros como máximo, ya que cuanto más largo sea éste más interferencias tendrá).

En cualquier caso, la distancia máxima entre el concentrador o conmutador y el equipo no podrá superar, nunca, los 100 metros.




Cortamos un poco el aislante con la punta de la crimpadora y pellizcamos el aislamiento o funda externa del cable creando una muesca a su alrededor.

Debemos separar algo más de 2 cm.



cables.





O Los ponemos en orden. Se tendrá en cuenta esta combinación en los dos extremos (Blanco-Naranja Naranja; Blanco-Verde Azul; Blanco-Azul Verde; Blanco-Marrón Marrón).



8 Se cortan con la crimpadora dejando unos 12 ó 13 milímetros de cable pelado.


Conviene no quedarse corto ni excederse en la medida de los cables. Para evitar su rápido deterioro.



9 Después introduciremos los hilos dentro del conector vigilando que entren por su carril hasta que hagan tope con el fondo.



10 Comprobamos el conector visto de frente, de manera que podamos ver las puntas de cobre de los hilos pegadas a la parte frontal.



Es importante que la funda del cable esté perfectamente introducida en la clavija.



12 Introducimos el conector dentro de la crimpadora poniendo especial cuidado en que, en la manipulación, no se desplacen los hilos que habíamos introducido en el conector



13 Presionaremos fuertemente la crimpadora para que se claven bien los contactos en el cable y la funda de plástico del mismo.



Repetiremos los pasos 1 al 9 en el otro extremo.



15 Ya está finalizado el cable.




USER MANUAL FOR NETWORK CONNECTOR RJ45 CATEGORY 5 NIU



1 Materials:

- Twisted pair UTP cable category 5 or 6 or shielded
- Crimper
- 2 RJ45 connectors



The network cards of computers use 4 of their 8 connectors to transmit data packets. The connection of cable pairs in a specific order allows equipment and concentrator devices or switches to be directly communicated.

The function of each of the connections is described in the attached image.



3 We take the cable (this will have to be at least 2 meters long and 50 meters maximum, since the longer it is, the more interference it will have).

In any case, the maximum distance between the concentrator or commutator and the equipment can not exceed 100 meters.



We cut the insulation a bit with the tip of the crimper and pinched the insulation or outer sheath of the cable creating a notch around it. We must separate something more than 2 cm.



5 When it is cut, strip the insulation until you see the 8 threads crossed in 4 pairs.





6 Separate and unwind the pairs of cables.



We put them in order. This combination will be taken into account at both ends (White-Orange Orange, White-Green Blue, White-Blue Green, White-Brown Brown).




They are cut with the crimper leaving about 12 or 13 millimeters of bare wire. It is advisable not to fall short or exceed the size of the cables. To prevent its rapid deterioration.



9 Then we introduce the wires inside the connector watching that they enter their lane until they make a stop with the bottom.



We check the connector seen from the front, so that we can see the copper tips of the wires stuck to the front.



11 It is important that the cable sheath is perfectly inserted into the plug.



(12) We introduce the connector inside the crimper, taking special care that, in the manipulation, the wires that we had introduced in the connector do not move.



We strongly press the crimper so that the contacts in the cable and the plastic sleeve of the same nail well.



14 We will repeat steps 1 through 9 at the other end.



15 The cable is already finished.