

Engineering assessment — BUS-204 engine failure of 12 July 2026

Vehicle	BUS-204 (VIN VF7AR12D0B4000204), Arvéa Citybus 12 D, commissioned 1 July 2011
Failure	12 July 2026 06:48 — loss of oil pressure, engine seized, line L07
Work order	WO-2026-071244
Odometer	742,380 km

Diagnosis

Crankshaft bearing failure due to wear. Oil sample taken after failure shows fuel dilution. The 60,000 km oil-analysis task (OIL-60K) was due at 739,980 km and had not been carried out: overdue by 2,400 km.

Assessment

The failure is consistent with end-of-life wear. The engineering team cannot exclude that the overdue oil analysis would have detected the dilution. This question is referred to commercial review under Article 34.4.4.

Recommendation

Rebuild the engine (quote Q-26-1187, €28,000 HT) only if the vehicle is needed until tranche 2 batch 3 arrives; otherwise withdraw BUS-204.