

Fig 14: Eutectoid Phase diagram




Fig 15: The Fe-Fe₃C Phase diagram Source: Calister Jr. Pg. 290




Fig 16: Cooling of Hypo-eutectoid and hypereutectoid steel

Source: Engineering materials by Donald Askeland 6th edition

Fe-Iron Carbide Diagram

- Most important commercial phase diagram
- Basis for the IRON and STEEL industries.

Cementite (Fe₃C)

Consists of 6.67%C

```
NOTE:(Fe_3C, C=12, Fe=56, Fe_3C=180 hence C/Fe_3C=12/180 \times 100\% = 6.67\%)
```

- Extremely hard, brittle phase of complex crystal structure
- Dissolves in ferrite interstitially
- Is the hardest substance found in the phase diagram

Ferrite (a-Solid solution)

- -BCC in structure
- -Soft and ductile phase
- -- Softest substance in the diagram
- -Can contain a maximum of 0.02%C

Austenite (γ-Solid solution)


- -Interstitial solid solution of carbon in iron
- -FCC in structure
- Slightly harder and less ductile than ferrite
- -Can contain a maximum of 2%C
- -Unstable at room temperature

Pearlite (0.8%C)

- -Eutectoid microstructure
- alternate layers of ferrite and Cementite
- -Plate-like (lamellar) mixture of ferrite and Fe₃C
- -Hardness and ductility lies between those of ferrite and Cementite See Fig 16

Ledeburrite (4.3 % C)

- -Eutectic microstructure
- -Occurs in cast irons (> 2%C)
- Colonies of Pearlite in matrix of Cementite



Point	Phase	comp	l. A	APY Mioni
	L	3%c	100%	0
2	L	7376	Essentially 100%, L	4
	X	~ 1.37.c	Negligible 8	
3		3.61.c	3-1-7 x 100= 68.	1 63 ×
	y	1.7%.0	= 100-68.4=31.6	(Ti
4	Jul don	TE 4.3%(3-1-1100=43.41	X
Julian	8	2.0/6	7.6.6 1/2	
5 just				

	(1) []	ine D	Relative Amount	
Point	Phases -	comphases	Relative Amounts	Approx. Sketel.
8	1/3/	1-50/0C	100%=L	
		•	THE THEFT END	
10 1	11.11	y 1 1 1 1 Y 7	16. 1 F. 1 - X - 11	
111	(1L)	7150.0	Essentially 100% L	6.
9	11	-1317000	ault of the	(00)
	8	-0.75%c	regligible &	
		()	9) - 101-1	18
- 4- 1	I LIN	2.2%	1.5-1.1 X100=36.4%	
01		THE SELA	2.2-1.1	
-	1	1.1% 011	= 63.6%	pro-enters,1
1		1. 20/6	Nagligisle L.	L. M. Co
-11		× 3°/55	20 23(19) 22 2	
-11	8	L8 125 %C	Essentially 100%	
	0.	20 123 /0	Escherally 100 100	1000/0
) - Jr. 111		
12	X	1. (0)	100%	0 primany
	X	40500	Essentially 100%8	Notific Es
13		0	- 17 Jak 1 2 1 5 2 14 1 - 1	CORP Y
	Fego	6.671,	Negigish Fey C	primary
)) 1	183 8= 88-11/s	Feg C
14	1 8	0.8.0	RS 0- 80°113	666
Just abov	0 60 6	6.67/5	111-0,8 200 = 11.91	10×6000×00×
TED	1 Fez C	0.01/2	1.7 0.8 x 12 = 11.9.1	
-3/		DATE - 7.	1 12 12 1 1 1 1 1 1 1 1	
15	X	0.02	X= 7777	Primary
Just	1100	9 190	<u> </u>	P3C
De la	w			L Eutechid
De la	D Fez (6.67%	1.5-0.02 X100	Fly (
	7.		6.67-0.02	




Fig 17: Binary phase diagram with other invariant points

Eutectic	$L_{2} \rightarrow \gamma + \beta$	γ
Peritectic	$\lambda + L_1 \longrightarrow \gamma$	$\lambda + L_1$ γ L_1
Monotectic	$L_1 \longrightarrow \gamma + L_2$	γ L_1 $\gamma + L_2$ L_2
Eutectoid	$\gamma \longrightarrow \alpha + \beta$	α $\alpha + \beta$ β
Peritectoid	$\alpha + \beta \rightarrow \mu$	$\alpha + \beta$ β

Fig 18: Diagram showing the invariant points




Fig 19: Al-Mg Phase Diagram




Fig 20 Cu-Sn Phase diagram

WATCH THIS VIDEO ON MANUFACTURE OF STEEL

https://www.youtube.com/watch?v=9A MbKpeJRoU

https://www.youtube.com/watch?v=xej nSzbFMQA