

Sample Defect Report

Cochin Port Authority, wharf 4, cycle 2, June 2026

Scope

Wharf 4 north face, 380 metres of quay structure, two rail mounted quay cranes and the associated fendering. Flown 11 June 2026 against the plan stored from cycle 1 in March.

Summary of findings

Severity	Count	Example	Recommended action
Critical	1	Section loss on bollard mounting plate 14	Structural assessment within 30 days
Major	6	Coating breakdown with active corrosion, crane leg 2B	Remediate within 90 days
Moderate	14	Fender panel displacement, bay 7	Schedule in next maintenance window
Minor	25	Surface staining and marine growth	Monitor at next cycle
Total	46	-	-

Critical finding, F 07

Corrosion with section loss on the seaward face of bollard mounting plate 14, position 9.9678 N 76.2603 E. Measured affected area 340 by 210 millimetres. Growth of 18 percent in area since cycle 1. Recommended action: structural assessment within 30 days.

Change since cycle one

Of 34 findings in cycle 1, 9 were repaired and closed, 21 are stable within measurement tolerance, and 4 have grown. 12 new findings were raised in cycle 2.

Method note

Measurements are photogrammetric with a stated accuracy of plus or minus 8 millimetres at the flown standoff distance. This report is an aid to inspection and does not replace a structural engineer's assessment.