

PUMP-204 MAINTENANCE HISTORY (SYNTHETIC)

This is a demo record. It is not a real plant log.

2026-06-12 Mechanical seal replaced (drive end).

Reason: visible weepage during walk-around.

Work: new seal kit, alignment check, 30-minute run test.

Result: leak stopped. Vibration 3.1 mm/s after work.

2026-08-03 Suction strainer cleaned.

Reason: flow had drifted down during summer load.

Result: flow returned to the normal band.

2026-09-01 Quarterly visual inspection.

Notes: coupling guard in place. No new oil stains at that date.

Next due: weekly vibration and temperature log.

Open items for PUMP-204 (demo)

- Recheck seal area after any vibration step-up above 7.0 mm/s
- Compare current vibration with the 3.1 mm/s post-seal baseline
- If temperature and vibration rise together, inspect bearings and strainer first

Related files: [pump_manual.pdf](#), [inspection_procedure.pdf](#), [sensor_data.csv](#).