

CORNER TILES BREAKAGE ON THE ROOF:

In the photos provided of the “corner breakage” tiles on the roof, it is not possible to identify how the tiles are supported by each other and how much slack they have in the assembly.

If you can identify **a very clearly defined break in the tile**, possibly the same length, always the same break line and in the form of an arch (these measurements would have to be checked).

All concrete roof tile models already have prefixed "design" values with manufacturing thicknesses and manufacturing weights (raw materials and curing) that are the standardised values for the good accommodation of the tile on the roof and values of resistance to bending,





Once checked the differences between the values given for the thicknesses of the manufactured tiles, it will be possible to make an initial assessment of possible causes of this breakage in the roof:

- a) If the tile breaks on the roof when walking, I consider that the tile does not support the effort downwards, when stepping on the tile in the centre with the support of the side (possible bad support in the area of assembly in the 2 tiles or lateral contact) and that facilitates making an **over lever effort that the tile cannot resist**, that area is too critical (fragile) before any value of resistance to bending of the standardised tile.
- b) If the tile breaks when it is placed on the roof, without additional external stress, it may be because there is already a crack in the tile that facilitates the breakage (when **fresh** by lifting that area of **the tile when cutting the tile** or in the **curing process** due to a shrinkage of the tile in the mould). There is less possibility of tile breakage due to **no good support** between tiles due to deformations in the aluminium moulds or **deformation in the profile** in the support area.

