FIRE SAFETY INSPECTION REPORT

PRM FASHIONS PVT. LTD.

ACCORD ID: 12808

SS SFB #5, SECTOR # 3, KARNAPHULI EXPORT PROCESSING ZONE, CHITTAGONG-4204, BANGLADESH (22.276409, 91.796774)

OTHER FACTORY (S): NONE



ACCORD
on Fire and Building Safety in Bangladesh

Inspected By: Dilip Kumar Mondal & Md. Ferdaus Jaman
Date: 06 April, 2017

Findings & Recommendations :

Table 1 summarizes the major fire safety issues identified during the inspection. Recommendations have been provided to address each issue. An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design/ installation constraints, shall be submitted to the Accord for approval.

Table-1:

Sl No.	Category	Findings	Required Action	Remediation Time Frame
1	Fire Rated Construction	The exit stair no-1 enclosure is not separated from work areas and other spaces on each floor by fire-rated construction(Non rated doors, unsealed penetrations and openings etc. such as HRD office, maintenance room, CAD room, Goods in/out room).	Provide minimum 1-hr rated doors for buildings with 3 or fewer stories and 1.5-hr fire rated doors for buildings that are 4 or more stories. Seal all unprotected openings to separate the exit stairs from work areas and other building spaces on all floor levels. Ensure that the fire doors are self-closing and positive latching and that they are provided with fire exit (panic) hardware where serving production floors. If fire doors are required to be held open for functional reasons, provide automatic closing devices tied to the fire alarm system. Once fire doors are installed, every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets.	Within 3 months







2	Fire Rated Construction	Unsealed penetrations and openings are located in the exit stair enclosures. **Location:** North side stair no-2 each floor.	Seal all penetrations and openings in exit stair enclosure walls to maintain the fire separations.	Within 3 months





3	Fire Rated Construction	Unsealed penetrations and openings are located in the fire rated floor/ceiling assemblies. **Location:** Sub-station room to storage area & store room to egress path on ground floor, production floor on 2nd & 3rd floor.	Seal all penetrations and openings in floors/ceiling assemblies to maintain the fire separation.	Within 3 months





4	Egress	Egress doors/gates with locking features not complying with NFPA101 are provided at building. **Location:** Ground floor & roof.	Remove locking features from all egress doors/gates. If locks are required for security reasons, utilize specialized door locking features complying with NFPA101.	Immediate





5	Egress	Storage was located in all exit stairs & ramp enclosure (machine storage) on ground floor.	Remove/relocate (separate by fire rated construction for idle machine room) storage from the exit stairs and egress path.	1 month







6	Egress	Parapets or guards are not provided in the roof accordance with Accord standard.	Provide parapets or guards with a minimum height of 1067mm (42 inch.).	Within 3 months





7	Fire Detection and Alarm System	Automatic fire alarm & detection system installation requires detailed review to confirm compliance with NFPA 72 and ACCORD standards. Still few areas are out of detection system.	Submit as-built drawings, testing records, equipment certification and other relevant documentation to the ACCORD for review and approval.	Within 3 months







8	Fire Protection System	The existing building has an occupied floor greater than 10 meter (33 feet) and requires standpipe system detailed review to confirm compliance with NFPA 14 and ACCORD standards.	Submit the as-built design of standpipe system throughout the building in accordance with NFPA 14.	Within 3 months





9	Fire Protection System	Fire pump installation requires detailed review to confirm compliance with NFPA 20 and ACCORD standards.	Submit as-built drawings, testing records, equipment certification and other relevant documentation to the ACCORD for review and approval.	Within 3 months





10	Fire Detection and Alarm System-ITM	Inspection, testing, and maintenance (ITM) for the fire detection system is not in accordance with NFPA 72.	Inspect, test and maintain the fire detection system, and keep written records on-site, in accordance with NFPA 72.	Within 3 months
11	Fire Protection System (ITM)	Inspection, testing and maintenance (ITM) of the standpipe system is not in accordance with NFPA 25.	Inspect, test and maintain the standpipe system and keep written records on-site, in accordance with NFPA 25 and ACCORD standards.	Within 3 months
12	Fire Extinguishers (ITM)	Inspection, testing and maintenance of portable fire extinguishers is not in accordance with NFPA 10.	Inspect, test and maintain the portable fire extinguishers and keep written records onsite, in accordance with NFPA 10 and ACCORD standards.	Within 3 months

13	Egress Lighting	The directional signs are not provided where there is a change in direction and where the continuation of the egress path is not obvious.	Install illuminated directional sign where there is a change in the direction of the path of travel.	Within 1 month
				
14	Egress Lighting	Manual on-off switch facility available for emergency lights/exit signs.	Remove manual on/off switches from emergency lighting units/ exit signs to prevent them from being switched off.	Within 1 month
				

15	Emergency Lighting-ITM	Inspection, testing, and maintenance (ITM) for the emergency lighting system were not in accordance with The ACCORD standard.	Inspect, test and maintain the emergency lighting system in the accordance with The ACCORD standard. Keep written records on-site.	Within 3 months
16	Egress Lighting	Emergency lighting did not function in test mode (burned out, broken, etc.). Several fog light on aisles.	Regularly test the emergency lighting system on each floor and replace/repair lights as needed.	Within 1 month



