INITIAL FIRE SAFETY INSPECTION REPORT

Ingenitex (BD) Limited

RSC ID: 24518

Jamgora, Zirabo, Ashulia, Dhaka

Other Factories: N/A



Inspected By: Mohammad Anayet Hossain & Meher Sultana Moitry

Date: 13 February, 2023

Fire Safety Inspection Report

Ingenitex (BD) Limited

Introduction:

Ingenitex (BD) Limited was surveyed for fire safety on **13/02/2023** by The RSC Inspection Team. The purpose of the survey was to identify significant fire safety issues and to provide recommendations for remediation based on applicable standards specified by the RSC. The scope of this initial fire safety inspection was limited to the review and identification of major fire safety issues. The inspection did not include identification of minor deficiencies, which will be further addressed as part of follow-up inspections.

Limitations

The information in this fire safety inspection report was obtained during a visit to the facility and during interviews with local factory management. It has not been possible to provide independent verification for all the information and data collected, and, therefore, The RSC cannot accept general responsibility for omissions or errors arising from inaccuracies in this report from the information obtained.
The findings and recommendations in this report are not intended to imply, guarantee, ensure or warrant compliance with any government regulations. Additionally, the results do not imply in any way that compliance with the findings or recommendations as stated in this report will eliminate all hazards, risks or exposures or that hazards, risks or exposures not referred to in this report do not exist. Compliance with the findings and recommendations stated in this report does not relieve the factory owner from obligation to comply with specific project requirements, industry standards, or the provisions of any local government regulations.

General Factory Information

Factory Building name(s): There is only one structure under this ID.
The name of the structures are as: 1. Factory Building (6 Storied RCC Building)

Findings & Recommendations :

Ingenitex (BD) Limited (RSC ID: 24518)

Table 1 summarizes the fire safety non-compliant issues identified during the inspection. Recommendations have been provided to address each issue with specific remediation timeline.

An implementation schedule shall be developed by the factory to remediate each of the findings. The specific timing of improvements, including any requested extensions due to design / installation constraints, shall be submitted to the RSC for approval.

Table-1:

Sl No.	Category	Findings	Required Action	Remediation Time Frame
F-1	Fire Rated Construction	The exit stair enclosures are not separated from [work areas, other spaces] due to penetrations and openings by fire-rated construction.	Separate the exit stairs from work areas and other building spaces on all floor levels by minimum 2-hr fire-rated construction. Provide minimum 1.5- hr fire rated doors and seal all unprotected openings and penetrations to maintain the fire separation. Ensure that all fire doors are self-closing and positive latching, and are provided with fire exit (panic) hardware where serving production floors or assembly occupancies. If fire doors are required to be held open for functional reasons, provide automatic-closing devices tied to the fire alarm system. Once fire doors are installed, every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets RSC Technical Guidelines (Standard) V1- 6.8.3.1.	Within 3 months
				

F-2	Fire Rated Construction	Areas used for combustible storage at several floors open to the factory are not separated by fire rated construction.	Provide defined storage areas and limit the storage arrangement as follows:- 1. General Condition: Maximum height of 2.4m and maximum area of 23m2. Separate areas of unenclosed combustible storage by a minimum clear distance of 3m. 2. If sprinkler protected: maximum height of 3.66m and maximum area of 93m2. Separate areas of unenclosed combustible storage by a minimum clear distance of 3m. or 3. Enclose the storage area from the surrounding occupancy with a minimum 1 hour construction.	Within 3 months
  				
F-3	Fire Rated Construction	Unsealed floor penetrations through Toilets, Sanitary Pipe, Fire cables shaft (inside), Floor windows (direct west side) are located in the fire-rated floor/ceiling assemblies.	Seal all penetrations and openings in floor/ceiling assemblies to maintain the fire separation at least by 3-hr. The used sealer shall be 3rd party certified and installation shall be as per manufacturer's datasheet. Or Provide a minimum 2-hr fire rated shaft to separate the utility risers from each floor if required.	Within 3 months

		   		
F-4	Fire Rated Construction	Elevator shafts are directly open into the inside of exit stair enclosure. Location: Stair 1 (South-West) and Stair 2 (South-East) of production building.	Modify the elevator shaft as per RSC Technical Guideline (Standard) V1-6.14.3. An exit stairway shall not be built around a lift shaft unless both of them are located in a smoke proof enclosure and made of a material with fire resistance rating required for the type of construction of smoke proof enclosure. So, ensure the lift shaft is 2-hr fire rated including opening protection with similar rating.	Within 3 months
		 		

F-5	Fire Rated Construction	Bonded ware house at stair 2 (1st floor), FG warehouse at stair 1 (1st floor) and accessories store at stair 2 (5th floor) discharge directly into the exit stair enclosures and are not meet the RSC Technical Guidelines (Standard) V1-6.14.3)	Openings from exit enclosure to storage rooms shall be provided with a vestibule with fire rated construction and openings as per RSC Technical Guideline (Standard) V1-6.14.3. Provide a 1.5 hr. fire rated door on the exit stair side and a 1-hr. fire rated door on the Store room side. Ensure that the fire rating of the vestibule construction matches that of the exit stair enclosure.	Within 3 months
				
F-6	Fire Rated Construction	Dining room and Prayer room are located at 1st floor are not properly fire separated from other occupancy by fire rated construction.	Separate the dining & prayer room from production & other occupancies (present sample section) by minimum 3-hr fire rated construction. Provide rated exit passageways leading directly to the exit stairs with the same resistance rating.	Within 3 months

				
F-7	Fire Rated Construction	A single means of egress is provided at Finished goods warehouse located at 1st floor, where the travel distance exceeds 75 feet (or, 23 meter) and does not meet the RSC Technical Guidelines (Standard) V1- 6.6.2)	Reconfigure the egress arrangement to reduce the maximum travel distance to not more than 23 meter (or, 75 feet). Or, -Provide additional means of egress.	Within 3 months
				
F-8	Fire Rated Construction	Compressor room located at ground floor is not properly separated by fire rated construction with exit stair enclosure 2.	Separate the compressor room by a minimum 2-hr fire rated construction. Seal and/or protected all openings to maintain fire separations. Or Relocate all to exterior of the building and maintain a minimum 3m (10 ft.) spatial separation distance from the building.	Within 1 month

				
F-9	Fire Alarm & Detection System (FADS)	Fire alarm and detection system installation requires detailed review to confirm compliance with NFPA 72 and RSC Technical Guidelines (Standard) V1.	Submit design, documents and calculations to RSC for review prior and based on the review modify the system if there is any. After installation the owner shall contact the RSC for witness of conducting the final acceptance testing of the fire detection & alarm system installation. Also inspect, test and maintain the fire alarm system, and keep written records on-site, in accordance with NFPA 72.	Design Review within 2 months and modification within 4 months (If require).
F-10	Inspection, testing, and maintenance	Inspection, testing and maintenance for the fire alarm system is not in accordance with NFPA 72.	Inspect, test and maintain the fire alarm system and keep written records on-site, in accordance with NFPA 72.	Within 1 month (after installation)
F-11	Fire Protection System (Standpipe System)	Standpipe system and fire pump installation requires detailed review to confirm compliance with NFPA 14 ,20 ,22, 24 and 25 and as per RSC Technical Guidelines (Standard) V1.	Submit the standpipe system drawing to RSC for review. Once reviewed, install or modify the standpipe system throughout the building in accordance with Accord standard and NFPA 14 and 20. The factory management shall contact RSC to conduct the final acceptance testing after the installation, testing & commissioning.	Design Review within 2 months and modification within 4 months (If require).
F-12	Inspection, testing, and maintenance	Inspection, testing, and maintenance for the Standpipe system is not in accordance with NFPA 25 or as per RSC standard.	Inspect, test and maintain the standpipe system and keep written records on-site, in accordance with NFPA 25 or as per RSC standard.	Within 1 month (after installation)
F-13	Inspection, testing, and maintenance	Inspection, testing, and maintenance for the Fire pump & water system is not in accordance with NFPA 25 or as per RSC standard.	Inspect, test and maintain the fire pump & water system and keep written records on-site, in accordance with NFPA 25 or as per RSC standard.	Within 1 month (after installation)

F-14	Egress	Building did not have stair designation signs at floor entrances and re-entry provisions where every door in a stair enclosure serving more than 5 stories.	Provide stair designation signs at required locations and every door in a stair enclosure serving more than 5 stories shall be provided with re-entry unless it meets the requirements of RSC Technical Guidelines (Standard) V1- 6.8.3.1.	Within 1 month
F-15	Egress lighting	Based on the number and location of emergency lights observed, adequate illumination levels are not anticipated along egress routes.	Test the emergency lighting system on each floor and provide additional emergency fixtures to provide adequate illumination along the means of egress. Provide a minimum illumination of 10 lux at the floor level within exit stairs and exit discharge paths and minimum 2.5 lux along exit access aisles.	Within 1 month
F-16	Inspection, testing, and maintenance	Inspection, testing, and maintenance for the exit sign and emergency lighting system was not in accordance with NFPA 10.	Inspect, test and maintain the exit sign and emergency lighting system in the accordance with NFPA 10. Keep written records on-site.	Within 1 month
F-17	Inspection, testing, and maintenance	Inspection, testing and maintenance of portable fire extinguishers is not in accordance with NFPA 10.	Inspect, test and maintain the portable fire extinguishers and keep written records on-site, in accordance with NFPA 10.	Within 1 month