INITIAL FIRE ASSESSMENT REPORT (FAR)

Factory Name:	**ULTIMATE FASHIONS LIMITED**
Address:	**South Gouripur, Ashulia, Savar Ashulia, Savar Dhaka Bangladesh**
Assessor:	**Shaheedullah**
Date:	**16 May 2016**

Introduction to the Report

The following report contains a site profile and summary of non-conformities identified during an onsite assessment commissioned by the Alliance for Bangladesh Worker Safety (Alliance) and conducted by a third-party Qualified Assessment Firm (QAF). The assessment was conducted against the Alliance for Bangladesh Worker Safety Assessment Protocols (APs) and Fire Safety and Structural Integrity Standard, which is harmonized with the factory assessment guidelines developed by Bangladesh University of Engineering and Technology (BUET) for the Bangladesh National Tripartite Plan of Action (NTPA). The goal of the Alliance process is to provide clear and practical technical requirements by which Bangladeshi Ready Made Garment (RMG) Factories producing for Alliance members may be consistently and fairly evaluated for fire, structural, and electrical safety in a non-duplicative manner. Each assessment will prompt action plans that will be used by RMG factories to systematically and sustainably improve safety conditions for garment workers. Beyond tracking and reporting on action steps taken in a transparent manner, the Alliance organization and its members will seek to further support factory improvements through technical assistance, training, implementation support for functional Worker Committees, and in some cases financial assistance and wage support for workers if factories are closed for remediation.

The contents of the report do not constitute a guarantee of compliance with the applicable laws, the Alliance Standard or the absolute or continued safety against fire, electrical and/or structural integrity issues that may lead to injury or loss of life. The report is designed to provide a non-exhaustive summary of risk issues, based on a limited sampling and duration of time onsite by the named QAF. Neither the QAF nor the Alliance can certify or guarantee the quality, outcome, or effectiveness of actions taken in response to the report.

For more information and report feedback please go to: www.bangladeshworkersafety.org.

GENERAL INFORMATION

General Information	
Factory Name:	ULTIMATE FASHIONS LIMITED
Address:	South Gouripur, Ashulia, Savar Ashulia, Savar Dhaka Bangladesh
Country:	Bangladesh
Province:	Dhaka
City:	Ashulia, Savar
Zip Code:	
Audit Duration:	2 Days
Re-Audit:	Re-Audit After 0 Months
Draft Report Date:	01.06.16
Final Report Date:	30.06.16
Are all Action Items From Previous Assessment Completed?:	N/A
Buildings in Complex:	There are 7 buildings, 2 main and 5 ancillary buildings. 1) Main Factory Building-1; 2) Main Factory Building-2; 3) Office Building; 4) Canteen & Storage Building; 5) Utility Building; 6) Generator Building; 7) Pump House.
Is the building(s) owned or rented by the Factory:	Rented
Number of Building Levels (Stories):	1) Main Factory Building-1: 1 story 2) Main Factory Building-2: 2 stories.
Approximate Building Area (SF):	1) Main Factory Building-1: 28,416 SF; 2) Main Factory Building-2: 35,842 SF.
Date of Building Construction:	1) Main Factory Building-1: 2010; 2) Main Factory Building-2: 2015; 3) Office Building: 2010; 4) Canteen & Storage Building: 2010; 5) Utility Building: 2015; 6) Generator Building: 2015; 7) Pump House: 2015.
Date of Last Building Renovation/Addition:	N/A
Ancillary Structures in Complex:	There are 5 Ancillary buildings. 1) Office Building; 2) Canteen & Storage Building; 3) Utility Building; 4) Generator Building; 5) Pump House.
Approximate Ancillary Structures Area (SF):	1) Office Building: 16,700 SF; 2) Canteen & Storage Building: 12,400 SF; 3) Utility Building: 1,110 SF; 4) Generator Building: 200 SF; 5) Pump House: 105 SF.

Number of Occupants:	Total occupants: 1067. 1) Main Factory Building-1: 385; 2) Main Factory Building-2: 610; 3) Office Building: 45; 4) Canteen & Storage Building: 23; 5) Utility Building: 4 6) Generator Building: 0; 7) Pump House: 0.
Number of Ancillary Levels (Stories):	1) Office Building: 4-stories; 2) Canteen & Storage Building: 3-stories; 3) Utility Building: 1 story; 4) Generator Building: 1 story; 5) Pump House: 1 story.
Occupancy Type:	Industrial- G2 (RMG)
Construction Type:	1) Main factory building-1: Non- rated; 2) Main Factory Building-2: Non- rated; 3) Office Building: Type-2; 4) Canteen & Storage Building: Type-2; 5) Utility Building: Type-2; 6) Generator Building: Non-rated; 7) Pump House: Type-2.
Height of Highest Occupied Floor Level Above Grade:	Highest Occupied Floor Level Above Grade: 1) Main Factory Building-1: At grade; 2) Main Factory Building-2: 4.65 m (15 ft 3 in.); 3) Office Building: 12.42 m (40 ft 9 in.); 4) Canteen & Storage Building: 6.4 m (21 ft.); 5) Utility Building: At grade; 6) Generator Building: At grade; 7) Pump House: At grade.

ASSESSMENT FINDINGS

Fire Protection Construction

Question:	Are openings and penetrations through rated walls and/or assemblies protected?
Priority Level:	High
Non-Compliance Level:	2
Description:	Openings through rated walls were noticed at the entrance to exit stair-1 & -2 in the Office Building. Doors to these stairs were also found provided with glass doors. Penetration of electrical cable through the rated wall of stair enclosure in Main Factory Building-2.
Source of Findings:	Photograph: I) Opening through the rated wall. II) Penetration through rated wall.
Suggested Plan of Action:	Provide fire-resistive rated opening or penetration protection for rated walls and assemblies in accordance with Alliance Standard Sections 4.6 and 4.7. Consult a qualified fire protection engineer to design the required opening or penetration protection systems.
Suggested Deadline Date:	30 Sep 2016
Standard:	Includes doors, windows, ducts, piping, etc. Reference Alliance Standards Part 4 Section 4.6 Opening Protectives and Section 4.7 Penetrations





Question:	Are separations between hazards provided with fire-resistive rated construction barriers.
Priority Level:	Medium
Non-Compliance Level:	2
Description:	The spot removing room located on the south side of the 1st floor of Main Factory Building-2 is provided with non-rated Thai- Al glass wall and a non-rated ceiling. The fire pump in the Canteen & Storage Building is not separated from storage areas or the maintenance workshop.
Source of Findings:	Photograph: Spot removing room.
Suggested Plan of Action:	Provide fire-resistive rated construction barriers (with associated opening protection) between hazard types in accordance with Alliance Standard Sections 3.4 and 4.5. Consult a qualified fire protection engineer to design the required rated construction barriers.
Suggested Deadline Date:	31 Dec 2016
Standard:	Reference Alliance Standards Part 4 Section 4.5 Separation



Question:	Certificates of Occupancy for each building have been issued and are on file.
Priority Level:	Low
Non-Compliance Level:	3
Description:	No occupancy certificates were provided for any building.
Source of Findings:	Document Review: No document was available during document review.
Suggested Plan of Action:	Apply to appropriate authority in an expeditious manner for issuance of the Certificates of Occupancy for each building and ancillary structure according to building use.
Suggested Deadline Date:	15 Aug 2016
Standard:	Are certificates of occupancy provided for each building or ancillary structure?

Fire Protection Systems

Question:	Does the building have a Standpipe System?
Priority Level:	High
Non-Compliance Level:	2
Description:	It was noticed that the factory is provided with a Class III Standpipe System but no approved design documents were available at the time of inspection.
Source of Findings:	Photograph: i) 2 1/2 in. hose connection at the roof of Office Building. ii) Hose station in the interior of the of Main Factory Building-2. iii) Standpipe system piping.
Suggested Plan of Action:	Prepare shop drawings and hydraulic calculations (as outlined in NFPA 14) for the installed system and submit to the Alliance for review. Should the existing standpipe system be found to be not in compliance with the design requirements of NFPA 14, modify or replace the system, as needed, for compliance. Prepare revised drawings and calculations for review by the Alliance prior to any modification or installation.
Suggested Deadline Date:	30 Sep 2016
Standard:	Does the building have a standpipe system installed where required. Alliance Standard Part 5 Section 5.4.2







Question:	Trouble or alarm notifications were not indicated on the fire alarm control panel.
Priority Level:	High
Non-Compliance Level:	2
Description:	The fire command room is housed on the ground floor of the Office Building, It was noticed that the alarm notification was indicated on the fire alarm control

	panel during a test run of the system.
Source of Findings:	Visual Assessment: visual assessment during the survey
Suggested Plan of Action:	Have the system inspected and/or repaired by a qualified fire alarm installation company.
Suggested Deadline Date:	14 Sep 2016
Standard:	Alliance Standard Part 13 Section 13.10 Maintenance of Fire Protection Equipment
Question:	Are notification and initiation devices for the fire alarm system installed at required locations based on occupancy type?
Priority Level:	High
Non-Compliance Level:	2
Description:	Notification and initiation devices for the fire alarm system were found to be installed in the facility. It was noticed that smoke detectors were provided in the toilets. No approved design document was provided during the inspection.
Source of Findings:	Photograph: i) Smoke detector in the ceiling. ii) Strobe on the wall. iii)FACP in the fire control room.
Suggested Plan of Action:	Develop and/or provide shop drawings for the installed automatic fire alarm and detection system for the buildings under assessment to the Alliance for review.
Suggested Deadline Date:	30 Sep 2016
Standard:	Pull stations at egress points, smoke detectors in air handling equipment, visual and audible devices spaced appropriately based on occupancy type. Reference NFPA 72
Question:	Does the building have a fire pump?
Priority Level:	High
Non-Compliance Level:	1
Description:	An electrically driven fire pump and a diesel operated standby fire pump of 500 gpm at 6.5 bar capacity were found installed for the facility, but no documents were available regarding listings of the pump. The pump is located on the ground floor of the Canteen & Storage Building without any separation from storage areas or the maintenance workshop. The exhaust of the diesel engine is within the pump room.
Source of Findings:	Photograph: The fire pump for the facility.









Suggested Plan of Action:	Prepare shop drawings and hydraulic calculations for the installed system and submit to the Alliance for review. Should the existing fire pump arrangement be found to be not in compliance with the design requirements of NFPA, modify or replace the system, as needed, for compliance. Prepare revised drawings and calculations for review by the Alliance prior to any modification or installation. Also the fire pump shall be provided with fire-resistive rated construction barriers in accordance with the standard.	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standard Part 5 Fire Protection Systems	
Question:	Fire extinguishers are inspected, tested, and maintained as required.	
Priority Level:	Medium	
Non-Compliance Level:	3	
Description:	No documents were available related to the inspection, testing, or maintenance of the fire extinguishers.	
Source of Findings:	Document Review: No document was provided.	
Suggested Plan of Action:	Establish an inspection, testing, and maintenance program for all fire extinguishers and prepare proper documentation. Program must comply with NFPA 10.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	NFPA 10 Chapter 7	
Question:	Are inspection, maintenance, and testing procedures of the standpipe and hose system documented and up to date? Including inspection and testing of hoses if provided.	
Priority Level:	Low	
Non-Compliance Level:	3	
Description:	No documents were available related to the inspection, maintenance, or testing procedures of the standpipe and hose system.	
Source of Findings:	Document Review: No document was provided.	
Suggested Plan of Action:	Establish an inspection, testing, and maintenance program for the standpipe system. Program must comply with NFPA 25. Any newly installed standpipe system needs to be evaluated for compliance with the design pressure and flow demands of NFPA 14 or BNBC Section 5.4.3.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Reference NFPA 25 Chapter 6 Standpipe and Hose Systems Table 6.1.1.2	

Question:	Are inspection, maintenance, and testing procedures of the fire pump documented and up to date?	
Priority Level:	Low	
Non-Compliance Level:	3	
Description:	No documents were available related to the inspection, maintenance, or testing procedures for the fire pump.	
Source of Findings:	Document Review: No document was provided.	
Suggested Plan of Action:	Establish an inspection, testing, and maintenance program for the fire pump. Program must comply with NFPA 25.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Reference NFPA 25 Chapter 8 Fire Pumps	
Question:	Is signage for the standpipe system installed at required locations and on required components?	
Priority Level:	Low	
Non-Compliance Level:	2	
Description:	Signage for hose stations, hose connections, and for Hydraulic Design Information was not noticed during the survey.	
Source of Findings:	Visual Assessment: Facility survey.	
Suggested Plan of Action:	Install signage at required locations and on required equipment. Signage must comply with NFPA 14.	
Suggested Deadline Date:	15 Aug 2016	
Standard:	Reference NFPA 14 Chapter 6	
Means of Egress		
Question:	Exit discharge is directly to the exterior of the building, unless the requirements of 6.17.2 are met, at grade or provides direct access to grade. Exit discharge shall not reenter a building.	
Priority Level:	High	
Non-Compliance Level:	3	
Description:	Exit discharge of the stairs of Main Factory Building-2 is to the interior of the production floor. Exit discharge of the Canteen & Storage Building reenters Main Factory Building-1.	
Source of Findings:	Photograph: One exit stair of Main Factory Building-2.	

Suggested Plan of Action:	Exit discharge shall not reenter other buildings. Route exits directly to the exterior or provide an exit passageway in accordance with Alliance Standard Section 6.15 or an Egress Court in accordance with Alliance Standard Section 6.17.2 for non-compliant arrangements. Consult a qualified fire protection engineer to design and/or approve the required exit passageway or egress court.	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standard Part 6 Section 6.17 Exit Discharge. See Section 16.7.2 and 16.7.3 for exceptions.	
Question:	Exterior exit stairs are separated from the building with the required rating. The rating of the exterior wall shall extend 3.05 m (10 ft) beyond the ends of the stair structure.	 
Priority Level:	High	
Non-Compliance Level:	3	
Description:	The exterior stairs of the Canteen & Storage Building (Stair-1 & -2) connect grade level through level 3. The exterior stair of the Office Building (Stair-2) are not separated from the buildings with the required rating due to window openings. These stairs are also not separated from the adjacent Main Factory Building-1 without having required rating of its exterior walls, as well as, required separation distances from the stairs.	
Source of Findings:	Photograph: i) Exterior stair #2 of 4 storied R.C.C building ii) Exterior stair #2 of 3 storied R.C.C building	
Suggested Plan of Action:	Provide a fire-resistive rated assembly between the exterior exit stairs (and 10 ft beyond the ends of the stairs) and the building to achieve the required separation. Enclose any openings (windows, etc.) with required fire rated construction within that 10 ft wall section. The rated assembly should be designed and/or approved by a qualified fire protection engineer.	
Suggested Deadline Date:	14 Dec 2016	
Standard:	Alliance Standard Part 6 Section 6.3.1.2. Three stories or less 1-hr rating. Four stories of more 2-hr rating	

Question:	Interior exit stairways and ramps terminate at an exit discharge except where terminating at a rated exit passageway.	 
Priority Level:	High	
Non-Compliance Level:	3	
Description:	Interior exit stair-1 of the Office Building and 3 exit stairways of Main Factory Building-2 do not terminate at an exit discharge, they terminate to the interior of the buildings on the ground floor.	
Source of Findings:	Photograph: i)Interior exit stairway of Office Building. ii)Interior exit stairway of Main Factory Building-2	
Suggested Plan of Action:	Exits shall discharge directly to the exterior of the building unless meeting the requirements of Alliance Standard Section 6.17.2 or 6.17.3. If requirements are not met, route exits directly to the exterior or provide an exit passageway in accordance with Alliance Standard Section 6.15 for non-compliant arrangements. Consult a qualified fire protection engineer to design and/or approve the required exit passageway.	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standard Part 6 Section 6.14 Exit Enclosures	
Question:	Travel distance to reach an exit does not exceed the maximum distance allowed by Occupancy Type.	
Priority Level:	High	
Non-Compliance Level:	2	
Description:	The maximum travel distance to reach an exit of Main Factory Building-1 is approximately 300 ft.	
Source of Findings:	Photograph: Production floor of the 1 storied steel shed (main factory)building., Visual Assessment: Facility survey.	
Suggested Plan of Action:	Provide some combination of adding/adjusting exits within 45 m (147.6 ft) to any point on the floor, and/or adjust building protective systems (fire alarm, standpipe, sprinklers) for compliance with Alliance Standard Sections 6.13.1, 6.13.1.1, or 6.13.1.2.	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standard Part 6 Section 13 Travel Distance and BNBC Part 4 Section 3.15.1	

Question:	All doors in a means of egress are of the side-hinged swinging type.	
Priority Level:	High	
Non-Compliance Level:	2	
Description:	Steel sliding doors, each 8 ft in width, for the means of egress are provided on the South-East and East exterior of Main Factory Building-1.	
Source of Findings:	Photograph: Steel sliding gate.	
Suggested Plan of Action:	Replace non-compliant doors and frames in the means of egress with side-swinging doors. Door swing must be in the direction of travel. Replacement doors shall be a minimum width of 0.8 m (32 in), and are listed, approved, self-closing, fire rated door assemblies (door and frame) with latching panic hardware.	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standards Part 6 Section 6.8 Doors and Gates	
Question:	Landings are provided on both sides of doors used along the path of egress. Doors do not swing out over stairs.	
Priority Level:	High	
Non-Compliance Level:	2	
Description:	Landings are not provided on both sides of the doors that are used along the path of egress in the Utility Building, or on the ground floor of the Canteen & Storage Building.	
Source of Findings:	Photograph: Landings are not provided on both sides.	
Suggested Plan of Action:	Revise the door arrangement so that the doors do not swing out over the stairs for compliance with Alliance Standard Section 6.8.5.	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standards Part 6 Section 6.8 Doors and Gates	
Question:	All occupied roofs are provided with parapets or guards with a minimum height of 1067 mm (42 in.).	
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	The occupiable roof of the Office Building was found to have a parapet wall with a height of 32 in.	
Source of Findings:	Photograph: Parapet of the Office Building.	
Suggested Plan of	Provide parapets or guards with a minimum height of 1067 mm (42 in.) for all	

Action:	occupiable roof areas in accordance with Alliance Standard Section 6.12.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Alliance Standard Part 6 Section 12 Handrails and Guards	
Question:	Occupant loads are posted for every assembly and production floor in a conspicuous space near the main point of egress.	 
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	Occupant loads are not posted at exit access doorways of the buildings under assessment, or at the assembly points.	
Source of Findings:	Photograph: i) Exit access doorway ii) Assembly area.	
Suggested Plan of Action:	Post the occupant load for all assembly and production floor areas in a conspicuous space near the main exit or exit access doorway for the space in accordance with Alliance Standard Section 6.4.4.	
Suggested Deadline Date:	31 Jul 2016	
Standard:	Alliance Standards Part 6 Section 6.4.4 Posting of Occupant Load	
Question:	Emergency power for means of egress illumination is verified at least once per year. If battery operated lights are used, these lights are tested on a monthly basis. Functional testing of battery powered lights is provided for a minimum 90 min once per year.	
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	No documents were provided indicating monthly or annual functional tests of the means of egress illumination were conducted.	
Source of Findings:	Document Review: No document was provided.	
Suggested Plan of Action:	Develop a testing and maintenance program that ensures the emergency power for all egress lighting is verified at least once per year. If battery-operated lights are used, these lights shall be tested on a monthly basis. Functional testing of battery powered lights shall be provided for a minimum 30 min once per year.	
Suggested Deadline Date:	15 Aug 2016	
Standard:	Alliance Standards Part 10 Section 10.12 Illumination of Exit Signs and Means Of Escape Lighting	
Question:	Illuminated exit signs are placed at entrances to exits and along the path of egress anywhere the continuation of egress is not obvious or there is a change	

	in the direction of the path of travel.	
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	Illuminated exit signs are provided at entrances to exits, but not for changes in direction on the ground floor of Main Factory Building-1 and the ground floor of Main Factory Building-2.	
Source of Findings:	Visual Assessment: Facility survey.	
Suggested Plan of Action:	Provide continuously illuminated exit signs per Alliance Standard Section 6.11. Signs shall be placed at all required exits and along egress paths, especially where there is a change in direction for the path of travel.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Alliance Standard Part 6 Section 6.11 Exit Signs	
Question:	Emergency power for exit signs is tested at least once per year. If battery operated, these lights are tested on a monthly basis. Functional testing of battery powered signs is provided for a minimum 90 min once per year.	
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	No documents were available related to monthly testing or functional testing of battery powered signs.	
Source of Findings:	Document Review: No document was provided.	
Suggested Plan of Action:	Develop a testing and maintenance program that ensures the emergency power for exit signs is verified at least once per year. If battery-operated signs are used, these signs shall be tested on a monthly basis. Functional testing of battery powered signs shall be provided for a minimum 90 min once per year.	
Suggested Deadline Date:	15 Jul 2016	
Standard:	Alliance Standard Part 10 Section 10.12 Illumination of Exit Signs and Means Of Escape.	
Question:	Handrails are provided on both sides of each stairway. Intermediate handrails are provided when the stair width exceeds 2.2 m (87 in.). Handrails are not mounted lower than 760 mm (30 in.) or higher than 1100 mm (44 in.).	
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	Handrails for 2 stairs in the Canteen & Storage Building and Stair-1 of Office Building are not provided with handrails on either side.	

Source of Findings:	Photograph: Handrails are not provided on both sides.	
Suggested Plan of Action:	Provide handrails on both sides of each stairway. Mount new handrail at a height consistent with existing height (between 30 in. and 44 in). The spacing between vertical members will not exceed 200 mm (8 inch).	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Alliance Standard Part 6 Section 6.9 Stairs and 6.12 Handrails and Guards	
Question:	Stair designation signs are provided at each floor entrance from the stair to the floor in English and Bengali. Signs indicate the name of the stair and the floor level. Signs are posted adjacent to the door.	
Priority Level:	Low	
Non-Compliance Level:	3	
Description:	Stair designation signs are not provided at each floor entrance from the stairs to the floors of the buildings in English and Bengali.	
Source of Findings:	Visual Assessment: Facility survey	
Suggested Plan of Action:	Install signage adjacent to each stair door indicating the stair name and the floor level in both English and Bengali.	
Suggested Deadline Date:	15 Aug 2016	
Standard:	Alliance Standard Part 6 Section 6.9 Stairs	
Fire Safety Programs		
Question:	Are the required number of people trained and certified in fire fighting, first aid, and rescue training by the appropriate authority.	
Priority Level:	High	
Non-Compliance Level:	2	
Description:	Only 17 workers have been trained and certified in fire fighting, first aid, and rescue training by the FS&CD authority.	
Source of Findings:	Document Review: Document reviewed.	
Suggested Plan of Action:	Provide training and certification for the required number of people (25% of total workers) in fire fighting, first aid, and rescue training by an appropriate authority in accordance with the Alliance Safety Training Curriculum.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Alliance Standard Part 13 Human Element Programs	
Question:	Training programs are implemented and documented in accordance with the	

	Alliance Safety Training Curriculum.	
Priority Level:	Medium	
Non-Compliance Level:	3	
Description:	Training programs are not implemented and documented in accordance with the Alliance Safety Training Curriculum.	
Source of Findings:	Document Review: The documentation was not provided.	
Suggested Plan of Action:	Implement training programs and document in accordance with the Alliance Safety Training Curriculum.	
Suggested Deadline Date:	15 Aug 2016	
Standard:	Alliance Standards Part 13	
Question:	Storage areas underneath the cutting tables are clear of combustibles.	
Priority Level:	Medium	
Non-Compliance Level:	2	
Description:	Storage of fabric materials under the cutting tables located on the ground floor of Main Factory Building-1 was noticed.	
Source of Findings:	Photograph: Storage under the cutting table.	
Suggested Plan of Action:	Remove all combustibles stored underneath the cutting tables in accordance with Alliance Standard Section 13.7.2.	
Suggested Deadline Date:	15 Jul 2016	
Standard:	Alliance Standard Part 17 Section 13.7.2 Cutting tables.	
Question:	Are all applicable permits up to date including Fire License & Boiler License.	
Priority Level:	Low	
Non-Compliance Level:	3	
Description:	Only Fire License was available during the inspection. Boiler License, Generator License, or Waiver Certificate, and ABC License for Electrician were not provided.	
Source of Findings:	Document Review: Only fire license was provided.	
Suggested Plan of Action:	Apply to appropriate authority in an expeditious manner for issuance of all applicable licenses.	
Suggested Deadline Date:	15 Aug 2016	

Standard:	Alliance Standard Part 13 Human Element Programs	
Question:	Fire Department pre-planning has been completed.	
Priority Level:	Low	
Non-Compliance Level:	2	
Description:	There was no documentation indicating that Fire Department pre-planning activities have been completed.	
Source of Findings:	Document Review: Document was not provided.	
Suggested Plan of Action:	Complete Fire Department pre-planning activities with the local Fire Service and Civil Defence in accordance with Alliance Standard Section 13.1.1(2).	
Suggested Deadline Date:	30 Sep 2016	
Standard:	Alliance Standards Part 13 Section 13.1 Fire Safety Director	
Question:	A hot-work permit program has been established.	
Priority Level:	Low	
Non-Compliance Level:	2	
Description:	Hot-work permit program has not been established.	
Source of Findings:	Document Review: No documentation was provided.	
Suggested Plan of Action:	Develop a hot work permit program. The program must comply with the requirements of NFPA 51B.	
Suggested Deadline Date:	31 Dec 2016	
Standard:	Alliance Standards Part 13 Section 13.4 Hot Work Permit and NFPA 51B	