Issue	**1**
Factory ID	**26329**
Date of Issue	**26-Mar-2026**

Fashion Knits

Pakistan ACCORD for Health and Safety in the Garment and Textile Industry

8000 Opposite Canal Road, Near Zeeshan Shah (Ex-MPA) Rd, Mian Pind, Mansoorabad
38000 Faisalabad
Punjab Pakistan

Latitude: [31.4412], longitude: [73.12]
Date of inspection: 11-Mar-2026

Electrical Safety Inspection Report

Observations & Actions



Authors	**Zeeshan Haider**
Reviewed by	**Muhammad Asif**
Approved by	**Paul Rigby**

Pakistan Accord Initial Safety Inspection Report

About this report:

This report has been prepared by the Health and Safety Accord Pvt Ltd after visiting the factory on 11-03-2026 as part of the inspection and remediation program of the Pakistan Accord on Health and Safety in the Textile and Garment Industry. The purpose of the report is to provide key findings and identify related safety improvements needed at the inspected factories. This inspection report may not identify minor deficiencies, which may be further addressed as part of follow-up inspections.

In addition, while this round of initial inspections covers fire, electrical and structural safety, the Pakistan Accord intends to include inspections on boiler safety and hazardous material in later rounds.

This report will serve to facilitate discussions between the Pakistan Accord, the factories and the responsible brands that source from this facility about the remediation requirements. An implementation schedule shall be developed by the factory in the form of a Corrective Action Plan (CAP) to remediate each of the findings identified in the inspection report, including timelines and cost estimates, for approval by the Chief Safety Officer (CSO).

Applied Standards:

This safety assessment was conducted by the Pakistan Accord with reference to the Pakistan Accord Building Standard.

Contents

1. Executive Summary 5
2. Building Extents 7
   - 2.1 Building Use 9
   - 2.2 Utility Source 10
   - 2.3 Backup source 11
3. Documentation 12
4. Electrical Safety Measures 13
5. Remediation Support 14
   - 5.1 Engineering Support 14
6. Diagrams & Drawings 15
   - 6.1 Single Line Diagram (SLD) 15
   - 6.2 Electrical layout drawing 16
7. DBs & Elec Protection Systems 17
   - 7.1 Circuit breakers 17
   - 7.2 Hot Spots 19
   - 7.3 Earthing system 22
   - 7.4 Panel/cabling/busbar 26
   - 7.5 Loop Connection 28
   - 7.6 Multiple Connections 30
   - 7.7 Openings 32
   - 7.8 Adequate accessibility 34
   - 7.9 Lightning Protection System (LPS) 36

8. Fire Alarm & Detection System (FADS)..... 38
8.1 Non-functional or incomplete..... 38
9. Emergency Lighting..... 41
9.1 Provided but insufficient..... 41
9.2 Independent power source..... 45
10. Cabling & Wiring..... 46
10.1 Cable support and protection..... 46
10.2 Splicing of cables..... 48
10.3 Colour coding..... 52
10.4 Fixtures..... 54
11. Assessment Limitations and Assumptions..... 57

1. Executive Summary

On 11-Mar-2026, Syed Hassan Hussain and Zeeshan Haider on behalf of the Pakistan Accord carried out an initial electrical inspection for Fashion Knits, a factory at the address and coordinates given on the cover page of this report. The inspection was carried out in accordance with the Pakistan Accord Building standards.

We met with factory management representative Mr. Umair Hafeez (Owner), Mr. Zain (Compliance Adviser), and Mr. Rafiq (Compliance Adviser), along with other staff members of the factory. As the assessment was being carried out as part of an overall Structural, Fire and Electrical initial inspection, other representatives from Pakistan Accord were also present.

The factory comprises of one main building, details of which are provided below:

Main Building - 3 storeys (Basement + Ground + 1). The building is used for finishing and packing (basement), cutting, admin offices and warehouse (ground floor), stitching (first floor). The building was constructed in 2022.

The factory complex is entirely occupied by Fashion Knits as owner.
The factory operates with general shift for all the activities except the dyeing department (three shifts). Approximately 50 workers operate in the factory out of which approximately 20% employees are female.

A summary of the main concerns in relation of life safety systems identified during the inspection (non-exhaustive) that should be actioned are as follows:

· **Hot Spots:** Hotspots were found exceeding safe limits in one distribution board within the facility. Significantly increases the risk of insulation failure, equipment damage, arc flashes, and fire outbreaks. They may also lead to unexpected power outages, operational disruptions, and potential injury to personnel. Immediate actions are required to resolve this issue.

· **Fire Alarm System:** The facility does not have a proper compliant fire alarm system. This creates significant fire safety risks, including delayed fire detection, absence of automatic initiation from smoke or heat, no early warning for occupants, and increased potential for fire spread before evacuation measures can be taken.

· **Emergency Lights:** Insufficient emergency lights and directional signage were found throughout the facility. These issues pose a serious risk to safe evacuation of workers during an emergency.

· **Earthing System:** The earthing system was non-compliant with the standard due to inaccessible earth pits and undersized earth cables. In addition,

bonding of cable trays, metal structures, doors, and metallic furniture/fittings were absent. These pose significant safety risks, such as electric shock, fire hazards, and potential equipment damage.

We see no reason to suspend operations in the facility due to these concerns, subject to the action identified being addressed within the specified timeframes.

Our Limitations and Assumptions are also noted at the end of this report.

For detailed analysis of the above, please refer to the full inspection report below, which further details each issue, and also includes photographs. Further actions with associated priorities and timeframes are also detailed with each issue. Please note that these actions should be completed as soon as practically possible and certainly within the timeframe noted.

2. Building Extents



Figure 1.1. Site plan (Satellite view) - Red dashed line indicates site boundary highlighted (blue) area indicates building inspected.



Figure 1.2. Site plan - Red dashed line indicates site boundary highlighted (blue) area indicates building inspected.

2.1 Building Use

The factory comprises one building, and the building uses per floor are as follows:

Main Building-01:
B00 - Basement: Finishing and packing.
L00 - Ground floor: Cutting, admin offices and fabric storage area.
L01 - First floor: Stitching.
L99 - Rooftop: Storage.

2.2 Utility Source

The factory receives a low-voltage electrical supply from WAPDA (25 kVA PMT shared connection), which is fed into the main panel, and then low-voltage power is distributed to the respective floors distribution boards.



Figure 1.3. Shared connection 25 kVA for facility primary power source

2.3 Backup source

The factory does not have any backup power source; only emergency lights equipped with built-in battery bank to provide limited backup during power outages. Additionally, no backup power arrangement was provided for the fire alarm system.

3. Documentation

This table shows the details of the documentation provided by the factory:

S.NO	Description	Available (Y/N)	Created Date	Status / Remarks
1	Electrical Layout Drawing	No		
2	Single Line Diagrams	No		
3	Fire Alarm Drawing	No		
4	Earth Test Report	No		
5	Thermographic Test Report	No		
6	Insulation Resistance Test Report	No		
7	LPS Risk Assessments	No		
8	Periodic Maintenance Record	No		
9	Transformer Oil Testing Report	No		

4. Electrical Safety Measures

During our electrical site inspection of Fashion Knits, a number of electrical issues were identified.

It is essential to address these electrical safety issues promptly to enhance safety and compliance within Fashion Knits. Each issue should be carefully evaluated, and the recommendations provided in this report should be followed diligently to rectify these concerns. The safety and well-being of the factory's employees depend on these corrective actions. Where issues are identified in the report, they are grouped by topic, not in order of importance. Please note that these actions should be completed as soon as practically possible and certainly within the timeframe noted.

Recommendations in this report are prioritized as follows:

Immediate: These recommendations address safety and compliance concerns that require immediate attention.

Medium term (within approx. 6-weeks): Recommendations of high importance but needing slightly more time to implement.

Longer term (within approx. 6-months): Important recommendations that require a longer period to fully implement or that enhance long-term safety and efficiency.

All survey, testing, and design activities specified in this report shall be performed by a qualified electrical engineer. The recommended installation and modification tasks should be executed by a trained professional electrician.

Before commencing any installation and/or modification works, the proposed design must be submitted to the Pakistan Accord for approval.

Upon completion of the works, the necessary evidence required to verify that the tasks have been completed to the agreed standards will be determined during the development of the Corrective Action Plan (CAP).

5. Remediation Support

5.1 Engineering Support

Some items in the Corrective Action Plan (CAP) will require remediation by a qualified engineer. Please refer to the Remediation Plan for guidance on which tasks can be completed using internal resources and which require engineering support. F-202603-063970

Timeline	Remediation Plan
Medium Term CAP-0074802	Factories should begin remediation of CAP items such as cleaning, cable organisation, and basic corrections using internal resources. For systems or design-related remediation, engagement of a qualified Electrical Engineer is required.

6. Diagrams & Drawings

6.1 Single Line Diagram (SLD)

This section refers to the entire facility.

It was found that the electrical single line diagrams (SLDs) for the factory were not available.

Single line diagrams are crucial for understanding the electrical distribution network and for troubleshooting issues effectively. Without these diagrams, maintenance personnel and emergency responders lack the critical information necessary for isolating faults and managing power during emergencies. This can lead to delays in addressing electrical issues, increasing the risk of electrical fires and potential harm to personnel. Moreover, the lack of SLDs complicates routine maintenance and inspection processes, potentially resulting in undetected electrical faults and system inefficiencies.F-202603-063958

Timeline	Remediation Plan
Medium Term CAP-0074807	Develope comprehensive electrical single line diagrams for the entire facility in accordance with the requirements outlined in Section 514.9.1 of BS7671 18th Edition + A2 (2022). Ensure all components and connections are accurately represented. Retain the drawings along with all O&M information for the facility.
Longer Term CAP-0074808	Implement a regular review and update process for the single line diagrams to reflect any changes in the electrical system. Conduct training sessions for maintenance personnel and emergency responders on interpreting and using the diagrams.

6.2 Electrical layout drawing

This section refers to the entire facility.

During the survey, it was observed that the factory does not have available electrical layout drawings, including power layouts, lighting layouts, fire alarm layouts, earthing layouts and containment layouts.

These drawings are vital for understanding the placement and connections of electrical systems, which is crucial for identifying and mitigating potential hazards. In emergencies, the lack of detailed layouts can delay the identification and isolation of electrical faults, increasing the risk of fire and electrical accidents. Additionally, without proper layout drawings, routine inspections and maintenance may overlook critical issues, potentially leading to system failures and safety breaches.F-202603-063963

Timeline	Remediation Plan
Medium Term CAP-0074805	Develop comprehensive electrical layout drawings in accordance with the requirements outlined in Sections 132.12 and 132.13 of BS7671 18th Edition + A2 (2022). To avoid drawings becoming overcrowded, separate drawings shall be prepared for each electrical system. Retain the drawings along with all O&M information for the facility.
Longer Term CAP-0074806	Implement a regular review and update process for the electrical layout drawings to reflect any changes in the system. Conduct training sessions for maintenance personnel and emergency responders on interpreting and using the layouts.

7. DBs & Elec Protection Systems

7.1 Circuit breakers

This section refers to the entire facility.
During the survey, the circuit breakers installed throughout the facility inside the electrical panels and distribution boards were inspected.

It was found that multiple circuit breakers had ratings that were not appropriate for the connected cable sizes such as:
a) Basement area distribution board 100A circuit breaker with 10sqmm cable.

Circuit breakers that are not properly sized may fail to trip during overload conditions, allowing excessive current to flow and causing overheating, which leads to a fire risk.F-202603-063956

Timeline	Remediation Plan
Medium Term CAP-0074826	Evaluate the breaker ratings and cable sizes for all circuits in the facility according to Section 433.1.1 and Appendix 4 of BS 7671 18th Edition + A2 (2022). Ensure that the breaker rating does not exceed the cable's current-carrying capacity. If the breaker has adjustable settings, they must be configured to allow current within the cable's ampacity after applying derating factors.



Figure 2.1 - Inadequate breaker rating at basement area distribution board 100A circuit breaker with 10sqmm cable

7.2 Hot Spots

This relates to the entire facility.
During the inspection, Thermographic surveys were conducted on the electrical boards.

The survey detected several hot spots in multiple distribution boards, observed at:
a). Basement area distribution boards (Temp. 65 °C).

Hot spots in electrical distribution systems can be caused by several factors, including:
> Loose connections
> Overloaded circuits
> Faulty components
> Improper sized cable
> Insulation degradation
All temperature related assessments are based on Table 100.18 of ANSI Standard 2019.

It was also found that the thermographic test report was not available at the site.

Circuit breakers are typically designed to operate safely within an ambient temperature range of -20°C to 40°C. Commonly used PVC insulated cables typically have a maximum operating temperature of 70°C. Prolonged exposure to temperatures above these can degrade the insulation of the breaker as well as the cable and result in reduced performance.

Hot spots in electrical systems pose significant life safety risks due to several factors. Overheated components can ignite surrounding materials, leading to electrical fires. This is particularly dangerous in densely packed panels and distribution boards where flammable materials may be present. Hot spots can degrade insulation on wires and components, increasing the risk of electrical shock to personnel who might come into contact with exposed conductive parts. Overheating can contribute to conditions that might trigger an arc flash, a dangerous high-temperature event that can cause severe injuries or fatalities to personnel working near the affected equipment.F-202603-063957

Timeline	Remediation Plan

Immediate CAP-0074829	Any circuits identified on site with temperatures exceeding 40°C above the ambient temperature, operating above 90°C or exhibiting visual signs of burning must be immediately isolated and taken out of service. These circuits should remain de-energized until a thorough review has been conducted and appropriate remedial actions have been implemented to resolve the underlying issues.
Medium Term CAP-0074830	During the inspection, several circuits were identified where the temperature was exceeding 20°C above ambient temperature. It is recommended that the factory conducts comprehensive thermographic surveys of all electrical panels to detect similar issues. Identified hot spots should be thoroughly reviewed to determine their underlying causes. Corrective actions must be taken to address and resolve these issues, ensuring safe and reliable operation of the electrical systems.
Longer Term CAP-0074831	Regular thermographic inspections should be incorporated into the maintenance schedule to proactively manage and mitigate the risks associated with overheating. Submit the thermographic test report to the Pakistan Accord for review.



Figure 2.2 - Hot spot was found at basement area distribution board



Figure 2.3 - Hot spot was found at basement area distribution board

7.3 Earthing system

This section relates to the entire facility.
During the inspection of the facility's electrical panels, distribution boards, and machinery, the following observations with the earthing system were identified.

i. It was found that the earth circuit distribution was missing in multiple distribution boards and stitching machines. Mostly, two pin power plug is used for stitching machines instead of a grounded three-pin power plug.
Observed at,
a) Basement, ground and first floor distribution boards and stitching machines.

ii. It was also found that the equipotential bonding for the distribution board front doors, cable trays, machines body, metallic cage of generator and panel covers were missing.
Observed at,
a) Basement, ground and first floor distribution boards, cable trays and stitching machines.

iii. The earth pits were inaccessible and unsuitably located at outdoor area of the facility.

iv. It was noted that the earth cables were not appropriately sized according to the relevant earthing standards.
Observed at
a) Ground floor main panel.

v. It was found that the earth testing record was not available at the site. Without earth testing records, it is difficult to ensure that the grounding system is functioning correctly and that maintenance activities.

vi. It was also observed that the factory does not have an earthing layout drawing available.

The lack of proper earthing system throughout the facility poses substantial safety risks, such as electric shocks, fires, and equipment damage. Implementing appropriate earthing measures is crucial to prevent hazardous voltage levels and ensure operational safety. F-202603-063955

Timeline	Remediation Plan

Medium Term CAP-0074817	i. Install earthing systems where absent, ensuring compliance with BS 7671 18th Edition + A2 (2022) Chapter 54. Fit all electrical boards with the required earthing cables. Ensure that earthing conductors are properly connected and comply with BS 7671 18th Edition + A2 (2022) Section 543.1.
Medium Term CAP-0074818	ii. Implement equipotential bonding for all cable trays to comply with BS 7671 Regulation 411.3.1.2. Ensure all exposed conductive parts are bonded to the main earthing terminal.
Medium Term CAP-0074819	iii. Relocate and redesign earth pits to make them easily accessible for maintenance and inspection, complying with BS 7671 18th Edition + A2 (2022) Chapter 54.
Longer Term CAP-0074820	iv. Replace all earthing cables with appropriately sized cables as per the requirements of BS 7671 18th Edition + A2 (2022) Appendix 4, Section 5. Verify that all earthing conductors meet the minimum cross-sectional area specified.
Longer Term CAP-0074821	v. Prepare and submit the earth testing record to the Pakistan Accord for review.
Longer Term CAP-0074822	vi. Develop and submit the earthing system design to the Pakistan Accord for review.
Longer Term CAP-0074823	Establish a schedule for regular maintenance and inspection of the earthing system and protective devices as per BS 7671 Regulation 651.2. Document all inspections and maintenance activities to ensure ongoing compliance. Provide training to facility maintenance personnel on proper earthing practices and the importance of maintaining electrical safety standards in line with BS 7671 requirements.



Figure 2.4 - Two pin power plug was used basement production machines



Figure 2.5 - Earth distribution and bonding connection were missing inside basement area distribution board



Figure 2.6 - Earth distribution and bonding connection were missing inside ground floor distribution board



Figure 2.7 - Earth distribution and bonding connection were missing inside ground floor distribution board



Figure 2.8 - Two pin power plug was used for ground floor cutting machines



Figure 2.10 - Two pin power plug was used for first floor stitching machines



Figure 2.9 - Earth distribution and bonding connection were missing inside first floor distribution board

7.4 Panel/cabling/busbar

This section relates to the entire facility.
The visual site inspection included an examination of the electrical panels, cables and busbars throughout the facility.

i. It was also found that there was loose wiring and insufficient working space inside the distribution boards for operation and maintenance. Loose wiring and insufficient space, lead to excessive heat generation which can cause the insulation to melt and potentially lead to fire. Observed at,
a) First floor production area near stairs distribution board.

ii. It was found that several distribution boards and cable terminals exhibited signs of corrosion, indicating potential exposure to moisture or other corrosive elements. Observed at,
a) First floor production area near stairs distribution board.F-202603-063962

Timeline	Remediation Plan
Medium Term CAP-0074836	i. Install wire ducts to organize and route wires neatly, remove loose cables, and ensure that no cables are attached to the bus bars. This may mean the addition of new distribution boards with proper accessibility for cables incoming and outgoing, bus-bar alignment.
Medium Term CAP-0074837	ii. Replace or refurbish corroded electrical distribution boards to prevent further degradation and potential safety hazards. Implement protective measures such as installing weatherproof enclosures or using corrosion-resistant materials.
Longer Term CAP-0074838	Establish a schedule for regular maintenance and inspection of the panel, cabling and busbars. Document all inspections and maintenance activities to ensure ongoing compliance. Provide training to facility maintenance personnel on the importance of maintaining electrical safety standards in line with BS 7671 requirements.



Figure 2.11 - Loose wiring and improper dressing was found inside first floor distribution board



Figure 2.13 - Corroded connection was fund inside first floor production area distribution board



Figure 2.12 - Corroded connection was fund inside first floor production area distribution board

7.5 Loop Connection

This section relates to the entire facility.

During the inspection loop connections were identified within the electrical distribution boards.
In these loop connections, one circuit breaker is energized by the live part of another circuit breaker, creating loops within the panel instead of using a busbar system.
Observed at,
a) First floor production area distribution boards.

Avoiding loop connections is crucial due to several significant risks. Loop connections can complicate maintenance activities, making it difficult to trace and isolate circuits. These connections can lead to increased resistance and overheating, potentially damaging components. Loop connections raise the risk of accidental phase mixing, which can result in short circuits. The above issues compromise personal safety and significantly increase the risk of fire.F-202603-063959

Timeline	Remediation Plan
Medium Term CAP-0074832	All electrical panels shall be modified to eliminate loop connections. A busbar system within the electrical panels shall be utilised to provide each circuit with the required live, neutral, and earth connections.



Figure 2.14 - Loop connections were found at first floor production area distribution board

7.6 Multiple Connections

This section relates to the entire facility.

During our inspection, multi looping was observed in a number of electrical panels across the facility. In these cases, multiple circuits were being protected by a single circuit breaker.
Observed at,
a) Building basement, ground and first floor distribution boards.

Multilooping can result in improper distribution of electrical current, leading to voltage drops and potential electrical hazards. To mitigate these risks and ensure the safety and reliability of the electrical system, it is essential to adhere to proper installation practices. This includes using appropriate dedicated circuit breakers for each circuit. F-202603-063960

Timeline	Remediation Plan
Medium Term CAP-0074833	The electrical installation throughout the facility shall be modified to ensure each circuit is protected by a dedicated circuit breaker of a suitable type and rating for each individual circuit in accordance with Section 430 of BS 7671 18th Edition + A2 (2022).



Figure 2.15 - Multiple connections were found at basement production area distribution board



Figure 2.16 - Multiple connections were found at ground floor production area distribution board



Figure 2.17 - Multiple connections were found at first floor production area distribution board

7.7 Openings

This relates to the entire facility of the factory.

During the visual inspection, the electrical panels and distribution boards were examined for unsealed openings to ensure compliance with the IP rating requirements.

It was found that many distribution boards have openings, which may cause potential hazards due to environmental factors.
Observed at,
a) Building ground-floor main changeover panel.
b) First floor distribution board near stairs.

These deficiencies pose multiple hazards. Unsealed openings and missing panels expose live electrical components, significantly increasing the risk of accidental contact and electric shock to personnel working nearby. The unsealed openings allow dust, debris, and moisture to enter, which can lead to short circuits and increase the risk of fire. The absence of proper sealing compromises the IP rating of the panels, which is crucial for ensuring safety and protection against environmental factors.F-202603-063961

Timeline	Remediation Plan
Medium Term CAP-0074834	Examine the entire facility panels to identify all openings, holes, and gaps that need to be sealed. Seal the openings, holes of panels, cable trays and trenches with metallic enclosures, and use cable glands for cable entry. The electrical system shall ensure compliance with Sections 614.2.1, 412.2.2, and 512.2 of BS 7671 18th Edition + A2 (2022).
Longer Term CAP-0074835	Conduct regular maintenance and maintain comprehensive records for all electrical panels to ensure there are no openings and that the IP ratings of the panels remain uncompromised.



Figure 2.18 - Unsealed opening was found inside ground floor main changeover panel



Figure 2.19 - Unsealed opening was found inside ground floor main changeover panel



Figure 2.20 - Unsealed opening was found inside first floor distribution board

7.8 Adequate accessibility

This section relates to the entire facility.
During the visit, the electrical panels and distribution boards were examined for adequate accessibility.

At multiple locations, it was found that the electrical distribution boards do not possess the required space for inspection or easy access to the panels and their components.
Observed at,
a) Building ground floor near the stairs changeover panel.

Limited accessibility to distribution boards and machine panels hampers effective maintenance and inspection procedures. This can potentially cause delays in addressing emergencies and troubleshooting electrical problems. These accessibility challenges could compromise the operational reliability and safety of the premises, as prompt maintenance and emergency responses are hindered. F-202603-063965

Timeline	Remediation Plan
Medium Term CAP-0074841	Electrical equipment shall be arranged to provide sufficient space for the initial installation and later replacement of individual items of electrical equipment. Sufficient allowance shall also be made for sufficient space for the initial installation and later replacement of individual items of electrical equipment in accordance with Section 132.12 of BS7671 18th Edition + A2 (2022).



Figure 2.21 - Inadequate accessibility was found for main changeover panels at ground floor near stairs

7.9 Lightning Protection System (LPS)

During the inspection, the lightning protection strategy of the factory was assessed.

It was found that no lightning protection system was installed, and there was no risk assessment provided to confirm whether it was not required.

Lightning strikes can cause significant damage to buildings, primarily through the ignition of fires. When lightning strikes a structure, it can cause an electrical surge that ignites flammable materials. Without a proper lightning protection system (LPS), the energy from a lightning strike can travel through the building's electrical and plumbing systems, creating sparks and starting fires. F-202603-063964

Timeline	Remediation Plan
Medium Term CAP-0074839	Engage a qualified lightning protection specialist to perform a comprehensive risk assessment (BS 62305). This assessment will determine the necessity of a lightning protection system (LPS) based on factors such as building height, location, occupancy, and the presence of sensitive electronic equipment.
Longer Term CAP-0074840	If the risk assessment concludes that an LPS is necessary, proceed with the design and installation of an appropriate system in compliance with relevant standards such as BS EN 62305 (Protection against Lightning).



Figure 2.22 - No lightning protection system was found within facility

8. Fire Alarm & Detection System (FADS)

8.1 Non-functional or incomplete

This section refers to the entire facility.
During the inspection, the Fire Alarm and Detection System (FADS) for the facility was evaluated.

It was observed that standalone, battery-operated smoke detectors with manual hooters were installed within the facility, providing limited coverage and audibility. The system does not comply with the requirements of NFPA 72, as it lacks a centralized control mechanism, the manual hooters were operating independently and activated on a point-to-point basis rather than centre control.

A non-functional/incomplete FADS significantly increases the risk of worker injury or fatality, substantial property damage, operational disruptions, legal liabilities, reputational damage, and environmental harm.F-202603-063969

Timeline	Remediation Plan
Medium Term CAP-0074842	Ensure the functionality and performance of the existing alarm system within facility.
Medium Term CAP-0074843	(i) Submit design documentation for new replacement system to Pakistan Accord for review before purchasing any new equipment. Design documentation to include drawings, technical data sheets and product certifications of all listed equipment to show full compliance of the Fire Alarm and Detection System (FADS) with NFPA 72.
Medium Term CAP-0074844	(ii) Submit documentation to Pakistan Accord showing that an L/C has been opened for import of any components required for the FADS design submitted earlier.
Medium Term CAP-0074845	(iii) Submit documentation to Pakistan Accord demonstrating that all materials, both imported and locally procured, have been purchased and are available on site for installation.
Longer Term CAP-0074846	(iv) Once installation of the FADS system is complete, factory to submit full "as-built" documentation of the system to Pakistan Accord for review.

Longer Term CAP-0074847	(v) Factory to advise Pakistan Accord when FADS installation fully completed and ready for review. Pakistan Accord will then arrange a verification inspection to ensure that the installation fully complies with the previously reviewed design documentation.
Longer Term CAP-0074848	(vi) Provide full testing and commissioning (T&C) certification from the FADS system installer and make provision for attendance of the system installer, factory technical personnel and Pakistan Accord technical team to witness a final T&C demonstration verification on site. On successful completion of this T&C verification inspection, remediation of the FADS system will be complete.



Figure 2.23 - Independent type fire detectors were found at production area of basement



Figure 2.25 - Manual hooter system was found at ground floor production area



Figure 2.24 - Manual hooter system was found at basement area



Figure 2.26 - Manual hooter system was found at first floor production area

9. Emergency Lighting

9.1 Provided but insufficient

The section refers to the entire facility.
During the inspection the emergency lighting arrangement throughout the facility was assessed.
The following observations were made:

i. During the inspection, it was observed that the emergency lighting layout drawing was not available at the site. The emergency lights and signage provided were insufficient to cover the entire facility, resulting in dark or poorly lit areas during power outages, which may lead to incidents during emergencies.
Observed at,
a) Main building all floors production area, offices, warehouses, stores, electric rooms, corridor area, and stairs.

ii. External emergency lighting was not provided for the facility, preventing people from reaching a place of safety outside the facility during nighttime evacuations. Observed at outdoor area of the facility.

iii. The backup power supply to the emergency luminaires is insufficient in different areas such as main building ground floor area emergency lights.

Adequate and functional emergency lighting throughout the facility is crucial for providing necessary illumination during power failures or other emergencies, ensuring the safe evacuation of workers.F-202603-063968

Timeline	Remediation Plan
Medium Term CAP-0074853	i. Conduct a comprehensive survey to identify areas lacking adequate emergency lighting. Submit the emergency lighting system design to the Pakistan Accord for review. Install additional emergency luminaires in these areas to meet the coverage requirements specified in the Building Code of Pakistan Fire Safety Provisions 2016, ensuring sufficient illumination for safe evacuation.
Medium Term CAP-0074854	ii. Install external emergency luminaires to enable safe evacuation during hours of darkness all the way to a safe place outside the building(s).

Longer Term CAP-0074855	iii. Upgrade the backup power supply to ensure it can adequately support all emergency luminaires during a power failure. This includes installing additional battery packs or generators as necessary to comply with the Building Code of Pakistan Fire Safety Provisions 2016.
Longer Term CAP-0074856	Establish a regular maintenance and testing schedule to routinely check the functionality of emergency lighting systems. This should include periodic tests, inspections, and prompt maintenance actions to address any issues. Maintain detailed records of all inspections, tests, repairs, and maintenance activities. Train facility maintenance staff on the procedures for inspecting and maintaining emergency lighting systems to ensure ongoing reliability and compliance with safety standards.



Figure 2.27 - Insufficient backup power was found for ground floor emergency lights



Figure 2.28 - Insufficient emergency lights were found at ground floor production area



Figure 2.29 - Non compliant emergency exit signage was found at basement area



Figure 2.30 - Insufficient emergency lights were found at first floor production area



Figure 2.31 - Emergency light were found missing at building stairs



Figure 2.32 - Emergency light were found missing at ground floor storage area



Figure 2.33 - Emergency light were found missing at ground floor main entrance

9.2 Independent power source

The section refers to the entire facility.

During the inspection, it was observed that the emergency lighting within the facility was not connected in a manner that would ensure automatic activation upon the loss of power to the general lighting in various spaces.

Proper circuitry is crucial to ensure that emergency lighting is automatically activated when general lighting fails. This automatic activation is essential for maintaining sufficient illumination, allowing for the safe evacuation of occupants and preventing panic during power outages. Further the emergency lights and exit signs be reconfigured to be connected on an independent single circuit, which must not include any other load except for the emergency lighting system according to the Building Code of Pakistan Fire Safety Provisions 2016, emergency lighting systems must be designed to provide immediate illumination in the event of power loss to ensure a clear and safe path for evacuation.

Ensuring that the emergency lighting is integrated with the facility's power system to activate automatically during power failures is critical for life safety. This integration helps prevent hazardous conditions that can arise in the dark, such as trips, falls, and confusion, thereby facilitating orderly and efficient evacuation during emergencies.F-202603-063966

Timeline	Remediation Plan
Medium Term CAP-0074857	Reconfigure the emergency lighting circuitry to ensure that emergency lights activate immediately when general lighting power fails, as required by the Building Code of Pakistan Fire Safety Provisions 2016.
Longer Term CAP-0074858	Establish a regular maintenance and testing schedule to routinely check the functionality of emergency lighting systems. This should include periodic tests, inspections, and prompt maintenance actions to address any issues. Maintain detailed records of all inspections, tests, repairs, and maintenance activities. Train facility maintenance staff on the procedures for inspecting and maintaining emergency lighting systems to ensure ongoing reliability and compliance with safety standards.

10. Cabling & Wiring

10.1 Cable support and protection

This section relates to the entire facility.
During the inspection of the entire facility, a visual survey of the cable containment system was conducted.

It was observed that cables were installed without proper containment systems such as cable trays, conduits, or ducting, and were laid directly on the floor. The absence of adequate cable containment and support can cause sagging or mechanical stress on the cables, potentially leading to damage or failure.
Observed at,
a) Ground floor building outdoor area cables.
b) Ground floor cutting table area cables.
c) First floor water cooler power cable.

Cables on the floor are susceptible to mechanical damage from foot traffic, material handling equipment, and other operations, which could result in electrical short circuits, potential electric shock, or even fire. Additionally, the exposed cables can cause workers to trip and fall, leading to possible injuries.F-202603-063951

Timeline	Remediation Plan
Medium Term CAP-0074859	Secure cables with appropriate containment and supports to prevent sagging, stress, and potential hazards. (Reference: BS 7671 18th Edition + A2 (2022) Regulation 522.8.5 for mechanical support and 526.5 for proper terminations).
Longer Term CAP-0074860	Implement a comprehensive cable management system with regular inspections to ensure cables remain properly supported and insulated over time.



Figure 2.34 - Cables were found without containment at main building outdoor area



Figure 2.35 - Cables were found without containment at ground floor cutting table area



Figure 2.36 - First floor water cooler cable was found without containment

10.2 Splicing of cables

This section relates to the entire facility.
During the inspection, the cable installation was visually surveyed throughout the facility. The following observations were noted:

i. It was found that cable terminations were made without using cable lugs, leading to broken strands and loose connections.
Observed at,
a) Building basement, ground and first floor distribution boards.

ii. PVC tape joints were found at multiple locations. This method of jointing is unreliable and can deteriorate over time, increasing the risk of electrical short circuits and fires. The adhesive on PVC tape can degrade, leading to exposed conductors that can spark and ignite surrounding materials, presenting both fire and life safety risks.
Observed at,
a) Building basement, ground and first floor distribution boards.
b) First floor water cooler cable and first floor stitching machines main power cable.

iii. It was noted that the insulation of ground floor cutting machine cable was damaged. Damaged insulation compromises current flow, potentially causing overheating. Persistent overheating degrades cable quality and raises fire risk.

For any future electrical work, the termination of stranded cables must be done with cable lugs and PVC tape joints shall not be utilized. Proper termination ensures secure and reliable connections, reducing the risk of electrical failures and enhancing overall safety. F-202603-063952

Timeline	Remediation Plan
Medium Term CAP-0074861	i. Install cable lugs on all improperly terminated cables within the distribution boards to secure connections and prevent breaking strands and loose connections in accordance with Regulation 526.1 of BS7671 18th Edition + A2 (2022).
Longer Term CAP-0074862	i. Implement a standard operating procedure (SOP) requiring the use of cable lugs for all future cable terminations. Regularly train and audit personnel to ensure compliance with this procedure, thus maintaining safe and reliable electrical connections.

Medium Term CAP-0074863	ii. Replace all PVC tape joints with proper terminal blocks or connectors to ensure secure and stable connections in accordance with BS7671 18th Edition + A2 (2022).
Longer Term CAP-0074864	ii. Establish a policy prohibiting the use of PVC tape for electrical jointing. Regularly inspect and maintain electrical installations to ensure compliance, and provide continuous training for staff on proper jointing techniques.
Longer Term CAP-0074865	iii. Repair or replace the damaged cable insulation to restore proper insulation, in compliance with BS 7671, Regulation 526.1, which requires all connections to be electrically sound and insulated to prevent accidental contact.



Figure 2.37 - Cables were terminated without cable lugs at ground floor production area changeover panel



Figure 2.38 - Cables were terminated without cable lugs at ground floor production area changeover panel



Figure 2.39 - PVC tape joint was found at first floor production area stitching machine cable



Figure 2.40 - Cables were terminated without cable lugs at basement production area distribution board



Figure 2.41 - PVC tape joint was found at ground floor production area distribution board



Figure 2.42 - Cables were terminated without cable lugs at first floor near stairs distribution board



Figure 2.43 - Cables were terminated without cable lugs at first floor near stairs distribution board



Figure 2.44 - PVC tape joint was found with main cable of first floor water cooler



Figure 2.45 - PVC tape joint was found at first floor production area stitching machine cable



Figure 2.46 - Insulation of ground floor cutting machine cable was found to be damaged

10.3 Colour coding

This section relates to entire facility.

During the inspection of multiple distribution boards, deviations from standard cable colour coding practices were identified.
Observed at,
a) Ground and first floor production area distribution boards.

Such deviations pose significant risks, as they can lead to the misinterpretation and misidentification of cables. This misidentification can result in incorrect connections, potentially causing unsafe working conditions and increasing the likelihood of electrical accidents, such as shocks or fires.

To mitigate these risks, it is imperative that all future electrical work strictly adheres to standardized colour coding as prescribed by BS 7671. This will ensure the accurate identification of conductors, thereby enhancing overall safety and operational efficiency.F-202603-063954

Timeline	Remediation Plan
Medium Term CAP-0074872	Conduct a comprehensive audit of all distribution boards to identify and correct any deviations from the standard cable colour coding. This involves re-labeling or re-insulating the cables with the appropriate colour codes as specified in BS 7671. Specifically, adhere to BS 7671 Regulation 514.3.1, which mandates the correct identification of conductors.
Longer Term CAP-0074873	Develop and enforce a strict protocol for cable colour coding to be followed for all future installations and maintenance activities. This protocol should include regular training sessions for electricians and maintenance personnel to keep them updated on the latest standards and practices.



Figure 2.47 - Colour coding violation was found at ground floor production area distribution board



Figure 2.48 - Colour coding violation was found at ground floor production area distribution board



Figure 2.49 - Colour coding violation was found at first floor production area near stairs distribution board

10.4 Fixtures

This section relates to the entire facility.
During the inspection, the electrical fixtures throughout the facility were visually surveyed. The following observations were noted.

i. It was observed that the wooden switch board were installed at many locations. Wood is flammable, and if the electric circuit inside the wooden switchboard generates excessive heat due to overloads or faults, it can ignite the wooden box. This can lead to a fire hazard.
Observed at,
a) Ground floor cutting area, main gate offices and first floor production area.

ii. It was also observed that the loose power boards were observed at multiple locations throughout the facility. Improperly fixed or unsecured power boards can lead to poor electrical connections, arcing, and overheating. These conditions significantly increase the risk of short circuits, fire outbreaks, or electrical shock to personnel.
Observed at,
b) Ground floor IT office room.

iii. It was noted that many lights were fixed by cable ties, ropes with cable trays and many LED lights were found hanged directly from cables, which posing a risk of equipment damage or incidents due to instability and potential for falling.
Observed at,
a) Building basement, ground and first floor production area light bulbs.F-202603-063953

Timeline	Remediation Plan
Medium Term CAP-0074866	i. Replace the wooden switchboard or compartment with a non-combustible enclosure designed for electrical installations. Additionally, replace the wooden ply with metallic brackets or stands.
Longer Term CAP-0074867	i. Establish a facility-wide standard to use only non-combustible materials for mounting electrical components, and conduct regular audits for compliance.
Medium Term CAP-0074868	ii. All loose power boards should be securely fixed in place. Use proper mounting hardware to ensure stability and safety.

Longer Term CAP-0074869	ii. Implement a regular inspection and maintenance schedule to check and secure all power receptacles, ensuring they remain safely and correctly installed.
Medium Term CAP-0074870	iii. Ensure all general lights are properly mounted using appropriate fixtures instead of cable ties or ropes. Install secure hanging supports to prevent instability and potential falling hazards.
Longer Term CAP-0074871	iii. Regularly inspect and maintain light fixtures to ensure safety and compliance.



Figure 2.50 - Wooden electric board was found at ground floor cutting area



Figure 2.51 - Loose and wooden electric board was found at ground floor cutting area



Figure 2.52 - Light bulbs were found inadequate support at basement area



Figure 2.53 - Light bulbs were found inadequate support at ground floor storage area



Figure 2.54 - Light bulbs were found inadequate support at first floor production area

11. Assessment Limitations and Assumptions

The information in this report was obtained during an inspection of the facility and based on information provided by factory management. It has not been possible to provide independent verification for all the information and data collected, and therefore, the Accord cannot accept general responsibility for omissions or errors arising from inaccuracies in this report from the information obtained.

The findings and recommendations in this report are not intended to imply, guarantee, ensure or warrant compliance with any government regulations. Additionally, the results do not imply in any way that compliance with the findings or recommendations as stated in this report will eliminate all hazards, risks or exposures or that hazards, risks or exposures not referred to in this report do not exist. Compliance with the findings and recommendations stated in this report does not relieve the factory owner from obligation to comply with specific project requirements, industry standards, or the provisions of any local government regulations.

Except as otherwise noted within this report, other systems or services were not viewed or tested during the assessment and are therefore similarly excluded from this report. We have not assessed any parts of the structure / building fabric / services which are covered, unexposed or inaccessible and we are therefore unable to report that any such part of the property is free from defect.

The observations in this report are based on the engineering judgement of the engineer at the time of the inspection.