

CCET 3680 Mill Lesson 4 Second Exercise


I. Wireframe:




II. Dimensions:




III. Solid:




IV. Toolpaths:




V. Name 2D Contour:




VI. Spot Drill:




VII. Peck Drill:




VIII. 2D Contour:




IX. 2D Chamfer Contour:




X: 2D Chamfer Contour:



XI: 2D Contour:



XII. Final Solid:



XIII. Method:

I drew two center anchored rectangles and then used offsets to create one copy of the repeating geometry. I then used the rotate tool to create four copies of the wireframe around the center.

XIV. GCode Changes

To modify my gcode to be compatible with the machine I first made sure the HAAS 3 axis post processor was selected when exporting the gcode. Then I removed the long lines at the beginning and edited the last G28 home command to not zero the x axis.

XV. Finished Part:



XV. Gcode:

%

033004

(WSHAKESPEAR_MILL LESSON 4B)

(DATE=DD-MM-YY - 03-02-23 TIME=HH:MM - 10:50)

(MCAM FILE - C:\USERS\WESTONSHAKESPEAR\DOWNLOADS\WSHAKESPEAR_MILL LESSON 4 SECO)

(NC FILE - C:\USERS\WESTONSHAKESPEAR\DOWNLOADS\GCODE\WSHAKESPEAR_MILL LESSON 4B)

(MATERIAL - ALUMINUM INCH - 6061)

(T5|1/8 SPOTDRILL|H5|D5|TOOL DIA. - .125)

(T3|1/2 SPOTDRILL|H3|D3|TOOL DIA. - .5)

(T1|1/8 DRILL|H1|D1|T00L DIA. - .125)

(T4|1/2 FLAT ENDMILL|H4|D4|TOOL DIA. - .5)

N100 G20

N110 G0 G17 G40 G49 G80 G90

N120 T5 M6

N130 G187 P3 E.001

N140 G0 G90 G54 X-.5682 Y.1221 S4966 M3

N150 G43 H5 Z.145

N160 G1 Z.118 F6.4

N170 X-.5347 Y-.0017 F40.

N180 X-.4972 Y.1221

N190 X-.4926

N200 X-.455 Y-.0017

N210 X-.4216 Y.1221

N220 Z.138 F6.4

N230 G0 Z.145

N240 X-.3145 Y0.

N250 G1 Z.118

N260 X-.3935 F40.

N270 Y.1203

N280 X-.3145

N290 Z.138 F6.4

N300 G0 Z.145

N310 X-.3191 Y.0628

N320 G1 Z.118

N330 X-.3935 F40.

N340 Z.138 F6.4

N350 G0 Z.145

N360 X-.2045 Y.0971

N370 G1 Z.118

N380 X-.2102 Y.1072 F40.

N390 X-.2193 Y.1149

N400 X-.231 Y.1195

N410 X-.2442 Y.1208

N420 X-.2599 Y.1186

N430 X-.2726 Y.1128

N440 X-.2815 Y.1037

N450 X-.2848 Y.0929

N460 X-.2808 Y.0791

N470 X-.2797 Y.0776

N480 X-.2677 Y.068

N490 X-.2622 Y.0654

N500 X-.2284 Y.056

N510 X-.2138 Y.0488

N520 X-.2096 Y.0448

N530 X-.204 Y.0343

N540 X-.2034 Y.0294

N550 X-.2066 Y.0185

- N560 X-.2151 Y.0088
- N570 X-.2278 Y.0022
- N580 X-.2442 Y0.
- N590 X-.2571 Y.0014
- N600 X-.2687 Y.0055
- N610 X-.2778 Y.0123
- N620 X-.2833 Y.0205
- N630 X-.2866 Y.0293
- N640 Z.138 F6.4
- N650 G0 Z.145
- N660 X-.1288 Y.1203
- N670 G1 Z.118
- N680 Y-.0017 F40.
- N690 Z.138 F6.4
- N700 G0 Z.145
- N710 X-.1747 Y.1203
- N720 G1 Z.118
- N730 X-.0835 F40.
- N740 Z.138 F6.4
- N750 G0 Z.145
- N760 X-.0557 Y.0599
- N770 G1 Z.118
- N780 X-.0517 Y.0826 F40.
- N790 X-.0513 Y.0838
- N800 X-.0394 Y.103
- N810 X-.0391 Y.1033
- N820 X-.0233 Y.1155
- N830 X-.0213 Y.1165
- N840 X-.0024 Y.1214
- N850 X.0007 Y.1215
- N860 X.02 Y.1175
- N870 X.0221 Y.1165
- N880 X.0383 Y.1049
- N890 X.0399 Y.1033
- N900 X.0515 Y.0852
- N910 X.0521 Y.0838
- N920 X.0565 Y.0615
- N930 Y.0599
- N940 X.0525 Y.0373
- N950 X.0521 Y.0362
- N960 X.04 Y.0168
- N970 X.0399 Y.0167

N980 X.0228 Y.0038

N990 X.0221 Y.0035

N1000 X.0026 Y-.0011

N1010 X.0007 Y-.0012

N1020 X-.0172 Y.0018

N1030 X-.0213 Y.0035

N1040 X-.0383 Y.0158

N1050 X-.0391 Y.0167

N1060 X-.0512 Y.036

N1070 X-.0513 Y.0362

N1080 X-.0557 Y.0578

N1090 Y.0599

N1100 Z.138 F6.4

N1110 G0 Z.145

N1120 X.0847 Y-.0017

N1130 G1 Z.118

N1140 Y.1221 F40.

N1150 X.1719 Y-.0017

N1160 Y.1221

N1170 Z.138 F6.4

N1180 G0 Z.145

N1190 X-.5095 Y-.094

N1200 G1 Z.118

N1210 X-.5432 Y-.0846 F40.

N1220 X-.5571 Y-.0764

N1230 X-.5608 Y-.0724

N1240 X-.5646 Y-.0652

N1250 X-.5659 Y-.0571

N1260 X-.5625 Y-.0463

N1270 X-.5537 Y-.0372

N1280 X-.541 Y-.0314

N1290 X-.5253 Y-.0292

N1300 X-.5121 Y-.0305

N1310 X-.5004 Y-.0351

N1320 X-.4912 Y-.0428

N1330 X-.4856 Y-.0529

N1340 Z.138 F6.4

N1350 G0 Z.145

N1360 X-.4845 Y-.1206

N1370 G1 Z.118

N1380 X-.4885 Y-.1079 F40.

N1390 X-.4907 Y-.1052

- N1400 X-.4984 Y-.0988
- N1410 X-.5095 Y-.094
- N1420 X-.5432 Y-.0846
- N1430 X-.5571 Y-.0764
- N1440 X-.5608 Y-.0724
- N1450 X-.5646 Y-.0652
- N1460 X-.5659 Y-.0571
- N1470 X-.5625 Y-.0463
- N1480 X-.5537 Y-.0372
- N1490 X-.541 Y-.0314
- N1500 X-.5253 Y-.0292
- N1510 X-.5121 Y-.0305
- N1520 X-.5004 Y-.0351
- N1530 X-.4912 Y-.0428
- N1540 X-.4856 Y-.0529
- N1550 Z.138 F6.4
- N1560 G0 Z.145
- N1570 X-.5253 Y-.15
- N1580 G1 Z.118
- N1590 X-.5089 Y-.1478 F40.
- N1600 X-.4962 Y-.1412
- N1610 X-.4877 Y-.1315
- N1620 X-.4845 Y-.1206
- N1630 X-.4885 Y-.1079
- N1640 X-.4907 Y-.1052
- N1650 X-.4984 Y-.0988
- N1660 X-.5095 Y-.094
- N1670 X-.5432 Y-.0846
- N1680 X-.5571 Y-.0764
- N1690 X-.5608 Y-.0724
- N1700 X-.5646 Y-.0652
- N1710 X-.5659 Y-.0571
- N1720 X-.5625 Y-.0463
- N1730 X-.5537 Y-.0372
- N1740 X-.541 Y-.0314
- N1740 X .541 1 .6514
- N1750 X-.5253 Y-.0292
- N1760 X-.5121 Y-.0305
- N1770 X-.5004 Y-.0351
- N1780 X-.4912 Y-.0428
- N1790 X-.4856 Y-.0529
- N1800 Z.138 F6.4
- N1810 G0 Z.145

N1820 X-.5677 Y-.1207

N1830 G1 Z.118

N1840 X-.5643 Y-.1295 F40.

N1850 X-.5589 Y-.1377

N1860 X-.5498 Y-.1445

N1870 X-.5382 Y-.1486

N1880 X-.5253 Y-.15

N1890 X-.5089 Y-.1478

N1900 X-.4962 Y-.1412

N1910 X-.4877 Y-.1315

N1920 X-.4845 Y-.1206

N1930 X-.4885 Y-.1079

N1940 X-.4907 Y-.1052

N1950 X-.4984 Y-.0988

N1960 X-.5095 Y-.094

N1970 X-.5432 Y-.0846

N1980 X-.5571 Y-.0764

N1990 X-.5608 Y-.0724

N2000 X-.5646 Y-.0652

N2010 X-.5659 Y-.0571

N2020 X-.5625 Y-.0463

N2030 X-.5537 Y-.0372

N2040 X-.541 Y-.0314

N2050 X-.5253 Y-.0292

N2060 X-.5121 Y-.0305

N2070 X-.5004 Y-.0351

N2080 X-.4912 Y-.0428

N2090 X-.4856 Y-.0529

N2100 Z.138 F6.4

N2110 G0 Z.145

N2120 X-.4559 Y-.1517

N2130 G1 Z.118

N2140 Y-.0279 F40.

N2150 Z.138 F6.4

N2160 G0 Z.145

N2170 X-.3652 Y-.0872

N2180 G1 Z.118

N2190 X-.4559 F40.

N2200 Z.138 F6.4

N2210 G0 Z.145

N2220 X-.3652 Y-.1517

N2230 G1 Z.118

N2240 Y-.0279 F40.

N2250 Z.138 F6.4

N2260 G0 Z.145

N2270 X-.3371 Y-.1517

N2280 G1 Z.118

N2290 X-.287 Y-.0279 F40.

N2300 X-.237 Y-.1517

N2310 Z.138 F6.4

N2320 G0 Z.145

N2330 X-.3197 Y-.1099

N2340 G1 Z.118

N2350 X-.2544 F40.

N2360 Z.138 F6.4

N2370 G0 Z.145

N2380 X-.2087 Y-.0279

N2390 G1 Z.118

N2400 Y-.1517 F40.

N2410 Z.138 F6.4

N2420 G0 Z.145

N2430 X-.1268 Y-.0279

N2440 G1 Z.118

N2450 X-.2087 Y-.1099 F40.

N2460 Z.138 F6.4

N2470 G0 Z.145

N2480 X-.1753 Y-.0765

N2490 G1 Z.118

N2500 X-.1228 Y-.1517 F40.

N2510 Z.138 F6.4

N2520 G0 Z.145

N2530 X-.0161 Y-.15

N2540 G1 Z.118

N2550 X-.0951 F40.

N2560 Y-.0297

N2570 X-.0161

N2580 Z.138 F6.4

N2590 G0 Z.145

N2600 X-.0951 Y-.0872

N2610 G1 Z.118

N2620 X-.0207 F40.

N2630 Z.138 F6.4

N2640 G0 Z.145

N2650 X.0118 Y-.1207

- N2660 G1 Z.118
- N2670 X.0152 Y-.1295 F40.
- N2680 X.0206 Y-.1377
- N2690 X.0298 Y-.1445
- N2700 X.0413 Y-.1486
- N2710 X.0542 Y-.15
- N2720 X.0706 Y-.1478
- N2730 X.0833 Y-.1412
- N2740 X.0919 Y-.1315
- N2750 X.095 Y-.1206
- N2760 X.091 Y-.1079
- N2770 X.0889 Y-.1052
- N2780 X.0811 Y-.0988
- N2790 X.07 Y-.094
- N2800 X.0363 Y-.0846
- N2810 X.0224 Y-.0764
- N2820 X.0187 Y-.0724
- N2830 X.0149 Y-.0652
- N2840 X.0137 Y-.0571
- N2850 X.017 Y-.0463
- N2860 X.0258 Y-.0372
- N2870 X.0385 Y-.0314
- N2880 X.0542 Y-.0292
- N2890 X.0674 Y-.0305
- N2900 X.0791 Y-.0351
- N2910 X.0883 Y-.0428
- N2920 X.0939 Y-.0529
- N2930 Z.138 F6.4
- N2940 G0 Z.145
- N2950 X.1235 Y-.1517
- N2960 G1 Z.118
- N2970 Y-.0297 F40.
- N2980 X.1711
- N2990 X.1843 Y-.0317
- N3000 X.1965 Y-.0381
- N3010 X.2054 Y-.0485
- N3020 X.2089 Y-.062
- N3030 X.2054 Y-.0754
- N3040 X.1965 Y-.0857
- N3050 X.1843 Y-.0921
- N3060 X.1711 Y-.0942
- N3070 X.1235

N3080 Z.138 F6.4

N3090 G0 Z.145

N3100 X.3163 Y-.15

N3110 G1 Z.118

N3120 X.2373 F40.

N3130 Y-.0297

N3140 X.3163

N3150 Z.138 F6.4

N3160 G0 Z.145

N3170 X.3117 Y-.0872

N3180 G1 Z.118

N3190 X.2373 F40.

N3200 Z.138 F6.4

N3210 G0 Z.145

N3220 X.3437 Y-.1517

N3230 G1 Z.118

N3240 X.3938 Y-.0279 F40.

N3250 X.4438 Y-.1517

N3260 Z.138 F6.4

N3270 G0 Z.145

N3280 X.3611 Y-.1099

N3290 G1 Z.118

N3300 X.4264 F40.

N3310 Z.138 F6.4

N3320 G0 Z.145

N3330 X.4721 Y-.1517

N3340 G1 Z.118

N3350 Y-.0298 F40.

N3360 X.5273

N3370 X.5402 Y-.0323

N3380 X.5511 Y-.0388

N3390 X.5587 Y-.0488

N3400 X.5616 Y-.0621

N3410 X.5587 Y-.0753

N3420 X.5511 Y-.0856

N3430 X.5402 Y-.0921

N3440 X.5273 Y-.0943

N3450 X.4721

N3460 Z.138 F6.4

N3470 G0 Z.145

N3480 X.5201

N3490 G1 Z.118

N3500 X.5335 Y-.1018 F40.

N3510 X.5436 Y-.1134

N3520 X.5682 Y-.1517

N3530 Z.138 F6.4

N3540 G0 Z.145

N3550 M5

N3560 G91 G28 Z0.

N3570 M01

N3580 T3 M6

N3590 G187 P3 E.001

N3600 G0 G90 G54 X-1.125 Y1.125 S4966 M3

N3610 G43 H3 Z.25

N3620 M8

N3630 Z.15

N3640 G99 G81 Z.05 R.15 F40.

N3650 X1.125

N3660 X-1.125 Y-1.125

N3670 X1.125

N3680 G80

N3690 Z.25

N3700 M5

N3710 G91 G28 Z0. M9

N3720 M01

N3730 T1 M6

N3740 G187 P3 E.001

N3750 G0 G90 G54 X-1.125 Y1.125 S5000 M3

N3760 G43 H1 Z.25

N3770 Z.15

N3780 G99 G81 Z-.155 R.15 F20.

N3790 X1.125

N3800 X-1.125 Y-1.125

N3810 X1.125

N3820 G80

N3830 Z.25

N3840 M5

N3850 G91 G28 Z0.

N3860 M01

N3870 T4 M6

N3880 G187 P3 E.001

N3890 G0 G90 G54 X-2.875 Y-1.375 S4966 M3

N3900 G43 H4 Z.25

N3910 Z.2

N3920 G1 Z0. F6.4

N3930 X-2.375 F40.

N3940 G3 X-1.875 Y-.875 IO. J.5

N3950 G1 Y-.625

N3960 G2 X-1.375 Y-.125 I.5 J0.

N3970 G1 Y.125

N3980 G2 X-1.875 Y.625 IO. J.5

N3990 G1 Y1.125

N4000 G2 X-1.125 Y1.875 I.75 J0.

N4010 G1 X-.625

N4020 G2 X-.125 Y1.375 I0. J-.5

N4030 G1 X.125

N4040 G2 X.625 Y1.875 I.5 J0.

N4050 G1 X1.125

N4060 G2 X1.875 Y1.125 I0. J-.75

N4070 G1 Y.625

N4080 G2 X1.375 Y.125 I-.5 J0.

N4090 G1 Y-.125

N4100 G2 X1.875 Y-.625 IO. J-.5

N4110 G1 Y-1.125

N4120 G2 X1.125 Y-1.875 I-.75 J0.

N4130 G1 X.625

N4140 G2 X.125 Y-1.375 I0. J.5

N4150 G1 X-.125

N4160 G2 X-.625 Y-1.875 I-.5 J0.

N4170 G1 X-1.125

N4180 G2 X-1.875 Y-1.125 IO. J.75

N4190 G1 Y-.875

N4200 G3 X-2.375 Y-.375 I-.5 J0.

N4210 G1 X-2.875

N4220 Z.2 F6.4

N4230 G0 Z.25

N4240 X-2.625 Y-1.375

N4250 Z.2

N4260 G1 Z0.

N4270 X-2.125 F40.

N4280 G3 X-1.625 Y-.875 IO. J.5

N4290 G1 Y-.625

N4300 G2 X-1.375 Y-.375 I.25 J0.

N4310 G1 X-1.125

N4320 Y.375

N4330 X-1.375

N4340 G2 X-1.625 Y.625 IO. J.25

N4350 G1 Y1.125

N4360 G2 X-1.125 Y1.625 I.5 J0.

N4370 G1 X-.625

N4380 G2 X-.375 Y1.375 IO. J-.25

N4390 G1 Y1.125

N4400 X.375

N4410 Y1.375

N4420 G2 X.625 Y1.625 I.25 J0.

N4430 G1 X1.125

N4440 G2 X1.625 Y1.125 I0. J-.5

N4450 G1 Y.625

N4460 G2 X1.375 Y.375 I-.25 J0.

N4470 G1 X1.125

N4480 Y-.375

N4490 X1.375

N4500 G2 X1.625 Y-.625 IO. J-.25

N4510 G1 Y-1.125

N4520 G2 X1.125 Y-1.625 I-.5 J0.

N4530 G1 X.625

N4540 G2 X.375 Y-1.375 I0. J.25

N4550 G1 Y-1.125

N4560 X-.375

N4570 Y-1.375

N4580 G2 X-.625 Y-1.625 I-.25 J0.

N4590 G1 X-1.125

N4600 G2 X-1.625 Y-1.125 IO. J.5

N4610 G1 Y-.875

N4620 G3 X-2.125 Y-.375 I-.5 J0.

N4630 G1 X-2.625

N4640 Z.2 F6.4

N4650 G0 Z.25

N4660 M5

N4670 G91 G28 Z0.

N4680 M01

N4690 T3 M6

N4700 G187 P3 E.001

N4710 G0 G90 G54 X-2.41 Y-1.375 S4966 M3

N4720 G43 H3 Z.25

N4730 Z.2

N4740 G1 Z.075 F6.4

N4750 X-1.91 F40.

N4760 G3 X-1.41 Y-.875 I0. J.5

N4770 G1 Y-.625

N4780 G2 X-1.375 Y-.59 I.035 J0.

N4790 G1 X-1.125

N4800 G3 X-.91 Y-.375 IO. J.215

N4810 G1 Y.375

N4820 G3 X-1.125 Y.59 I-.215 J0.

N4830 G1 X-1.375

N4840 G2 X-1.41 Y.625 IO. J.035

N4850 G1 Y1.125

N4860 G2 X-1.125 Y1.41 I.285 J0.

N4870 G1 X-.625

N4880 G2 X-.59 Y1.375 IO. J-.035

N4890 G1 Y1.125

N4900 G3 X-.375 Y.91 I.215 J0.

N4910 G1 X.375

N4920 G3 X.59 Y1.125 I0. J.215

N4930 G1 Y1.375

N4940 G2 X.625 Y1.41 I.035 J0.

N4950 G1 X1.125

N4960 G2 X1.41 Y1.125 I0. J-.285

N4970 G1 Y.625

N4980 G2 X1.375 Y.59 I-.035 J0.

N4990 G1 X1.125

N5000 G3 X.91 Y.375 I0. J-.215

N5010 G1 Y-.375

N5020 G3 X1.125 Y-.59 I.215 J0.

N5030 G1 X1.375

N5040 G2 X1.41 Y-.625 IO. J-.035

N5050 G1 Y-1.125

N5060 G2 X1.125 Y-1.41 I-.285 J0.

N5070 G1 X.625

N5080 G2 X.59 Y-1.375 I0. J.035

N5090 G1 Y-1.125

N5100 G3 X.375 Y-.91 I-.215 J0.

N5110 G1 X-.375

N5120 G3 X-.59 Y-1.125 IO. J-.215

N5130 G1 Y-1.375

N5140 G2 X-.625 Y-1.41 I-.035 J0.

N5150 G1 X-1.125

N5160 G2 X-1.41 Y-1.125 IO. J.285

N5170 G1 Y-.875

N5180 G3 X-1.91 Y-.375 I-.5 J0.

N5190 G1 X-2.41

N5200 Z.2 F6.4

N5210 G0 Z.25

N5220 G187 P3 E.001

N5230 X-2.535 Y-.5

N5240 Z.2

N5250 G1 Z-.05

N5260 X-2.035 F40.

N5270 G3 X-1.535 Y0. I0. J.5

N5280 G1 Y1.5

N5290 G2 X-1.5 Y1.535 I.035 J0.

N5300 G1 X1.5

N5310 G2 X1.535 Y1.5 I0. J-.035

N5320 G1 Y-1.5

N5330 G2 X1.5 Y-1.535 I-.035 J0.

N5340 G1 X-1.5

N5350 G2 X-1.535 Y-1.5 IO. J.035

N5360 G1 Y0.

N5370 G3 X-2.035 Y.5 I-.5 J0.

N5380 G1 X-2.535

N5390 Z.2 F6.4

N5400 G0 Z.25

N5410 M5

N5420 G91 G28 Z0.

N5430 M01

N5440 T4 M6

N5450 G187 P3 E.001

N5460 G0 G90 G54 X-2.75 Y-.5 S4966 M3

N5470 G43 H4 Z.25

N5480 Z.2

N5490 G1 Z-.14 F6.4

N5500 X-2.25 F40.

N5510 G3 X-1.75 Y0. I0. J.5

N5520 G1 Y1.5

N5530 G2 X-1.5 Y1.75 I.25 J0.

N5540 G1 X1.5

N5550 G2 X1.75 Y1.5 I0. J-.25

N5560 G1 Y-1.5

N5570 G2 X1.5 Y-1.75 I-.25 J0.

N5580 G1 X-1.5

N5590 G2 X-1.75 Y-1.5 I0. J.25

N5600 G1 Y0.

N5610 G3 X-2.25 Y.5 I-.5 J0.

N5620 G1 X-2.75

N5630 Z.2 F6.4

N5640 G0 Z.25

N5650 M5

N5660 G91 G28 Z0.

N5670 G28 X0. Y0.

N5680 M30

%