
Session 4 (2h) — Post-Processing

Core concepts (1h)

- **Support removal** — flush cutters or pliers for grid supports; tree supports usually snap off cleanly by hand. Always remove supports before test-fitting parts together.
- **Cleanup tools:**
 - Deburring/hobby knife — for stray strings and the seam line
 - Sandpaper (progressively finer grits, e.g. 220 → 400 → 800) — for smoothing visible faces
 - Files — for cleaning up holes/slots so screws or pins fit
- **Test fit before final assembly** — press-fit and screw holes almost never come out exactly to spec on the first print; expect to file/sand a hole slightly, or reprint with an updated tolerance (this is why Session 4 of [cad-design-prep/](#) matters).
- **Optional finishing** (situational, not needed for every prototype):
 - Acetone vapor smoothing (ABS only — not PLA)
 - Primer + paint for a clean surface finish
 - Heat-set threaded inserts (soldering iron pressed into a pre-sized hole) for a durable screw connection that survives repeated assembly/disassembly

On-site task link

This is the direct rehearsal for 후처리 (post-processing) on the internship's on-site task list.

Hands-on practice (1h)

1. If you have a printed part (from any earlier practice or a lab sample), remove its supports with flush cutters and clean the seam line with a hobby knife.
2. Sand one face progressively (220 → 400 grit) and compare its finish to an un-sanded face.
3. Test-fit a screw or pin into a printed hole; if it's too tight, practice carefully filing it slightly larger and re-testing.
4. If no printed part is available yet, do this as a written walkthrough: for your CAD enclosure, list each hole/mating surface and what post-processing step you expect it to need.

Checkpoint

- ☐ Removed supports and cleaned a seam line on a real (or planned) part
- ☐ Understands progressive-grit sanding and when it's worth the time
- ☐ Can describe a test-fit-and-adjust workflow for a too-tight hole