INTERNAL USE

MEDIATEK

MTK_MT8183_N_Customization_SOP_Thermal_v1



Recommend for Bring up issue

Thermal projecting function will trigger reboot/shutdown once any thermal zone overheat.

- What case cause a bring up issue
 - NTC table is NOT match between source code to really thermal resistor value.
- Workaround
 - BTS return 0 degree to avoid reboot issue of wrong temperature.

```
diff --git a/drivers/misc/mediatek/thermal/common/thermal_zones/mtk_ts_bts.c
    b/drivers/misc/mediatek/thermal/common/thermal_zones/mtk_ts_bts.c
index 074c2a2..00b1941 100644
--- a/drivers/misc/mediatek/thermal/common/thermal_zones/mtk_ts_bts.c
+++ b/drivers/misc/mediatek/thermal/common/thermal_zones/mtk_ts_bts.c
@@ -593,6 +593,8 @@ int mtkts_bts_get_hw_temp(void)
    t_ret = get_hw_bts_temp();
    t_ret = t_ret * 1000;
+ t_ret = 0;
+
    mutex_unlock(&BTS_lock);
```

MEDIATEK

everyday genius

Copyright © MediaTek Inc. All rights reserved.