

EQUIPMENT INSPECTION REPORT

Mechanical Integrity – Routine Scheduled Inspection

Report number	MIR/2026/0431
Equipment tag	P-101B – Crude Charge Pump (standby)
Unit	Crude Distillation Unit
Inspection date	14 February 2026
Inspector	R. Nair, Mechanical Inspection

1. OBSERVATIONS

- 1.1 Casing external surface shows light surface corrosion on the discharge side. No measurable wall loss detected.
- 1.2 Mechanical seal exhibits intermittent weeping, approximately 3 to 4 drops per minute during sustained operation.
- 1.3 Bearing housing temperature recorded at 71 degrees C against an alarm limit of 80 degrees C.
- 1.4 Vibration measured at 4.1 mm/s RMS. ISO 10816 Zone B.
- 1.5 Coupling guard fastener missing at position 3 of 4.

2. MEASUREMENTS

Suction pressure	2.4 bar g
Discharge pressure	18.6 bar g
Minimum measured wall thickness	11.2 mm (nominal 12.7 mm)
Retirement thickness	9.5 mm

3. INSPECTOR RECOMMENDATION

Equipment remains fit for continued service. Replace the missing coupling guard fastener before the next start. Schedule mechanical seal replacement at the next available maintenance window. Re-inspect casing corrosion at the next turnaround.

Prepared by: R. Nair

Reviewed by: _____