

Inspection Exception Digest - Mechanical Machining Cell

Prepared for Manufacturing Readiness Review. Open High and Critical exceptions block production release unless a signed engineering-change authority decision says otherwise.

Open Blocking Exceptions

Exception ID	Part ID	Inspection Area	Severity	Status	Finding	Blocks Release	Required Disposition
IX-3103	MP-021	FAI dimensional	High	Open	Datum-B hole true position exceeds tolerance on pump guard hinge boss.	Yes	Rework and re-inspect before release; resolved category Inspection Remediation.
IX-3108	MP-023	Document control	Critical	Open	Material certificate and first-article data package missing; no defensible release date.	Yes	Defer until material cert and FAI evidence are provided.
IX-3112	MP-039	Weld/visual inspection	Critical	Open	Guard end-plate weld crack found after trial fit-up.	Yes	Weld repair, NDT check, and inspector sign-off required.
IX-3124	MP-044	Material certification	High	Open	Heat-treatment certificate package is incomplete for 42CrMo4 QT lift-lug doubler plate.	Yes	Supplier material hold until certificate package is complete.
IX-3117	MP-047	FAI dimensional	High	Open	Spacer datum ring slot width is out of tolerance against latest drawing.	Yes	Correct slot width and repeat first-article inspection.

Inspection Exception Digest - Closed or Nonblocking Notes

Closed exceptions below do not create release blockers. Commercial or routing decisions still follow signed engineering-change authority where applicable.

Closed and Nonblocking Exception Notes

Exception ID	Part ID	Inspection Area	Severity	Status	Finding	Release Effect	Cross-reference Note
IX-3084	MP-009	Surface finish	Medium	Closed	Fixture polish mark was corrected during trial run.	No blocker	SCR-2008 cost claim was rejected by signed authority.
IX-3092	MP-012	Burr inspection	Low	Closed	Burr remediation on guard top panel is closed.	No blocker	Commercial review is based on signed SCR-2011, not inspection status.
IX-3110	MP-033	Tab straightness	Medium	Closed	Guard tab rework was accepted by inspection.	No blocker	SCR-2029 cost claim has no approved value after authority rejection.
IX-3115	MP-034	Deburr/edge break	Low	Closed	Deburr remediation closed after sample verification.	No blocker	SCR-2030 is signed and exceeds cost-review threshold.
IX-3122	MP-041	Supplier handoff	Low	Closed	Supplier responsibility transfer confirmed after NCR closure.	No blocker	Accountable supplier follows ECO-VN-041.

Region/Cell Notes by Machine Group

Machine Group	Inspection Manager Notes
VMC-1	Prioritize MP-023 evidence recovery and MP-047 repeat FAI. Do not release parts with missing material certificate evidence or open high dimensional exceptions.
VMC-2	MP-021 requires rework and repeat inspection before release. MP-029 has no inspection blocker; open supplier cost request remains commercial follow-up only.
HMC-1	MP-044 is a supplier material hold until the heat-treatment certificate package is complete. MP-034 inspection is closed; cost review remains active because SCR-2030 is signed.
Mill-Turn-1	MP-006 and MP-018 are not inspection-remediation holds; their release constraints come from material/capacity and signed authority decisions.