

## MANUFACTURING PLAN

RAW MATERIAL STOCK: Aluminum 1"x1" Angle Stock

STEP	PROCESS DESCRIPTION	MACHINE	FIXTURE	TOOL(S)	SPEED (RPM)
1	Cut Raw Stock	Bandsaw	Bandsaw Vise		
2	Find Center	Mill	Vise 1.375"	Edge Finder with Chuck	100
3	centerdrill	Mill	Vise 1.375"	Centerdrill with chuck	100
4	Drill Bottom Hole	Mill	Vise 1.375"	#30 Drill Bit/ 1/4" Collet	700
5	Rotate Part				
6	Find Center ( TOP )	Mill	Vise 1.375"	Edge Finder	100
7	centerdrill	Mill	Vise 1.375"	Centerdrill with chuck	100
8	Drill Top Hole	Mill	Vise 1.375"	13/64" Drill Bit, 3/8" Collet	700
9	Ream Top Hole	Mill	Vise 1.375"	3/8" Collet, 3/8" Ream	100
10	Face Front Side	Mill	Vise 1.375"	7/16" Endmill, 7/16" Collet	850

В

A

SHEET 2 OF 2