# VAYU-BSP-01.01.03.13 ReleaseNotes

### **BSP Version 01.01.03.13**

Release Notes 13th February, 2014

### **Important Note**

This release is for TDA2xx (Vayu) and TI814x (Centaurus for serial drivers only) platforms

### **Document License**

This work is licensed under the Creative Commons Attribution-Share Alike 3.0 United States License. To view a copy of this license, visit http://creativecommons.org/licenses/by-sa/3.0/us/or send a letter to Creative Commons, 171 Second Street, Suite 300, San Francisco, California, 94105, USA.

### Introduction

This release notes provides important information that will assist you in using the BSP software package. This document provides the product information and know issues that are specific to the BSP software package.

#### **New in this Release**

- MISRA C Compliance for BSP Drivers
  - MISRA C KW Report with full details of drivers compliant to MISRA-C is included in the docs folder
- Bug Fixes
- Validated TDA2XX ES1.1 Silicon
- Capture
  - New IOCTL's added:
    - IOCTL\_VPS\_CAPT\_REGISTER\_OVF\_INTR: This will register for the interrupts from hardware in case on overflow on VIP
    - IOCTL\_VPS\_CAPT\_UNREGISTER\_OVF\_INTR: This will unregister from the interrupts for overflow.
    - IOCTL\_VPS\_CAPT\_CHECK\_OVERFLOW: This will check for the overflow on particular VIP instance
    - IOCTL\_VPS\_CAPT\_RESET\_VIP\_PORT: This will reset the VIP port. It will not completely reset the port. It can be used to stop the port and then reset it
  - New function prototype Vps\_CaptVipOverflowFxn added
    - This is the function prototype of the overflow callback function
  - · New structures added
    - Vps\_CaptOverflowParams: This structure contains the parameters required for registration of the overflow interrupt.
    - Vps\_CaptOverflowCheckParams: This structure is filled as a result of the call to IOCTL\_VPS\_CAPT\_CHECK\_OVERFLOW IOCTL.
- UART: Supported Interrupt mode, but some random junk characters are seen in this mode of operation.
- McASP: HAL Support for McASP IDLE Mode Settings
- Fvid: New data formats added in Fvid2\_DataFormat structure.
  - FVID2\_DF\_RGBX16\_4444

- FVID2\_DF\_XRGB32\_8888
- FVID2\_DF\_BGRX32\_8888
- FVID2\_DF\_BGRA16\_1555
- FVID2\_DF\_BGRX16\_1555
- FVID2\_DF\_BGRA32\_1010102
- FVID2\_DF\_BGRX32\_1010102
- FVID2\_DF\_RGBA32\_1010102
- FVID2\_DF\_RGBX32\_1010102
- FVID2\_DF\_BGRA64\_16161616
- FVID2\_DF\_BGRX64\_16161616
- FVID2\_DF\_ABGR64\_16161616
- FVID2\_DF\_XBGR64\_16161616

## **Installation and Usage**

Installation and Usage of the BSP package could be found at BSP\_UserGuide

## **Upgrade and Compatibility Information**

#### Common

- dcoClk member is replaced with pixelClk in structure Bsp\_PlatformSetPllFreq, this member should be set to pixel clock frequency in KHz. dcoClkPostDiv[] array is removed from the structure Bsp\_PlatformSetPllFreq in bsp\_platform.h file.
- isCrossBarSettingReq member is split into two members isIrqXBarSettingReq and isDmaXBarSettingReq in Bsp\_PlatformInitParams structure. These variables should be updated accordingly.
- New isAllMcSPIInitReq member added to Bsp\_PlatformInitParams structure, by default only McSPII will be initialized if isAllMcSPIInitReq is set to true all four McSPI's will be initialized.
- sys\_config library should be added as a dependent library if bsp\_platform library is used. If this is not taken care linker error is seen for DMAXBARConnect\_function

#### VIP Capture

- None
- VPE M2M
  - None

#### DSS Display

- In Display Controller Driver, IOCTL\_VPS\_DCTRL\_SET\_VENC\_OUTPUT should be called before IOCTL\_VPS\_DCTRL\_SET\_CONFIG.
- UART
  - None
- McSPI
  - configChfmt structure name changed to Mcspi\_ConfigChfmt in bsp\_mcspi.h file
- I2C
  - None
- McASP
  - None

#### Audio

• None

### **Dependencies**

This release requires following tools/packages to be installed.

Starterware Package: 01.01.01.18
Code Composer Studio Version: 5.4
XDC Tools Version: 3.25.05.94

CG Tool (TMS470) Version: 5.0.7CG Tool (C6000) Version: 7.4.2

• EDMA LLD: 02.11.11.13

• BIOS Version: 6.37.01.24

### **Devices Supported**

- TDA2xx ES1.0,ES1.1
- TI814x (for Serial Drivers only)

## **Application Boards Supported**

- TDA2xx Base board + LCD board
- TDA2xx Vision application board
- TDA2xx Vision application board with Multi-deserializer board
- TDA2xx JAMR3 application board

### What is Supported

#### Common

- Supports for TDA2xx EVM/VIRTIO/Zebu
- Supports FVID2 interfaces for all the supported drivers
- Package includes BSP driver sources, sample applications that demonstrate use of drivers and sample applications
  executables
- · SYS BIOS mode is tested
- Benelli M4 (IPU1) Core 0 for TDA2xx
- · Virtual to physical address translation for VPDMA descriptor memory is supported

### **VIP Capture Driver**

- Supports VIP capture driver (12 instance on TDA2xx)
- Support for OV10635 sensor present in TDA2xx vision daughter card
- Support for Aptina A0132 sensor present in TDA2xx vision daughter card
- Support for HDMI sil9127 receiver present in TDA2xx vision daughter card
- Support for 6-channel LVDS capture from multi-deserializer board
- · Support for LI sensor present in base board
- Support for TVP5158 decoder present in JAMR3board

#### **VPE M2M Driver**

- Supports VPE1 path
- Supportted Input Formats: YUV422I, YUV420SP and YUV422SP
- Supportted Output Formats: YUV422I, YUV420SP, YUV422SP, RGB888 and YUV444
- Supports SC and DEI
- Supports sliced based scaling

### **DSS Display Driver**

- Supports DSS display driver with all pipelines going to any LCD, blended or without blending
- Supports display controller driver to set the display paths and VENC resolution
- Supports LCD and On-Chip HDMI display

#### **UART Driver**

- Device Driver for UART on ARM M3,M4
- Sample Application that demonstrate the use of driver for UART Echo Test.

#### McSPI Driver

- Device Driver for McSPI on ARM Cortex M3,M4
- Sample Applications that demonstrate the usage of Driver:
  - Writes to On Board Serial Flash in case of TI814X
  - EVM to EVM Communication for both TI814X and TDA2XX
  - Loopback Testing for TDA2xx
  - Writes to McSPI Slave Adaptor with McSPI as Master for TDA2XX

#### **I2C Driver**

- Device Driver for I2C on M4 Core
- GIO and IOM Model APIs are supported for Application
- Sample Application that demonstrate the usage of Driver:

### **McASP Driver**

- Device Driver for McASP on DSP Core
- Sample Application that demonstrate the usage of Driver:
- Driver expects the data (samples) to be in a specific format when requesting for an IO transfer based on below configurations
  - · Single Serializer
  - Multiple Serializer
  - BurstMode
  - Multislot TDM/I2S
  - DIT

### **Audio Driver**

- Device Driver for Audio on DSP Core
- Every Instance can support multiple codecs
- Sample Applications that demonstrate the usage of Driver
  - Sine Tone Generation
  - Loopback Application

### **Aic31 Driver**

- Device Driver for AIC31 on DSP Core
- Appropriate interfaces to configure the initial values of gain, sample rate
- Interfaces to control the codec specific features like sample rate etc

### **Features**

# **VIP Capture Driver Features**

Feature	Supported	Tested on EVM
12 instances (3 VIP x 2 Slice x 2 Port)	YES	YES, Only VIP1 Slice 0 Port A
8-bit Embedded Sync (BT.656)	YES	YES
16-bit Embedded Sync (BT.1120)	YES	NO
24-bit Embedded Sync	YES	NO
8-bit Discrete Sync	YES	YES (only VSYNC/HSYNC mode)
16-bit Discrete Sync	YES	YES
24-bit Discrete Sync	YES	NO
8-bit YUV422 Input	YES	YES
16-bit YUV422 Input	YES	NO
24-bit YUV444 Input	YES	NO
16-bit RGB656 Input	YES	NO
24-bit RGB888 Input	YES	YES
12/16-bit RAW Input	YES	NO
24-bit RAW Input	YES	NO
YUV422I, YUV420SP, YUV422SP, RGB888, YUV444 and RAW output formats	YES	YES
Embedded Sync Multiplexed Modes	NO	NO
Ancillary (VBI) data capture	NO	NO
Bypass mode (RAW to RAW - no processing)	YES	NO
Inline SC Support (cropping, down scaling)	YES	YES
Inline CSC	YES	YES
Configurable VPDMA Line Limit Feature	YES	YES
Tiled (2D) output	NO	NO
Dual stream output (scaled/non-scaled)	NO	NO
Sub-frame based capture	YES	YES

Sub-frame based OTF use case	YES	NO
Re-packer	YES	YES (only on TDA2xx Zebu)
VIP Parser Crop	YES	YES
Buffer Capture Modes - drop frame, last frame repeat, circular frame repeat	YES	YES
Frame Drop IOCTL	YES	YES
Instance and channel status	YES	YES

# **VPE M2M Driver Features**

Feature	Supported	Tested on EVM
VPE1 instance	YES	YES
YUV422I, YUV420SP, YUV422SP input formats	YES	YES
YUV422I, YUV420SP, YUV422SP, RGB888, YUV444 output formats	YES	YES
Tiler (2D) input/output	YES	YES
Tiler Rotation/Mirroring	YES	YES
SC (cropping, scaling)	YES	YES
DEI (bypass and in deinterlacing mode)	YES	YES
VC1 range mapping and reduction	NO	NO
DEI FMD mode	NO	NO
Multi-Handle	YES	YES
Multi-Channel	YES	YES
Lazy loading of SC coefficient	YES	YES
Slice based scaling (only horizontal slices)	YES	YES
Runtime parameter change	YES	YES

# **DSS Display Driver Features**

Feature	Supported	Tested on EVM
Video pipeline (Video 1,2,3)	YES	YES
Graphics pipeline (GRPX1)	YES	YES
Writeback pipeline	NO	NO
All LCD/DPI outputs	YES	YES (only DPI1 tested on EVM)
On-Chip HDMI 1.4 Support	YES	YES
HDMI 3D	NO	NO
HDMI 36-bit RGB Color	NO	NO
HDMI HDCP 1.4	NO	NO
HDMI Deep color mode	NO	NO
8-bit Embedded Sync (BT.656)	YES	NO
16-bit Embedded Sync (BT.1120)	YES	NO
24-bit Discrete Sync	YES	YES

8/16 bit Discrete Sync	NO	NO
HDMI PLL	YES	YES
VIDEO 1/2 PLL	YES	YES
YUV422I (YUYV),YUV422I (UYVY),YUV420SP, RGB888 input formats	YES	YES
YUV444 input formats	NO	NO
Tiler Memory (2D)	NO	NO
Tiler Rotation/Mirroring	NO	NO
VC1 Range Mapping (for Video Pipes)	NO	NO
Bypass mode	NO	NO
Inline SC	YES	YES
Inline CSC	YES	YES
Blending	YES	YES
Low-latency display (ability to queue frame to driver/hardware just before VSYNC)	YES	YES
Interlaced scan format	YES	NO
Fields merged and separated interlaced buffers	YES	NO

# **UART Driver Features**

Feature	Supported	Tested
Single instance	YES	YES
Multi instance and Re-Entrant	YES	NO
Each Instance as Transmitter and / or receiver	YES	YES
DMA Mode Of Operation	YES	YES
POLLED Mode Of Operation	YES	YES
INTERRUPT Mode Of Operation	YES	YES

# **I2C Driver Features**

Feature	Supported	Tested
Single instance	YES	YES
Multi instance and Re-Entrant	YES	YES
Slave Device Probe IOCTL	YES	YES
Each Instance as Master Transmitter	YES	YES
DMA Mode Of Operation	NO	NO
POLLED Mode Of Operation	YES	YES
INTERRUPT Mode Of Operation	YES	YES

# **McSPI Driver Features**

Feature	Supported	Tested on Tda2xx	Tested on TI814x
Single instance	YES	YES	YES
Multi instance and Re-Entrant	YES	YES	YES
Each Instance as Transmitter and / or receiver	YES	YES	YES
DMA Mode Of Operation	YES	YES	YES
POLLED Mode Of Operation	NO	NO	NO
INTERRUPT Mode Of Operation	NO	NO	NO

# **Audio Driver Features**

Feature	Supported	Tested on Tda2xx	Tested on TI814x
Multi instance and Re-Entrant	YES	YES	YES
Each Instance as Transmitter and / or receiver of an audio device	YES	YES	YES
DMA Mode Of Operation	YES	YES	YES
POLLED Mode Of Operation	NO	NO	NO
INTERRUPT Mode Of Operation	NO	NO	NO

# **McASP Driver Features**

Feature	Supported	Tested on Tda2xx	Tested on TI814x
Single instance	YES	YES	YES
Multi instance and Re-Entrant	YES	YES	YES
Each Instance as Transmitter and / or receiver	YES	YES	YES
Multiple Data Formats	YES	NO	NO
Configurations to operate: multi-slot TDM, I2S, DSP	YES	YES	YES
Configurations to operate: DIT (S/PDIF)	YES	NO	NO
Desired data (such as NULL tone), when idle Transmission Mechanism.	YES	YES	YES
Explicit control of PIN directions for High Clock, Bit Clock and Frame Sync PINS.	YES	YES	YES
DMA Mode Of Operation	YES	YES	YES
POLLED Mode Of Operation	NO	NO	NO
INTERRUPT Mode Of Operation	NO	NO	NO

# **AIC31 Codec Driver Features**

Feature	Supported	Tested
Multi instance and Re-Entrant	YES	YES
Independent Configuration of Transmitter and receive of an audio device with and multiple audio codecs	YES	YES
Interfaces to control the codec specific features like sample rate etc	YES	YES
Appropriate interfaces to configure the initial values of gain, sample rate etc	YES	YES

# **Driver Maturity**

# **Driver Maturity**

Driver	TDA2xx	TI814x
VIP Capture	Beta 1.0	NA
VPE M2M	Beta 1.0	NA
DSS Display	Beta 1.0	NA
UART	Beta 1.0	Beta 1.0
McSPI	Beta 1.0	Beta 1.0
I2C	Beta 1.0	Beta 1.0
McASP	Beta 1.0	Beta 1.0

# Supported/Validated Examples on TDA2XX-EVM

# **Supported/Validated Examples**

Examples	Supported	Validated
VIP Capture	YES	YES
VIP Sub-frame	YES	YES
VPE M2M	YES	YES
DSS Display	YES	YES
Loopback	YES	YES
UART ECHO	YES	YES
MCSPI LOOPBACK	YES	NO
MCSPI MASTER SLAVE BOARD TO BOARD	YES	NO
MCSPI PERFORMANCE APP	YES	YES
I2C ON Board LED Blink	YES	YES
Audio SINE TONE GENERATION using AIC31Codec	YES	YES
Audio Loopback Application	YES	YES

• Examples could be found at \$BSP\_Install\_Dir\examples\

# What is Not Supported

- · Checking for most of the input parameters for out of range and invalid values is not done
- · Scaler lazy loading and user coefficient loading are not supported in VIP capture driver
- VIP Reset IOCTL is not supported in VIP capture driver. The driver internally resets the VIP during driver create.
- Mux-mode VIP capture is not supported
- Multiple stream outputs from same video source is not supported
- McASP and McSPI does not support Interrupt/Polled mode
- I2C is not supported in DMA mode

### **Fixed in this Release**

### **Fixed in this Release**

ID	Headline	Module	Remarks
OMAPS00297591	[Display] - Pink Lines seen on LCD with Ramps Test pattern	DSS	NA
OMAPS00305909	MCASP POWERIDLE_SYSCONFIG register setting to recommended value	MCASP	NA
OMAPS00304666	[App] AMMU configuration is incorrect in default application cfg file	Memory MAP	NA
OMAPS00304437	It seem transfer count of DMA is smaller than expect in UartEdma driver.	UART	NA
OMAPS00304360	Display of YUV 420 SP not working	DSS	NA
OMAPS00304133	[LCD] LCD controller mode selection is not proper	LCD Driver	NA
OMAPS00303787	Crash in the driver for IOCTL_VPS_DISP_GET_DSS_PARAMS call	DSS	NA
OMAPS00301418	[DSS] Display sample application results in asserts for HDMI options 6 & 7	DSS	NA
OMAPS00301549	[DSS] Fields are interchanged for 1080i60 Display Output	DSS	NA
OMAPS00302222	[McSPI] McSPI TX/RX FIFO Buffer configuration Failure	McSPI	NA
OMAPS00302288	Power ON Sequence for McASP, McSPI Bug	McASP	NA
OMAPS00302444	[HDMI] - Driver asserts when standard timing is used instead of custom.	DSS	NA
OMAPS00302522	[Display] - During HDMI display the same content was display on LCD	DSS	NA
OMAPS00303658	[Display]- No Grpx output on HDMI display	DSS	NA
OMAPS00305304	[Board] Base board is detected as UNKNOWN board	Board	NA
OMAPS00302776	[Build] evmDRA7XX should be used as XDC platform instead of simVayu	Platform	NA
OMAPS00302080	Inconsistent memory section placements for arrays in bsp_examples_utility	Build	NA
OMAPS00306129	In User guide it is not clearly specified to place the VPDMA descriptor section in non-cached mem	Documentation	NA
OMAPS00300787	[Platform] - Programming of video PLL is incomplete	Platform	NA

# **Known Issues / Limitations**

### **Known Issues**

ID	Headline	Module	Workaround in this release
OMAPS00306090	[Makerules] Wrong linker command options used for CGTools	Tools	NA
OMAPS00296239	Display: VID3 pipeline output results in black output when zorderEnable is disabled	Display Driver	Enable Z-order and assign proper order
OMAPS00303494	SIL9127 errata needs to be implemented fully before CES	SIL Driver	NA
OMAPS00301476	[LVDS] Re-run of the any LVDS option results in I2C issues	Capture Driver	Disable I2C probe all at the start of device init by setting isI2cProbingReq of Bsp_DeviceInitParams init parameter to FALSE
OMAPS00303975	[Display] - Error Interrupts are not logged in driver	Display Driver	NA
OMAPS00303850	[Display app] Downscaling on HDMI gives distorted image as output	Display Driver	NA
OMAPS00305622	[I2C] I2C read to a known slave fails after I2C write to absent slave timesout	I2C Driver	NA
OMAPS00306536	No Signal warning in the HDMI display	HDMI Driver	NA
OMAPS00305906	FVID2Stop On one of the video pipe halts all video Pipe,	Display Controller Driver	NA
OMAPS00305846	Vayu: McASP driver create causing ROV HeapMem corruption	McASP Driver	NA
OMAPS00304966	UART DMA Mode does not work for Tx Threshold other than 56	UART Driver	NA
OMAPS00302354	[EDMA LLD] Spurious EDMA CC Interrupts on Enabling McSPI DMA Mode	McSPI Driver	NA
OMAPS00299974	[Docs] App notes for Selective VIP/VPE/DSS build/package	Documentation	NA
OMAPS00306622	EDID Prog Fails on LVDS setup	Capture Driver	NA
OMAPS00297823	[Display] - AppNote required for BT.601 support with DSS	Documentation	NA
OMAPS00297821	[Display] - BT656 display mode not working	Display Driver	This is DSS IP Bug
OMAPS00294864	[Vayu ] McASP Slave Mode Testing for audio codec application is not supported	McASP Driver	This is Vayu EVM Limitation
OMAPS00291957	Display :- Low latency display is not supported for Overlays other than LCD1.	Display Driver	This is DSS IP Limitation

OMAPS00301599	Random FVID2_TIMEOUT error during sensor configuration in LVDS use case	Capture Driver	After debugging, this is root caused because of Deserializer watchdog time out of 500ms for the control channel to the serializer. This needs to be debugged further with the EVM team
OMAPS00305590	Infinite blocking of the UART Read if there is no data available.	UART Driver	NA
OMAPS00306882	Random Junk Characters on console with UART write in Interrupt	UART Driver	NA
OMAPS00306977	[UART UT] UART DMA Mode IOCTOL Tests are Failing	UART Driver	NA
OMAPS00306979	[UART UT] DMA Mode InSync Tests Fail	UART Driver	NA
OMAPS00306980	[Audio UT] Audio Noise on McASP UT Tests	McASP Driver	NA

#### Common

• While validating the sample application on Zebu, it is observed that when very short frames is given as input to VIP or very small size sub-frame is configured in VIP or when the display resolution is small, the M4 is not getting time to run the task context. This is because of back-to-back interrupts from the VIP/DSS. Because of this the application task never gets time to execute and hence the application never ends even though the outputs are captured/displayed properly. Hence it is recommnended to use bigger frame size for VIP/DSS. This issue is also due to the fact that the M4 in Zebu is currently configured to run in bypass mode (equivalent to 20 MHz) and also cache is disabled.

### **VIP Capture Driver**

- 24-bit RAW capture No support in EVM
- RGB888 input to VIP No support in EVM/Simulator
- Various discrete sync modes except HSYNC/VSYNC mode No support in EVM

### **VPE M2M Driver**

• YUV444 output is not modeled in Virtio and the test results in hang. This feature is validated/supported only on Zebu/Silicon.

#### **DSS Display Driver**

• Blended output (say 1 Video + GRPX) on Virtio is not proper as it is not modeled properly on Virtio

#### **Serial Drivers**

- UART Baud rates greater than 115200 are not supported due to high error percentage observed for baud rates greater than 115200.
- UART single byte transfer is supported in Polled Mode and not in DMA Mode.
- A15 needs to be running while loading and running applications on DSP Core

### **Validation Information**

- This release is validated on TDA2xx (Silicon Revisions ES1.0, ES1.1) EVM for the above mentioned components
- In case of serial drivers, this release is validated on TI814x ES2.1 as well

# **Technical Support and Product Updates**

For further information or to report any problems, contact http://e2e.ti.com or http://community.ti.com or http://support.ti.com.

33.13 ReleaseNotes Source: http://ap-fpdsp-swa	apps.dal.design.ti.com/index.php?oldid=181682 Con	ntributors: A0131716, A0132325, Jags269, SivarajR