SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Mold Assessment Report

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Assessment date: 11/05/2026

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

Year built: 1925

1. Findings by room

Room 1: Bedroom

Room dimensions: 12 ft x 8 ft, ceiling height 8 ft

Visible mold growth was observed on the underside of the wood flooring across the entire bedroom floor.

Affected area: 96 SF

Room 2: Hallway
Room dimensions: 10 ft x 4 ft, ceiling height 8 ft
Growth observed on approximately 50% of the hallway floor, along the bedroom doorway.
Affected area: 20 SF
Room 3: Closet
Room dimensions: 4 ft x 3 ft, ceiling height 8 ft
Visible growth across the entire closet floor.
Affected area: 12 SF
Living room: no visible growth observed.
Room dimensions: 14 ft x 12 ft, ceiling height 8 ft
Flooring: the wood flooring runs continuously from the bedroom into the hallway, closet and living room with no threshold or natural break.

2. Remediation plan

Moisture source: leak at the radiator supply valve. The leak has been repaired by the building.
Subfloor: clean and treat the plywood subfloor (do not remove).
Walls: no growth observed on wall surfaces.
Baseboard: no growth observed on baseboard backs.
Framing: no growth observed on accessible framing.
Containment: full containment of the bedroom, hallway and closet with HEPA negative air.
Removal: remove all wood flooring and underlayment with growth, extending 2 ft beyond visible growth.
Post-remediation verification: by an independent licensed mold assessor; visual inspection, moisture readings at or below dry standard, and air samples comparable to outdoor.