CALDERBANK VINE

Chartered Building Surveyors | 18 Greyfriars Lane, Coventry CV1 2GW

BUILDING SURVEY REPORT

(Acquisition due diligence — abbreviated for the data room)

Property	**Meridian Trade Park, Siskin Drive, Coventry CV3 4FJ**
Prepared for	**Aldous Wren Capital Limited**
Surveyor	**Roger Calderbank MRICS, Calderbank Vine**
Date of inspection	**10-11 November 2025**
Date of report	**12 November 2025**

1. Instructions and scope

We were instructed by Aldous Wren Capital Limited to carry out a building survey of Meridian Trade Park in connection with its proposed acquisition. Our inspection was a visual inspection of the accessible parts of the nine units, the external envelope, the estate roads and the common areas. We did not open up the structure or test services. This report summarises our principal findings and should be read with the photographic schedule and the costed defects schedule appended to the full report in the data room.

2. Construction and general description

The estate was constructed in two phases (c.1996 and c.2004). The units are of steel portal frame construction with profiled metal cladding to walls and roofs, brick/blockwork to lower elevations, concrete floor slabs, and roller shutter and personnel access doors. Each unit has ancillary two-storey offices with suspended ceilings and carpet/vinyl finishes. The estate roads and yards are surfaced in tarmacadam with concrete apron slabs to the loading areas.

3. Condition — summary by element

Element	Condition	Comment
Structure (portal frames)	**Good**	**No evidence of distress, corrosion or movement. Adequate for continued use.**
Roofs (Phase 1 — Units 1-5)	**Fair / Poor at Unit 2**	**Single-skin and twin-skin profiled sheeting nearing the latter part of its serviceable life. Localised water ingress at Unit 2 (failed laps and corroded fixings) — see section 4.**
Roofs (Phase 2 — Units 6-9)	**Good**	**Composite panels in good order with residual life of 15+ years.**
Wall cladding	**Good**	**Minor surface staining; no significant defects.**
Floor slabs	**Good**	**Some surface dusting and minor cracking consistent with age and use.**
Loading doors	**Fair**	**Generally serviceable; routine maintenance recommended to two roller shutters (Units 3 and 7).**
Drainage / yards	**Fair**	**Localised ponding to the Unit 4 yard; gully clearance recommended.**
Asbestos	**Managed**	**ACMs present in soffits to Units 3 and 7; managed under the asbestos management plan. No action required beyond ongoing management.**

4. Unit 2 roof — principal defect

The roof to Unit 2 exhibits active water ingress at the eaves and at sheet laps on the north-facing slope, caused by corroded fixings and failed sealant at the laps. Internal staining and minor corrosion to a small number of purlins was noted. In our opinion the most cost-effective remedy is localised overcladding of the affected north slope together with replacement of fixings and lap sealant, rather than full roof replacement. We estimate the cost of the recommended works at £68,000 to £78,000 plus VAT and professional fees. We understand a retention of £65,000 has been agreed in the Contract to cover these works, which we consider adequate.

5. Costed repairs — indicative (next 10 years)

Item	Priority	Indicative cost
Unit 2 roof — localised overcladding & repairs	**Immediate (retention)**	£73,000
Roller shutter overhaul (Units 3 & 7)	**1-2 years**	£9,500
Yard drainage / gully clearance (Unit 4)	**1 year**	£4,200
Phase 1 roof refurbishment (Units 1,3-5)	**5-8 years**	£240,000
Resurfacing of estate roads (patch & overlay)	**6-10 years**	£120,000
Total indicative (10-year)		**£446,700**

6. Conclusion

The estate is generally in fair to good condition and is fit for its current purpose. The principal short-term liability is the Unit 2 roof, which is adequately addressed by the agreed retention. The Phase 1 roofs will require refurbishment within the medium term and should be reflected in the Buyer's asset management plan and reserve. Subject to those matters, we consider the Property a sound acquisition from a building condition perspective.

Roger Calderbank MRICS — Calderbank Vine — 12 November 2025