#### **General recommendations:**

- For exams in presence: to access the software on the provided laptops, go on browser → Favourites →
  Managed favourites → Virtual Desktop and enter your Polimi credentials.
- write the solutions in CLEAR and READABLE way on paper and show (qualitatively) all the relevant plots;
- avoid (if not required) theoretical introductions or explanations covered during the course;
- always state the assumptions and report all relevant steps/discussion/formulas/expression to present and motivate your solution;
- when using hypothesis tests provide the numerical value of the test statistic and the test conclusion in terms of p-value.
- Exam duration: 2h 10min
- MULTICHANCE STUDENTS SHALL SKIP: Exercise 1) point c, Exercise 2) point d.

#### Exercise 1 (15 points)

A company produces titanium impellers for the oil and gas sector. To meet sustainability targets, the company started monitoring the spindle power consumption during machining operations. The production of each impeller consists of four consecutive machining steps: step 1, 2 and 3 are roughing operations, while step 4 is the finishing operation. Table 1 includes power consumption data gathered during the production of ten consecutive impellers.

Step Step X (kW) X (kW) X (kW) X (kW) Step Step 12,05 12,09 1 3 12,12 1 11,79 3 2 12,2 4 2 11,68 11,84 12 4 3 1 3 12.14 11,86 11,96 11,95 4 2 4 2 11,81 12,05 11,76 12,07 12,24 3 11,95 12,16 1 1 12,03 3 2 12,17 4 11,67 2 12,07 4 12,2 3 12,05 1 11,93 3 11,87 1 11,98 4 11,79 2 11,88 4 11,59 2 11,86 1 11,92 3 11,87 1 11,91 3 11,98 2 12,19 4 11,63 2 11,97 4 11,75

Table 1

- a) Find a suitable model for power consumption data in Table 1.
- b) The head of the quality department is interested in using spindle power data to monitor the stability of the process. Based on the result at point a) design a suitable control chart with  $ARL_0 = 200$ . Assume the existence of assignable cause if out of control observations are present.
- c) By using a suitable statistical test, determine whether the power consumption of the finishing operation is statistically lower than the power consumption during the roughing phase (exclude out of control observations identified in point b), if any).

#### Exercise 2 (15 points)

A wine producer decides to apply statistical process monitoring tools to keep under control the quality of his production. During the barrel aging phase, he periodically measures four quality variables, x1, x2, x3, x4 taking a wine sample from randomly selected barrels. Data collected in successive samples are reported in Table 2.

ľ	al	)	e	2

Sample	X1	X2	Х3	X4
1	30,7	15,2	294,6	75,6
2	32,2	16,1	292,5	76,9
3	27,2	14,7	295,9	77,5
4	31,1	16,7	299,3	79,2
5	29,4	16,4	293,8	87,2
6	28,4	14,7	302,1	73,5
7	29,5	13,7	286,6	75,4
8	30,4	15,8	294,8	74,6
9	34,4	18,7	305,5	75
10	33,4	17,2	290,4	78
11	28,3	15	296,1	78,8
12	33,7	17,6	295,6	76
13	30,9	15,2	293,7	76,6
14	29,9	15,2	295	75,5
15	30,9	14,8	286,3	78,4
	/ -	/-	/-	, .

- a) The wine maker is interested in using the PCA to analyze these data. Would it be more appropriate to use the sample variance-covariance matrix or the sample correlation matrix to estimate the principal components?
- b) Estimate the PCA model for data in Table 2 by retaining the number of principal components required to capture at least 75% of the overall variability (report the eigenvalues and eigenvectors of retained PCs).
- c) Based on the result of point b), design a Hotelling's  $T^2$  control chart for the wine data with  $ARL_0 = 200$ . Can we conclude that the barrel aging process is stable and in-control?
- d) How do the result of point c) changes if the Hotelling's  $T^2$  control chart is designed using m+1 principal components, where m is the number of PCs used in point c)? Discuss the results.
- e) The wine maker decides to extend the data collection for a longer period. Based on the collection of 100 samples, he estimates the following sample mean and variance-covariance matrix:

$$\bar{x} = [28.8 \ 12 \ 288 \ 75], \mathbf{S} = \begin{bmatrix} 1.4 & 0.75 & 0.1 & 0.5 \\ 0.75 & 1.3 & 1.7 & 0.5 \\ 0.1 & 1.7 & 6.6 & 0.3 \\ 0.5 & 0.5 & 0.3 & 3.6 \end{bmatrix}$$

Design a statistical test to determine if the variances explained, respectively, by the first and second PC estimated from the new data are statistically different from the ones estimated from data in Table 2 (use a familywise confidence level  $\alpha = 0.05$ ; assume that the new sample is random, normal and independent from the data sample in Table 2).

#### Exercise 3 (3 points)


Using the sample statistics defined in point e) of Exercise 2, report the eigenvalue and eigenvector corresponding to the first PC. Show that the variance explained by this first PC is higher than the variance explained by a simple linear combination of the four variables where equal weight is given to all the variables (for sake of comparison, remind the normalization constraint a'a = 1). Discuss the result.

#### **Solutions**

#### **Exercise 1**


#### <u>a)</u>

Time series plot of the spindle power data:




There is a meandering pattern with a seasonal drop of the spindle power in correspondence of step 4.

This lag 4 effect is also visible from the SACF:



The way in which the power varies along the different process steps is shown in the following scatter plot:



A part from one apparent outlying value, step 4 (finishing) yields a lower power consumption, as expected.

Based on this, it would be possible to fit a model of the spindle power using as regressor the categorical variable "step" as follows:

ESE'

#### Regression Analysis: X versus step

#### Method

Categorical predictor coding (1; 0)

#### **Regression Equation**

X = 11,9950 + 0,0 step\_1 + 0,0510 step\_2 - 0,0050 step\_3 - 0,2230 step\_4

#### Coefficients

Term	Coef	SE Coef	T-Value	P-Value	VIF
Constant	11,9950	0,0424	282,80	0,000	
step					
2	0,0510	0,0600	0,85	0,401	1,50
3	-0,0050	0,0600	-0,08	0,934	1,50
4	-0,2230	0,0600	-3,72	0,001	1,50


#### **Model Summary**


S	R-sq	R-sq(adj)	R-sq(pred)
0,134128	40,74%	35,80%	26,84%

#### **Analysis of Variance**

Source	DF	Adj SS	Adj MS	F-Value	P-Value
Regression	3	0,4452	0,14841	8,25	0,000
step	3	0,4452	0,14841	8,25	0,000
Error	36	0,6477	0,01799		
Total	39	1,0929			

The residuals are normal but not independent:





Bartlett's test at lag = 1 (95% confidence):

$$|r_k| = 0.361$$

$$\frac{z_{\alpha/2}}{\sqrt{n}} = 0.31$$

The autocorrelation at lag 1 is significant.

Therefore, it is possible to refit the model by including an autoregressive term AR(1):

#### Regression Analysis: X versus AR1; step

#### Method

Categorical predictor coding (1; 0) Rows unused 1

#### **Regression Equation**

ste	0
1	X = 7,73 + 0,361 AR1
2	X = 7,71 + 0,361 AR1
3	X = 7,64 + 0,361 AR1

X = 7,44 + 0,361 AR1

#### Coefficients

Term	Coef	SE Coef	T-Value	P-Value	VIF
Constant	7,73	1,88	4,12	0,000	
AR1	0,361	0,160	2,27	0,030	1,62
step					
2	-0,0226	0,0687	-0,33	0,744	2,13
3	-0,0970	0,0732	-1,33	0,194	2,42
4	-0,2948	0,0682	-4,32	0,000	2,10


#### **Model Summary**


S	R-sq	R-sq(adj)	R-sq(pred)
0.128313	48.30%	42.22%	29.23%

#### **Analysis of Variance**

Source	DF	Adj SS	Adj MS	F-Value	P-Value
Regression	4	0,52299	0,13075	7,94	0,000
AR1	1	0,08450	0,08450	5,13	0,030
step	3	0,49107	0,16369	9,94	0,000
Error	34	0,55979	0,01646		
Lack-of-Fit	31	0,51289	0,01654	1,06	0,569
Pure Error	3	0,04690	0,01563		
Total	38	1 08277			

Model residuals are normal and independent. The model is appropriate.





#### **Test**


Null hypothesis H<sub>0</sub>: The order of the data is random Alternative hypothesis H<sub>1</sub>: The order of the data is not random

#### Number of Runs Observed Expected P-Value


20 20,38 0,900

### <u>b)</u>


With  $ARL_0 = 200$ ,  $z_{\alpha/2} = 2.807$ . The I-MR control charts for model residuals are the following (do not consider the limits at k=3 in the figure).



Observation 36 violates the control limits of both charts. Assuming the existence of an assignable cause, it is possible to introduce a dummy variable that is equal to 1 for this observation and 0 elsewhere. The new model is still appropriate, with normal and independent residuals:



The resulting control chart is the following:





No further violation is present. The design phase is over.

#### <u>c)</u>

To make a test, it is possible to split the data into two vectors, one for spindle power measurements in the roughing operation (step 1, 2 and 3) and one for the measurements in the finishing operation (step 4). The out-of-control observation has been removed.

The two samples are normal and independent (although for the second sample the power of tests is quite low due to the small size of the sample).





#### **Test**

Null hypothesis Ho: The order of the data is random Alternative hypothesis  $H_1$ : The order of the data is not random

#### Number of Runs

#### Observed Expected P-Value

12 15,93 0,142

Null hypothesis Ho: The order of the data is random Alternative hypothesis H<sub>1</sub>: The order of the data is not random

#### Number of Runs

## Observed Expected P-Value 5 5,44 0,748

The p-value may not be accurate for samples with fewer than 11 observations above K or fewer than 11 below.

We shall first test for equality of variances:

#### Test and CI for Two Variances: step123; step4

#### Method

 $\sigma_{\scriptscriptstyle 1}$ : standard deviation of step123

 $\sigma_2$ : standard deviation of step4

Ratio:  $\sigma_1/\sigma_2$ 

The Bonett and Levene's methods are valid for any continuous distribution.

#### **Descriptive Statistics**

#### Variable N StDev Variance 95% CI for $\sigma$

step123 30 0,118 0,014 (0,098; 0,152) step4 9 0,086 0,007 (0,060; 0,156)

#### **Ratio of Standard Deviations**

#### Estimated 95% CI for Ratio 95% CI for Ratio

Ratio	using Bonett	using Levene
1,37731	(0,758; 2,027)	(0.733; 2.279)


#### **Test**

Null hypothesis  $H_0$ :  $\sigma_1 / \sigma_2 = 1$ Alternative hypothesis  $H_1$ :  $\sigma_1 / \sigma_2 \neq 1$ Significance level  $\sigma = 0.05$ 

#### Test

#### Method Statistic DF1 DF2 P-Value

Bonett \* 0,267 Levene 1,39 1 37 0,245



There is no statistical difference between the two variances. Thus, it is possible to make the following two-sample t test with equal variances:

## Two-Sample T-Test and CI: step123; step4

#### Method

 $\mu_1$ : population mean of step123  $\mu_2$ : population mean of step4 Difference:  $\mu_1$  -  $\mu_2$ 

Equal variances are assumed for this analysis.

#### **Descriptive Statistics**

Sample	Ν	Mean	StDev	SE Mean
step123	30	12,010	0,118	0,022
step4	9	11,7244	0,0857	0,029

#### **Estimation for Difference**

	9	5% Lower Bound
Difference	Pooled StDev	for Difference
0,2859	0,1119	0,2141

#### Test


T-Value DF P-Value 6,72 37 0,000

The test confirms that the power consumption during the finishing operation is statistically lower than the one in the roughing operation.


#### Exercise 2

<u>a)</u>

The time series plot of the four variables:



#### Their scatterplot:



The four variables are on different scales with different variances, as shown below. In this case, the PCA on the correlation matrix is the appropriate choice.

#### **Statistics**

Variable	Mean	StDev
x1	30,693	2,064
x2	15,800	1,321
x3	294,81	5,06
x4	77,213	3,214

#### <u>b)</u>

PCA on the sample correlation matrix:

ESE2


Principal Component Analysis: x1; x2; x3; x4

#### **Eigenanalysis of the Correlation Matrix**

Eigenvalue 1,9945 1,1151 0,8622 0,0282 Proportion 0,499 0,279 0,216 0,007 Cumulative 0,499 0,777 0,993 1,000

#### **Eigenvectors**

Variable	PC1	PC2	PC3	PC4
x1	0,605	0,159	0,518	0,583
x2	0,679	0,234	-0,088	-0,690
x3	0,406	-0,439	-0,725	0,342
x4	-0.091	0.852	-0 446	0.257




The number of PCs to retain to explain at least 75% of the overall data variability is 2.

#### <u>c)</u>

Before designing the  $T^2$  control chart on the scores of the first 2 PCs, assumptions shall checked (marginal normality is assumed as a sufficient condition for multivariate normality).

The scores of the two PCs are normal and independent.



#### Test


Null hypothesis H<sub>0</sub>: The order of the data is random Alternative hypothesis H<sub>1</sub>: The order of the data is not random

## Number of Runs Variable Observed Expected P-Value

y1 9 7,67 0,417 y2 10 8,20 0,313

The p-value may not be accurate for samples with fewer than 11 observations above K or fewer than 11 below.

With  $ARL_0 = 200$ ,  $\alpha = 0.005$ . The  $T^2$  control chart is the following (ignore the control limit at k=3).




The process is in-control.

#### <u>d)</u>

By adding the third PC, about 99% of the overall variability is explained. Before re-designing the control chart it is necessary to check assumptions for the scores of the third PC as well.

They are normal and independent.




# Test Null hypothesis H<sub>0</sub>: The order of the data is random Alternative hypothesis H<sub>1</sub>: The order of the data is not random Number of Runs


Observed Expected P-Value
7 8,20 0,502

The p-value may not be accurate for samples with fewer than 11 observations above K or fewer than 11 below.

The resulting control chart is the following:



Now, sample 5 is out of control. The anomaly in sample 5 corresponds to a peak in variable x4. When only the first 2 PCs are monitored, sample 5 is a bit outlying along PC2, as shown in the figure below where sample 5 is highlighted in red (note that PC2 associates a high weight to variable x4), but not enough to signal an alarm. When the third PC is included, the sample 5 anomaly is emphasized in the space spanned by PC2 and PC3, as shown below.



Looking at the eigenvectors, PC2 associates a high weight to variable x4 and contrasts it against variable x3. PC3 is instead a contrast between variables x3 and x4 on one side, and variable x1 on the other side. PC1 associated a very low weight to variable x4, instead.

## **Eigenvectors**

Variable	PC1	PC2	PC3	PC4
x1	0,605	0,159	0,518	0,583
x2	0,679	0,234	-0,088	-0,690
х3	0,406	-0,439	-0,725	0,342
x4	-0,091	0,852	-0,446	0,257

In the presence of the violation of the control limit at sample 5, a search for assignable causes shall be carried out. In the absence of further information, the control chart design phase is over.

The new dataset consists of 100 samples and its sample variance-covariance matrix is the following:

$$\mathbf{S} = \begin{bmatrix} 1.4 & 0.75 & 0.1 & 0.5 \\ 0.75 & 1.3 & 1.7 & 0.5 \\ 0.1 & 1.7 & 6.6 & 0.3 \\ 0.5 & 0.5 & 0.3 & 3.6 \end{bmatrix}$$

In order to compare the new PCs with the old ones in terms of explained variance, we shall compute the sample correlation matrix, reminding that:

$$\rho_{ij} = \frac{\text{cov}(x_i x_j)}{\sqrt{V(x_i)V(x_j)}}$$

The correlation matrix is the following:

1	0,56	0,033	0,22
0,56	1	0,58	0,23
0,033	0,58	1	0,06
0,22	0,23	0,06	1

The eigenvalues of this matrix are:

 $\lambda 1 = 1,92269$ 

 $\lambda 2 = 1,04890$ 

 $\lambda 3 = 0.81935$ 

 $\lambda 4 = 0.20906$ 

The eigenvalues estimated with Table 2 data were:

 $\lambda 1 = 1,99454$ 

 $\lambda 2 = 1,11505$ 

 $\lambda 3 = 0.86217$ 

 $\lambda 4 = 0.02823$ 

Considering a familywise  $\alpha = 0.05$  and assuming that normality and randomness hold for the new data as well, and that the two samples are independent, the following two tests can be designed to compare the explained variances of PC1 and PC2:

#### PC1:

ESE2

#### **Test and CI for Two Variances**

#### Method

 $\sigma_1^2$ : variance of Sample 1  $\sigma_2^2$ : variance of Sample 2

Ratio:  $\sigma_1^2/\sigma_2^2$ 

F method was used. This method is accurate for normal data only.

#### **Descriptive Statistics**

Sample	Ν	StDev	Variance	97,5% CI for o
Sample 1	10	1,412	1,995	(0,924; 2,844)
Sample 2	100	1 387	1 923	(1 195. 1 647)

#### **Ratio of Standard Deviations**

Estimated 97,5% CI for Ratio Ratio using F 1,01851 (0,643; 2,075)

## Test

Null hypothesis  $H_0$ :  $\sigma_1 / \sigma_2 = 1$ Alternative hypothesis  $H_1$ :  $\sigma_1 / \sigma_2 \neq 1$ Significance level  $\sigma = 0.025$ 

 Test

 Method
 Statistic
 DF1
 DF2
 P-Value

 F
 1,04
 9
 99
 0,832

#### PC2:

ESE2

#### Test and CI for Two Variances

#### Method

 $\sigma_1^2$ : variance of Sample 1  $\sigma_2^2$ : variance of Sample 2 Ratio:  $\sigma_1^2/\sigma_2^2$ 

F method was used. This method is accurate for normal data only.

#### **Descriptive Statistics**

Sample	Ν	StDev	Variance	97,5% CI for σ
Sample 1	10	1,056	1,115	(0,691; 2,126)
Sample 2	100	1,024	1,049	(0,883; 1,216)

#### **Ratio of Standard Deviations**

Estimated 97,5% CI for Ratio Ratio using F 1,03105 (0,651; 2,101)

#### Test

Null hypothesis  $H_0$ :  $\sigma_1 / \sigma_2 = 1$ Alternative hypothesis  $H_1$ :  $\sigma_1 / \sigma_2 \neq 1$ Significance level  $\sigma = 0.025$ 

| Test | Method | Statistic | DF1 | DF2 | P-Value | F | 1,06 | 9 | 99 | 0,794 |

There is no statistical difference between the variances of the first 2 PCs estimated with data in Table 2 and data from the new extended measurement campaign.

#### Exercise 3

The eigenvalues and eigenvectors of the correlation matrix for the given data are:

Eigenvalues:

 $\lambda 1 = 1,92269$ 

 $\lambda 2 = 1.04890$ 

 $\lambda 3 = 0.81935$ 

 $\lambda 4 = 0.20906$ 

Eigenvectors:

#### **Matrix EIG100**

0,496346 0,456492 -0,563462 0,477249 0,667311 -0,141026 -0,135166 -0,718706 0,457667 -0,675402 0,283056 0,504234 0,314447 0,561746 0,764278 0,037997

Let  $\mathbf{a}' = [a_1 \ a_2 \ a_3 \ a_4]$  be a 4x1 vector of weights of a linear combination  $\mathbf{a}'\mathbf{x}$  where  $a_1 = a_2 = a_3 = a_4$ .

Under the constraint a'a = 1,  $a_1 = a_2 = a_3 = a_4 = 0.5$ .

The variance of such linear combination is V(a'x) = a'Ra, where **R** is the sample correlation matrix. The variance is V(a'x) = 1.8415, which is lower than  $\lambda 1 = 1,92269$ . Indeed, the first PC is, among all possible linear combinations, the one that maximizes the explained variance.