OpenCore

Errata Sheet

[2025.10.10]

Copyright ©2020-2024 vit9696

1 Introduction

This document provides information on select issues discovered in the released versions of OpenCore and provides workarounds whenever possible. This document is updated after OpenCore is released and is thus not contained in the binary packages.

This document contains issues considered causing significant impact on the end-user. More details on all known issues including feature requests and development version issues can be found at Acidanthera Bugtracker.

2 Issue list

- **Identifier**: `ERR059-1`
  Published: 2020-06-02 08:06 MSK
  Updated: 2020-06-21 18:22 MSK
  Affected versions: 0.5.9
  Resolved in: 0.6.0 (9d5aa267)
  Description:

  Boot picker menu may not show when upgrading macOS with the following error:

  ```
  OCUI: Entry kind 16 unsupported for Icon
  OCB: ShowMenu failed - Unsupported
  Halting on critical error
  ```

  Possible workarounds:

  - Add `run-efi-updater` variable with `NO` string value `OR`
  - Avoid using OpenCanopy `OR`
  - Disable showing picker by setting `ShowPicker` to `false` `OR`
  - Update to master version

- **Identifier**: `ERR059-2`
  Published: 2020-06-02 08:06 MSK
  Updated: 2020-06-21 18:22 MSK
  Affected versions: 0.5.9
  Resolved in: 0.6.0 (670d4e0c)
  Description:

  Incorrect operating system may be selected as the default during macOS upgrade when Windows and macOS are installed on the same disk. Reference: acidanthera/bugtracker#948.

  Possible workarounds:

  - Add `run-efi-updater` variable with `NO` string value `OR`
  - Install Windows on a separate disk `OR`
  - Update to master version

- **Identifier**: `ERR059-3`
  Published: 2020-06-21 18:22 MSK
  Updated: 2020-06-21 18:22 MSK
  Affected versions: 0.5.9
  Resolved in: 0.6.0 (2449e47c)
  Description:

  DEBUG builds may fail to load due to unaligned access assertion when accessing device paths. Reference: acidanthera/bugtracker#951.

  Possible workarounds:

  - Avoid using DEBUG builds `OR`
  - Update to master version

- **Identifier**: `ERR059-4`
  Published: 2020-06-24 21:18 MSK
  Updated: 2020-07-05 23:20 MSK
  Affected versions: 0.5.9
  Resolved in: 0.6.0 (d8ace476)
  Description:

  Driver injection into `kernel collections` normally used in macOS 11, and required for macOS 11 installer, is unsupported.

  Possible workarounds:

  - For **preview** version of KernelCollection injection code please update to commit `d8ace476` and make sure that variables forcing legacy kernel loading (`booter-fileset-kernel` and `booter-fileset-basesystem`) are deleted from NVRAM.
  - For **preinstalled** versions of macOS 11 add NVRAM variable `7C436110-AB2A-4BBB-A880-FE41995C9F82:booter-fileset-kernel` with `00` value; for some EfiBoot variants it may also be required to set `booter-fileset-basesystem` variable with `00` value.

- **Identifier**: `ERR059-5`
  Published: 2020-07-25 18:24 MSK
  Updated: 2020-07-25 18:24 MSK
  Affected versions: 0.0.3-0.5.9
  Resolved in: 0.6.0 (426a5dbe)
  Description:

  `OSXSAVE` CPUID feature may not be reported to macOS release kernels when emulating the CPUID causing crashes of select programs relying on `Hypervisor.framework` like Docker. Reference: acidanthera/bugtracker#1035.

  Possible workarounds:

  - Manually enable the `OSXSAVE` bit in `ECX` register `OR`
  - Update to master version

- **Identifier**: `ERR060-1`
  Published: 2020-08-22 03:10 MSK
  Updated: 2020-08-22 03:10 MSK
  Affected versions: 0.0.1-0.6.0
  Resolved in: 0.6.1 (89be8ea5)
  Description:

  APFS-formatted macOS Recovery (e.g. Big Sur Recovery) will not load with a boot failure error. Reference: acidanthera/bugtracker#1078.

  Possible workarounds:

  - Enable `JumpstartHotPlug` `OR`
  - Update to master version

- **Identifier**: `ERR061-1`
  Published: 2020-09-11 14:55 MSK
  Updated: 2020-09-11 14:55 MSK
  Affected versions: 0.5.3-0.6.1
  Resolved in: 0.6.2 (d3cf117c)
  Description:

  APFS-formatted drives previously made available with `ApfsImageLoader.efi` driver are no longer visible with OpenCore builtin `EnableJumpstart` APFS functionality on platforms that need `UnblockFsConnect` quirk. Reference: acidanthera/bugtracker#1128.

  Possible workarounds:

  - Update to master version `OR`
  - Disable `ConnectDrivers` and enable `GlobalConnect` (may cause performance and compatibility issues depending on the driver use)

- **Identifier**: `ERR062-1`
  Published: 2020-10-25 01:22 MSK
  Updated: 2020-11-01 13:28 MSK
  Affected versions: 0.6.1-0.6.2
  Resolved in: 0.6.3 (1b004149)
  Description:

  Booting Big Sur beta 10 or newer will cause a kernel panic in `apfs.kext` with the `Rooting from the live fs of a sealed volume is not allowed on a RELEASE build` message. Reference: acidanthera/bugtracker#1235.

  Possible workarounds:

  - Update to master version `OR`
  - Set `SecureBootModel` to `Disabled`

  Note: On virtual machines `ForceSecureBootScheme` will also need to be enabled if `SecureBootModel` is different from `x86legacy` or `Disabled`.

- **Identifier**: `ERR067-1`
  Published: 2021-02-20 10:42 MSK
  Updated: 2021-02-20 10:42 MSK
  Affected versions: 0.6.6
  Resolved in: 0.6.7 (b4449f48)
  Description:

  Loading OpenCore via bootstrap may fail on certain Mac firmwares. Reference: acidanthera/bugtracker#1502.

  Possible workarounds:

  - Update to master version

- **Identifier**: `ERR088-1`
  Published: 2023-01-07 21:29 MSK
  Updated: 2023-01-07 21:29 MSK
  Affected versions: 0.8.8
  Resolved in: 0.8.9 (092af5d9)
  Description:

  Loading macOS in OpenDuet may fail. Reference: acidanthera/bugtracker#2190.

  Possible workarounds:

  - Update OpenDuet to master version

- **Identifier**: `ERR088-2`
  Published: 2024-02-06 13:36 GMT
  Updated: 2024-02-06 13:36 GMT
  Affected versions: 0.8.8+
  Resolved in: Won't fix
  Description:

  Some released versions of Linux kernel 6.7 and release candidates of 6.8 fail to load when using OpenDuet. This has been acccepted as a bug in the Linux kernel, for which a fix will be released in 6.8 and backported to 6.7. Reference: acidanthera/bugtracker#2371.

  Possible workarounds:

  - Use OpenDuet 0.8.7 or earlier, or wait for fixed Linux kernels to be released.

- **Identifier**: `ERR098-1`
  Published: 2024-02-08 09:28 GMT
  Updated: 2024-02-08 09:28 GMT
  Affected versions: 0.9.8
  Resolved in: 0.9.9 (4314fb31)
  Description:

  `ocvalidate` may report that `OpenVariableRuntimeDxe.efi` is incompatible with `FirmwareSettingsEntry.efi` even when `FirmwareSettingsEntry.efi` is not included and active in `config.plist` `Drivers` section. Reference: acidanthera/bugtracker#2379.

  Possible workarounds:

  - For 0.9.8 use version of `ocvalidate` provided in a comment on the above issue.

- **Identifier**: `ERR102-1`
  Published: 2024-11-30 18:46 GMT
  Updated: 2024-11-30 18:46 GMT
  Affected versions: 1.0.2

Resolved in: 1.0.3 (35bcb134)
Description:

Vault `sign.command` from 1.0.2 cannot correctly sign 1.0.2 `RELEASE` build. Reference: acidanthera/bugtracker#2443.

Possible workarounds:

- If it is required to sign 1.0.2 releases, the updated `sign.command` provided with 1.0.3 may be used.

- **Identifier**: `ERR105-1`
  Published: 2025-08-02 23:08 MSK
  Updated: 2025-08-02 23:08 MSK
  Affected versions: 1.0.5
  Resolved in: N/A
  Description:

  Linux may fail to load with OpenDuet. Reference: acidanthera/bugtracker#2507.

  Possible workarounds:

  - Enable `SyncRuntimePermissions` quirk.

- **Identifier**: `ERR001-1`
  Published: 2025-10-10 10:38 BST
  Updated: 2025-10-10 10:38 BST
  Affected versions: 0.0.1-1.0.5
  Resolved in: 1.0.6 (ec2713af)
  Description:

  In an OpenDuetPkg bug dating back to when DuetPkg was ported from edk to edk2, the ACPI RSDP table is published as ACPI 2.0 regardless of which version of ACPI is present. On old ACPI 1.0 systems (and on QEMU by default) this can result in bootloaders such Grub 2 trying to dereference the ACPI 2.0 XSDT pointer from uninitialised memory. Hence Linux may fail to boot on such systems, typically with a protection fault or page fault.

  Possible workarounds:

  - Use RELEASE rather the DEBUG build of OpenDuet if launching Grub 2 on a system with ACPI 1.0 (may still fail on some systems, depending on memory contents).