

Mobil™

Unit ID: 531.LQ110

Asset ID: 52305255

Description: Cement Mill #1 Inlet Shoe Beating Lubrication Unit

Account Information

Sample Information

Equipment Information

ID: 462031

Name: ASEC - ACC

Address: , , EG

Sample ID: 26124405250

Service Level: Enhanced

Bottle ID: b098085707

Tested Lubricant: MOBILGEAR 600 XP 460

Asset Class: Circulating System

Manufacturer: NA

Model:

Lubricant: MOBILGEAR 600 XP 460

Sample Data & Trends

Report StatusAlert

Sample ID26124405250

Service LevelEnhanced

Bottle IDb098085707

Tested LubricantMOBILGEAR 600 XP 460

Sampled27 Apr 2026

Reported05 May 2026

Equipment Age

Oil Age

Make-up Volume

Oil Changed

Filter Changed

Contamination RatingAlert

Equipment RatingAlert

Lubricant RatingNormal

ISO Code (4/6/14)

Particle Count >4um

Particle Count >6um

Particle Count>14um

PQ Index97

Visc@40C (cSt)442.3

Oxidation (Ab/cm)0

Water (Vol%)0.300

Ag (Silver)0

Al (Aluminum)15

Cr (Chromium)0

Cu (Copper)21

Fe (Iron)37

Mo (Molybdenum)0

Ni (Nickel)0

Pb (Lead)0

Sn (Tin)5

K (Potassium)0

Na (Sodium)0

Si (Silicon)57

B (Boron)16

Ba (Barium)0

Ca (Calcium)178

Mg (Magnesium)2

P (Phosphorus)330

Zn (Zinc)2

Viscosity

Wear

Contaminants

Physical Properties

442.3

27 Apr 2026

Visc@40C (cSt)

40

27 Apr 2026

Ag (Silver)

Al (Aluminum)

Cr (Chromium)

Cu (Copper)

Fe (Iron)

Ni (Nickel)

Pb (Lead)

Sn (Tin)

75

27 Apr 2026

Na (Sodium)

K (Potassium)

Si (Silicon)

0.4

27 Apr 2026

Water (Vol%)

Oxidation (Ab/cm)



Alert

Unit ID: 531.LQ110

Asset ID: 52305255

Description: Cement Mill #1 Inlet Shoe Beating Lubrication Unit

Account Information

ID: 462031
Name: ASEC - ACC
Address: , , EG

Sample Information

Sample ID: 26124405250
Service Level: Enhanced
Bottle ID: b098085707
Tested Lubricant: MOBILGEAR 600 XP 460

Equipment Information

Asset Class: Circulating System
Manufacturer: NA
Model:
Lubricant: MOBILGEAR 600 XP 460

Recommendation/Comments

ACTION REQUIRED - EXCESSIVE FERROUS DEBRIS. Determine cause of ferrous debris and take corrective action. If the ferrous debris level is elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. Potential causes of excessive ferrous debris include: a. Abnormal metallic component wear caused by abrasive dirt (or other contaminants); b. Material fatigue from heavy loads or other adverse operating conditions; c. Corrosive wear due to water, acids, or other contaminants in the lubricant; d. Normal "break-in" wear of new or recently replaced equipment. Inspect the equipment for signs of damage. Change the oil after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - ELEVATED SILICON LEVEL. Determine source of Silicon (Si) and take corrective action. If the silicon level is elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. If the wear metals levels are low, then the silicon likely exists in a non-abrasive form. Possible sources of non-abrasive silicon include: a. Defoamants; b. Sealant compounds. If wear metals levels are elevated, then the silicon likely exists in an abrasive form. Possible sources of abrasive silicon include: a. Abrasive dirt; b. Contamination from environment during an equipment overhaul or shutdown. Other possible sources of silicon include: a. Inefficient or leaking air intake filters; b. Leaking pipes; c. Clogged oil bath air filter; d. Poor oil filtration; e. Dirty sample containers or improper sampling procedures. In landfill gas applications, silicon can enter the engine as a siloxane. This material is a gas and is not normally abrasive; however, siloxanes can easily mask the presence dirt. The oil may be unfit for continued use and should be monitored closely for further condition regressions. Prolonged usage of lubricants with elevated levels of abrasive silicon can cause severe wear and damage to the equipment. Inspect the equipment for signs of excessive wear and change the oil immediately if damage is detected. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - EXCESSIVE WATER CONTAMINATION. Determine source of water and take corrective action. Analyze the oil with an on-site water test if accessible. Potential sources of water include: a. Leaking seals; b. Condensation resulting from low operating temperatures or prolonged shutdowns; c. Compromised oil cooler; d. Direct exposure to atmosphere as a result of compromises to system components (i.e. improperly sealed tank fill access point. Remove water from oil using centrifuges or dehydration units, or drain the oil and recharge the system with new oil. Resample the system after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - UNSATISFACTORY OIL CONDITION. Test results indicate that the condition of this oil sample is unsatisfactory. The oil may be unfit for continued use and should be closely monitored further condition regressions. Contact your ExxonMobil representative for further assistance if necessary.

ADMINISTRATION - PARTICLE COUNT DATA NOT REPORTED. The sample is heavily contaminated with visible sediment. Oil samples that contain significant levels of any contaminant can damage the laboratory's precision equipment. As a result, the particle count test was not completed, and analysis could not be provided. Before sending future samples to the laboratory, please ensure that no signs of visible sediment contamination are present. Consider the following: 1. The sample may not be representative of the system if it was acquired from a non-turbulent area (i.e. tank bottom); 2. Installing sample ports helps ensure that the sample is taken from the same location every time; 3. Tank fill caps and breathers might not be properly secured; 4. The filter / centrifuge may be operating incorrectly. If the sample was representative of the system, change the oil immediately to prevent equipment damage. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 27 Apr 2026 12:57 PM - Abd El Rahman Khaled - In Service Oil Sample: Comments: Photo: