

Mobil™

Alert

Unit ID: 531.MD302

Asset ID: 52305303

Description: Cement Mill #1 Separator Gearbox

Account Information

Sample Information

Equipment Information

ID: 462031

Name: ASEC - ACC

Address: , , EG

Sample ID: 26124405206

Service Level: Enhanced

Bottle ID: b098084875

Tested Lubricant: MOBIL SHC 632

Asset Class: Gear Drive

Manufacturer: FLENDER

Model: N/A

Lubricant: MOBIL SHC 632

Sample Data & Trends

Report StatusAlert

Sample ID26124405206

Service LevelEnhanced

Bottle IDb098084875

Tested LubricantMOBIL SHC 632

Sampled27 Apr 2026

Reported05 May 2026

Equipment Age

Oil Age

Make-up Volume

Oil Changed

Filter Changed

Contamination RatingAlert

Equipment RatingNormal

Lubricant RatingNormal

Diluted ISO Code (4/6/14)

ISO Code (4/6/14)

Particle Count >4um

Particle Count >6um

Particle Count>14um

PQ Index12

Visc@40C (cSt)274.9

TAN (mg KOH/g)1.40

Water (Vol%)0.100

Ag (Silver)0

Al (Aluminum)4

Cr (Chromium)0

Cu (Copper)0

Fe (Iron)44

Mo (Molybdenum)2

Ni (Nickel)0

Pb (Lead)0

Sn (Tin)0

K (Potassium)0

Na (Sodium)0

Si (Silicon)68

B (Boron)10

Ba (Barium)0

Ca (Calcium)115

Mg (Magnesium)5

P (Phosphorus)659

Zn (Zinc)26

Viscosity

Wear

Contaminants

Physical Properties

274.9

50

100

2

27 Apr 2026

27 Apr 2026

27 Apr 2026

27 Apr 2026

Visc@40C (cSt)

Ag (Silver)

Al (Aluminum)

Cr (Chromium)

Cu (Copper)

Fe (Iron)

Ni (Nickel)

Pb (Lead)

Sn (Tin)

Na (Sodium)

K (Potassium)

Si (Silicon)

Water (Vol%)

TAN (mg KOH/g)



Alert

Unit ID: 531.MD302

Asset ID: 52305303

Description: Cement Mill #1 Separator Gearbox

Account Information

ID: 462031
Name: ASEC - ACC
Address: , , EG

Sample Information

Sample ID: 26124405206
Service Level: Enhanced
Bottle ID: b098084875
Tested Lubricant: MOBIL SHC 632

Equipment Information

Asset Class: Gear Drive
Manufacturer: FLENDER
Model: N/A
Lubricant: MOBIL SHC 632

Recommendation/Comments

ACTION REQUIRED - ELEVATED SILICON LEVEL. Determine source of Silicon (Si) and take corrective action. If the silicon level is elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. If the wear metals levels are low, then the silicon likely exists in a non-abrasive form. Possible sources of non-abrasive silicon include: a. Defoamants; b. Sealant compounds. If wear metals levels are elevated, then the silicon likely exists in an abrasive form. Possible sources of abrasive silicon include: a. Abrasive dirt; b. Contamination from environment during an equipment overhaul or shutdown. Other possible sources of silicon include: a. Inefficient or leaking air intake filters; b. Leaking pipes; c. Clogged oil bath air filter; d. Poor oil filtration; e. Dirty sample containers or improper sampling procedures. In landfill gas applications, silicon can enter the engine as a siloxane. This material is a gas and is not normally abrasive; however, siloxanes can easily mask the presence dirt. The oil may be unfit for continued use and should be monitored closely for further condition regressions. Prolonged usage of lubricants with elevated levels of abrasive silicon can cause severe wear and damage to the equipment. Inspect the equipment for signs of excessive wear and change the oil immediately if damage is detected. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - EXCESSIVE WATER CONTAMINATION. Determine source of water and take corrective action. Analyze the oil with an on-site water test if accessible. Potential sources of water include: a. Leaking seals; b. Condensation resulting from low operating temperatures or prolonged shutdowns; c. Compromised oil cooler; d. Direct exposure to atmosphere as a result of compromises to system components (i.e. improperly sealed tank fill access point. Remove water from oil using centrifuges or dehydration units, or drain the oil and recharge the system with new oil. Resample the system after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - UNSATISFACTORY OIL CONDITION. Test results indicate that the condition of this oil sample is unsatisfactory. The oil may be unfit for continued use and should be closely monitored further condition regressions. Contact your ExxonMobil representative for further assistance if necessary.

ADMINISTRATION - SAMPLE NOT ANALYZED. Diluted Particle Count could not be performed due to the sample property of hazy, which does not comply with the operating limitations of the laboratory equipment responsible for conducting diluted particle count tests. Contact your ExxonMobil representative for further assistance.

Sample Timeline

- 27 Apr 2026 2:55 PM - Abd El Rahman Khaled - In Service Oil Sample : Comments: Photo:

Results and comments of this analysis are advisory only. The validity of the data may be impaired by a non-representative sample or incorrect data. © 2016-2024 ExxonMobil. ExxonMobil and Mobil are trademarks or registered trademarks of ExxonMobil Corporation or one of its subsidiaries. Other trademarks shown are property of their respective owners.