

MobilTM			Alert	
			Unit ID: 541.BE180	Asset ID: 52305290
			Description: Cement Mill #1 Belt Bucket Elevator Gearbox	
Account Information			Sample Information	Equipment Information
ID: 462031 Name: ASEC - ACC Address: , , EG			Sample ID: 26124405228 Service Level: Enhanced Bottle ID: b094005349 Tested Lubricant: MOBIL SHC 632	Asset Class: Gear Drive Manufacturer: FLENDER Model: N/A Lubricant: MOBIL SHC 632
Sample Data & Trends				
Sample Info	Report Status	Alert	Viscosity	
	Sample ID	26124405228		
	Service Level	Enhanced		
	Bottle ID	b094005349		
	Tested Lubricant	MOBIL SHC 632		
	Sampled	27 Apr 2026		
	Reported	05 May 2026		
	Equipment Age			
	Oil Age			
	Make-up Volume			
	Oil Changed			
	Filter Changed			
Lubricant	Contamination Rating	Alert		
	Equipment Rating	Normal		
	Lubricant Rating	Caution		
	ISO Code (4/6/14)			
	Particle Count >4um			
	Particle Count >6um			
	Particle Count>14um			
	PQ Index	12		
	Visc@40C (cSt)	257.8		
	TAN (mg KOH/g)	1.50		
	Water (Vol%)	0.110		
Wear (ppm)	Ag (Silver)	0		
	Al (Aluminum)	1		
	Cr (Chromium)	0		
	Cu (Copper)	0		
	Fe (Iron)	3		
	Mo (Molybdenum)	0		
	Ni (Nickel)	0		
	Pb (Lead)	0		
	Sn (Tin)	0		
Contaminant (ppm)	K (Potassium)	0		
	Na (Sodium)	0		
	Si (Silicon)	28		
Additive (ppm)	B (Boron)	10		
	Ba (Barium)	0		
	Ca (Calcium)	22		
	Mg (Magnesium)	2		
	P (Phosphorus)	377		
	Zn (Zinc)	13		



Alert

Unit ID: 541.BE180

Asset ID: 52305290

Description: Cement Mill #1 Belt Bucket Elevator Gearbox

Account Information	Sample Information	Equipment Information
ID: 462031 Name: ASEC - ACC Address: , , EG	Sample ID: 26124405228 Service Level: Enhanced Bottle ID: b094005349 Tested Lubricant: MOBIL SHC 632	Asset Class: Gear Drive Manufacturer: FLENDER Model: N/A Lubricant: MOBIL SHC 632

Recommendation/Comments

ACTION REQUIRED - EXCESSIVE WATER CONTAMINATION. Determine source of water and take corrective action. Analyze the oil with an on-site water test if accessible. Potential sources of water include: a. Leaking seals; b. Condensation resulting from low operating temperatures or prolonged shutdowns; c. Compromised oil cooler; d. Direct exposure to atmosphere as a result of compromises to system components (i.e. improperly sealed tank fill access point. Remove water from oil using centrifuges or dehydration units, or drain the oil and recharge the system with new oil. Resample the system after corrective measures have been implemented. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - UNSATISFACTORY OIL CONDITION. Test results indicate that the condition of this oil sample is unsatisfactory. The oil may be unfit for continued use and should be closely monitored further condition regressions. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - ELEVATED TAN. The Total Acid Number (TAN) of the sampled oil is above the Original Equipment Manufacturer (OEM) limits for this grade. Determine cause of elevated TAN and take corrective action. If the TAN is elevated for the first time with no history of an increasing trend, then resample immediately to confirm condition. Possible causes of an elevated TAN include: a. High oil temperature; b. Localized hot spots; c. Over-extended oil service life; d. Contamination with an oil that has a higher TAN; e. High rates of oxidation and nitration resulting in the formation of organic and inorganic acids. Contact your ExxonMobil representative for further assistance if necessary.

ACTION REQUIRED - REDUCED OIL VISCOSITY. Determine cause of reduced oil viscosity and take corrective action. Reduced viscosities can impair the lubricant's ability to protect the equipment. Possible causes of reduced viscosity include: a. Initial fill or contact with oil that has a lower viscosity; b. Contamination with a fuel or solvent; c. Incorrectly labeled sampled. Inspect the system for signs of fuel or coolant ingress. Resample the oil after corrective actions have been implemented. If the condition continues or escalates, recharge the system with new oil. Contact your ExxonMobil representative for further assistance if necessary.

ADMINISTRATION - PARTICLE COUNT DATA NOT REPORTED. The sample is heavily contaminated with visible sediment. Oil samples that contain significant levels of any contaminant can damage the laboratory's precision equipment. As a result, the particle count test was not completed, and analysis could not be provided. Before sending future samples to the laboratory, please ensure that no signs of visible sediment contamination are present. Consider the following: 1. The sample may not be representative of the system if it was acquired from a non-turbulent area (i.e. tank bottom); 2. Installing sample ports helps ensure that the sample is taken from the same location every time; 3. Tank fill caps and breathers might not be properly secured; 4. The filter / centrifuge may be operating incorrectly. If the sample was representative of the system, change the oil immediately to prevent equipment damage. Contact your ExxonMobil representative for further assistance if necessary.

Sample Timeline

- 27 Apr 2026 3:08 PM - Abd El Rahman Khaled - In Service Oil Sample : Comments: Photo: