

6 litres, new drain and fill plugs were put out for the service. The old ones looked fine but they do this perhaps not because they have to but because they can.



Removal of under panel



Draining oil then install new drain plug. Oil looked new



tape applied to protect pan seal



static refilling of PDK , the oil fill hole is quite difficult to get to and the pump he used had a 90 degree elbow fitting on the end of it to get to the hole.



engine running and running of PDK thru gears then engine off
filling PDK again



engine running and running thru gears again then engine off

hook up PIWIS, start car, bring PDK up to 30 degrees (about 4 minutes) place car in PDK FILL MODE and add Pentosin to finish PDK fill till running out of the fill hole and then replace new fill plug. This PIWIS process took no more than 5 minutes as stated in procedure list





Drain the PDK transmission fluid, replace the drain plug if possible (the Factory installed drain plug is plastic).
Replace the PDK transmission pan and all the pan bolts. Note:
The PDK transmission oil pan incorporates the filter assembly. All

the PDK Transmission oil pan bolts (6.00mm x 25.00mm) are of aluminum construction. It is recommended to always replace aluminum fasteners as a general rule, to never reuse them. Torque all the aluminum oil pan bolts to 24.0" In-Lb. (24.0 Inch Pounds).

Place masking tape on the seam of the oil pan to the transmission, directly under the fill Plug area to keep oil out of the Crevice/Seam mating area (The masking tape length should be roughly 6" long).

Static fill the PDK transmission with fluid until it runs out of the fill-plug hole, leave the fill plug off for now.

Connect a suitable scan tool and then set it up to monitor the PDK fluid temperature. Attention: Hot oil can scold!

Start and run the engine in "Park", immediately add fluid if it is not running out of the fill plug hole, carefully maintain this fluid level throughout the whole fill process.

Cycle the shifter through all shift modes of R-N-D at least once, pausing for 1-2 seconds in each mode.

Move the shifter selector into "Park" mode.

Closely monitor the PDK fluid temperature. When the PDK fluid reaches the temperature of 30°C (86°F), you must command the vehicle utilizing a scan tool into the transmission "Fill mode". The scan tool will not enter the "Fill Mode" until the PDK transmission oil temperature reaches 30°C (86°F), BUT at no higher than 40°C (104°F). PLEASE NOTE; this process must be expediently followed because the "Oil Fill" mode ends sharply after 5 minutes. Now fill the PDK fluid while the transmission is in the "Fill Mode". Put the PDK fluid fill plug in and torque it to 26.0' +/- 2.0 Ft-Lbs. (26.0 Foot Pounds) while the engine is still running.

Remove the previously applied tape and then clean all the residual fluid off of the exterior surfaces.

Turn the engine off.

Reassemble the car as per the Workshop Manual in PIWIS TSI Online.

As a recommendation only, it is best to check the rear wheel alignment on the Mid-Engine Sports Cars due to having the Chassis Strengthening Plate removed for the PDK fluid service. NOTE: The Porsche factory recommended Service Interval for the PDK transmission fluid is every 60,000 miles. It might be advisable to recommend this service every 40,000 miles for a healthier transmission and also for better shifting characteristics.

NOTE: Consult with PIWIS TSI Online for any additional needed information.

Transmission Pan/Filter Kit PN: 9G1.321.025.00 (This kit includes the drain plug and all the oil pan bolts)

Transmission Fluid PN: 000.043.207.29 (Usually requires roughly 4.5 – 5.5 Liters)