INY3 M25B

LIMPIAR ZONA DEL MOLDE

	100L1X				0.1263
\sim	191.7263 loc face 100 en X	191.0000	191.6000	190.4000	0.7263

CAMBIAR PIN

1041L2				0.0831
169.6831	168.7000	169.6000	167.8000	0.9831
loc fond 1041 / X				

NO SE PUEDE CAMBIAR PIN EN MAQUINA


1061L2 0.0181 169.4181 168.5000 169.4000 167.6000 0.918 loc fond 1081 / X	Q

FALTA DE MATERIAL EN C300


	3.1.4				
	3072L2				-0.6730
\sim	182.0270 loc face 3072 / X	183.3000	183.9000	182.7000	-1.2730


APORTAR MATERIAL EN EL MODE






V1102SQ1B








Exceso material pieza: Aportar material con Spark Depo

LIMPIAR MOLDE


41	21SQ1			0.1463
	1.3463	0.0000	1.2000	1.3463
X	-105.6058	-105.6058		0.0000
	-95.9280	-95.2842		-0.6438
Ζ,	-143.5183	-143.7151		0.1968


CAMBIAR PIN

4140L2				0.1848
57.1848 loc fond 4140 / Y	56.4000	57.0000	55.8000	0.7848





APORTAR MATERIAL AL MOLDE






SOLO SE PUEDE LIMPIAR ALUMINIO









Faltas material pieza: SOLO SE PUEDE LIMPIAR ALUMINIO Exceso material pieza: NO TOCAR

SOLO SE PUEDE LIMPIAR ALUMINIO

