Fault code: 4010 Furnace Motor Faulty

Туре
Error Code
Solution
IMPORTANT:
Do not rotate the furnace with your hands as it may be hot.
1. If this fault occurs, determine whether the furnace head is rotating? If so, restart the machine and check whether the fault is removed
2. If the furnace head does not rotate, or is in the jitter state, shut down and take a tool to turn the furnace head to see if there is resistance, no resistance, check whether the furnace head drive line is loose
3. If there is resistance during rotation, open the stove head cover to check whether there is syrup attached to the center pipe, if so, it is necessary to clean up the remaining syrup and ensure it rotates smoothly.
Created by
J Jason Lopez