Service Bulletin SB-2025-04 – Thermostatic valve on VS-37 units

Affected units: VS-37 compressors with serial numbers VS37-19-xxxx to VS37-21-xxxx (this includes COMP-A-01 and COMP-A-02).

Issue: the wax element of the thermostatic valve may degrade after about 20 000 operating hours. A sticking valve sends too little oil through the cooler and causes high discharge temperature warnings (A-12) even with a clean cooler.

Recommended check

1. If A-12 occurs twice within 60 days and the cooler is clean, measure oil temperature before and after the cooler.
2. A difference below 5 °C at full load indicates a faulty thermostatic valve.
3. Replace with kit TV-37-B (new wax element, opening at 71 °C).

Parts

Part number	Description
TV-37-B	Thermostatic valve kit, revision B
OR-37-TV	O-ring set

Table 1 – Parts

NOTE – This bulletin does not change the oil change interval (4000 h with MD-Lub S46).