

Engineering Change Notice

ECN-1042

ECN Number:	ECN-1042
Title:	Pressure Sensor Replacement (PS-04 → PS-04A) and Operating Pressure Update
Effective:	Software Revision 3.2
Affected Assembly:	Hydraulic Power Unit (HPU)
Status:	Released

1. Description of Change

Effective software revision 3.2, pressure sensor **PS-04** is replaced by pressure sensor **PS-04A** at the HPU discharge line. PS-04A uses an updated signal conditioning circuit and is not a form-fit-function replacement for PS-04; controller firmware must be at revision 3.2 or later to read PS-04A correctly.

Alongside the sensor change, the normal HPU discharge pressure setpoint is revised from **180 bar** to **200 bar**. This is a deliberate process change, not a sensor calibration artifact: the higher setpoint improves press cycle time on Series-7 units manufactured after 2024.

PS-04 remains installed and supported on units running software revisions prior to 3.2. Do not install PS-04A on a controller running firmware older than 3.2.

2. Reason for Change

Field data showed PS-04's signal drift exceeded tolerance after approximately 18 months of continuous service in high-cycle installations, occasionally triggering nuisance Alarm A19 (Sensor Signal Invalid). PS-04A corrects this drift behavior.

3. Impacted Documentation

Operator Manual AEG-OM-700, Maintenance Manual AEG-MM-700, and Component Register AEG-CR-700 have been updated to reflect PS-04A and the 200 bar setpoint. See also ECN-1058 for a related alarm threshold correction.